

Uttar Gujarat Vij Company Ltd ,Mehsana		
Performas for FY 2024-25		
<u>Performa No.</u>	<u>Particulars</u>	<u>Remarks/Report</u>
SoP 001	Fatal & Non Fatal Accident Report	Yearly Report
SoP 002	Action taken report for safety measures complied for the accidents occurred	Yearly Report
SoP 003	Register for compiling the complaints classification wise	Yearly Report
SoP 004	Actions or steps carried out by UGVCL towards public awareness in the year	Yearly Report
SoP 005	Failure of Distribution Transformer.	Yearly Report
SoP 007	Sample Test result for Neutral Voltage	Yearly Report
SoP 008	Sample result for Voltage Variations	Yearly Report
SoP 009	Sample Test result for Harmonics	Yearly Report
SoP 010 - A	System Average Interruption Frequency Index (SAIFI)	Yearly Report
SoP 011	System Average Interruption Duration Index (SAIDI)	Yearly Report
SoP 012	Momentary Average Interruption Frequency Index (MAIFI)	Yearly Report
SoP 013	Customer Average Interruption Duration Index (CAIDI)	Yearly Report
SoP 014	System Losses at EHT / 11 KV and below	Yearly Report
SoP 015	Meter Faults	Yearly Report
SoP 016	Compensation Details	Yearly Report
SoP 017	Individual Complaint where Compensation has been paid	Yearly Report
SoP 018	Unauthorised Use of electricity	Yearly Report
SoP 019	Theft of electricity	Yearly Report

Uttar Gujarat Vij Company Limited

Performa - SoP 001 : Fatal and Non-fatal Accident report

YEAR 2024-25 (April-24 to March-25)

Sr. No.	Name of Circle	No.of accidents during the quarter					Cumulative since the first quarter of the current FY				
		Departmental		Outside			Departmental		Outside		
		FH	NFH	FH	FA	NFH	FH	NFH	FH	FA	NFH
1	Sabarmati	1	15	47	32	4	1	15	47	32	4
2	Mehsana	0	7	31	16	4	0	7	31	16	4
3	Palanpur	0	8	31	16	8	0	8	31	16	8
4	Himatnagar	0	4	22	39	3	0	4	22	39	3
	<u>TOTAL</u>	1	34	131	103	19	1	34	131	103	19

SOP 002 Action taken report for safety measures compiled for the accidents occurred yearly 2024-25 (April-2024 to March-2025)											
Sr. No.	Circle, Division, Subdivision	Location of Accident and Rural or Urban	Name of Victim/Owner & Designation	Date of Occurance	Type of Accident FHD/NFHD/FHO/NFHO/F AO	Cause of Accident	Findings of CEI/EI/ AEI	Remedies suggested by CEI / EI/ AEI in various cases	Whether the remedy suggested is complied	Action taken to avoid recurrence of such Accident.	Amount of Compensation and Date of compensation paid (in Rs.)
1	2	3	4	5	6	7	8	9	10	11	12
1	Sabarmati/ Sabarmati/ Mandal	Endla/ Rural	B.P.Nayakpuria(Ele.Asst)	09.04.24	NFH	As per site visit, the victim and other staff after taking l.c of 11 kv Jesangpura Jgy from 66 kv Endla ss, made earthing on 2 side of the above said location and isolating the section by opening AB switch prepared for wire stringing with Safety belt and helmet. Victim climbed the PSC pole no. 17 Jesangpura JGY with extension, hooked up the safety belt in V-x arm, opened up the 1st pin binding, meanwhile the pole tilted down and fell on to the ground, and right leg of victim came under V-x arm's one side and got injured . Then immediately victim was shifted to Shiv Hospital at Viramgam by private vehicle for further medical treatment. On Further investigation in site pole was found cracked & damaged beneath the ground level.	Yet not received	N/A	N/A	NEW POLE ERECTED	
2	Sabarmati/ Bopal// /Changodar	Navapura/ Rural	Jigarkumar R Thakor EA	10.04.24	NFH	On Date 10/04/24 Approximately 13:20 HR at Navapura , Sun Shine Ind hub shri Jigar R Thakor EA was working for binding a insulated twin wire on Transformer centre's pole , near DO's Angle to lift the Service wire to be laid for new service connection. As 11 kv power supply was ON at the upper side of DO fuse , while binding this wire suddenly the wire came in contact with live side of DO pin and he got shocked, electrocuted and fell down from the pole but he was still conscious	Regulation 14 and 15 of central electricity authority regulations 2023 has been violated	Earthing must be done before start the work	Yes	Memo issued by SDO for proper observing safety norms and Monthly one Safety meeting carried out for line staff by SDO in which they are educated for the same.	
3	Sabarmati/ Bavla// /Sanand-2	Iyava/ Rural	Rabari Ramjibhai Vastabhai	12.04.24	FA	While eating leaves of Neem tree Camel came in contact with live conductor of 11 kv Khenderaopura AG HT line and got electrocuted and died	Regulation 14 and 50 of central electricity authority regulations 2023 has been violated	Earthing must be done before start the work and electrical lines should be properly checked to ensure that they are safe.	Yes	LINE RE-STRINGING OF LINE & RE STRAIGHTTNING OF GUY DONE & TREE CUTTING	
4	Sabarmati/ Gandhinagar / U/ Adalaj	Moti Adaraj / Rural	Thakor Dashrathji Rajiji	27.04.24	FH	On dt 27.4.24 time 18:30 hrs there is a marriage function at Thakor Bhikhaji jivaji 's home. so Shri Dashrathji Rajiji Thakor come to there house and climb on LT LINE POLE for hanging light Fox for lighting on street. During climbing on LT pole he fall down on RCC road and then people took him to Gandhinagar / civil but Doctor declared him dead.	Regulation 21 and 75 of central electricity authority regulations 2023 has been violated	No work should be done on pole without permission of the company.	NA	No any Action Taken	
5	Sabarmati/ Bopal// Bavla/ Ind.	Ch Vasna/ Rural	Amrutbhai Kachrabhai Prajapati LM	04.06.24	NFH	On Dt.04/06/24 at 2.22 am Msg received from 66 kv Bhat Substation that 11kv Shivanta Ind Feeder under p.f. So Mr A K Prajapati LM & Other EA went to attend Feeder fault and while Feeder Petrolling they came to know that One heavy Tractor having 21ft height passed near fourvent company and broken HT line conductor in Akshar Industrial Park as well as jumper burnt on Schackle Pole at Loc.13 & Loc.14 then after disconnecting AB Switch at Loc no.10 & Feeder made ON and then after rectified fault in Akshar Park they shifted on Loc13 to attend Burnt Jumper and Mr A K Prajapati (L.M) climb on Pole to rectify jumper and suddenly Power came from unknown location (Location still not identified) and he got shocked, electrocuted and hanged on 9ft. Angle of Two Pole Structure and other staff Mr K K Sathwara E.A.(V.S) has taken him out from the Pole and shifted him for primary treatment at Sola Civil Hospital, Ahmedabad and then shifted at SAL Hospital for further treatment and at present Mr A K Prajapati is in normal condition and conscious .	Regulation 14 and 21 of central electricity authority regulations 2023 has been violated	The line should be properly shut before start electric work.	Yes	Memo issued by SDO for proper observing safety norms and Monthly one Safety meeting carried out for line staff by SDO in which they are educated for the same.	
6	Sabarmati/ Bavla// Barejadi	Kanij/ Rural	Hajaraben Mohamadbbhai Vohra	06.06.24	FH	As per site visit investigation, at consumer no: 26501102154 name: AMINABEN KASHAMBHAI MANSHURI, power supply at accident place is given. Approx.07:30am dated: 06.06.2024 accident took place and we visited the site at 11:30 am on dated: 06.06.2024. Arriving at site, we firstly inspected the service connection wire of consumer no: 26501102154 and found that service connection wire was not cracked, damaged as well as not puncharted (leakage) neither was cut nor joint from anywhere around. On further investigating the site, near the entrance of the house we found the iron rope wire was one side tied with supporting wood clamp for metal roof sheet and another side with the plastic pipe of the bathroom terrace. Across the plastic pipe there was a private wire (for bathroom bulb connection) which was tied surrounding the plastic pipe and iron rope wire and the private wire was found puncharted (Insulation was broken). That private wire (Insulation was broken) was in contact with the iron rope wire. As per witness present, Victim was drying wet clothes on that rope wire and got electrocuted. It can be conclude that accident was taken place due to the consumer wiring. At Premises no MCB or ELCB was installed. So, Meter connection is disconnected till new test report is submitted by consumer. No any complain received from kanij village regarding above-mentioned	Yet not received	N/A	N/A	TEST REPORT WAS ACCEPTED WITH NEW ELCBS TESTING REPORT	
7	Sabarmati/ Gandhinagar / R /Dehgam T	Dehgam/ Rural	Amit A Dantani EA	08.06.24	NFH	on dt. 07/06/2024 @ 11.40 pm shivnagar area power off complaint registered on complaint office no.vide 2096. @ 12.00 am Shri Amit A Danatani Electrical assistant & shri P A Mahida apprentice lineman reach at site and they found that LTDB switch was OFF and he tried twice to ON without stripping of transformer DO but it didnot. Again he try to ON the switch and suddenly Blast occured and shri A A dantani, EA came in touch with the flame of fire and his face, hair, and left hand scene burnt and he was transferred to the Civil Hospital, Dehgam and he has taken primary treatment then present Dr referred him to private hospital. He was then admitted to Shelby Hospital, Naroda in office vehicle. Now he is stable .	Regulation 21 of central electricity authority regulations 2023 has been violated	Safety gadgets must be used	Yes	FAULTY LTDB REMOVED FROM PLACE AND POWER SUPPLY RESTORED	
8	Sabarmati/ Bavla// /Dhandhuka	Dhandhuka/ Rural	Musebhai Rahimbhai Desai	13.06.24	FA	Return power came on neutral on Tc due to contact with street light phase to fabrication of pole and due to heavy wind dp box open and came in touch with fencing. Water logging under tc structure and fencing. When cow passing through water in which leakage current flow from fencing so cow is electrocuted and died. Cow was pregnant.	Yet not received	N/A	N/A	LEKAGE CURRENT PROBLEM RESOLVED	15000/ 9.8.24

Sr. No.	Circle, Division, Subdivision	Location of Accident and Rural or Urban	Name of Victim/Owner & Designation	Date of Occurance	Type of Accident FHD/NFHD/FHO/NFHO/F AO	Cause of Accident	Findings of CEI/EI/ AEI	Remedies suggested by CEI / EI/ AEI in various cases	Whether the remedy suggested is complied	Action taken to avoid recurrence of such Accident.	Amount of Compensation and Date of compensation paid (in Rs.)
1	2	3	4	5	6	7	8	9	10	11	12
9	Sabarmati/ Gandhinagar U /Ognaj	Jagatpur/ Rural	Mahipal Ravji Nanoma	15.06.24	FH	Late Shri Mahipal Ravji Nanoma was doing hole in the wall for wiring with cutter machine . The plug of the cutter machine was connected with binding wire which is further connected with extra long wire to switch board.The plug of the cutter machine which is connected with wire was found open and might be live while making hole in the wall.The live plug might have came in contact with body and victim might be electrocuted from live plug.Final actual cause of accident may be known after PM report and EI report.	Uses of hanging, exposed, dangerous, temporary power wiring should be avoided accidents.	Residual current device should be used in working condition in power connection.	Yes	Not applicable .Inside Private Premises	
10	Sabarmati/ Bavla/ Koth	Dholi/ Rural	Chavda Natvarbhai popatbhai	23.06.24	FA	While going to the field for grazing the Cow .cow is passing below the HT Line of 11 kv Sarandi Ag Feeder. suddenly due to heavy wind Conductor Broken and Fell down on Cow. And due to cow came in live wire contact got electrocuted and die.	Regulation 14 and 50 of central electricity authority regulations 2023 should be followed	measure such as proper and efficient installation should be done and electrical lines should be properly inspected and ensure that they are safe.	Yes	SNAPPED HT CONDUCTOR RECTIFIED	30000/ 4.12.24
11	Sabarmati/ Sabarmati/ Naroda U	Enasan/ Rural	Thakor Karan Ravjibhai	25.06.24	FH	On dated 25.06.2024 around 02:20 am during night hours outside person Other than Indian oil petrol pump namely Jitendra Rohit Bhai Chauhan resident at Enasan park their Kia car behind the petrol pump open space area. After parking their car nearer white iron ladder height around 5 MTR found at that location, for no further scratch or damage by this iron ladder while in the rainy atmosphere he gave directives to Shri Karan Ravjibhai Thakor to take it to other open space by pushing it, And during this iron ladder touch the live 11 kv rudra fdr line & electrocuted & died. Height of 11 kv rudra fdr line to ground level 6.2 MTR, but in petrol pump premises height of 11 kv rudra fdr 4.8 MTR due to sand filling area. No any line shifting or line raising application given by the petrol pump premises owner.	Regulation 14,60 and 66 of central electricity authority regulations 2023 has been violated	Proper distance of the power line from the ground should be maintained and care should be taken that no iron or metal object should be taken under the power line.	Yes	HT LINE INSIDE PETROL PUMP AREA SHIFTING OUT SIDE DONE DUE SAFETY POINT OF VIEW.	100000/ 4.9.24
12	Sabarmati/ Sabarmati/ Viramgam R	Meldinagar/ Rural	Bharvad Nanubhai Lalabhai	25.06.24	FA	A cow is passing through near by TC center and During the time of Horn of cow is entangled in Transformer Fencing touches when leakage current passed by Transformer earthing to Fencing.Therefore power becomes earth and cow got electrocuted and died.	Yet not received	N/A	N/A	NEW TC EARTHING PROVIDED	
13	Sabarmati/ Bavla/ Dholka R	Rajpur/ Rural	Anandbhai Maheshbhai Chauhan	25.06.24	FH	when he went to see if there was water fill up on the roof of the house, he may got electrocuted by nearby HT line passing over the roof of the house.	Yet not received	N/A	N/A	LINE SHIFTING ESTIMATE ISSUED BUT NPC.	
14	Sabarmati/ Bopal/ Changodar	Juna Vanjar/ Rural	Popatbhai Nanjibhai Ninama EA (Emp No 12434)	28.06.24	NFH	On Date 28/06/24 in the morning there was a tripping on Ashapura JGY feeder @ 0557 am , feeder was kept in PF after not getting ON and SS staff informed Shri Popatbhai Ninama so he got ready with his safety equipment to attend the fault meanwhile he got a call from Juna Vanjar village that HT pole (location no 228)broken by Dumper near village TC so immediately he rushed to the location and made feeder ON after isolating the section of Juna Vanjar as the pole was broken and hanging above the road he needs to get the pole moved aside the road, shri Popatbhai Ninama EA was removing the conductors from the pole but while removing last conductors suddenly and accidentally pole got swing and fallen on left feet of Shri Popatbhai Ninama and he got injured so immediately he called his colleague EA Shri Sanjay Ninama , and Shri Sanjay Ninama took him to the nearest hospital, Navjivan hospital, Sarkhej, Shri Popat Ninama was given first aid there and as he got Major injury he was taken to CIMS hospital, Sola , Ahmedabad	Yet not received	N/A	N/A	Memo issued by SDO for proper observing safety norms and Monthly one Safety meeting carried out for line staff by SDO in which they are educated for the same.	
15	Sabarmati/ Sabarmati/ Vinzol	Dhamatvan/ Rural	Kanubhai Naranbhai Rabari	29.06.24	FA	a fatal accident occurred due to a cow came in contact of fencing of transformer of Bhatthiji maharaj temple,On inspecting site, no leakage current found on fencing or transformer earthing, hence accurate decision can be taken after post mortam report	Accident occurred due to unbalance of electrical load on the 11 kv/440 volt transformer. The wire was broken.	Electricity should be repaired periodically as per regulation no.14 of central electricity authority regulations 2023	Yes	EARTHING RECTIFICATION DONE	
16	Sabarmati/ Bopal/ Changodar	Changodar/ Town	Luvkush Yadav	30.06.24	FH	On Date 30/06/24 @ 2050 hrs the evening It was raining , Victim shri Luvkush Yadav came to the Grocery Shop of Shri Ramesh Yadav which is located at Tajpur road near Ratnam residency , he was a regular customer of this shop , he came for "Garam Masala " so he was finding on his own in the shop , somehow suddenly he hold the shutter by his right hand and he got shocked and stuck to the shutter so he screamed , Shri Ramesh Yadav , shop keeper , saw him so immediately he tried to separate him from shutter with his bare hand so Ramesh Yadav also got shocked and fell down so he took wooden strip and separated him from the shutter , as soon as he separated Luvkush fainted on ground and got unconscious. Ramesh Yadav and other customer shri Rinku took him to nearby hospital but Doctor referred Victim to bring him to Civil hospital, Ahmadabad , so he was taken to the Civil Hospital, Sola . Where he was declared dead by resident doctor	Residual current device should be used in working condition in power connection.	Avoid using faulty wiring	Yes	Advised Shop Owner Not To Use MCB Instead Of That Strictly Instructed Him To Use ELCB / RCCB	
17	Sabarmati/ Gandhinagar U /Chandkheda	Chandkheda / Town	Kinjal Ben Sahdevbhai Rabari	01.07.24	NFH	As per report received of Chandkheda police station as on dated 2.7. 24 at 6.00 pm Kinjal Ben sahdev Bhai Rabari as on dated 01.7.24 at approx 7 pm during shifting of house hold on first floor of new made house she touch Ugvcl LT line passing near to the wall of First floor gallery. She stand up in gallery and touches the hand of LT line and electrocuted . immediately Sent to shayon hospital by her family members .As on dated 2.7.24 at evening discharged to the victim and health is normal .This office had already given notice to owner and line shifting estimate but not paid by owner. Estimate with Notice outward no 4717/ 18.12.2023 .. eventhough issue notice owner had made new/extension of house near by UGVCL line...	Accident occurred due to illegal construction	Vericle and horizontal clearance are maintained to prevent such accidents.	Yes	1nos of Pole Shifted ..and Restraining Work Carried out	

Sr. No.	Circle, Division, Subdivision	Location of Accident and Rural or Urban	Name of Victim/Owner & Designation	Date of Occurance	Type of Accident FHD/NFHD/FHO/NFHO/FAO	Cause of Accident	Findings of CEI/EI/ AEI	Remedies suggested by CEI / EI/ AEI in various cases	Whether the remedy suggested is complied	Action taken to avoid recurrence of such Accident.	Amount of Compensation and Date of compensation paid (in Rs.)
1	2	3	4	5	6	7	8	9	10	11	12
18	Sabarmati/ Gandhinagar U/ Ognaj	Jagatpur/ Rural	Mahendrasinh Mohansinh Ravat	01.07.24	FH	During site visit, it is found that one white coloured metal cabin installed for the employee of the contractor and from this cabin one iron sheet supported through iron angle to top of this cabin and other side of iron sheet also supported to ground through iron angle. Behind the cabin one ELCB and MCB installed for electricity of the cabin. When checked, the outgoing wiring from ELCB to cabin it is found that one red colour and one black colour wire's insulation found broken. After giving power supply to this ELCB and MCB and checked by tester on broken wire, leakage current found on tester. As per statement from person available at site on date of accident there was rain and one labour named Mahendrasinh Ravat was passing near this cabin and due to wet ground due to rain, victim slipped and lost his balance and taken the support of iron angle and may be electrocuted due to leakage of current passing from broken wire from ELCB outgoing to metal cabin and iron sheet to iron angle...	Yet not received	N/A	N/A	Not applicable ..Inside Private Premises	
19	Sabarmati/ Bopal/ SHILAJ	Ambali/ Rural	Achintabhai Dhirendranath Bishvas	02.07.24	FH	On Date 02/07/2024 @ 1830 hrs the evening shri achintabhai dhirendrabhai bisvaas was came at his onsite iron container Type residence beside west side of Village ambali. When he had just touch the handle of door of container to open, he suddenly got shocked and fell down on ground and shouting other for help so nearer neighbour took him to hospital for primary treatment but at late night doctor of hospital declared him as dead.	Residual current device should be used in working condition in power connection.	Avoid using faulty wiring	Yes	ELCB Installed	
20	Sabarmati/ Bopal/ Sanand 1	Vadnagar/ Rural	RM Chauhan	03.07.24	NFH	On Date 3-7-2024 Shri RM Chauhan EA and Shri CB Dabhi EA has sent for complain of light off of single house at village Vadnagar. At location there is tree near pole and tree branch cut down by both EA. At that time Shri RM Chauhan try to cut upper tree branches and somehow his leg slipped and fallen on RCC road street. He got injury on his head and shifted to near by hospital at Sanand and then after he was shifted to Sterling Hospital, Drive In road, Ahmedabad for further treatment.	Yet not received	N/A	N/A	Mechanical Accident due to tree branches fallen during tree cutting,	
21	Sabarmati/ Bavla/ Koth	Vejalka/ Rural	Sabhad Sardulbhai Bhikhabhai	04.07.24	FA	Due to Heavy rain the bending of the pole of 11 kv motiboru jgy emitting of 66 kv kth ss so the wire comes down at the time the cow is going to the field for grazing and contact with 11 kv motiboru jgy live wire and got electrocuted and die.	Yet not received	N/A	N/A	TILTED POLE RECTIFIED	
22	Sabarmati/ Kalol /Chhatral	Chhatral/ Town	Thakor Aashishji Arjanji	05.07.24	FH	Victim working in factory, while switch on the power by switch of extension board by one hand and having hand drill in another hand of victim, the hand drill found short circuited, and victim electrocuted by short circuited hand drill machine having iron body. Thus the accident occurred due to internal fault of hand drill machine i.e factory side internal fault	ELCB/RCCB not used	Earthing must be done and ELCB/RCCB should be used	Yes	CONNECTION DISCONNECTED AND NOTICE GIVEN FOR ELCB INSTALLATION.	
23	Sabarmati/ Sabarmati/ Viramgam R	Ogan/ Town	Gangadhar Sohanlal Rajput	07.07.24	FH	As per report received by Viramgam-rural police station victim got shock and died while doing internal electrical bulb wiring under the shed of HYS comp. After site visit it is observed that there were two private live internal cable wire one with connector and one without connector. As per site available representative victim tries to do wiring for bulb connection and he may touched live phase neutral and got electric shock and died.	Yet not received	N/A	N/A	DC DONE AND NEW TEST REPORT AWAITED FOR RECONNECTION	
24	Sabarmati/ Kalol /Nardipur	Langhnaj / Rural	Vijaykumar Manilal Mistri	08.07.24	FH	as per eye witnesses victim got electric shock while victim was wet his cloth in his house, During site visit no any leakage current found but thoroughly check service found spark and jointed with angle and current may be pass through angle, channel, cloth wire tied with iron channel in his house and victim got electrocuted.	Yet not received	N/A	N/A	CONNECTION DISCONNECTED AND NOTICE GIVEN FOR ELCB INSTALLATION.	
25	Sabarmati/ Sabarmati/ Gobljaj	Chandana/ Rural	Parasbhai Sahiravalji Raval	09.07.24	FH	As per information received by Kheda police station, & as per site visit and witness statement, the victim was trying to change/install bulb near his premise (shed). It is presume, that while doing internal electrical bulb wiring outside his premise, might have accidentally got shocked. As per site visit, it is observed, that one live wire (with one phase without insulation) is found on site. As per victim's brother statement, as per his talk with victim on previous night, he informed to replace bulb in the premise. It can be assume, he may touched live phase and got electric shock and died.	ELCB/RCCB not used	Safety gadgets and ELCB/RCCB must be used	Yes	TEST REPORT WAS TAKEN WITH NEW ELCB TESTING REPORT	
26	Sabarmati/ Bavla/ Dholka T	Dholka/ Rural	Unknown	09.07.24	FA	Accident occurred on 9.7.24 near B P Davda High School, Dholka, on TC near above location. The Phase wire of 150mm2 cable of TC got heat and touch nearby neutral of service wire of 6mm2 on TC. Due to above leakage current was flowing in earthing of TC, while cow was passing nearby TC came in area of earthing so got electrocuted and died.	Yet not received	N/A	N/A	LEKAGE OF CURRENT PROBLEM RESOLVED.	
27	Sabarmati/ Bopal/ Changodar	Visalpur/ Rural	Sanjay Kalaji Ninama EA	10.07.24	NFH	On Date 10/07/24 in evening @ 1735 hrs, Shri Sanjay Ninama received a complaint of broken service wire from consumer Shri Rajnikant Vegda of Vankar Vas, Visalpur so he went to the site, and after making joint in the service line he was working on the pole to make connections with the LT line while moving his right hand, touched his elbow to the live phase of the 6 mm2 ideal cable and he got shock so he lost his hold from the pole and fell down to the ground. He got injured in his right elbow and in his Back. Gathered villagers brought him to nearby local clinic for emergency treatment but as he had too much pain in his back and elbow so brought him to CIMS hospital, Sola, Ahmedabad. he was fully conscious after met with accident	Regulation 14 and 21 of central electricity authority regulations 2023 should be followed	While repairing the power line, power line should be shut off properly and safety equipments must be used	Yes	Memo issued by SDO for proper observing safety norms and Monthly one Safety meeting carried out for line staff by SDO in which they are educated for the same.	
28	Sabarmati/ Sabarmati/ Viramgam R	Hansalpur / Rural	Ranchhodbhai Somabhai Bharvad	15.07.24	FA	A Cow passing through LT pole (Pole number : TC/4/P/8) and there were little rainy water nearby area of the pole. GI earthing wire of this LT pole found broken from upper side and touched with phase of LT line. Hence earth leakage current is flowing through GI wire and water around this pole may also under induction zone. As cow passing near this pole, cow got electrocuted and died.	Yet not received	N/A	N/A	RECTIFICATION DONE TO AVOID LEAKAGE CURRENT	

Sr. No.	Circle, Division, Subdivision	Location of Accident and Rural or Urban	Name of Victim/Owner & Designation	Date of Occurance	Type of Accident FHD/NFHD/F AO	Cause of Accident	Findings of CEI/EI/ AEI	Remedies suggested by CEI / EI/ AEI in various cases	Whether the remedy suggested is complied	Action taken to avoid recurrence of such Accident.	Amount of Compensation and Date of compensation paid (in Rs.)
1	2	3	4	5	6	7	8	9	10	11	12
29	Sabarmati/ Sabarmati/ Viramgam R	Hansalpur / Rural	Rameshbhai Manabhai Bharvad	15.07.24	FA	A Cow passing through LT pole (Pole number : TC/4/P/8) and there were little rainy water nearby area of the pole. GI earthing wire of this LT pole found broken from upper side and touched with phase of LT line. Hence earth leakage current is flowing through GI wire and water around this pole may also under induction zone. As cow passing near this pole, cow got electrocuted and died.	Yet not received	N/A	N/A	RECTIFICATION DONE TO AVOID LEAKAGE CURRENT	
30	Sabarmati/ Kalo/ Kalo-2	Vadma/ Rural	Chavda Mahendrasinh Kacharaji	17.07.24	FA	While going to the field for grazing the buffalo. buffalo was passing from the transformer structure of 11 kv vadma ag feeder and during that time the rain was raining and the buffelows came in contact of stay wire of the transformer structure and fell down at site and die. The proper reason will get after post mortem report because during the panchanama time there was no any leakage current found at site	Yet not received	N/A	N/A	Maintanance done of 11 KV Vadma AG feeder	15000/30.8.24
31	Sabarmati/ Bavla/ Sanand-2	Rethal/ Rural	Jetabhai Khengarabhai Bharvad	19.07.24	FA	Buffaloes were electrocuted due to return power from a hooking in the LT line passing through the nearby area. The power had been switched off in the specific area for safety reasons	Yet not received	N/A	N/A	NEW POLE ERECTED & ACCIDENT OCCURED DUE TO DIRECT HOOKING BY MR. MATHURBHAI JERAMBHAI BOOKED U/S 135.	45000/21.11.24
32	Sabarmati/ Gandhinagar / R Rakhiyal	Sahelji na muvada/ Rural	Zala Dilipsinh Gulabsinh	19.07.24	FA	The Buffalo was passing through incident site. buffalo near existing lt pole buffalo used to scratch near the electricity pole. leaked current to stay wire therefore the buffalo was electrocuted and died near existing pole.	The electric current passed down through wire	Periodically maintainance should be done	Yes	WIRE IS REMOVED	30000/24.12.24
33	Sabarmati/ Sabarmati/ Kujad	Bakrol- Bajrang/ Rural	Ramkishan Premlal Goswami	21.07.24	FH	As per site visit, primarily (as per owner's statement), while cleaning the bathroom through pvc coated pipe connected through motor, he got electrocuted. As per primary investigation neutral return power found on bulb holder's copper coated cap.	Yet not received	N/A	N/A	TEST REPORT WAS TAKEN WITH NEW ELCB TESTING REPORT	
34	Sabarmati/ Gandhinagar U/ Adalaj	Adalaj/ Town	Thakor Baldevji Amaji	21.06.24	FH	On dtd 29.06.2024 at approx. 13:00 pm hours a letter received from police station that a person named Baldevji Amaji Thakor working at Trisha Crane Service has died on dtd 21.06.2024 due to current. While doing site visit on dtd 05.07.2024, it was found that Baldevji Amaji Thakor was working as driver cum mechanic at Trisha Crane Service. While doing service of Crane no- RJ 27 EA 0711, the boom of crane was opened by Baldevji Amaji Thakor and by mistake it was touched to the agriculture HT line which were passing by. Trisha Crane Service is situated in open farm at Adalaj-Trimandir road, opp. Manekba School where so many cranes are parked and everyday cranes are moving in and out. The HT line that is located above is at proper height and clearance from ground is also appropriate and as per rules. From the above mentioned situation, it is found that Baldevji Amaji Thakor was either servicing of driving the crane and by opened the crane boom and by mistake, the boom was touched to the line and he may get electrocuted. The tyres and rubber pipes of the crane were perfectly fine. No any information about accident given by Trisha Crane Service on dtd 21.06.2024 at UGVCL. No post mortem carried out at Civil Hospital. Whether Thakor Baldevji Amaji had license for driving or not is not confirmed by Trisha Crane Service.	Yet not received	N/A	N/A	No any Action Taken	
35	Sabarmati/ Gandhinagar R/ Dehgam R	Vehlal/ Rural	Sonu Brajmohan Rajput	23.07.24	FH	As per information received date 25.07.24 evening by Police, we have site visited but above said Plot was shutter Locked and no any labour or owner at site. So as per kanbha police station letter information, we have observed at site that the victim might walking with iron bed (Khatalo) on Iron made round Fix ladder outside nearby Entry Gate and nearby 11KV Vibrant Industrial Feeder Line 10 Meter PSC Pole line passing where one room entry on first floor but some how Iron bed (Khatalo) above side touch with line while walking with Iron bed (Khatalo) and victim might got shocked and felt down, time 13:05 pm, immediately he was admitted at SELBI hospital Naroda where death occurred at Time 13:57 pm but no any information give by Owner or Victim's relative yet. We approached to owner on telephone for said incident matter but he was Outside and as per discussed with Owner, no any mistake of UGVCL but their side victim's mistake or lacuna.	Yet not received	N/A	N/A	CLOSE LADDER	
36	Sabarmati/ Gandhinagar R/ Chiloda-1	Limbadiya / Rural	R V Makawna (EA)	23.07.24	NFH	Shri R V Makawana (EA) was working on LT pole after string of wire he try to cut old stay wire and his leg slip from pole so he fall down on land.	Yet not received	N/A	N/A	DVICE FOR PROPERLY TAKEN CARE WHILE WORKING	
37	Sabarmati/ Bavla/ Dholka R	Sahij/ Rural	Sanjaybhai Chehubhai Devipujak	25.07.24	FH	victim was working on the roof of the house and fixing iron rods for construction of a house, while working he was electrocuted by a nearby HT line of 11 kv zanand jgy feeder and fell from the roof of the house and died while being taken to the hospital for treatment.	Yet not received	N/A	N/A	LINE SHIFTING ESTIMATE PAID ON 14-08-2024 & WORK DONE	
38	Sabarmati/ Sabarmati/ Gobljaj	Pansoli/ Rural	Ratilal Harjibhai Bharvad	26.07.24	FA	A buffalo was grazing near Ongc Well-293 transformer. The buffalo While rubbing her trumpet with guy wire of the Transformer, the guy wire accidentally come off and touch with live DO of the Transformer. The buffalo came in contact with live wire, and got electcuted and fatal accident occurred.	Yet not received	N/A	N/A	THE GUY WIRE WAS REFITTED AND ENTIRE TC LOCATION WAS PILFUR PROOFED FOR ANY LEAKAGES	1500/3.10.24

Sr. No.	Circle, Division, Subdivision	Location of Accident and Rural or Urban	Name of Victim/Owner & Designation	Date of Occurance	Type of Accident FHD/NFHD/FHO/NFHO/F AO	Cause of Accident	Findings of CEI/EI/ AEI	Remedies suggested by CEI / EI/ AEI in various cases	Whether the remedy suggested is complied	Action taken to avoid recurrence of such Accident.	Amount of Compensation and Date of compensation paid (in Rs.)
1	2	3	4	5	6	7	8	9	10	11	12
39	Sabarmati/ Gandhinagar R/ Dehgam R	Vehlal/ Rural	(1) Harish Tripathi (2) Bansilal Mina (3) Kanubhai Gadiya (4) other one	26.07.24	NFH	As per information received yesterday 26.07.24 by local line staff, we have site visited Owner not present. Labour nearby Plots were present. As information received for accident, immediately local line staff reached at site. Where Iron Shed work was going on and 2 Labours residing Ahmedabad were came for shed Fitting work and other 2 Labours Local from Shed owner. They all walking with Fully Iron 4 leg ladder without tyre (Sid) in hand above land height and without not watching above paaaling line so touch 11 KV line. Instant line was tripping but all got shocked. They informed to Local Village staff so they reached and line Touched ladder was removed and after then 11 KV line made ON. 11 KV line on 8 Meter PSC Pole at proper height but ladder for shed work so length was more and also in victims hand above height from land so incident occurred. All were taken to private Hospital Ahmedabad by Local rent owner Jayeshbhai Patel and all were normal and treatment was going on. We approached to owner on telephone for said incident matter but he was at hoapital and as per discussed with him, no any mistake of UGVCL but their side all victim's mistake or lacuna.	Accident occurred due to victims fault	Any items or material should not be stored under the earth line.	Yes	LADDER IS REMOVE FROM THERE	
40	Sabarmati/ Gandhinagar U/ Adalaj	Adalaj/ Town	Desai Ravibhai Virambhai	29.07.24	FA	While going for eating leaves, the cow was roaming in the Bagaliya vas and she got electrocuted by the leakage current comes from street light service which contact with stay and flowing through stay set of LT pole	The electric current passed down through wire	Periodically maintainance should be done	Yes	Stay Set was removed.LT maintainance Completed	
41	Sabarmati/ Bopal/ Shela	Kolat/ Rural	Rabari Jivanbhai Iaxmanbhai	02.08.24	FA	While buffalo was roaming at jivanpura kolat road nr shiv Shiva residency, buffalo was electrocuted by came in contact of broken LT conductor due to tree branch fallen on line	2 wires out of 4 wires of the power line were broken	Electrical line should be properly checked and maintained to be safe and tree cutting should be done where necessary.	Yes	Power Supply Is Disconnected After Receiving Message And Tree Branch Fallen On LT Line Which Is Removed. Also Line Rectified After Police Panchanama And PM	30000/13.1.25
42	Sabarmati/ Bopal/ Changodar	Visalpur/ Rural	Ajitbhai Gandaji Thakor	09.08.24	FH	On Date 09.08.24 @ 0740 hrs in the morning , Victim shri Ajitbhai Gandaji Thakor was working on the steel platform to get ON the power supply of Vibrator Needle , as soon as he put ON the switch of the Panel suddenly he collapsed and fell down on the platform and got unconscious, he was given primary treatment but he couldn't make it so he was taken to the Civil Hospital, Sola . Where he was declared dead by resident doctor As came to know yesterday only by police department, site visited by sdn today , i.e. on 21.08.24 As per statement of Eyewitness Shri Piyush hai Patel , he is not sure about Ajitbhai got electrocuted because right after the incident he checked the leakage on panel	Yet not received	N/A	N/A	ELCB installed by consumer .	
43	Sabarmati/ Kalol/ Kalol-1	Arasodiya/ Rural	Deepchand Manohardas Bavari	13.08.24	FH	At place of accident 04,Amiganga socity renovation and extention of house under construction. victim was doing furniture work of first floor of above mention address. During furniture work victim pulled stainless steel pipe(approx 12 feet)from ground floor to first floor, near newly constructed stair. which is below existing 11 KV Marketyard feeder line. While Deepchand Manohardas Bavari was pulling stainless steel pipe from ground floor to first floor pipe came in contact with 11 KV line, he was electrocuted being taken to the hospital for treatment, where he declared as died.	Regulation 63 and 66 of central electricity authority regulations 2023 has been violated	unauthorized construction had not been done near the power line	Yes	CONNECTION DISCONNECTED AND NOTICE GIVEN FOR UNAUTHORISED CONSRUCTION NEAR BY 11 KV MARKET YARD FDR.	
44	Sabarmati/ Bopal/ Bavla/ Ind	Dhedhal/ Rural	Rathod Bharatbhai Punjabhai	14.08.24	FH	On Date 14/8/24 in morning @ 1030 hrs , Due to Heavy water logging in Victim's House of Rajput was of Dhedhal Village then Lt Shri Bharatbhai Punjabhai Rathod came in the house and was working to pumping out the water with a 1ph 1.6hp Motor in his house and suddenly he got shocked through his internal wiring, Fallen down and got electrocuted and died at site.	Yet not received	N/A	N/A	Connection is disconnected.	
45	Sabarmati/ Kalol/ Kalol T	Kalol/ Town	Karan Arjanbhai Salat	14.06.24	FH	The victim was washing the tractor at work space area of Dhiraj Engineering, GIDC , Kalol by means of water tube connected to the three phase motor. Suddenly he got electric shock and fell on the ground. The nearby worker saw the situation and instantly switched off the motor and took him to the Nearby Private hospital where he was declared dead by the In charge doctor.	ELCB/RCCB not used	Earthing should be done and ELCB must be used	Yes	CONNECTION DISCONNECTED AND NOTICE GIVEN FOR ELCB INSTALLATION.	
46	Sabarmati/ Gandhinagar U/ Motera	Chandkheda / Town	Goswami kaushikgiri rameshgiri	26.08.24	FH	Illegal wire extension from RGP connection to Parlor , Parlor close & leakage current running in parlor, victims touch with parlor & got shocked & died.	Yet not received	N/A	N/A	Not applicable ..Inside Private Premises	
47	Sabarmati/ Gandhinagar U/ Motera	Chandkheda / Town	Thakor Rohitji Prahladi	26.08.24	NFH	Illegal wire extension from RGP connection to Parlor , Parlor close & leakage current running in parlor, victims touch with parlor & got shocked but no any causality with him as per eye witness statement.	Yet not received	N/A	N/A	Not applicable ..Inside Private Premises	
48	Sabarmati/ Bavla/ Koth	Gangad/ Rural	Munjava Ganshyambhai Bholabhai	26.08.24	FA	Due to Heavy wind and rain tree branch fallen on LT line of koth jgy emitting from 66kv koth ss so It conductor broken and comes down from the baffelo.At the time baffelo is contact with live It wire and got electrocuted and died.	Yet not received	N/A	N/A	DAMAGED LT LINE RECTIFIED	15000/18.10.24

Sr. No.	Circle, Division, Subdivision	Location of Accident and Rural or Urban	Name of Victim/Owner & Designation	Date of Occurance	Type of Accident FHD/NFHD/FHO/NFHO/F AO	Cause of Accident	Findings of CEI/EI/ AEI	Remedies suggested by CEI / EI/ AEI in various cases	Whether the remedy suggested is complied	Action taken to avoid recurrence of such Accident.	Amount of Compensation and Date of compensation paid (In Rs.)
1	2	3	4	5	6	7	8	9	10	11	12
49	Sabarmati/ Gandhinagar U /Adalaj	Moti Adraj/ Rural	Rabari Kismet Amrutbhai	26.08.24	FA	While going for grass eating, one cow went to the left side of the road where 4W LT line was broken due to heavy rain and got electrocuted	Accident occurred due to snapping of conductor	Periodically maintainance should be done	Yes	Stay Set was removed.LT maintainance Completed	
50	Sabarmati/ Kalol /Kalol-2	Navapura/ Rural	Natubhai Raymalbhai Rabari	26.08.24	FA	Conductor of phase wire of 2 wire line broken due to tree branch fallen on line due to heavy rain and thunderstorm. The buffalo was tied up in the enclosure below came to contact with broken conductor and got electrocuted and died.	Yet not received	N/A	N/A	Maintanance done of 11 KV Nvapura JGY feeder, and consumer awared for risk of tie any animal under the electric line.and instructed not to repeat the mistake.	15000/11.10.24
51	Sabarmati/ Bopal/ Sanand 1	SANAND/ Town	Ashok Girilal Parmar	26.08.24	FH	As per statement of eyewitness there was heavy rain at sanand area on dt 26.8.24. Victim It. Ashok Girilal Parmar was climbing on iron stairs which was inside the house and got electrocuted and died.	Yet not received	N/A	N/A	ELCB Installed	
52	Sabarmati/ Gandhinagar R /Gandhinagar	Unava/ Rural	Dinesh S Ambliya	27.08.24	NFH	While attending 11kv jogmaya feeder fault.While going to cut baval tree near talav.Leg slip due to wet and water logging And felt down.Staff taken him to High tech hospital Gandhinagar / for treatment As per Dr report fracture occured in leg near Anckle	Yet not received	N/A	N/A	NA	
53	Sabarmati/ Bavla/ Koth	Bagodara/ Rural	Solanki Dineshbhai mohanbhai	27.08.24	FH	In consumer promises out going flexible internal wire installation in house passing through the dor ,the dor section is alluminium, wire insulation damage due to many time open-close dor and damage wire contact with dor section at the time the victim is contact with alluminium dor and died on the spot due to electrocution.	Yet not received	N/A	N/A	IT IS OCCURED IN PRIVATE PREMISES & SAID CONNECTION CUT & INFORMED TO APPLY FOR NEW TEST REPORT.	
54	Sabarmati/ Gandhinagar U/ Ognaj	Jagatpur/ Rural	Roshani Vijaybhai Bharathari	29.08.24	FH	As per Eye witness statement and person available during panchnama , victim was doing floor cleaning work inside house With water , She was plugging 2 pin plug of table fan into switch board laid on speaker on floor of room and at the same time she got electrocuted. There is no ELCB installed in house. Victim was taken to nearest hospital for treatment and after short treatment doctor declared her dead.	Yet not received	N/A	N/A	Not applicable .Inside Private Premises	
55	Sabarmati/ Bavla/ Dholka R	Chandisar/ Rural	Ashokbhai Dhilajibhai Palat,EA	31.08.24	NFH	On Dt:31.08.24 a LT complain was registered at Dholka R complain center by Phone from Chandubhai Hirabhai Kabira, 05 nos. Houses power off at Valmiki was village Chandisar. While attending complain after TC DO removed from particular X'mer anyhow victims leg slip from LT pole and he Fallen down on ground and injured.	Yet not received	N/A	N/A	WARNING MEMO ISSUED TO A.D.PALAT VIDE LETTER NO:- 871 ON DATED :- 26-09-2024 & SAME WARNING MEMO ISSUED TO R.H.BHOI VIDE LETTER NO:-872 ON DATED :- 26-09-2024	
56	Sabarmati/ Bavla/ Dholka T	Dholka / Rural	Pareshbhai Gafurbhai Rabari	01.09.24	FA	Live LT line of trasad ag FDR conductor broken near Gimatex company (trasad road) while both cow was passing nearby live lt conductor area so got electrocuted and both cows died.	Yet not received	N/A	N/A	BROKEN L.T.LINE WIRE RECTIFIED	30000/11.9.24
57	Sabarmati/ Sabarmati/ Barejadi	Sadra/ Rural	Harjibhai Sharkabhai Rabari	04.09.24	FA	Herd of cow was gazing near TC structure as routine. Since many days heavy rainfall with heavy wind has blown and due to it service cable from Transformer LT side to terminal cable(for nearby 1 pH 2 wire LT lines)was broken and leakage current was flowing to earth through pole due to rain. And cow was gazing nearby TC structure and got electrocuted and cow died.	Yet not received	N/A	N/A	6SQM MM BROKEN SERVICE CABLE WAS REPLACED	
58	Sabarmati/ Bavla/ Koth	Bagodara/ Rural	Boliya Vitthalbhai Bhurabhai	20.08.24	FA	11 kv Loliya Ag line emitting from Bagodara 66 kv substation. The pole of the line fell down but power was ON, at that time the cow was grazing on that side and came in contact with a live conductor and died on the spot due to electrocution.	Yet not received	N/A	N/A	DAMAGED POLE RECTIFIED	15000/18.10.24
59	Sabarmati/ Kalol /Chhatral	Bileshwarpu ra / Rural	Komalsinh Bindarsinh Gond	05.09.24	FH	As per site visit victim working in factory he was trying to move the pedestal fan having iron body by his wet hand got electrocuted.he may electrocuted through either leakage from jointed wire near by fan body due to touching to fan or by holding jointed wire having insulated tape by wet hand. Actual cause of death will be decided after receiving of P. M. Report.thus the accident occurred at factory Side wiring.	Yet not received	N/A	N/A	CONNECTION DISCONNECTED AND NOTICE GIVEN FOR ELCB INSTALLATION.	
60	Sabarmati/ Sabarmati/ Kathwada	Kathwada/ Rural	Pintu Kedar Mahto	05.09.24	FH	As per eye witness statement, while working on buffing machine, the victim got electric shock from the motor and lost his life. But at site, we could not find any clue for leakage current from the motor.	Yet not received	N/A	N/A	DC DONE AND NEW TEST REPORT AWAITED FOR RECONNECTION	

Sr. No.	Circle, Division, Subdivision	Location of Accident and Rural or Urban	Name of Victim/Owner & Designation	Date of Occurrence	Type of Accident FHD/NFHD/FHO/NFHO/F AO	Cause of Accident	Findings of CEI/EI/ AEI	Remedies suggested by CEI / EI/ AEI in various cases	Whether the remedy suggested is complied	Action taken to avoid recurrence of such Accident.	Amount of Compensation and Date of compensation paid (in Rs.)
1	2	3	4	5	6	7	8	9	10	11	12
61	Sabarmati/ Gandhinagar U/ Adalaj	Adalaj/ Town	Baldevbhai Sartanbhai Desai	06.09.24	FA	A Live wire Flexible wire comes into its mouth ,While a Buffalo eating grass at shivpuri hudko Adalaj , she got electrocuted by the leakage current comes from flexible wire.	No any clarification	NA	NA	No any Action Taken required	
62	Sabarmati/ Gandhinagar R /Dehgam T	Dehgam/ Rural	Parbatsinh Punjaji Solanki	09.09.24	FA	Herd of Buffalow was gazing near TC structure as routine. Since it was rainy season and ckt cable was jointed and leakage current was flowing through it to earthing wire through pole. And buffelo was gazing nearby TC structure and touch the Earthing wire and got electrocuted and died.	Regulation 14 and 50 of central electricity authority regulations 2023 has been violated	Periodically maintenance should be done	Yes	EARTHING REACTIVATED	3000/27.2.25
63	Sabarmati/ Gandhinagar R /Gandhinagar	Randheja/ Rural	Jaydip Gandbhai Patel	11.09.24	FH	Due to short circuit of single pole MCB of domestic flour mill victim came in contact with metal part of flour mill with main switch in ON position got electrocuted and died.	Yet not received	N/A	N/A	ADVISE TO INSTALL ELCB FOR SAFETY PURPOSE	
64	Sabarmati/ Bopal/ Bavla Ind.	Nani Devti/ Rural	Lavkush Rambhavan Nishad	15.09.24	FH	As msg recieved from Police Station Sanand Police On dt.18.09.24 regarding Fatal human accident that on Dt.15.09.24 in night @ 2100 hrs , Victim was working inside his house and keeping his wet clothes on Iron string inside his house but by mistake he had connected iron string on live wire and got electrocuted and shifted to Civil Hospital Sanand where he had declared as Dead.	Yet not received	N/A	N/A	ELCB Installed	
65	Sabarmati/ Bopal/ Changodar	Moraiya/ Rural	Prakashbhai Nanjibhai Nayak	29.09.24	FH	On Date :29/09/24 @ 1100 hrs in the morning , Victim shri Prakashbhai was working for Giving water supply to the Astron Packaging by his Tractor with Tank , it was raining in the morning and water logged surrounding the tractor , he was getting empty his tank which was attached to the single phase Motor , as per saying of company's Employee he connect the wire of single ph motor to the MCCB near to the tank and made the power supply ON , after getting the supply ON he went back to his driver seat , as soon as he hold the handle pipe he might have got shock of electric current and fallen on the ground after giving him primary treatment at place immediately he was brought to Civil Hospital, Sola . Where he was declared dead by resident doctor.	Yet not received	N/A	N/A	Connection is disconnected.	
66	MSH/Detroj/ Kadi	Kukvav(rural)	Solanki Kuldipsinh Madhubha	13.07.24	FHO	Victim was climbed on HT pole of 11 KV Kukvav JGY Feeder at-kukvav village. At that time body part of victim was touched to open conductor of 11 KV line and victim got electrocuted and fall down on ground. He was taken to the hospital for first aid where the doctor was declared him dead.	people are educated to keep safe clearance from electric line	people should stay away from electric line	Yes	Victim climbed himself on HT line	100000
67	MSH/Kadi/Detroj	Madrisana(rural)	Cow of Rabari Manubhai Shankarbhai	01.07.24	FAO	As per site visit At-Madrisana village, near primary school, left side of Madrisana- Indrapura road one dead cow (animal) found on the grass approximately 2-3 feet away from existing LT Line pole and there is no any avoidance found for electrical accident. Also we tested earthing wire of this pole, there is no any current found in GI wire & no any electric spot found.	Yet not received	N/A	N/A	Earthing reactivation and maintenance is done	
68	MSH/Kadi/Kadi-1	Zalora (rural)	Damor Jaydeepbhai Kanubhai	14.04.24	NFHO(Elect.)	At Village- Zalora, Ta. Kadi, During Erection work of new AG connection, Victim who was labour of Contractor, climbed on 11Kv pole of Chandanpura AG feeder to dismantle off power LT line conductor where HT & LT line was on same pole and Three phase power supply of 11 KV Chandanpura AG was ON in the line/Pole. Due to live power of 11 kV line, When Victim stand near V cross arm & his chest part touched with 11 kV conductor & got electric shocked & fell down from pole. His team member & other villagers sent him to hospital for further treatment.	Yet not received	N/A	N/A	People should ensure the power poistion before commencement of work	
69	MSH/Kadi/Kadi-1	Rangapurda(rural)	Bhupendrakumar Dhuljibhai Taral, Electrical Assistant	12.09.24	NFHD(elect.)	During work of change of jumper of 11 KV XLPE HT Cable at outside Gentry of 11 KV Veer Ind. feeder in Rangapurda S/S , Generator back power may came from any industries in one phase at outdoor cable box to AB Switch jumper, where victim was changing middle jumper of AB switch - outdoor cable box and touched with jumper. At that time Generator back power may came from any industries and victim get an electric shock /current. Victim felt down from Gentry structure on land below 11 KV Gentry. Victim burnt at leg, hand, bump part and head. Victim admitted at Bhavyoday Hospital. Kadi, then transferred at K.D. Hospital Ahmedabad for further treatment. The work was carrying out by taking line clear of the feeder by supervisor- P.S. Parmar Lineman, The 11 KV Veer Ind Feeder is having XPLE HT U/G Cable from S/S. Thus as per preliminary report the accident occurred due to back power of Generator may came from any Industry.	Yet not received	N/A	N/A	Line staff were educated to ensure power off postion and utilise safety gadgets before starting of work	
70	MSH/kadi/Kadi-2	Deusana(rural)	Gajiben Revabhai Raval	29.08.24	FHO	As per information received from site, victim was trying to switch on the some electric instrument by connecting to defective switchboard, having open inhouse defective wiring. While doing this accidently touch that defective wiring victim was got shock and electrocuted	Yet not received	N/A	N/A	Accident occurred in private primises due to faulty inhouse wiring and premises owner are educated to rectify inhouse wiring and provide proper ELCB.	
71	MSH/kadi/Kadi-2	Karannagar(Urban)	Jayani Chunilal Fusaram Dangaram	30.08.24	FHO	As per letter received from police inspector ,kadi police station victim was trying to cover the truck by tarpaulin and iron pipe (approx 20 feet) which was standing under the HT line but anyhow iron pipe had been touch to lower conductor of budasan ag HT line which was approximately 18 feet from the ground and he got electrocuted and immediately shifted to private hospital at kadi and he was declared dead at hospital ,	people are educated to keep safe clearance from electric line	people should park their vehicle at safe clearance from electric line	Yes	Accident occurred due to victim side fault. Also primises ownerd is educated to take proper care while doing any work below the line and maintain safe clearance from existing HT Line..	

Sr. No.	Circle, Division, Subdivision	Location of Accident and Rural or Urban	Name of Victim/Owner & Designation	Date of Occurance	Type of Accident FHD/NFHD/FHO/NFHO/FAO	Cause of Accident	Findings of CEI/EI/ AEI	Remedies suggested by CEI / EI/ AEI in various cases	Whether the remedy suggested is complied	Action taken to avoid recurrence of such Accident.	Amount of Compensation and Date of compensation paid (in Rs.)
1	2	3	4	5	6	7	8	9	10	11	12
72	MSH/Kadi-1/Kadi	Visatpura(rural)	1 nos Buffalo of Bharvad baldevbhai vashrambhai	07.07.24	FAO	As, per Statement of owner, Buffalo of Bharvad Baldevbhai Vashrambhai was grazing in the Farm Visatpura Village. While grazing, Buffalo came in contact with Stay wire of D.P. structure location no. 97 of 11kV Charol Ag feeder. This HT location was shakle type D.P. structure having A.B. switch mounted on it. While buffalo was grazing near the pole, buffalo came in contact with stay wire & horns of buffalo was stucked with stay wire and due to this stay wire broken from anker rod & lower part from stay insulator of stay wire came in contact of jumper wire of A B Switch. Due to this current passes through the stay wire and as buffalo was in contact with the stay wire, it got electric shock and died on the spot.	line maintenance work will be done on regular interval.	line maintenance should be done on regular interval and replace detoriated stay set.	Yes	Routine maintence of HT network is done.	30000
73	MSH/Kadi-2/Kadi	Indrad(rural)	Sharma Shani Savarajit	13.05.24	FHO	As per the statement given by person present on site The victim was working on iron plat and doing hole in plate using magnet drill machine & While doing work by this machine which may be faulty & leakage current drawn in Magnet drill machine & while during work with faulty magnetic drill machine victim was electrocuted.	Yet not received	N/A	N/A	Accident occurred in private premises due to faulty consumer side wiring and company supervisor is educated to rectify internal wiring and provide proper ELCB.	
74	MSH/Kadi-2/Kadi	Katosan Road(Urban)	Solanki Uttamsinh Pravinsinh	27.05.24	NFHO(Elect.)	As per eye witness statement, Victim was doing sprinkler work on Dt. 27.05.2024, at Approx 10.45 AM, on a roof of a newly under constructed shop. While doing sprinkler work, victim came in contact with live wire of 11 KV Katosan road jgy feeder's HT line, which is passing above shop's roof and that time victim got shocked and felt down on ground.	Yet not received	N/A	N/A	Accident occurred due to victim side fault and also provided new 10 mtr psc pole below the Existing 11 kv line to improve vertical clearance. Also premises ownerd is educated to take proper care while doing any work below the line and maintain safe clearance from existing HT Line.	200000
75	MSH/Kadi-2/Kadi	Indrad(rural)	Yashvant Subhashbhai patel	22.05.24	FHO	As per site visit & eye witness statement victim was doing a welding work of a PA fan airbox in a boiler in a Aksherchem company and at that time somehow by doing above work victim electrocuted & died in private premises,	Yet not received	N/A	N/A	Accident occurred in private premises due to faulty consumer side wiring and company supervisor is educated to rectify internal wiring and provide proper ELCB.	
76	MSH/Mehsana/Dhinoj	Mervada(rural)	Patel Prakashbhai Jayantibhai	23.05.24	FHO	Victim was outsider. Tractor with thressar was under line 11 kVAg feeder. A victim tried to clean charna of thressor extrsact with taveta of thressar and came to induction zone and electrocuted. He fell on ground he was shifted to lanva CHC by EECO car. present doctor there declared him dead	Yet not received	N/A	N/A	Line clearance should be maintained as per regulation	
77	MSH/Mehsana/Dhinoj	Laxmipura(rural)	Patel Jaimin Vipulbhai, Age- 22 years	01.09.24	FHO	The Victim was repalcing the bulb of Sarapanch Gram panchayat street light at umiyapara in the railwaypura village. while working on the pole victim came into contact with the service line extension of street light on same pole. As a result, he lost his balance and fell to the ground. The victim was immediately shifted to hospital, where doctors declared him dead. The victim was a trainee apprentice lineman under dhinoj subdivision he was on Leave due to sunday and was not programmed by the subdivision office.	Yet not received	N/A	N/A	Public is advised to do not climb to UGVCL HT/LT/TC unathorisedly.	100000
78	MSH/Mehsana/Jotana	Tejpura (rural)	Raval Kirankumar Amrutbhai (EA)	07.04.24	NFHD(Mech.)	On Dtd. 07-04-2024 at morning, a private vehicle damaged the LT pole near the cabin of Dasharathsinh Hathsinh Zala near the Gram Panchayat water tank at Tejpura village. Therefore, Supervisor Shri R K Panda, LI and Shri Kiran Raval, EA were tasked to restore power at Tejpura village using a contractor gang. Before arrival of contractor gang initially they have decided to cut down the damaged portion of the line to restore power to the remaining portion of the village. Hence, it is necessary to cut down the power supply from the shackle near this broken pole. For the same work, both employees isolated the power supply of the same LT line feeding from the transformer center near Gram Panchayat. After isolating the power supply, Victim Shri K A Raval, EA climbed the pole connected to the damaged pole near the house of Rabari Dharamsinhbhai Karmanbhai. During the removal of the shackle; suddenly the LT pole broken from the bottom side (inside the ground). As a result, the victim fell down from the LT pole onto the ground. The victim was immediately shifted to Vibrant Hospital	Yet not received	N/A	N/A	Line staff were educated to inspect the pole before commencement of work	
79	MSH/Mehsana/Mehsana Highway	Mehsana(Urban)	Vaghari (Devipujak) Ramubhai Varvabhai	31.05.24	FHO	While operating electric water motor to his working place, victim Late Vaghari (Devipujak) Ramubhai Varvabhai got electrocution due to live motor operation . Then shifted to Lions hospital & site doctor declared as dead. The cause of dead in PM report is shock due to head injuries.	Yet not received	N/A	N/A	Public was awared to installed ELCB & house wiring must be installed by Approved electrical contractor to prevent leakage current.	

Sr. No.	Circle, Division, Subdivision	Location of Accident and Rural or Urban	Name of Victim/Owner & Designation	Date of Occurance	Type of Accident FHD/NFHD/FHO/NFHO/FAO	Cause of Accident	Findings of CEI/EI/ AEI	Remedies suggested by CEI / EI/ AEI in various cases	Whether the remedy suggested is complied	Action taken to avoid recurrence of such Accident.	Amount of Compensation and Date of compensation paid (in Rs.)
1	2	3	4	5	6	7	8	9	10	11	12
80	MSH/Mehsana Rural	Hanumat Heduva(rural)	Lavar Rameshbhai Chhaganbhai & Lavar Dasharathbhai Virambhai	19.07.24	NFHO(Elect.)	In priate property of Acharya Ankitbhai Hariharbhai at acharya Farm Vill-Hanumant Heduva, A construction of new shed is under progress. The victims were working there as labour contractor and a labour. Both victims were transporting a 16.2 feet long ladder from one plase to other place and while doing so, the ladder came in contact with the live electric line of 11kv Hebuva Ag feeder which is also at 16.2 feet from ground level and both got electrocuted. Thus the accident was occured because the metallic ladder of height 16.2 feet came in contact with the electric line.	Yet not received	N/A	N/A	Consumer is advised to do not work below HT/LT line	
81	MSH/Mehsana/Mehsana Rural	Rajgar Heduva(rural)	Thakor Vinuji Javanaji	24.07.24	FAO	On date 24.06.2024 at around 15.30 Hrs. an incident of Buffalo electrocution was occurred under TC structure of AG-A1 tariff connection named Thakor Pradhanji Jesangji with Con no. 20917001320 at village Rajgar Heduva. The incident was caused by fault in internal wiring of consumer's private installation. A ceiling fan was short circuited in consumer's installation and thus the current leaked to neutral wire of transformer centre. Due to heavy rain the surrounding area was wet. The buffalo was passing nearby the TC structure and came in contact with the TC structure and got electrocuted.	Yet not received	N/A	N/A	Consumer is advised to use Earth Leakage circuit breaker to avoid such occurrence. Also proper consumer wiring to be doen by consumer	Police punchanama not done by consumer.
82	MSH/Mehsana/Visnagar-1	Kansa(rural)	Thakor Mayurji Narshihji	03.08.24	FHO	Fatal human outsider electrical accident occured to Thakor Mayurji Narshihji on Dated 03.08.24 time approx 9:00 AM Victim was work on Vibrator machine for making blocks and cleaning platform due to moisture atmosphere while cleaning the platform his hand touch to platform he got electrocuted and fallen down near to vibrator machine and he is admitted to civil hospital visnagar where victim wad declered dead by doctor.meter and service line are found in good condition no leakage current fond at the time of site investigation	Yet not received	N/A	N/A	The Faulty Motor of Pvt Primise was replaced and aware people about to use healthy equipment .	
83	MSH/Patan/harij	Harij(Urban)	Bharvad Kanubhai Ganeshbhai	14.05.24	FAO	During site visit it was found that 11 kv nedharland jgy feeder ht line is passing through thakkar vipulkumar ishvarlal farm. There is one conductor broken between location number 8 and 9 of 11 kv nedharland jgy feeder. in this situation feeder power is still on. At early morning three buffalows of shree bharvad kanubhai ganeshbhai was passing from farm of thakkar vipulkumar ishvarbhai, at that time all three buffalows came in contact with live broken conductor and got electrocuted.	Yet not received	N/A	N/A	Maintenance work of HT line carried out	45000
84	MSH/Patan/Harij	Nana(rural)	(1) Thakor Keshaben Mafaji (FH) (2) Thakor Sejalben Alkeshji (FH) (3) Thakor Alkeshji Abhuji (NFH)	02.07.24	FHO & NFHO	During site visit it was found that 1 Ph. Connection in name of Thakor Keshaben Mafaji is exist at Indiranagar area of Nana village. Outgoing cable of meter connected to simple on-off switch & from switch, two core cable connected to switch board. There is adjacent another house of same owner. This house have cement sheet roof by support of iron hollow square pipe. This second house is used as kitchen purpose by owner. Owner of house has extended illegally two core cable to adjacent house from their first house switch board and this illegally cable was passing in between cement sheet & horizontal iron hollow square pipe and same pipe is supported by vertical iron square pipe. The open space in front of second house is fenced by iron wire and tied with this verical iron pipe. Due to friction of insulation of two core cable between cement sheet roof & iron pipe, a live wire of cable is touched to iron horizontal pipe and then current passed through verical iron pipe and then passed to fencing iron wire. At early morning approx. 6 o'clock, Thakor keshaben mafaji touched to fencing wire and got electrocuted and to seeing that, Thakor sejalben alkeshji rushed and in attempt of save her life, she also got electrocuted. Both of them transferred to pvt.hospital of Harij where doctor has declared dead.	House wiring to be done by Approved electrical contractor and ELCB must required	ELCB to be provided to prevent leakage current	Yes	Public was awared to installed ELCB & house wiring must be installed by Approved electrical contractor to prevent leakage current.	
85	MSH/Patan/Harij	Harij(Urban)	Shailendra Shyamsunder Goswami	21.08.24	FHO	During site visit & ground witness statement it was found that on dtd.21.08.24 ,victim shri Shailendra Shyamsundar Goswami has came for colour work on private street Light Tubalar poles at Harij ITI with other two labour. At around 8.00 AM ,when he was transferring the aluminium ladder from one street light pole to another street light pole ,at that time the ladder came in contact with conductor of 11 KV Kukarana Ag feeder which is passing from ITI campus and got electrocuted. Then after victim shri Shailendra was trasferred to Harij hospital by two others labour for further treatment. where doctor has declared him dead.	Yet not received	N/A	N/A	Prpoer safety norms must be followed by while working near to live conductor.	
86	MSH/Patan/Jangral	Mesar(rural)	Buffalo of Shri Thakor Arvindji Vanvirji	26.06.24	FAO	During Site Visit, A Single Phase Connection Of Mr.Thakor Vanvirji Dhiraji connected from the Agriculture transformer of Mr. Thakor Arvindji Vanvirji, an agricultural consumer in Mesar village. The service line of 1-ph connection touches near by shade due to wind and rain and insulation is damaged and the line leakage current return from the agriculture transformer descends to the earth, and the Buffalo dies due to electric current coming into contact with this agriculture transformer.	Yet not received	N/A	N/A	Service Line is replaced and required maintenance is done	15000
87	MSH/Patan/Patan Rural	Dharnoj(rural)	Patel Pitambarbhai shivrambhai	03.06.24	FHO	During site visit , it was found that the victim often used to fillup mineral water from Dharnoj PHC centre. On dtd 03.06.2024 he came at PHC centre for filling up mineral water in his jug. After filling up his jug with mineral water, he found no powersupply in PHC premise. So he kept his water filled jug inside PHC and without informing anyone he went outside to the LT pole from where service wire was coming to PHC centre. He climbed up the LT pole to start powersupply and thus came in contact with live conductor and electrocuted and fell down. The patient outside the PHC centre informed to PHC centre employees. After which PHC centre employee gave him(victim) first aid treatment and for further reference sent to Civil hospital Patan in Pvt vehicle where present doctor declared him dead.	Yet not received	N/A	N/A	People were awared about no any work to be carried out unauthorized working on Discom Network	100000
88	MSH/Patan/Patan Rural	Sagodiya(rural)	Bharvad Haribhai Ganeshbhai	31.07.24	FAO	As per site visit, it was found that at around 10:00 am buffalo of Shri Haribhai Ganeshbhai Bharvad was grazing at Sagodiya sim farm where 11 KV HT line of Kunvarika JGY feeder emnating from 66 KV Kimbuva ss passed. Buffalo might have came near Loc no 168 Switch pole's stay wire anchor rod for itching and got stuck in horn of buffalo and in panic buffalo removed anchor rod and died.	Yet not received	N/A	N/A	Sufficient distance between AB switch jumper and stay wire is kept	15000

Sr. No.	Circle, Division, Subdivision	Location of Accident and Rural or Urban	Name of Victim/Owner & Designation	Date of Occurance	Type of Accident FHD/NFHD/FHO/NFHO/FAO	Cause of Accident	Findings of CEI/EI/ AEI	Remedies suggested by CEI / EI/ AEI in various cases	Whether the remedy suggested is complied	Action taken to avoid recurrence of such Accident.	Amount of Compensation and Date of compensation paid (in Rs.)
1	2	3	4	5	6	7	8	9	10	11	12
89	MSH/Patan/Patan Rural	Bhemosan(rural)	Thakor Niteshji Abhesangji	09.08.24	FHO	As per information received from Divyabhasker Newspaper on Dt:11.08.2024. The site is visited and as per statement of eye witness the victim Thakor Niteshji Abhesangji was playing at Home and The private wire coming from Swich bord which goes to singal phase in the moter, The child died of Electrocutation by touching the wire and the actual causewill be found out after futher detail investigation and PM Report. and child transferred to hospital whwre Doctor has declared dead.	Yet not received	N/A	N/A	People were awared to installe ELCB and joint in wiring to be avoided	
90	MSH/Patan/Sami	Vaval(rural)	Mahadevji Ratuji Thakor	12.06.24	FAO	During site visit it was found that HT line of 11 KV Varana AG feeder is passing through Nadoda Kanubhai Motibhai farm. There is one conductor snapping between location no. 139/18/17 & 139/18/16 from Shackle Pole Side of 11 KV Varana AG feeder and power of feeder found lying on land. During early morning 2 nos Buffalo's & 1 no Calf was passing from farm of Nadoda Kanubhai Motibhai, at that time all three buffalos came in contact with live broken conductor and got electrocuted	Yet not received	N/A	N/A	Maintenance work of HT line carried out	32500
91	MSH/Patan/Sami	Sami(Urban)	Mahadevbhai Matambhai Bharwad	14.06.24	FAO	During site visit, it was found that, Accident site is located near Waterworks sump of Ektanagar Sami on mujpur Road, There is a LT pole on site, on which 200A LT DB Switch mounted on LT PSC pole. The incoming cable come to LTDB Switch is of 25 mm2 LT PVC 3 Phase 4 Wire cable, which is hinged on PSC Pole to LT DB Switch, From this LT DB Switch two Conductor of Coated wire of 34 mm2 is in outgoing side and running up side to this LT PSC pole and connected in 1 Phase 2 wire LT line conductor. Also Found that this insulation of this LT coted 34 mm2 conductor is rusted due to heating & Aging effect and Phase conductor may be come in contact with said LT PSC Pole. On Date of Accident ie 14.06.2024, Land Surrounding to said LT PSC pole was highly wet. So cow passing through that wet land and come in contact with leakage current, and got eletrocuted and met with Fatal electrical Accident.	Yet not received	N/A	N/A	Maintenance work of LT line carried out	15000
92	MSH/Patan/Sami	Khandiya(rural)	Buffalo of Shankarbhai Sangrambhai Rabari	02.07.24	FAO	During site visit, it was found that, Accident site is located near Shakti Mataji Temple at Village Khandiya. There is a single phase connection having consumer No. 28841101113 of Temple,for said connection LT line of 3-Ph 4 Wire LT ABC coming from Kandiya village Transformer Under 11 KV Bolera JGY Feeder. Also there is a LT PSC Pole Where this Accident occured found completely wet due to heavy rain on dated 02/07/24. Also the Land surrounding this LT Pole found water logged. LT ABC cable tied on this LT PSC Pole via LT shackle Insulator and one of the phase of this LT ABC cable come in contact with wet psc pole. Also found that the Insulation of LT ABC cable phase touching with LT psc pole was rusted due to heating effect. On date of Accident around 10:00 AM buffalo of Shankarbhai Sangrambhai Rabari may passed near this wet LT psc pole and come in contact with leakage current through wet PSC pole and got electrocuted and met with Fatal electrical Accident.	Yet not received	N/A	N/A	Routine maintence of LT network is done.	15000
93	MSH/Patan/Sami	Jilwana(rural)	Bharwad Rajabhai Malubhai-Savasda	10.07.24	FAO	During site visit, it was found that, on date of Accident the one conductor of 11 KV Ravad AG Feeder from pin pole location no. 67/Ravad AG feeder was snapped from Pin Insulator of said pole due to heavy wind. At that time one cow of Bharwad Rajabhai Malubhai Passed through Agriculture Land Below this Electrical line of Which one Conductor Snapped from PSC pole. So cow may be came in contact of that live conductor and got electrocuted and met with Fatal electrical Accident. PM Report & Police Panchnama awaited.	Yet not received	N/A	N/A	Routine maintence of HT network is done.	15000
94	MSH/Vijapur/Gozariya	Gozariya(rural)	Raval Rajnikant Amratbhai	19.06.24	FHO	While Plugging male contact of plug into female contact of plug which was installed on motor body, victim got electric shock due to contact with live part of male contact of plug. Because switch where plug was connected was on	Only two pin plug used instead on three pin plug with earthing terminal	Use proper three pinplug with earthing terminal, also install ELCB/MCB/RCB for safety	Yes	People were educated to install ELCB at their premises	
95	MSH/Vijapur/Kukarvada	Umiyanagar (Bilodara)(rural)	Rabari Vishnubhai Prabhatbhai	15.05.24	FAO	Due To Internal Fault Of Consumer Motor So Leakage Current Found At Ag Tc Centre At The Time Cow Touch To Gi Wire Of Ag Tc Centre And Cow Got Electrocuted And Died.	Transformer Earthing without PVC Pipe	Install proper PVC Pipe on Transformer Earthing	Yes	Give advice for proper house wiring.	30000
96	MSH/Vijapur/Ladol	Falu(rural)	Suryaben Chhabilsinh Rathod	07.05.24	FHO	The victim got electrocuted when she came in contact with iron wire (Vargadi) in her house. This iron wire (Vargadi) was in contact with iron shed and this iron shed was in contact with short circuit ceiling fan through from which current leakage was happening.	Yet not received	N/A	N/A	People were educated to keep safe distance and not to tied varangni with Pole	
97	MSH/Vijapur/Ladol	Mandali(rural)	Amitaben Pravinji Thakor	13.08.24	FHO	The victim got electrocuted when she came in contact with iron wire (Vargadi) in her house. This iron wire (Vargadi) was in contact with iron shed and this iron shed was in contact with short circuit ceiling fan through from which current leakage was happening.	Yet not received	N/A	N/A	People were educated to remove varagani and keep safe distance from Network	
98	MSH/Vijapur/Lodra	Anodiya(rural)	Rathod Ramilaben Ranjitsinh	02.07.24	FAO	Accident occurred on dtd:- 02.07.2024 about 05:30 am. Big neem tree fallen on 2W LT line so conductor broken from LT pole and conductor fallen on 2 buffeloes and got electrocuted and died..	Tree Cutting should be done regualrly	Tree Cutting should be done regualrly	Yes	Tree cutting maintenance has been carried out	60000

Sr. No.	Circle, Division, Subdivision	Location of Accident and Rural or Urban	Name of Victim/Owner & Designation	Date of Occurrence	Type of Accident FHD/NFHD/FHO/NFHO/FAO	Cause of Accident	Findings of CEI/EI/ AEI	Remedies suggested by CEI / EI/ AEI in various cases	Whether the remedy suggested is complied	Action taken to avoid recurrence of such Accident.	Amount of Compensation and Date of compensation paid (in Rs.)
1	2	3	4	5	6	7	8	9	10	11	12
99	MSH/Vijapur /Lodra	Mahudi(rural)	Rathod Dolatsinh Laxmansinh	26.08.24	FAO	Accident occurred on dtd:- 26.08.2024 about 02:00 am. Due to heavy rain and cyclone big tree fallen on 2W LT line and conductor fallen on ground and bullock touch in contact with conductor got electrocuted and died.	Tree Cutting should be done regularly	Tree Cutting should be done regularly	Yes	Maintenance of line is carried out	25000
100	MSH/Visnagar/Kheralu-2	Mandal(rural)	Prajapati Amitkumar Ramjibhai, Electrical Assistant	25.04.24	NFHD(Mech.)	During conductor replacement of 11kV Virpura Ag feeder, Victim was on HT shackle Pole Location 67, one side replaced by new conductor and was making new jumper with other side old conductor. Mean while old conductor jumpering work other side old conductor was accidentally broken. And Victim lost his balance and fallen down from pole.	Yet not received	N/A	N/A	Line staff were educated to inspect the pole before commencement of work	
101	MSH/Visnagar/Satlasana	Sudasana(rural)	Shri Rathod Takhaji Madji	20.05.24	FHO	Information received from 108 person on mobile about electrical accident occurred at sudasna village. And by knowing further information from villagers victim working on his metal shed and then after during climb down from shed, victim may be got electric shock by his internal wiring. Further detail investigation is in under progress	House wiring to be done by Approved electrical contractor and ELCB must required	ELCB to be provided to prevent leakage current	Yes	People were educated to install ELCB at their premises	
102	MSH/Visnagar/Satlasana	Rinchhada(rural)	Smt Chaudhari Ashaben Raghjibhai	17.07.24	FHO	At the time of site inspection inspection it was found that victim was taken cloth from iron string(Vargani) one end tied with roof angle and other end with roof vertical cement support inside her premises (osri) and got electric shock due to leakage current from electrically short consumer ceiling fan. In osri Current passing from ceiling fan to tied iron rod to support horizontal iron angle for roof support where iron string (vargani) is tied. Victim was came with electrically live iron string (vargani) contact and got electricuted, she is admitted to Satlasana PHC	House wiring to be done by Approved electrical contractor and ELCB must required	People should avoid using metal wire for drying cloths, Also use ELCB, MCCB, RCCB for avoid such accidents	Yes	People were educated to keep safe distance and not to tied varangni with Pole	
103	MSH/Visnagar/Vadnagar-1	Vaktapura (rural)	Patel Sureshbhai Bhikhabhai	12.04.24	FHO	On dated 12.04.2024 call received around 7.00pm on DE's mobile that victim Sh. Patel Sureshbhai Bhikhabhai was fatal under Transformer center due to got electric accident and take him at civil hospital for PM. At that time DE visit hospital but hospitalize victim was declared dead by hospital. Immediately than after DE with staff are visited accident place on dated 12.04.24 around 08:30 PM and next day on dated 13.04.2024. It has been observed that there were not found any sparking mark on the parts of Ag transformer center like earthing wires, stay wires, all MS angels and also not found any dark spot on vela (galo) which were wrapped up with left side of transformer center's cement pole, stay wires, earthing wire and also not found any leakage current at transformer center and near vela (galo). As per 66 KV schedule of 11 kv undani ag feeder was under 1 phase from 07:00 to 23:00 and no tripping recorded of this feeder at 66 KV KHANPUR SS on date 12.04.2024.	Yet not received	N/A	N/A	AS PER FORENSIC REPORT CAUSE OF DEATH IS NOT ELECTRIC CURRENT ALSO EI LETTER RECEIVED EI/FA/499 DT:26.06.2024	
104	HMT / BHILODA / BHILODA-1	MAU(SATKORA) / (RURAL)	KHARADI MANHARBHAI CHUNILAL	17.09.24	FAO	On dtd. 17.09.2024 at 09:30 Pm approx. Due to a big tree near to party's house fall on 1ph 2w abc line passing through There so line break down and conductor fall on Buffalo tied under line hence electrocuted and buffalo died on the spot	RECEIVED	NA	NA	LINE MAINTENANCE DONE	30000/20.1.2025
105	HMT / BHILODA / CHORIWAD	ISHAVARPURA KAMPA / (RURAL)	ASHVINSINH VAKHATSHINH ZALA	08.09.24	NFHD	Non Fatal Departmental Accident occurred to victim at village : Ishavarpura kampa, Ta: idar, Dist:S.K.. Approx 17:00 pm, while attending pole plumbing complained of 11KV Takhatgad Ag feeder at Ishavarpura village with A R parmar(EA). That time attend the complaint victim climbed on sonariya TC structure for cutting the jumper to dead 11 KV line. suddenly victim was fell down on the ground due to electrocution and was admitted to idar Pancham Hospital for treatment	Yet not received	N/A	N/A	LINE MAINTENANCE DONE	-
106	HMT / BHILODA / CHORIWAD	KESHARPURA / (RURAL)	DUND NIRMABEN PRAKASHBHAI	14.05.24	FHO	An outsider Fatal Human accident was occurred to victim at : Kesharpura, Ta: Vadali, Dist: S.K. on dated: 14-05-2024 time, approximately 10:30 am due to leakage current passes in iron channel through faulty wiring in House. Iron wire tied with iron channel of house, victim got electrocuted and died on the spot in consumer premises.	Yet not received	N/A	N/A	Give advice for proper house wiring.	
107	HMT / BHILODA / VIJAYNAGAR	JALETI / (RURAL)	BODAT KIRTANKUMAR CHINUBHAI	8.11.24	FHO	As per eye witness statement the victim was climbed on 11 Badarkha AG feeder passing from his farm the neighbours shouted and asked him to come down but the victim might have been drunk and not come down and his left hand elbow touched live wire and electrocuted and fell down from pole and died	Yet not received	N/A	N/A	LINE MAINTENANCE DONE	100000/25.10.2024
108	HMT / HIMATNAGAR / GAMBHOI	AMBAVADA / (RURAL)	RATHOD GANPATISINH KESHARISINH	8.5.24	FAO	On date 05.08.2024 at approximately 17:25 hours a buffalo was grazing in a fallow land of Ambavada village. A LT line with 4 wires emerges from the transformer of 11 KV Lalpur AG feeder in the fallow land. Due to the LT wires broken of this outgoing LT line due to the wind, the return power entered the neutral of transformer. The buffalo came in contact with leakage current and died due to electrocution on the spot. The cause of leakage current Stop by binding the wire with LT line.	RECEIVED	NA	NA	CONDUCTOR RE JOINT & RESTRINGING DONE	30000/23.1.2025

Sr. No.	Circle, Division, Subdivision	Location of Accident and Rural or Urban	Name of Victim/Owner & Designation	Date of Occurrence	Type of Accident FHD/NFHD/FHO/NFHO/FAO	Cause of Accident	Findings of CEI/EI/ AEI	Remedies suggested by CEI / EI/ AEI in various cases	Whether the remedy suggested is complied	Action taken to avoid recurrence of such Accident.	Amount of Compensation and Date of compensation paid (In Rs.)
1	2	3	4	5	6	7	8	9	10	11	12
109	HMT / HIMATNAGAR / GAMBHOI	Mahadevpur a(kevan) / (RURAL)	MAKAVANA KAMLESHSINH VAKTUSINH	8.5.24	FHO	On dt.05.08.2024 Makwana Kamlesh Singh Vaktusinh, a native of Mahadevara Kevan village, who has singal phase motor which is outside of his house. During afternoon about 1 pm, victim switched on the motor by wire was insterted from the switch board of the house for household work. Later he was touched the motor meanwhile leakage came in motor & victim was got electrocuted and died on the spot , after which he was taken to Gambhoi Government Hospital for treatment where he was declared brought dead. The incident of this electrical accident has not been reported by any person to the office here.Accident occurred due to internal wiring's fault in Pvt premises.	Yet not received	N/A	N/A	Give advice for proper house wiring.	
110	HMT / HIMATNAGAR / HIMATNAGAR TOWN	HIMMATNAGAR / (TOWN)	Barot Radhaben Rajubhai	6.26.24	FHO	PRIMARY OBSERVATION FOUND THAT IN EXISTING PREMISE RENOVATION WORK OF WALL IS UNDER PROGRESS. SO SMC BOX AND PRIVATE CONSUMERBOARD REMOVED AND PLACED ON GROUND BY PARTY ITSELF WITHOUT INFORMING TO UGVCL. METER SERVICE WIRE AND METER ARE FOUND IN GOOD CONDITION.THE PARTYSIDE WIRING FOUND FAULTY HENCE ANYHOW THE VICTIM MAY CAME IN CONTACT WITH FAULTY CONSUMER WIRING, SO SHE GOT ELECTROCUTED.THE POWER SUPPLY OF SAID CONNECTION DISCONNECTED IMMEDIATELY. SHE WAS SHIFTED TO HOSPITAL FOR TREATMENT. DETAILS INVESTIGATION FOLLOWS THE SAID ACCIDENT OCCURED IN PARTY PREMISE & NO FAULT AT UGVCL SIDE	Yet not received	N/A	N/A	Give advice for proper house wiring.	PRIVATE PREMISIS
111	HMT / HIMATNAGAR / HIMATNAGAR T	Shantipura / (RURAL)	Rathod Narendrasinh Devusinh	5.2.24	FHO	On dt. 02/05/2024 message regarding fatal accident occurred. given by Nagarpalika employees Shri Rambhai and Dineshbhai at complain center OF UGVCL at about 16:35 hrs.Immediately site has been visited and panchanama carried out.Victim and his colleague Shree Sajjansinh started the work of attending street light complaint lodged at Nagarpalika Himmatnagar without any information to UGVCL office & with live LT line.It is found that stand for work on pole utilized by victim rest at second hole of the said pole. Any how the victim fallen down from the pole to otlr near by said pole and severe injury occurred to head of Victim .There are signs of blood found on the otlr,then after surrounded people gathered and called to 108 ambulance and immediately shifted the victim at Hope hospital for treatment but the victim died and dead body shifted to Civil hospital Himmatnagar for PM.PM report and eye witness statement is awaited.Victim himself is responsible for the accident & there is no any fault at UGVCL side.	Yet not received	N/A	N/A	ACCIDENT DUE TO NEGLIGENCE OF NAGARPALICA PERSON(CAME IN CONTACT WITH LIVE WIRE)	100000/- & 9.8.2024
112	HMT / HIMATNAGAR / HIMATNAGAR TOWN	HIMMATNAGAR / (TOWN)	1) Mangalram Ukarji Prajapati 2)Rahulkumar Jashavantibhai Dabagar	5.13.24	NFHO	on dtd 13.05.24 about 15:45 hrs heavy cyclonic wind & rain started in him atnagar and surrounding area. The telephonic message regarding the incident has been received from shak market. Immediately power supply cut off of 11 kv Durga urban feeder and power supply disconnected of shop no :33.due to power given in iron shed in front of this shop.due to rainy day the iron wire and tad patri wet and tadpatri came in contact with faulty wire to pin connected in internal wiring of shop no 33.No major injuries found to both victim.(1) 1 st Victim has been found electric spot in his both palm and head injuri found on his back side head (2) nd Victim has been found slide injuri on his noze due to he helt on the ground & no electric spot found in his body.	Yet not received	N/A	N/A	Consumer is advised to use Earth Leakage circuit breaker to avoid such occurrence. Also proper consumer wiring to be doen by consumer	PRIVATE PREMISIS
113	HMT / HIMATNAGAR / HMT R	MOTI DEMAI / (RURAL)	MAKAVANA FATAJI JAVANJI	7.17.24	FHO	On dated 17.07.2024,at about 19:30 hours (Evening) victim named Fataji Javanji Makwana was Spreading Towel after bath on Iron wire wound on Iron Pole Stuck with Outer balcony of house at that time Incoming Service wire came in contact with faulty wire of street light lamp connected which was before Egg ,Reel Insulator of GI wire and Victim got electrocuted and died As no other person was present at the time of electrical accident, some neighbors saw the victim laying on ground so, they gathered to all and admitted to Civil Hospital Himatnagar by private vehicle, where consult medical officer declared him dead.accident occurred due to negligence of gram panchayat .	Yet not received	N/A	N/A	FAULTY STREET LIGHT WIRE REMOVE & ASK PANCHAYAT TO REPLACE WITH NEW WIRE	100000/- & 12.9.2024
114	HMT / HIMATNAGAR / HMT R	hadiyol / (RURAL)	Parmar Savaji Kalaji	4.22.24	FHO	on dated 22.04.2024 at village Hadiyol human fatal outsider accident occur in party premieses. Victim Parmar Savaji Kalaji age 37 yr (approx) died due to touching private premises fencing wire of farm . there was no any cause and fault of leakage current by UGVCL line in this incident.	Yet not received	N/A	N/A	Prpoer safety norms must be followed by while working near to live conductor.	
115	HMT / HIMATNAGAR / HMT T	HIMMATNAGAR / (TOWN)	DESAI SHNAKRBHAI CHEHARBHAI	7.27.24	FAO	As soon as telephonic complain received at complain centre regarding accident on dtd 27.6.24 Approx. 21:28 hrs.Immediately site has been visited and it is found that Nagarpalika street light repairing-maintainance person has given extra twin core wire in LTDB box of Avadh park soc.in that wire there is a joint which touch the LTDB & leakage current flow to fencing.The cow came in contact with leakage current So got electrocuted & died.The Details investigation follows.The cause of leakage i.e. extra wire that was joined by Nagarpalika person remove & leakage stopped.	RECEIVED	NA	NA	FAULTY EXTRA WIRE JOINT BY NAGARPALIKA WAS DISMENTAL	30000/23.1.2025
116	HMT / HIMATNAGAR / MEHTAPURA	ILLOL / (RURAL)	RABARI RAGHUNATHBHAI MANDANBHAI	8.11.24	FAO	On Dt. 11.08.2024 , At Village. IlloI , Darbargadh area village transformer a black clour cow was died near trasformer fencing. At the time of inspection it was found that the D.O. Fuse of trasformer centre was found removed , trasformer LT Side power was off at that time , After our UGVCL Employees had turn on the power of trasformer providing HT Side D.O. Fuse , thus after that LT Power supply was restored & at that time no leakage power was present at transformer neutral earthing , but when gram panchayat water works 3 ph motor started for water supply , there was leakage current present at trasformer neutral , thus water work 3 ph motor was found short (faulty) . cow's death reason will be confirmed after post mortem report of vaternity officer . may be due to return current on netural wire cow get electrocuted	RECEIVED	NA	NA	PANCHAYAT MOTOR SHORT & IT WAS REPLACED WITH NEW BY PANCHAYAT	30000/23.1.2025
117	HMT / HIMATNAGAR / MEHTAPURA	ILLOL / (RURAL)	VANZARA TULSIBEN JIVAJI	9.2.24	FAO	On Dt. 02.09.2024 , At Village. IlloI , Near Vanzara vas to Dhavni river road , a aluminium weasal conductor of agricultural 4 wire LT Line was broken & fallen on ground , while victim's buffalo was passing from said road , it comes in direct contact with live wire & died at spot .	RECEIVED	NA	NA	CONDUCTOR RE JOINT & RESTRINGING DONE	30000/08.1.2025

Sr. No.	Circle, Division, Subdivision	Location of Accident and Rural or Urban	Name of Victim/Owner & Designation	Date of Occurance	Type of Accident FHD/NFHD/FHO/NFHO/FAO	Cause of Accident	Findings of CEI/EI/ AEI	Remedies suggested by CEI / EI/ AEI in various cases	Whether the remedy suggested is complied	Action taken to avoid recurrence of such Accident.	Amount of Compensation and Date of compensation paid (in Rs.)
1	2	3	4	5	6	7	8	9	10	11	12
118	HMT / HIMATNAGAR / PRANTIJ	PRANTIJ (RAMNAGAR) / (RURAL)	SAVITABEN AMRUTJI MAKWANA	6.20.24	FHO	THE VICTIM WAS DOING NORMAL HOUSE HOLD WORK AT HER HOUSE AS PER ROUTINE SCHEDULE.DURING ABOVE SAID WORK SHE GOT ELECTROCUTED,WHILE SHE HOLDS IRON GRILL WHICH WAS CONNECTED ALONG WITH GALVANISED ROOF OF HER HOUSE AS PER DETAILED INVESTIGATION A TWIN CORE PVC SERVICE CABLE FIRED AND CAME IN CONTACT WITH GI WIRE NO 10,RESULTING LEAKAGE POWER PASSES AT IRON GRILL THROUGH GALVANIZED ROOF OF HOUSE AND SHE GOT ELECTROCUTION AND DIED DUE TO ELECTRIC SHOCK.	Yet not received	N/A	N/A	SERVICE WIRE REPLACED WITH PROVIDING NEW GI WITH EGG & REEL	100000/29.11.2024
119	HMT / HIMATNAGAR / PRANTIJ	BALISANA / (RURAL)	MAHENDRASINH SOMSINH RATHOD	8.26.24	FAO	On dated 26.08.2024 around 3:00 am due to hevly rain & wind big tree fallen on Unchha JGY It line at balisana village so one conductor broken from It line & came in contact with Buffalo. Buffalo died on spot.	RECEIVED	NA	NA	CONDUCTOR RE JOINT & RESTRINGING DONE	30000/23.1.2025
120	HMT / HIMATNAGAR / PRANTIJ	PRANTIJ / (URBAN)	KANAIYALAL VARSANGJI MAKWANA	7.2.24	FHO	On dated 02.07.2024,at about 14:30 hours victim named Kanaiyalal Varsangji Makwana was storing water at under premises water tank from panchayat water supply. For that purpose he was using 0.5 HP single phase motor having black color flexible wire(1/18) with joint and another plug point was laid on ground level .Plug point laid at ground level was connected through motor (single phase) having blue color flexible wire with black PVC tape. Due to some electrical fault in said motor wiring or mal operation by victim the leakage current was passes through his body & gets electrocuted. On dated 03.07.2024 said site was visited by undersigned and JE, technical staff at that time the wiring of said meter up to meter incoming points and outgoing points were normal. As no other person was present at the time of electrical accident, some neighbors saw the victim laying on ground so, they gathered to all and admitted to CHC Prantij by private vehicle, where consult medical officer declared him dead.	Yet not received	N/A	N/A	Prpoer safety norms must be followed by while working near to live conductor.	PRIVATE PREMISIS
121	HMT / HIMATNAGAR / Salal	Amodara / (RURAL)	MUKESHBHAI LAXMANBHAI NADIYA	4.26.24	NFHD	on dt. 26/04/2024 programme of Maintenance 11KV Deep Industrial feeder was given from office. Prantij TMS staff alongwith Salal Supervisor M R. Patel had started work after having all procedure of Line clear permit of 11KV Deep industrial feeder. After Every safety precautions like- Line discharge, earthing of line, disconnect cross boundary switch & pole erthing was done. Then with safety gadget staff started work. During that victim M L Nadiya (E A) & G C Makwana (ALM) went for maintenance works. Suddenly He came down from the pole to ground. On inquiry of present staff, it was shown that by one or other reason victim M L Nadiya climbed over nearby 11Kv Mark Industrial feeder, which was already On. He got induction & fallen down. After sound of victim near by working line staff rushed at accident location & gave him primary treatment then took him to local dispensary. The local Dr. Advised to Admit him to Himatnagar civil hospital. Later on after treatment Himmatnagar Civil hospital he was taken to Appolo hospital, Ahmedabad for further treatment.	Yet not received	N/A	N/A	ACCIDENT DUE TO NEGLIGENCE OF EMPLOYEE & SHOW CAUSE ISSUED	NA
122	HMT / IDAR / DESHOTAR	VERABAR / (RURAL)	PATEL RAKESHBHAI RAMANBHAI	8.27.24	FAO	ON DATE 27/08/2024@ 03.00 PM Patel Rakeshbhai Ramanbhai buffaloes were tied to wall by metal chain under the electric line in front of his own house. During that time, very heavy rain and wind pressuer 1 ph service wire broken suddenly fall down live electric service wirecame with conctect buffelo and fell on the buffaloes and cow tied down and died on the spot.	RECEIVED	NA	NA	maintenance done	30000*2-60000/06.01.2025
123	HMT / IDAR / JADAR	RUDARDI / (RURAL)	Patel Mihirbhai Kanubhai (Montu)	9.6.24	NFHO	For the Purpose of suicide , The victim caught with Non Fatal human outsider electrical accident occured to patel Mihirbhai Kanubhai on dated- 05.09.2024 time approx 06:20 AM. As Victim was mentally disturbed due to some reason hence he dicided to suicide so he climbed on 11 kV line of jogani ag feeder location no-76 and touch to the live conductor of 11 kv jogani ag feeder and got electrocuted and fall down.after that he was taken to private hospitals idar for primary treatment and after that victim shifted to civil hospital ahemdabad for more treatment.at present victim health is good and stable and conscious.	Yet not received	N/A	N/A	Mmaintenance Done	
124	HMT / IDAR / KHEDBRAHMA	KHEDBRAHMA, BHATVAS / (TOWN)	Vanzara Sureshbhai Babubhai	7.4.24	FAO	Vanzara Sureshbhai Babubhai's buffaloes were tied to wall by metal chain under the electric line in front of his own house. During that time, a live electric line suddenly broke from the electric pole and fell on the buffaloes tied down and died unfortunately on the spot.	RECEIVED	NA	NA	It abc provided	30000*2-90000/06.1.2025
125	HMT / IDAR / KHEDBRAHMA	KHEDBRAHMA, BHATVAS / (TOWN)	RABARI BHERAJI DUNGARAJI	8.26.24	FAO	The Accident occurred at village: - Khedbrahma dated 26.08.2024 at approx. 14:30 near virbavaji mandir, Rabari bheraji dungaraji was returning to home after grazing his cow and buffalo, one buffalo passed by a broken conductor on the road near the virbavaji temple and died instantly. seeing that Rabari Bheraji Dungaraji drove away his other cow and buffaloes, another cow also died unfortunately on the spot due to passing through the broken live conductor.	RECEIVED	NA	NA	It spacer provided	30000*2-60000/06.01.2025
126	HMT / IDAR / KHEROJ	Navamota / (RURAL)	Gamar Mashrubhai Ratabhai	9.4.24	FAO	On dtd. 04-09-2024 11KV Navamoya JGY LT 1-PH service cracked due to heavy rain and wind GI wire touched to turn buckle touched to Stay wire after stay insulator and it came in contact with metal shade where cow was tied with pole of metal shade and got electrocuted and died on the spot.	RECEIVED	NA	NA	Mmaintenance Done	30000/06.1.2025
127	HMT / IDAR / VADALI	MAHOR / (RURAL)	RABARI VIRABHAI GOBARBHAI	8.27.24	FAO	ON DATE 27.08.2024 RABARI VIRABHIA GOBARBHAI buffaloes were tied to wall by metal chain under the electric line in front of his own house. During that time, very heavy rain and wind pressuer a tree baranches suddenly fall down on the l live electric conductor and so broke from the electric pole and fell on the buffaloes and cow tied down and died on the spot.ess.	RECEIVED	NA	NA	It spacer provided	30000*2-60000/06.01.2025

Sr. No.	Circle, Division, Subdivision	Location of Accident and Rural or Urban	Name of Victim/Owner & Designation	Date of Occurrence	Type of Accident FHD/NFHD/FHO/NFHO/FAO	Cause of Accident	Findings of CEI/EI/ AEI	Remedies suggested by CEI / EI/ AEI in various cases	Whether the remedy suggested is complied	Action taken to avoid recurrence of such Accident.	Amount of Compensation and Date of compensation paid (in Rs.)
1	2	3	4	5	6	7	8	9	10	11	12
128	HMT / IDAR / VADALI	KUBADHAROL / (RURAL)	RADHABEN DILIPBHAI PATEL	7.30.24	FHO	A Fatal human outsider electrical accident occurred to radhaben dilipbhai patel on dated- 30.07.2024 time approx 08:30 AM. Victim was cutting the grass from chap cutter machine, at that time due to internal electrical wiring problem current leakage on chap cutter machine and she got electrocuted and died on spot. Accident occurred at consumer premasis ,After metering point UGVCL not Responsible for Accident.	Yet not received	N/A	N/A	Prpoer safety norms must be followed by while working near to live conductor.	
129	HMT / Modasa / Malpur	Tiski / (RURAL)	Kotwal Ramanbhai Ramabhai	8.25.24	FAO	As per information received from Owner of Bullock, While in night approx at around 11:40 pm, he found that one of Bullock was lying dead over one of the broken conductor of 3 wire JGY LT line under which the Bullock had been tied by the owner. The suspected cause of the conductor snapping could be due to touching of tree branches over the conductor. Thus, due to snapping of LT conductor over the Bullock tied under the line resulted in electrocution of the Bullock which could have led to its death on spot.T	RECEIVED	NA	NA	stringing of conductor and tree cutting caried out	25000/23.1.2025
130	HMT / Modasa / Meghraj 1	Mevda / (RURAL)	Patel kanubhai dhulabhai	8.6.24	FAO	Patel Kanubhai Dhulabhai, a resident of Mevda village, was going to his farm along with his wife in a bullock cart to get fodder. There, a wire (neutral wire) of Ag LT line of u.g.v.c.l. passing through the farm of Patel Gordhanbhai in the eastern direction adjacent to his farm was broken and fell down. So Patel Kanubhai Dhulabhai's bull got electrocuted and died when it came in contact with the broken wire.	RECEIVED	NA	NA	stringing of conductor and tree cutting caried out	25000/23.1.2025
131	HMT / Modasa / Meghraj-1	Bhemapur / (RURAL)	Katara kalubhai navabhai	4.13.24	FHO	A fatal human Outsider electric accident occurred in Private premises on dated 13-04-2024 Shri Katara kalubhai navabhai. While checking the spot, Katara Kalubhai Navabhai in Mandli area of Bhemapur village, customer no. 29217/00482/0 load. 5 Hp by Agricultural power connection has been provided. On the load side of the connection, the consumer connected a private flexible wire to the starter of the motor and turned on the LED bulb. There are many joints at some distance between the flexible wire and the other flexible wire strung on a stick between the irrigated fields. On dt. 13/04/2024, consumer Katara Kalabhai Navabhai while irrigating the field died due to electrocution at the place where he came in contact with the jointed wire of the flexible wire tied on the wood towards the bulb.	Yet not received	N/A	N/A	Prpoer safety norms must be followed by while working near to live conductor.	PRIVATE PREMISIS
132	HMT / Modasa / Meghraj-2	Vank / (RURAL)	Bhambhi Kanabhai Punjabhai	5.30.24	FHO	AS PER INFOMRMATION HAS BEEN GOT FORM OUR STAFF ON DATED 30.05.2024 AT AROUND 1:00 PM VICTIM SHREE BHAMBHI KANABHAI PUNJABHAI WAS TREE CUTTING WORK AT THEIR FARM. HE WAS CUTTING TREE NEAR 11 KV MUNSHIWADA AG LINE AND SUDDENLY ONE LONG BRANCH OF THAT TREE FALLEN ON 11 KV MUNSHIWADA AG LINE DUE TO THAT BHAMBHI KANABHAI PUNJABHAI GOT ELECTRIC SHOCK & FALL DOWN ON EARTH. AND DIED ON PLACE AT THAT TIME.	Yet not received	N/A	N/A	Mmaintanance Done	100000/8.10.24
133	HMT / Modasa / Meghraj-2	Kasana / (RURAL)	Solanki Yashpalsinh Dolatsinh	9.29.24	FAO	FATAL ANIMAL ACCIDENT OCCURRED TO BUFFALO(SHE) OF SOLANKI YASHPASINH DOLATSINH AT KASANA (LIMDA PADAR) VILLAGE, TA - MEGHRAJ, DIST-ARVALLI. AT AROUND 08:30 PM, AS PER TELEPHONIC INFORMATION FROM OWNER. THE ANIMAL FATAL ELECTRICAL ACCIDENT OCCURRED TO BUFFALO(SHE). BUFFALO(SHE) WAS TIED NEAR 11 KV CHIKARI JGY FEEDER LT LINE. ACCIDENTLY NEUTRAL LINE CONDUCTOR (LT LINE) OF 11 KV CHIKARI JGY FEEDER WAS BROKEN AND FALLEN ON EARTH. AS NEUTRAL LT LINE CONDUCTOR BROKEN, IT TOUCHED TO AG LT LINE OF 11 KV MANDA AG FEEDER PASSING UNDER, HENCE CURRENT GOT PASS THROUGH THAT NEUTRAL LINE CONDUCTOR (LT LINE) OF 11 KV CHIKARI JGY FEEDER. BUFFALO(SHE) CAME IN CONTACT WITH THAT LIVE WIRE (LT LINE) OF 11 KV CHIKARI JGY FEEDER ON EARTH AND GOT ELECTROCUTED AND DIED ON THE SPOT.	RECEIVED	NA	NA	stringing of conductor and tree cutting caried out	30000/16.1.2025
134	HMT / Modasa / Meghraj-2	Moti Panduli / (RURAL)	Kharadi Hirabhai Sardarbhai	9.8.24	FHO	AS PER INFORMATION RECEIVED FROM OUR STAFF (WHO WAS INFORMED BY LOCAL VILLAGER) ON DATED 08.09.2024 AT AROUND 10.00 AM. ON VISITING SITE, DEADBODY OF VICTIM SHREE KHARADI HIRABHAI SARDARBHAI WAS FOUND IN FARM. BROKEN LT LINE CONDUCTOR WAS FOUND UNDER HIS FEET. AS THE STENCH OF THE ROTTING BODY WAS HIGH, IT WAS DIFFICULT TO LOCATE THE MARK OR SPOT ON DEAD BODY WHETHER LT LINE CONDUCTOR TOUCHED BODY.	Yet not received	N/A	N/A	stringing of conductor and tree cutting caried out	
135	HMT / Modasa / Modasa R1	Galsundra / (RURAL)	Parmar Nareshbhai Lalaji	8.31.24	FAO	Fatal Animal Accident occurred to 1 nos of Cow of Parmar Nareshbhai Lalaji at Village Galsundra, Ta. Modasa, Dist. Arvalli around 08.00 am. As per owner's statement, around 08.00 am. Conductors of 3ph 4wire ag LT line which was passing above the open area where cow were tied under the LT line, Conductor broken from 5span and one side of broken conductor comes towards the cow of Parmar Nareshbhai Lalaji, conductor may be broken due to tree branch fall to conductor of LT line. Because of coming in contact of live broken conductor Buffaloe may got shock and died,	Yet not received	N/A	N/A	stringing of conductor and tree cutting caried out	15000/12.9.24
136	HMT / Modasa / Modasa R1	Kolikhad / (RURAL)	Bharvad Dahyabhai Mathurbhai	9.8.24	FAO	Fatal Animal Accident occurred to Cow of Bharvad Dahyabhai Mathurbhai at Village:kolikhad, Ta. Modasa, Dist. Arvalli around 05.00 pm on date 08.09.2024. As per owner's statement, around 05.00 pm cows were grazing in field. Out of which one cow went near 63 KVA TC structure and cow may come in contact of earthing wire and cow may got shock and died.	Yet not received	N/A	N/A	Mmaintanance Done	15000/8.10.24
137	HMT / Modasa / Modasa R2	Amalai / (RURAL)	Khant Kankabhai Abhubhai	5.15.24	FAO	On date 15.04.24 approx. 12:10 hr, at Amlai-Mathasuliya road the owner of Bullock sh. Kankabhai Abhubhai Khant was passing with his Bullock under the HT line of 11 KV Napa Ag feeder and at the same time one conductor of Y-Ph was snapped from joint and the Bullock was came contact with live wire and got electric shock and died on the spot. 11 Kv Napa Ag Feeder was tripped at 12:17 PM.	RECEIVED	NA	NA	stringing of conductor and tree cutting caried out	25000/23.1.2025

Sr. No.	Circle, Division, Subdivision	Location of Accident and Rural or Urban	Name of Victim/Owner & Designation	Date of Occurance	Type of Accident FHD/NFHD/FHO/NFHO/FAO	Cause of Accident	Findings of CEI/EI/ AEI	Remedies suggested by CEI / EI/ AEI in various cases	Whether the remedy suggested is complied	Action taken to avoid recurrence of such Accident.	Amount of Compensation and Date of compensation paid (in Rs.)
1	2	3	4	5	6	7	8	9	10	11	12
138	HMT / Modasa / Modasa R2	Sakariya / (RURAL)	Chamar Rameshbhai Kuberbhai	6.9.24	FAO	On date 09/06/2024, approx at 11:00 hr, at Sakariya,theowner of Buffalo Shri. Rameshbhai Kuberbhai chamar waspassing with his Buttalo when they approached near thetransformer center of Girishbhai Ramnbhai patel of 11 kvsakariya ag feeder, Buffalo came in contact with iron wire anddied on spot.iron wire was connected to the neutral earthwire and stay wire,so due to leakage current of transformerthrough the conductor wich was joint with stay wire oftransformer Buffalo got electric shock and died on the spot.	RECEIVED	NA	NA	Mmaintanance Done	30000/23.1.2025
139	HMT / Modasa / Modasa R2	DUGARVAD A / (RURAL)	Rabari Mafatbhai karsanbhai	7.19.24	FAO	On date 19.07.24 approx. 18:10 hr, at near Devjibhai dhulabhai farm of village Dugarvada, the one conductor of 4 wire LT line of 11 KV Kadamb Ag feeder was snapped due to Su-baval tree fallen on line and the cow of sh. Lagdhirbhai mafatbhai rabari was grassing near the conductor was came in contact with Live conductor wire and got electric shock and died on the spot.	RECEIVED	NA	NA	stringing of conductor and tree cutting caried out	30000/23.1.2025
140	HMT / Modasa / Modasa R2	volva / (RURAL)	Bharvad vastabhai Naranbhai	8.29.24	FAO	On date 29.08.24 approx. 13:05 hr, at near Shirram soc. Volva village farm of punjabhai revabhai the one conductor of 4 wire LT line of 11 KV vanyiad Ag feeder was snapped due to tree fallen on line and the Two nos sheep & one nos Goat of sh. Vastabhai naranbhai bharvad was grassing near the conductor was came in contact with Live conductor wire and got electric shock and died on the spot.	RECEIVED	NA	NA	dead line dismentalled	9000/23.12.2024
141	HMT / Modasa / Tintoi	Charanvada / (RURAL)	Parmar Dashratsinh Takhtatsinh	8.10.24	FAO	on 10/08/2024 Buffalo of Parmar Dashratsinh Takhtatsinh, resident of village Charanwada, tied in his barn but the buffalo rubs his horns with earthing wire of LT pole due to this at the upper end of pole one open end of service tapping wire touches with earth wire resulted into leakage current passes through earth wire to bottom of pole where buffalo came in contact with earth wire got electrocution and died.	RECEIVED	NA	NA	Mmaintanance Done	30000/23.1.2025
142	HMT / TALOD / BAYAD	DAKHANESH WAR / (RURAL)	Raval Sureshbhai urfe Dipakbhai Kalabhai	7.26.24	FHO	As per eye witness and panchnama nivedan, On date 26/7/24 Time approx 11.30 am,Victim was climbed on iron shed was built under 5 wire LT line of Arjanvav JGY Feeder.This iron shed was illegally constructed recently.Distance between Iron shed to bottom LT Conductor was approx 3.25 ft.Victim was climbed on iron shed to his house roof for his slab leakage repairing work. After completed repairing work he passed on iron shed under LT line, suddenly Victim was lapsed and touches to LT line,got electrocuted and death at site. Police panchnama and PM report awaited. Remarks-For this Fatal Accident case UGVCL is not responsible.	Yet not received	N/A	N/A	THERE IS NO ANY NEGLIGENCE FOUND IN NETWORK . ITS VICTIME FAULT.	100000/-
143	HMT / TALOD / BAYAD	Jumatral / (RURAL)	Raval Dineshbhai Sankalbhai	9.2.24	FAO	Date:- 02/09/2024, at 05:30 pm approximate Mr Raval DineshbhaiSakalbhai 's Cow was tied near of his house under Single phase, Three wire LT line of 11KV Sarsoli JGY feeder which eminating power from 66KV BayadSs. At this time due to heavy rain and wind pressure LT wire Snapped and fall down on cow & cow came contact with live conductor she got electrocuted and died on the spot.	RECEIVED	NA	NA	Mmaint+L188+G187:K1+C188:K188	30000/16.1.2025
144	HMT / TALOD / BAYAD	Demai / (RURAL)	BHARVAD BABU HAKA	9.16.24	FAO	On Date 16.09.2024 Approx 12.05 Pm Bharvad Babubhai Hakabhai Cow Was Eating Grass Came In Contact With Earthing Wire Of Transformer Body Of AG Tc Of 11 Kv Kashipura Ag Fdr,Which Eminating Power From 66 Kv Demai Ss.As Per Owner And Surrounding Peoples Statement Cow Came In Contact With Earthing Wire Of Transformer Body,She may Electrocuted And Died On The Spot.	RECEIVED	NA	NA	TC MAINTENANCE WORK CARRIED OUT.	30000/16.1.2025
145	HMT / TALOD / CHOILA	CHOILA / (RURAL)	ZALA VISHNUBHAI BADAJI	8.4.24	FHO	As on dated 5.8.24 information received by police station Bayad, under singh visited site on dated 5.8.24 ,4:30 pm. As per eye witness and panchanama nivedan, On Dated 4.8.24 time Approx 3:30 pm, Victim was arrived at Patel Kiritbhai Bhikhabhai house for plumbing work, said victim climbing at second floor for plumbing work like fitting of water tank and pipe line. 11 KV Ghadiya Jgy Ht line passed above second floor front side salb wHich is unauthorised construction under HT line, so Some How said victim come in induction zone and touched this 11 Kv Ghadiya Jgy line and got electrocuted and fall down from second floor to first floor unauthorised slab and victim died. police panchanama and PM report awaited. Remarks:For This Fatal Accident case UGVCL is not responsible. NOTE:-Notice for Unleagal Construction under HT line is already issued wide letter No:- UGVCL/Choila/3512 dated 15.12.23.	Yet not received	N/A	N/A	THERE IS NO ANY NEGLIGENCE FOUND IN NETWORK . ITS VICTIME FAULT.	NILL
146	HMT / Talod / CHOILA	Junvada / (RURAL)	Vaghari Sajjanben Manubhai	6.25.24	FAO	Date:- 25/06/2024, at 16:30 pm approx on 11 kv Tenpur ag fdr pin pole - As an iron senting wire was placed by a bird on the top wire of the pin pole, due to the wind the iron senting wire touched the iron top of the pole and leakage current was passing through pole. At that time cow passing near the pin pole and touch the pole, she got electrocuted & died on spot,	RECEIVED	NA	NA	CENTING WIRE REMOVED FROM THE LT LINE & STRINGING WORK DONE	30000/16.1.2025
147	HMT / TALOD / CHOILA	PALDI / (RURAL)	Vanjara Lilaben Hsamukhbhai	8.30.24	FAO	As per primary investigation on dated 30.08.2024 time 12.00 approx owner of She Baffalo name Vanzara Lilaben Hasmukhbhai going for grazing grass for She Baffalo. and due to heavy wind and rain, 11 kv Sultanpur AG LT line pole tilted, so that LT Line to land distance was reduced, at that time She Baffalo going under this LT line and touched the line and electrocuted and died.	RECEIVED	NA	NA	TILTED POLE RECTIFIED & MAINTENANCE WORK CARRIED OUT.	30000/08.1.2025

Sr. No.	Circle, Division, Subdivision	Location of Accident and Rural or Urban	Name of Victim/Owner & Designation	Date of Occurance	Type of Accident FHD/NFHD/FHO/NFHO/F AO	Cause of Accident	Findings of CEI/EI/ AEI	Remedies suggested by CEI / EI/ AEI in various cases	Whether the remedy suggested is complied	Action taken to avoid recurrence of such Accident.	Amount of Compensation and Date of compensation paid (in Rs.)
1	2	3	4	5	6	7	8	9	10	11	12
148	HMT / TALOD / CHOILA	Dabha / (RURAL)	ZALA BHUPATSINH CHANDRESH (FH) ZALA VIRENDRASINH BHUPAT (FH) ZALA KAILASHBA BHUPATSINH (NFH)	8.14.24	FHO	AS PER PRIMARY INVESTIGATION IN DABHA VILLAGE AN IRON SHEET SHED IS INSTALLED IN THE FRONT OF THE JOINT HOUSE WITH THE COMMON WALL OF ZALA BHUPATSINH CHANDRASINH AND ZALA UMEDSINH CHANDRASINH THE CELLING FAN WAS INSTALLED WITH IRON ANGLE UNDER THE IRON SHEET SHED IN THE FRONT OF ZALA UMEDSINH HOUSE THE WIRING OF THE CELLING FAN IS OPENED AND SHORTED SO THAT THE THE LEAKAGE CURRENT WAS PASSING IN THE IRON SHEET SHEDAND ALSO THE IRON SENTING WIRE WHICH WAS ATTACHED TO TABELO WHICH WAS MADE IN THE BACK OF THE HOUSE THE ROOF OVER ZALA BHUPATSINH HOUSE WAS ALSO MADE OF IRON SHEET WHICH WERE CONNECTED TO THIS FRONT SIDE IRON SHEET SHED TO BACK SIDE IRON SENTING WIRE SO LEAKAGE PASSING FROM CELLING FAN TO IRON SHED AND IRON SHED TO ROOF OF IRON SHEET AND ALSO IRON SENTING WIRE TO TABELO ON DATED 14.8.2024 TIME 6.30 AM APPROX ZALA BHUPATSINH CHANDRASINH TOUCHED THIS IRON SENTING WIRE SO HE ELECTROCUTED SO THAT SON ZALA VIRENDRASINH AND HIS WIFE KAILASHBA WENT TO SAVE ZALA BHUPATSINH SO THAT BOTH ARE ALSO ELECTROCUTED AFTER TAKING EVERYONE TO THE HOSPITAL ZALA BHUPATSINH CHANDRASINH AND HIS SON ZALA VIRENDRASINH BHUPATSINH DIED AND HIS WIFE CURRENTLY UNDERGOING TREATMENT IN THE PRIVATE HOSPITAL AND THEIR HEALTH IS GOOD	Yet not received	N/A	N/A	Give advice for proper wiring.	PRIVATE PREMISIS
149	HMT / TALOD / CHOILA	Moti Zer / (RURAL)	ZALA MAHESH SANA (FH) ZALA MAHESH BALA (NFH)	9.3.24	FHO	AS PER PRIMARY INVESTIGATION ON DATED 3.9.24 APPROX 9.00 PM ZALA MAHESHBHAI SANABHAI AND ZALA MAHESHBHAI BALABHAI ARE WENT FOR TAKING CARE OF CROP WHICH LAND IS TAKEN ON RENT BY SAID VICTIM WHILE THEY ARE GOING FOR CARRING CROP AT THAT TIME IN BETWEEN NEAR TO ZALA RANGITBHAI FARM VIA IRON SENTING WIRE POWER TAKEN ON FARM BORDER AT ALL FOUR SIDE SO THAT SAID VICTIM SOME HOW TOUCHED THIS IRON WIRE AND ELECTROCUTED SO ZALA MAHESHBHAI BALABHAI RAN FOR SAVE TO ZALA MAHESHBHAI SANABHAI SO HE WAS ALSO ELECTROCUTED BUT ZALA MAHESHBHAI SANABHAI AT THAT TIME DIED AND ZALA MAHESHBHAI BALABHAI NON FATAL AND TAKEN ON PHC HOSPITAL FOR PRIMARY TREATMENT	Yet not received	N/A	N/A	People were educated to not use unauthorized electricity	PRIVATE PREMISIS
150	HMT / TALOD / DHANSURA	SIKKA / (RURAL)	Khant Arajanbhai Mathurbhai	7.1.24	FAO	On date:- 1/7/2024, at 10:30 am approximate, Khant Arajanbhai Mathurbhai 's a cow and a buffello were going for grassing and both came in contact to fencing of village tc near gram panchayat and got electrocuted due to leakage current and died at location.As per site verification by sdn officer the site is wet and water logged due to rainy atmosphere And There was no leakage current found.	RECEIVED	NA	NA	TC FENCING MAINTENECE WORK COMPLETED	30000/-
151	HMT / Talod / Sathamba	TALOD / (RURAL)	1. BARIYA JAGATSINH FATAJI AND 2. BARIYA ASHWINSINH BUDHAJI	4.8.24	FHO	On Dated 08.04.2024 call received on Complaint Centre regarding Snapped Conductor and NonFatal Accident. DE Sathamba visited the site. 11 KV Hamiriya AG passing from farm of Parmar Muljibhai Khanabhai and Parmar Ramanbhai Mayabhai. Very Old GI wire tied on Pole from Loc No 23 to 30(Which was previously used for earthing)Due to some reason, GI wire snapped from Loc No 23 and one end of GI Wire fitted to 11 KV Hamiriya AG feeder and touched to said ag feeder and broken GI wire's other end fallen on ground. At that time, Fatal Victim Bariya Jagatsinh Fataji came in Farm for routine labour work and Accidentally said Victim came in contact with GI wire and dead on spot while on the other side another Non Fatal Victim Bariya Ashwinsinh Budhaji touched the GI wire and got electrocuted and sent to Hospital for Further Treatment. During whole Incident there is no any Tripping recorded in 11 KV Hamiriya AG at SS End. . Police	Yet not received	N/A	N/A	HT SPAN STRINGING WORK COMPLETED & EXTRA GI WIRE REMOVED FROM LINE	100000/-
152	HMT / TALOD / SATHAMBA	Bhempoda / (RURAL)	Khant Bhupatbhai shanabhai	9.6.24	FAO	On Date 16.09.2024 Approx 12.05 Pm Bharvad Babubhai Hakabhai Cow Was Eating Grass Came In Contact With Earthing Wire Of Transformer Body Of AG Tc Of 11 Kv Kashipura Ag Fdr,Which Eminating Power From 66 Kv Demai Ss.As Per Owner And Surrounding Peoples Statement Cow Came In Contact With Earthing Wire Of Transformer Body,She Got Electrocuted And Died On The Spot.	RECEIVED	NA	NA	LT POLE RECTIFICATION WORK CARRIED OUT	30000/16.1.2025
153	HMT / TALOD / Talod-1	Mahiyal / (RURAL)	Desai Naranbhai Vihabhai	5.24.24	FAO	Date:- 24/5/2024, at 8:30am approximate LT pole having 1-ph 2-wire ABC, which was stand in pond's water logging area, said pole had fallen in water of pond, but DO fuse link of transformer had not burnt & current remains flowing in water, as when owner of cow passing near this pond with his cattles out of them one cow came near pond for drinking water, she got electrocuted & died on spot	Yet not received	N/A	N/A	LT ABC LINE STRINGING WORK COMPLETED	15000/-
154	HMT / TALOD / Talod-1	BHATIYA / (RURAL)	SOLANKI DIPSINH KARANSINH	8.29.24	FAO	Date:- 29/08/2024, at 04:30am approximate Mr Solanki DillipsinhKarnsinh 's She Buffalo was tied front of his house under Three phase, four wire LT line of 11KV Chamunda Ag feeder which eminating power from 66KV Dalani Muvadi Ss. At this time due to heavy rain and wind pressure LT wirebroken and fall down on buffalo and buffalo came contact with live conductor she got electrocuted and died on the spot.	Yet not received	N/A	N/A	BROKEN CONDUCTOR JOINTED & MAINTENANCE WORK CARRIED OUT	15000/-
155	PLN/DEESA-1/DEESA R-2	JUNA DEESA AND RURAL	Mali (Parmar) Naitik Kumar Nalin Bhai	01.04.2024	FHO	As per Primairy report On site inspection at Village Juna Deesa in Farm land of Shri Mali Hira Bhai Pitamabar Bhai in this Land One Transformer in which Power feed From 11 kv Swami Ag Feeder From 66 kv Juna Deesa ss & One Installation room of A2 Conn.No.74326026782 in which three phase meter & load side. Outgoing 3 Fuses,starter etc .in Farm Fencing done by using Wires around Farm Boundaries. any Illegal Person done Unauthorized connection by Using Extra Private Cable (Approx. 227.4 Meter) of size 2.5 SQ.MM Cable, this Extra Cable Connected between Outgoing Fuses of Ag Connections & fencing Wires,So Illegal Current flow in all wires of fencing in farm. on Date-01-04-2024 The victim was Passes toward fencing ,victim touch with Wire of fencing in which already electric current flow Due to Illegal Connection, Victim got electrocuted,Fallen in land and died on the spot.	Yet not received	N/A	N/A	inform consumer's not use unathorise power	NOT ELIGIBLE

Sr. No.	Circle, Division, Subdivision	Location of Accident and Rural or Urban	Name of Victim/Owner & Designation	Date of Occurance	Type of Accident FHD/NFHD/FHO/NFHO/FAO	Cause of Accident	Findings of CEI/EI/ AEI	Remedies suggested by CEI / EI/ AEI in various cases	Whether the remedy suggested is complied	Action taken to avoid recurrence of such Accident.	Amount of Compensation and Date of compensation paid (in Rs.)
1	2	3	4	5	6	7	8	9	10	11	12
156	PLN/DEESA-1/DEESA R-2	JUNA DEESA / Rural	Thakor Jasvantsingh Khetaji (Urfe Udaysinh)	07.04.2024	FHO	Raval Hargovan Bhai Mafa bhai (Conn.no. 74326120967)house Power off Complain on date 07-04-2024,at evening around 19:00 p.m.,Consumer's wife Surya ben Raval Seen that Jasvantsingh (urfe Udaysinh) going on the road & informing Jasvantsingh for her house power off Complain , then Jasvantsingh Shows that 1 Wire of Cable got loose (i.e.seperate) from LT Pole, then Jasvantsingh was climbing with taking iron stand for lag support which is insert on top hall of Electric LT pole ,then he take a position on iron stand for repair the loose cable wire ,he suddenly sleeping due to unbalanced iron stand & fall down on land badly & injured on Right back of head ,victim dead on spot at around 19:00 p.m.	Received			inform consumer's not to touch any electrical wire	100000/25.11.24
157	PLN/SIDHPU R/SIDHPUR-T	SIDHPUR / Urban	Thakor Haresh kumar Jivan bhai	21.04.2024	FHO	During Site observation It is found that 11KV Ambaji Feeder is passing from Dethali Circle to Dethali road & near to Shivanagar Society Main gate . There was marriage function in house of Shri Bharatbhai Laxman bhai thakor. During marriage wedding hall/ mandap was built up near the 11 KV Ambaji feeder urban feeder. After completing marriage dismantling work of mandap/weeding hall was continue and dismantling work carried out by Haresh kumar Jivanji Thakor & on that time dismantled big Iron pied was trying to put in Pick up dala by Haresh kumar Thakor .& dismantled IRON PIPE was touched with 11 KV Ambaji Urban Feeder & got electric Shock & he injured & refer to hospital at Sidhpur Civil found he was died .	Received			inform consumer's not to touch any electrical wire	PC pending
158	PLN/PLN-2/DANTA	MOR DUNGARA / Rural	Dabhi Karniben Ashvinbhai & Dabhi Divaben Ashvinbhai	05.04.2024	FHO	As per site visit private black colour twin core cable used for 1 ph motor starter which is binding on swing and this cable end side both phase and neutral open from starter contact and touched to iron swing and 3 nos. Of Girls electrocuted. Which are swinging on swing. This private cable coming from consumer load side near by rooms where our 1 ph meter is provided. so UGVCL is not responsibal for this accident.	Yet not received	N/A	N/A	aware consumer to use ELCB	NOT ELIGIBLE
159	PLN/SIDHPU R/SIDHPUR-R	KAHODA / Rural	THAKOR KIRANKUMAR VELAJI	17.05.2024	FHO	ON DTD:17.05.2024 APPROX TIME: 04:00 A.M. SHRI THAKOR KIRANKUMAR VELAJI VICTIM IS EARLY MORNING GO TO WASHROOM THAT'S TIME VICTIM TOUCHED GI VARGADI AND GI VARGADI FITTED WITH IRON ANGLE OF HOUSE SHED AND IN HOUSE THAKOR JESHAJI NATHAJI LEAKAGE CURRENT FLOW BECAUSE OF CEILING FAN IS SHORT AND POWER SUPPLY ON THATS TIME PROBABILITY VICTIM GOT ELECTROCUTED AND FATAL ELECTRICAL ACCIDENT OCCURED AND DIED.	Yet not received	N/A	N/A	aware consumer to use ELCB	NOT ELIGIBLE
160	PLN/DEESA-1/SHIHORI	JAMNAPADA R / Rural	Bhildiya Ashwinji Paraji,Bhildiya Kiranji Panjiji,Dhumadiya Shivaji Babuji	13.05.2024	NFHO	As per telephonic message received from line staff at 11.00 am about non fatal human outsider accident occurred at vill. Jamanapadar, Dy engg Shihori personally visit the site and as per eye witness statement at site a live DJ with vehicle Eischer passing from Deliyathara to Jamanapadar to attend marriage function, at that time at approximately 10.25 hrs live DJ with vehicle passing from road in front of Thakor Padji Virchandaji farm house at village Jamanapadar. At that time of live DJ program all the people enjoying dance program on live DJ vehicle, at that time Shri Bhildiya Kiranji Panjiji who climbed on DJ set which was set up on vehicle, came in live contact with 11 KV Panna Ag feeder line crossing through road and other two victims Bhildiya Ashwinji Paraji & Dhumadiya Shivaji Babuji who also in physical contact with Bhildiya Kiranji Panjiji got electrocuted.	Yet not received	N/A	N/A	inform consumer's not to touch any electrical wire	NOT ELIGIBLE
161	PLN/DEESA-1/SHIHORI	UMBARI / Rural	(Buffalow-01) Thakor Sangramaji Gumji	29.05.2024	FAO	As per telephonic message received from line staff at 10.00 am about fatal animal accident occured at vill. Umbari , Dy engg Shihori personally visit the site and as per eye witness statement, at approximately 7.00 am when he was brushing conductor of Ag 3ph4w LT line passing near his house was broken due to wind and fall on a Buffalo eating grass under Lt line. Live Broken conductor snapped and fall on Buffalo and due to this buffalo got electrocuted on her stomach portion and died immediately on the spot.	Yet not received	N/A	N/A	To Avoid Any More Unwanted An Electrical Accident Our Line Staff Had Been Repaired Broken Conductor And Repaired Wire Restringing Also Done.	15000/30.11.24
162	PLN/PLN-1/PLN-T	PALANPUR / Urban	Lalabhai Gajrabhai Kharadi- Contractor Labour-Age 19 years aprox	09.05.2024	NFHO	The Fatal Human (outsider-Contractor Labour) Electrical Accident occurred while replacement of deteriorated pole at Oad vas after dismantalling of service lines and LT line conductor from old deteriorated pole by contractor labour shri Lalabhai Gajrabhai Kharadi , New LT pole was erected than after while stringing of LT line conductor again by contractor labour shri Kharadi Lalabhai Gajrabhai suddenly he felt induction and got electric shock. Immediately he admitted to civil hospital for further treatment and after primary treatment he discharged from hospital. No any current burn on body,only. experience of jur , no any type of injury.	Yet not received	N/A	N/A	work with safety	NOT ELIGIBLE
163	PLN/PLN-1/PLN-T	PALANPUR / Urban	PATNI ROHITKUMAR PAPPUBHAI-OUTSIDER-AGE 09 YEAR APROX	30.05.2024	FHO	The Fatal Human (outsider) Electrical Accident occurred in private premises (in Home) of shri Ishwarbhai Raymalbhai Patni, Consumer No: 70106/10904/9 to Shri Rohitkumar Pappubhai Patni due to leakage current flows from faulty ceiling fan to iron shed in home and victim was touches the iron string tied up with iron sheet shed pole in home and victim got electric shock and died.	Yet not received	N/A	N/A	aware consumer to use ELCB	NOT ELIGIBLE
164	PLN/DEESA 2/PANTHAWADA	GUNDARI / Rural	Dhanaram Nebaram Meghwal	03.05.2024	FHO	Fatal Human Outer side electric accident was occurred on dated 03.05.2024 around 8:30 am at Gundari .Duringsite observationit is found that temporary connection of Shri Kanaksing Karatngsing Thakor exist at PanthawadaGundri highway in front of Police check post, after Ugvlc meter and MCB, private black colour twin core cable and flexible cable used for operation of uria pump and other lightning work, which is clamping with iron frame of uria pump machine structure and also adjoining lightning pole where led focus lamp installed. Moreover, lightning pole structure tightening by iron wire (used as stay) which is joint with nearby uria tank iron frame stand. Due to leakage current in private cable/wire in lightning pole structure which is connected with uria tank frame by iron wire , victim touched the uria tank iron frame and got electric shock and died	Yet not received	N/A	N/A	aware consumer to use ELCB	NOT ELIGIBLE

Sr. No.	Circle, Division, Subdivision	Location of Accident and Rural or Urban	Name of Victim/Owner & Designation	Date of Occurrence	Type of Accident FHD/NFHD/FHO/NFHO/FAO	Cause of Accident	Findings of CEI/EI/ AEI	Remedies suggested by CEI / EI/ AEI in various cases	Whether the remedy suggested is complied	Action taken to avoid recurrence of such Accident.	Amount of Compensation and Date of compensation paid (in Rs.)
1	2	3	4	5	6	7	8	9	10	11	12
165	PLN/DEESA 2/ ZERDA	BHADATH / Rural	Sonalben Hathising Vaghela	18.05.2024	FHO	As per daily news paper Press note ,accident occurred on dated:18.05.2024 but no one informed to UGVCL office.After Press note report Site visited by SDO,Zerda on dated:03.06.2024 but due to Suicide case,no further information found at that time and second time visited on 13.06.2024.As per Victim father's statements Sonalben herself Climbed on 11 KV Balwada Ag feeder(single phase time) at location no:125/24/20/3 in their farm.As per PM report ,Cardio-Respiratory arrest due to heavy electric burn, she was died.	Yet not received	N/A	N/A	inform consumer's not to touch any electrical wire	PC pending
166	PLN/PLN-2/DANTA	RANGPUR / Rural	Chauhan Kiranbhai Ishvarbhai	05.06.2024	NFHD	As per statement of victim and other line staff working on 11 KV Rangpur AG feeder Provide New Shackle with Switch. During working two line staff working on pole one Top phase work complete after work on side phase victim suddenly feel induction or by any others reason and fallen from v cross arms of pole and hanging on pole by safety belt after help with other staff victim remove from safety belt and down on ground after that for medical treatment admit at private hospital Satlasna now victim health is stable other EA working on pole is safe no any induction zone	Yet not received	N/A	N/A	work with safety	NOT ELIGIBLE
167	PLN/SIDHPU R/UNJHA-R	UNAVA / Rural	NAVITKUMAR AMRABHAI KHANT	07.06.2024	NFHD	ON DTD 7.06.02024 AT AROUND 5:45PM SHRI NAVITKUMAR AMRABHAI KHANT WAS STRINGING A 2CORE 4MM CABLE AND GI WIRE OF SERVICE CONNECTION OF EXISTING SINGLE PHASE CONNECTION OF SHRI BABULAL PRAHLADBHAI MEWADA (CONS NO:22301002624) AT UNAVA DURING STRINGING A GI WIRE GETS BROKEN AND VICTIM LOST HIS BALANCE AND FELL DOWN ON GROUND AND GET INJURED.ESS.	Yet not received	N/A	N/A	work with safety	NOT ELIGIBLE
168	PLN/PLN-2/AMBAJI	NAVAVASKA NTHA / Rural	(01 BULLOCK) Gamar Vinodbhai Ajkabhai	22.06.2024	FAO	Due to rain and heavy wind, big pipal tree broken and fall on AG LT Wire and LT wire broken from Pole ,both tree and LT wire fall on bullock and it had "major head stock by tree branch and Bullock directly connect with live LT conductor" and get shocked than after died.	Received			At accident spot the tree cutting work done. Also in all span of It wire conductor stringing work done and all conductor properly tightening with It shackle insulator.	NOT ELIGIBLE as per pm report
169	PLN/PLN-2/AMBAJI	BAMNOI / Rural	(01 COW) Kodarvi Rameshbhai Bhudabhai	25.06.2024	FAO	During heavy rain,a cow eating a grass near by village TC ,cow got electrocuted due to ground voltage difference leakage current paas and died.	Yet not received	N/A	N/A	Remove the leakage current	15000/20.08.24
170	PLN/PLN-1/GADH	MADANA / Rural	UNKNOWN UNIDENTIFIED MALE PERSON	28.06.2024	FHO	AN UNIDENTIFIED MALE PERSON HMSELF CLIMB ON 11 KV SALLA FEEDER POLE LOCATION NO 91/6 DUE TO ANY REASONE AND CAME WITH CONTACT OF 11 KV SALLA FEEDER LIVE CONDUCTOR AND DIED.	Yet not received	N/A	N/A	inform consumer's not to touch any electrical wire	100000/21.10.24
171	PLN/PLN-1/DANTIWA DA	VELAVAS / Rural	BHUTADIYA PARTHIBHAI LAXMANBHAI AGE-65 YEARS APPRX	29.06.2024	FHO	AS PER FIRST EYE WITNESS STATEMENT , VICTIM SHRI BHUTADIYA PARTHIBHAI LAXMANBHAI WENT TO START THE MOTOR OF AGRICULTURAL CONNECTION NO-70930/00113/3 (A1 CATEGORY) AND WHILE VICTIM WAS OPERATING THE FUSE MAY CAME IN CONTACT WITH LIVE PART OF FUSE AND GOT ELECTROCUTED AND DIED. VICTIM WAS IMMEDIATELY SHIFTED TO CHC DANTIWADA AND WAS DECLARED DEAD	Yet not received	N/A	N/A	inform consumer's not to touch any electrical wire	NOT ELIGIBLE
172	PLN/SIDHPU R/SIDHPUR	BHUNAV / Rural	THAKOR JIVANJI MANAJI	17.07.2024	FHO	ON DATED:17.07.2024 APPROX TIME:06:30 P.M SHRI THAKOR JIVANJI MANAJI WORK VICTIM WAS WET BATHROOMAL PUT ON ALUMINIUM GI VARGADI,BUT GI VARGADI FITTED AT ONE POINT WITH IRON ROD ELECTRIC ROOM OF PATEL MANIL RAMDAS AND IRON ROD CONTACT WITH OPEN PHASE WIRE INTO SWITCH BOARD TO LED BULB THAT'S TIME VICTIM TOUCH GI VARGADI AND OPEN PHASE WIRE CONTACT WITH IRON ROD CURRENT FLOW POWER SUPPLY ON THAT'S TIME PROBABILITY VICTIM GOT ELECTROCUTED AND FATAL ELECTRICAL ACCIDENT OCCURED AND DIED AND HIS DAUGHTER CAME TO SAVE BUT THAT'S TIME CURRENT FLOW IN THAKOR DAXABEN JIVANJI.	Yet not received	N/A	N/A	aware consumer to use ELCB	NOT ELIGIBLE
173	PLN/DEESA 2/DHANERA 2	MANDAL / Rural	Rishipalsinh Sujansinh Solanki	10.07.2024	FHO	As per site visited & Farm owner's Son Shri Narpatsinh statement Ag flat tariff Ag Connection no 71425000924 is running in his father name Solanki Savsibhai Versibhai.fencing done around Agriculture land which is farming by Narpatsinh.He has illegle flexible single core wire connected from Ag(A1)connection on fencing instead of Zatka machine and Current passes in fencing,Victim Solanki Rishipalsinh Sujansinh came in contact with live power fencing and died on the spot	Yet not received	N/A	N/A	inform consumer's not to touch any electrical wire	NOT ELIGIBLE
174	PLN/PLN-1/GADH	SASAM / Rural	Mukeshji Mafaji Bokarvadiya (Thakor)	04.07.2024	FHO	As per information received from social media, Shri Mukeshji Mafaji Bokarvadiya (Thakor) got electric shock due to came in contact with iron pipe.this leakagr current flow through a NRGp Connection Consumer number: 70742/10018/9 private wire given to outside shop cabin and this private wire hanging on iron aple ,in detail investigation, this private wire insulation punctured touch with angle and victim came in contact with private iron pole connected with this angle and got electric shock & died	Yet not received	N/A	N/A	aware consumer to use ELCB	NOT ELIGIBLE
175	PLN/PLN-1/PLN-R	BANASDAIRY ,LALAWADA / Rural	Pritambhai Kamleshbhai Raval	15.07.2024	FHO	Ondate: 15.07.2024 , 10:30 AM (Approx time) a private person of Vendor replacing valve in butter -2 plant of Banas dairy, Palanpur. At the working site insulation of phase wire of tubelight power supply found damaged and live phase wire found open, unfortunately the said person during work came in contact with this live phase of wire and got electrocuted.	Yet not received	N/A	N/A	aware consumer to use ELCB	NOT ELIGIBLE

Sr. No.	Circle, Division, Subdivision	Location of Accident and Rural or Urban	Name of Victim/Owner & Designation	Date of Occurance	Type of Accident FHD/NFHD/FHO/NFHO/FAO	Cause of Accident	Findings of CEI/EI/ AEI	Remedies suggested by CEI / EI/ AEI in various cases	Whether the remedy suggested is complied	Action taken to avoid recurrence of such Accident.	Amount of Compensation and Date of compensation paid (in Rs.)
1	2	3	4	5	6	7	8	9	10	11	12
176	PLN/PLN-2/VADGAM	IOBALGADH / Rural	Harssadbhai Savjibhai Chaudhary (33years)	06.07.2024	NFHD	onsumer no 70306/10060/6, After removing DO fuse from Separate Transformer , Victim climb on maintenance of 2 core cable and giving new connection on LT side of transformer. A flying peacock is strike on in between DO , So victim got momentary current on his right hand , and burns on his right hand also the Victims may came in contact with LT side stud and may got current , So victim is got treatment at Narendra Chaudhary Ankur hospital and Anil D Sulhar Ravi surgical Hospital Visnagar for primary medical treatment. Health conditions of victim is fine currently.	Yet not received	N/A	N/A	work with safety	NOT ELIGIBLE
177	PLN/SIDHPUR/UNJHA-R	MAHERWADA / Rural	(1) THAKOR ARUNABEN SURESHJI (2) THAKOR ARUNABEN SURESHJI	02.07.2024	NFHO	ON DTD 2.07.2024 (11:00PM)IN THE HOUSE OF THAKOR KANAJI KUVARJI FLEXIBLE WIRE WAS WINDED AROUND ROOF SUPPERT MADE OF IRON.DUE TO DAMAGED INSULATION OF FLEXIBLE WIRE CURRENT START TO FLOW IN THE IRON ROOF AND MAIN DOOR MADE OF IRON.AT THE TIME VICTIMS CAME IN CONTACT WITH THE DOOR AND GOT ELECTROCUTED SO FATAL ELECTRICAL ACCIDENT OCCURED.	Yet not received	N/A	N/A	aware consumer to use ELCB	NOT ELIGIBLE
178	PLN/DEESA 2/LAKHANI	CHITRODA / Rural	Chauhan Kiranbhai Ishvarbhai	18.08.2024	FHO	One bat(Chamachidiyu)bird sitted on LT line wire and short circuit occurred between three LT wire and one LT wire conductor broken near pole side.Victim at that time working in tabela of buffalo and broken wire fallen on Thakor Balvantiji Rupshiji and died on the spot.	Yet not received	N/A	N/A	To Avoid Any More Unwanted An Electrical Accident Our Line Staff Had Been Repaired Broken Conductor And Repaired Wire Restrstring Also Done.	PC pending
179	PLN/RADHANPUR/RADHANPUR R-2	RADHANPUR / Rural	NARSANGBHAI GOVABHAI CHOUDHARY	08.04.2024	FAO	A FATAL ANIMAL ELECTRICAL OUTSIDER ACCIDENT OCCURRED DUE TO CONDUCTOR OF 11 KV JAVANTRI AG FDR GOT BROKEN AT THE PLACE OF INCIDENT AND IT FELL ON GRASS (JAR PULA) THE FDR GOT TRIPPED BUT AS A ROUTINE FOR TRY WAS TAKEN TO RESTORE POWER SUPPLY AND THE GRASS UNDER THE LINE FIRE. THE SPREAD THE FIRE TO ADJACENT BUFFALOW HOUSE WHOSE ROOF COVERED WITH GRASS AS PER EYE WITNESS STATEMENT THE INTESTY OF FIRE WAS HIGH SO UNABLE TO HELP POOR BUFFALOW AND BOTH BUFFALOWS DIED BY SHOCK DECLARE BY POST MORTEM REPORT.	Yet not received	N/A	N/A	To Avoid Any More Unwanted An Electrical Accident Our Line Staff Had Been Repaired Broken Conductor And Repaired Wire Restrstring Also Done.	LEGAL NOTICE ISSUE TO UGVCL
180	PLN/RADHANPUR/DEODAR 2	CHIBHDA / Rural	SONI ROHITBHAI NAGJIBHAI	13.05.2024	FHO	AS PER PRESSNOTE IN SANDESH NEWS PAPER (BANASKANTHA AVRUTI) ON DTD 15.05.2024 ABOUT FATAL HUMAN ACCIDENT AS PER SITE VISITED ACCIDENT TOOK PLACE IN THE PREMISES OF SHRI SONI MERUMAL KALIDAS HAVING CONSUMER NO. 73934001637 AT METER INSTALLATION CONSUMER HAS INSTALLED THE ELCB WHICH ARE NOT CONNECTED WITH EARTHING WIRE ON DTD 13.05.2024 LATE SHRI SONI ROHITBHAI NAGJIBHAI PLAN TO DRAIN THE WATER WHICH ARE LOGGING NEAR BATHROOM SIDE HE WAS DRILLING THE WALL BY DRILL MACHINE WHOSE BODY ARE FULLY COVERED BY METAL HE WAS HANDELLING THE DRILL MACHINE WITHOUT HAND GLOVES AND SHOES AND SAME TIME LAND WAS WET DUE TO CYCLONE .HE HAD PLUGGED MACHINE FROM NEAR BY PLUG POINT IN HOUSE AS HE HAD SWITCH ON THE DRILL MACHINE FAULT HE GOT THE ELECTRIC SHOCK AND ELECTROCUTED AND LAID DOWN THE SPOT THIS ACCIDENT TOOK PLACE INSIDE THE CONSUMER PREMISESAND AFTER THE UGVCL METER INSTALLATION.	Yet not received	N/A	N/A	Use ELCB connected with earthing	NOT ELIGIBLE
181	PLN/RADHANPUR/RADHANPUR 1	BHILOT / Rural	AHLETAR JASWANTKUMAR KANJIBHAI	18.05.2024	NFHD	AS PER STATEMENT OF EYE WITNESS & SUPERVISOR WHILE ATTENDING COMPLAIN REGARDING POWER OFF IN TWO AG CONNECTION BEING FED FROM 11 KV RANGPURA AG FDR THERE WAS ONE NEEEM TREE BRANCH FOUND FALLEN ON THIS 11 KV LINE SUPERVISOR TOOK LC FROM 66 KV DAISAR SS AT TIME 12:45 & ALSO SHACKLE POINT JUMPER ALREADY CUTTED AT LOCATION NO.RANGPURA AG/92/41/32/18/5 AS IT WAS REQUIRED TO CUT NEEEM TREE VICTIM CLIMBED ON THIS TREE TO CUT ITS BRANCH AND WHILE DOING SO A SQUIRREL SUDDENLY CAME IN TOUCH WITH HIS LEG AND HE LOST HIS BALANCE AND FELL DOWN FROM A TREE FROM HEIGHT @15 FEET AND VICTIM MEET AN UNFORTUNATE NON FATAL MECHANICAL ACCIDENT	Yet not received	N/A	N/A	work with safety	NOT ELIGIBLE
182	PLN/RADHANPUR/THAR A	BHADREVADI / Rural	DESAI ASHISH SAVABHAI	05.06.2024	NFHO	AS PER THE STATEMENT OF EYE WITNESS AT VILL BHADREWADI NEAR DUDH MANDALI WHERE 11 KV SHIYA AG FDR PASSES FROM THE FRONT SIDE OF THIS DAIRY IN MORNING TODAY AT @ 10:45 AM A VEHICLE OF BANAS DAIRY VEHICLE NO GJ 213 Y5404 CAME TO FILL UP THE MILK STORED IN THIS DAIRY WITH NEW DRIVER AND CLEANER AND THEY PARK THIS VEHICLE EXACTLY BELOW THIS EXT HT LINE OF 11 KV SHIYA AG FDR AS PER EYE WITNESS A CLEANER CLIMBED ON VEHICLE TO OPEN A CAP OF MILK TANK WITH A MONKEY WALK SO AS TO FILL UP MILK AND WHILE REACHING NEAR CAP VICTIM SUDDENLY STOOD UP AND THERE HIS HEAD CAME IN CONTACT WITH LIVE CONDUCTOR A WHILE SPARK WAS OBSERVED IN TYRE AND VICTIM GOT ELECTROCUTED AND FELL DOWN AND MEET AN UNFORTUNATE NON FATAL ELECTRICAL ACCIDENT.	Yet not received	N/A	N/A	inform consumer's not to touch any electrical wire	NOT ELIGIBLE
183	PLN/RADHANPUR/RADHANPUR R-2	CHHANİYAT HAR / Rural	BHARWAD VISNUBHAI BHAGABHAI	29.08.2024	FAO	RAINY SEASON DUE TO HEAVY WIND AND RAIN LT CONDUCTOR BROKEN AND ONE NO COW CAME IN CONTACT WITH LIVE BROKEN CONDUCTOR AND ELECTROCUTED AND DIED ON SPOT	Yet not received	N/A	N/A	To Avoid Any More Unwanted An Electrical Accident Our Line Staff Had Been Repaired Broken Conductor And Repaired Wire Restrstring Also Done.	15000/03.09.24
184	PLN/RADHANPUR/RADHANPUR R-2	JUNA PORANA / Rural	RABARI HEMABHAI GOVINDBHAI	29.08.2024	FAO	RAINY SEASON DUE TO HEAVY WIND AND RAIN LT CONDUCTOR BROKEN AND ONE NO COW CAME IN CONTACT WITH LIVE BROKEN CONDUCTOR AND ELECTROCUTED AND DIED ON SPOT	Yet not received	N/A	N/A	To Avoid Any More Unwanted An Electrical Accident Our Line Staff Had Been Repaired Broken Conductor And Repaired Wire Restrstring Also Done.	15000/03.09.24

Sr. No.	Circle, Division, Subdivision	Location of Accident and Rural or Urban	Name of Victim/Owner & Designation	Date of Occurance	Type of Accident FHD/NFHD/FHO/NFHO/FAO	Cause of Accident	Findings of CEI/EI/ AEI	Remedies suggested by CEI / EI/ AEI in various cases	Whether the remedy suggested is complied	Action taken to avoid recurrence of such Accident.	Amount of Compensation and Date of compensation paid (in Rs.)
1	2	3	4	5	6	7	8	9	10	11	12
185	PLN/PLN-2/DANTA	KANBIYAVAS / Rural	Lalabhai Dharmabhai Pargi	28.08.2024	FAO	As per eye witness statement during there was continues heavy rain with wind snapping of LT wire on farm and Buffalo grazing on farm and come in contact with live wire and got electrocuted.	Yet not received	N/A	N/A	To Avoid Any More Unwanted An Electrical Accident Our Line Staff Had Been Repaired Broken Conductor And Repaired Wire Restraining Also Done.	15000/16.10.24
186	PLN/DEESA-1/BHILDI	MOTI GHARNAL / Rural	1) Rupsang Parthiji Solanki (Thakor)-FH 2) Panchal Chothabhai Babubhai- NFH 3) Panchal Chetanbhai Choithabhai-NFH	16.08.2024	FHO-1 NFHO-2	During the construction of a cattle shed at the site, the victim attempted to erect an angle or channel to support the structure. Unfortunately, the angle/channel inadvertently came into contact with a nearby high-tension (HT) line associated with the Chitroda AG feeder. As a result, the victim received a severe electric shock.	Yet not received	N/A	N/A	inform consumer's not to touch any electrical wire	100000/17.02.25
187	PLN/DEESA-1/DEESA R-2	NAVA / Rural	1) PARMAR(THAKOR) PARJJI VELAJI'S COW	28.08.2024	FAO	During rain and due to wind in morning, Dry Acacia tree branch fall on LT line so 1 LT wire broken and fallen on land in between cow of shri thakor parjiji velaji passes on this broken wire and got electrocuted and died on the spot	Yet not received	N/A	N/A	At accident spot the tree cutting work done. Also in all span of It wire conductor stringing work done and all conductor properly tightening with It shackle insulator.	15000/03.12.24
188	PLN/SIDHPU R/KAKOSHI	KAKOSHI / Rural	THAKOR VIKESHJI VANAJI	10.08.2024	NFHO	LM Shri M P Baranada(work supervisor) of Kakoshi City has started the work for ground clearance maintaining work of 11 KV Kakoshi JGY Feeder by power Off through operating of AB Switch . After erection work completion of HT Line, shri M P Baranda informed to contractor Gang leader that he is restoring the power supply of 11 KV Kakoshi JGY feeder and then we will start the work of LT Line.After ward he, Shri M P Baranda gone to AB Switch operation. Mean while Contractor Gang leader start the work without any presence & inform to UGVCL supervisor and Contractor labour climbed on LT Pole of 11 KV Kakoshi JGY feeder and start the work of opening of LT binding. In between LM shri MP Baranda has restored the power of 11 KV Kakoshi JGY Feeder by operating AB Switch, hence viciium has electrocuted.	Yet not received	N/A	N/A	inform supervisor before work start	NOT ELIGIBLE
189	PLN/SIDHPU R/UNJHA-R	AITHOR / Rural	THAKOR KAJALBEN GOVINDJI	09.08.2024	FHO	AT AITHOR VILLAG IN THE HOUSE OF THAKOR VALAJI AMTHAJI ON THE SUPPORT ANGLE OF ROOF AN IRON WIRE IS TIGHTENED AND TWO CORE PRIVATE CABLE OF INTERNAL OPEN WIRING IS PASSING ON THE SAME IRON ANGLE.DUE TO DETERIORATION OF INSULATION OF TWO CORE CABLE LIVE PHASE WIRE GET SHORT WITH THE IRON WIRE AND CURRENT STARTED TO FLOW FROM IRON WIRE.ON DTD 9.08.2024 AT AROUND 9:00PM THAKOR KAJALBEN GOVINDJI CAME IN CONTACT WITH THE LIVE IRON WIRE AND GOT ELECTROCUTED AND DIED.	Yet not received	N/A	N/A	aware consumer to use ELCB	NOT ELIGIBLE
190	PLN/RADHANPUR/VARAH	JARUSHA / Rural	SIPAI HANIFBHAI ABRAHMBHAI	28.08.2024	FAO	RAINY SEASON DUE TO HEAVY WIND AND RAIN LT CONDUCTOR BETWEEN AND OUTGOING NEUTRAL WIRE OF LT CONDUCTOR BROKEN AND BUFFALOW CAME IN CONTACT WITH LIVE BROKEN CONDUCTOR AND ELECTROCUTED AND DIED ON SPOT.	Yet not received	N/A	N/A	To Avoid Any More Unwanted An Electrical Accident Our Line Staff Had Been Repaired Broken Conductor And Repaired Wire Restraining Also Done.	15000/03.09.24
191	PLN/PLN-1/GADH	SAGROSANA / Rural	(1) Judal Manjibhai Rajsangbhai (2) Judal Bhikhiben Manjibhai	01.09.2024	FHO	As per received First information of accident by pressnote in Divyabhaskar News Paper on Dtd 03.09.24, DE Gadhsdn has visited site and as per Eye witness Statement it is state that on dtd 01.09.24 time approx 5.30 am Shri Manjibhai Rajsangbhai Judal-Husband & his wife Shrimati Bhikhiben Manjibhai Judal went to his farm at sagrosana village and those both victims are came with contact of Zatk machine wire which are wired between headland (SHEDHA) of his own farm as per eye witness at that time rainy season. 11KV Sagrosana agriculture feeder line is 30 meter away from accident place without any creeper on pole and no any LT line OR other UGVCL Network near by accident place.One agricultural connection is 100 meter away from accident place	Yet not received	N/A	N/A	inform consumer's not use unathorise power	NOT ELIGIBLE
192	PLN/PLN-1/PLN-T	PALANPUR Urban	Rajubhai Natwarlal Joshi-Age-51 years,Lineman, Employee No:6651	17.09.2024	NFHD	The Non Fatal Mechanical accident occurred to Shri R N Joshi,LM During cable replacement work of consumer Patel Daxaben Hareshbhai, conn No:70101/10180/5, P/Vt Waterworks. While working on an Iron ladder (Ghoda) to replace a cable, he suddenly lost his balance by any reason and fell down to the ground. So,He was taken to Gokul Hospital for medical treatment . And the heel of the Left Leg is fractured. Then, He is discharged and advised to rest.	Yet not received	N/A	N/A	work with safety	NOT ELIGIBLE
193	PLN/DEESA-1/DEESA-T	DEESA / Urban	BADARSINH ISHVARSINH CHUNDAVAT	26.09.2024	FHO	When sudden rain and cyclone came, LT wire broken and fell on his Icecream lorry at that location of sid tc, victim touched to this LT conductor for make away from his lorry and came in contact with live line and got shocked and met with non fatal human accident then he was shifted to hospital by nearby public where after some time he was declared as dead so converted in fatal accident.	Yet not received	N/A	N/A	To Avoid Any More Unwanted An Electrical Accident Our Line Staff Had Been Repaired Broken Conductor And Repaired Wire Restraining Also Done.	100000/07.12.24

Sr. No.	Circle, Division, Subdivision	Location of Accident and Rural or Urban	Name of Victim/Owner & Designation	Date of Occurrence	Type of Accident FHD/NFHD/FHO/NFHO/F AO	Cause of Accident	Findings of CEI/EI/ AEI	Remedies suggested by CEI / EI/ AEI in various cases	Whether the remedy suggested is complied	Action taken to avoid recurrence of such Accident.	Amount of Compensation and Date of compensation paid (in Rs.)
1	2	3	4	5	6	7	8	9	10	11	12
194	PLN/DEESA 2/RAH	MORTHAL / Rural	Surekhaben Ashokbhai Mali	11.09.2024	FHO	fatal human accident outsider occurred approximately 09:15 A.M to Mali Surekhaben Ashokbhai, Age – 30 Years on Dated – 11.09.2024 at Village –Morthal, Ta – Tharad On Dated 11.09.2024, Surekhaben was electrocuted when she was plugging the open wire (Without Plug) of Valona in to the plug in the switch board Filled in her House for buttermilk churn.The house in which the electrical accident occurred, There is no any UGVCL Connection exist but they are using power from nearby Residential farm house Connection of shri MALI BABUJI SAVAJI through extended about 15 mtr black color 2 – core wire. The customer number of this meter is 76924100260. ELCB / MCCB is not installed in any of the two houses. UGVCL service cable and meter are in Good Condition and no any fault.	Yet not received	N/A	N/A	aware consumer to use ELCB	NOT ELIGIBLE
195	PLN/DEESA 2/DHANERA 2	BHATIB / Rural	BUFFALOW OF LAVAR KANTIBHAI MANJIBHAI	13.09.2024	FAO	As per site visited & talk with the EA, there was one load side line conductor of 11 KV Manthan AG Feder (under 3-ph power Schedule Bhatip s/s) broken from shackle insulator (tapping pole no: 23/1) falldown in small pond so feeder tripped . After few minutes, No any message received from field , So Sub station staff has taken Second try of feeder to ON but feeder not ON but at the time of feeder's Second try one Buffalo was came in contact with broken Conductor which was lay down in small pond. buffalo was came in contact with load side conductor and due to return power of feeder , Buffalo got electric shock and died on the spot . But feeder was not tripped from Sub station side due to return conductor broken.	Yet not received	N/A	N/A	To Avoid Any More Unwanted An Electrical Accident Our Line Staff Had Been Repaired Broken Conductor And Repaired Wire Restraining Also Done.	15000/25.10.24
196	PLN/RADHANPUR/THAR A	BHALGAM / Rural	VIMLABA VINUBHA VAGHELA	11.08.2024	FAO	AT @9:30 AM IT WAS FOUND THAT MINOR LEAKAGE CURRENT FLOW IN EARTHING OF BHALGAM VILLAGE TC WHERE STAY OF LT POLE SUPPORTED WHICH ALSO HAVING SUPPORT OF FENCING DUE TO THAT LEAKAGE CIRRENT PASSES THROUGH IN MORNING COW WHICH TRY TO PASSES BETN NARROW PASSAGE BETN WALL AND FENCING GOT ELECTROCUTED AND MET WITH FATAL ELECTRICAL ACCIDENT .	Yet not received	N/A	N/A	Remove the leakage current	15000/18.11.24
197	PLN/RADHANPUR/THAR A	BHALGAM / Rural	MUNECHA (BHANGI)JITUBHAI JYANTIBHAI	09.08.2024	FAO	AT @11.05 AM IT WAS FOUND THAT DUE TO HEAVY WIND TREE BRANCHES FALLEN ON LT LINE OF BHALGAM VILLAGE TC AND LT LINE OF OF VILLAGE TC CONDUCTOR SNAPPED DURING THAT TIME THE CALF WAS PASSING FROM THERE WHERE IT CAME IN CONTACT WITH BROKEN CONDUCTOR AND GOT ELECTROCUTED AND MET WITH FATAL ACCIDENT .	Yet not received	N/A	N/A	At accident spot the tree cutting work done. Also in all span of It wire conductor stringing work done and all conductor properly tightening with It shackle insulator.	8000/18.11.24
198	PLN/SIDHPUR/SIDHPUR-T	SIDHPUR / Urban	Prajapati Pankaj Kumar Dhanjibhai (Electrical Assistant)	18.09.2024	NFHD	A non fetal Mechanical Departmental accident occured to Shri.P.D.Prajapati EA while attaining complain of Shri Lokhandwala Hamida husain consumer no-22207004791. An Iron Stand was placed between 3rd & 4th step of PSC pole(Approximately height 3to 3.5 meter from ground & victim was was trying to climb on PSc pole for attending service replacement Complain of Shri. Lokhandwala Hamida Hussain during that time his right lag slipped from PSc pole & fall down & injured his left hand.	Yet not received	N/A	N/A	work with safety	NOT ELIGIBLE
199	PLN/SIDHPUR/SIDHPUR-R	BHUNAV / Rural	THAKOR BHARATJI PRAHLADJI	24.09.2024	FAO	In bHUNAV village near matsiya mahadev Temple near Transformer cetnre of 11 kv Kahoda Telephone jgy feeder Loc no.108/2,Shri Thakor Bharatji Prahladi's buffalo came to drink water in artificial reservoir at near Transformer cetnre.at that time buffalo might came in contact with Leakage current flowing from Post office electrical equipment shot ann monkey jump on neutral cable break and touch with stay wire and During drinking water in reservoir buffalo might got shocked and died in the Reservoir.	Yet not received	N/A	N/A	Remove the leakage current	PARTY HAS NOT CARRIED OUT PM
200	PLN/SIDHPUR/CHHAPI	NALASAR / Rural	(1) ANGARI LALABHAI CHANDUBHAI AGE-41 YEARS (2) ANGARI DILIPBHAI URFE KALUBHAI CHANDUBHAI AGE 41 YRS RES-AT VILL- PIPALIYA,TA- POSHINA,SABARKANTHA	08.09.2024	FHO	AS PER STATEMENT OF LAND OWNER SHRI DALSANGBHAI LALJIBHAI CHAUDHARY & POLICE STATION REPORT ON DTD:08.09.2024 APPROX TIME: 00.30 A.M. VICTIM SHRI LALABHAI CHANDUBHAI ANGARI & DILIPBHAI URFE KALUBHAI CHANDUBHAI ANGARI WAS COME IN CONTACT WITH THE WIRE IN WHICH THE ELECTRIC CURRET PASSES GOT SHOCKED AND DIED ON THE SPOT.THE CURRENT WAS COME FROM THE ZATKA MACHINE PUT BY FARMER TO AVOID DAMAGE IN FARM DUE TO ANIMALS.IN THE MORNING THE RELATIVES OF BOTH VICTIMS WERE COME & INFORM TO CHHAPI POLICE STATION & VICTIM WERE TAKEN TO VADGAM CIVIL HOSPITAL FOR PM.	Yet not received	N/A	N/A	Aware line staff about safety	NOT ELIGIBLE
201	PLN/PLN-2/DANTA	KUNDEL / Rural	Ajaybhai Monabhai Saragra	06.08.2024	FHO	As per eye witness statement victim doing water heating in steel basket by electric heater and leakage current flow in water that time victim touch to basket and got electrocuted	Yet not received	N/A	N/A	aware consumer to use ELCB	NOT ELIGIBLE
202	PLN/PLN-2/AMBAJI	JETVAS / Rural	Jitendrakumar Ramanbhai Solanki	16.09.2024	NFHO	As per eye witness statement solanki Jitendrakumar Ramanbhai appx 35 yr himself climb on 11 kV Koteswar JGY DP structure due to unknown reason and touch 11 kV Koteswar JGY live conductor and got electical shock and fall under DP structure fencing.	Yet not received	N/A	N/A	inform people's not to touch any electrical wire	NOT ELIGIBLE
203	PLN/PLN-2/MALAN	VIRAMPUR / Rural	Shri Parathibhai Vasharambhai Parmar	17.09.2024	NFHD	The non fatal Electrical accident occurred to Shri P V parmar, EA, while attaining complain of shri Rupsinh Gumansinh consumer no 77339/00007/0 and others on Ag TC loc no 27/1-2. victim got electric shock and he met with non fatal electrical accident while working on transformer. He got injury of burn on left leg foot and peeling of skin over left elbow	Yet not received	N/A	N/A	work with safety	NOT ELIGIBLE

Sr. No.	Circle, Division, Subdivision	Location of Accident and Rural or Urban	Name of Victim/Owner & Designation	Date of Occurance	Type of Accident FHD/NFHD/FHO/NFHO/FAO	Cause of Accident	Findings of CEI/EI/ AEI	Remedies suggested by CEI / EI/ AEI in various cases	Whether the remedy suggested is complied	Action taken to avoid recurrence of such Accident.	Amount of Compensation and Date of compensation paid (in Rs.)
1	2	3	4	5	6	7	8	9	10	11	12
204	PLN/PLN-2/DANTA	CHHOTA BAMODRA / Rural	Bumbadiya Sureshbhai Bandhubhai	26.09.2024	FAO	As per Preliminary investigation due to heavy wind from LT line phase wire slipped from shackle insulator and touch to U Clamp and leakage current pass through earth wire to ground that time Bullock passes near pole and contact in leakage current and got electric shocked and death on the spot and fetal Animal Accident occurred .	Yet not received	N/A	N/A	Remove the leakage current	12500/22.10.24
205	Sabarmati/ Gandhinagar R /Rakhiyal	Mithana muvada/ Rural	1)VijayKumar Anusinh Zala 2)Adarsinh Bhavansinh Zala	10.1.24	FAO	Due to Vaagod short on pin of 11 KV sampa JGY feeder one conductor was break from pin of 11 KV line & fallen on buffaloes & buffaloes got electrocuted and Death at Site.	Regulation 14 and 15 of central electricity authority regulations 2023 has been violated	Power line should be maintained time to time.	Yes	JOINING OF CONDUCTOR AND FAULTY PIN CHANGED	60000/15.2.25
206	Sabarmati / Bavla /Dholka T	Dholka/ Rural	Vinubhai Butabhai Bharwad	10.1.24	FAO	On Dt:01.102024 when cow passing from near by Lt pole come in contact with earthing wire and got electric shock and die. (Binding wire of phase wire is open on Lt pole and touch with earthing wire so power leakage on earthing wire.)	Yet not received	N/A	N/A	PIN BINDING OF LT WIRE WAS DONE	15000/18.10.24
207	Sabarmati /Gandhinagar R /Dehgam T	Palaiya/ Rural	Vijaybhai Sanabhai Raval	10.1.24	FHO	Victim touched defective instrument at construction site, got electrocuted and died.	Yet not received	N/A	N/A	attribute to victim and awerness to the villagers given	0
208	Sabarmati /Sabarmati /Goblaj	Sarsa/ Rural	Jibaben Kantibhai Chauhan	10.5.24	FHO	As per site visit, the victim was cutting grass in her farm. The LT wire of sarsa ag feeder was broken and fell on the fencing made by victim by metal wire. Due to Lt wire contact, whole fencing become live and victim might have accidentally touched the live fencing wire and got electrocuted.	Yet not received	N/A	N/A	The LT Span Where Conductor Is Broken, Is Replaced With New Conductor.	100000/28.10.24
209	Sabarmati/ Gandhinagar U/ Motera	Bhat/ Rural	Jivach Nakchedi Raugaredi	7.15.24	FHO	As per Eye witness report, victim was working of cleaning work at Narayani Hotel small kitchen at vill. Bhat. He was working with cleaning MOP steel rod for cleaning of kitchen. His cloth was fully wet during work. There was leakage in Freeze which was lying in kitchen. Suddenly victim's MOP steel rod touched with leakage part of freeze leakage part & got shocked at site then other people took him to Apollo hospital & declare victims as dead.	Yet not received	N/A	N/A	Proper Wiring to be done at consumer premises to avoid any type of leakage current	0
210	Sabarmati Kalol Chhatral	Dhanot/ Rural	Navinkumar Shaileshbhai Patel((EA)	10.10.24	NFHD	As he was climbing on pole no 16 of Suzuki feeder for pole jumpering work during ss shutdown, while climbing the pole he slipped from 3rd window of psc pole and injured, sent to hospital detected injured on left shoulder having crack (fracture)	Safety equipments should be used when carring out electrical repairs.	Such accident can be avoided if precautionary measures are taken by using proper safety equipment while doing work.	Yes	Line staff should inspect the pole before commencement of work and maintain safety aspect during work	0
211	Sabarmati /Kalol /Kalol-1	Kalol/ Town	1.Velabhai Bijalbhaj Desai 2.Ladchiben Bijalbhaj Desai	10.10.24	NFHO	As per site visit and information given by Eye witness of the accident location, At 9:30 am 11 kv Stp jgy HT Location -09, one nos HT Wire of span between Ht location 09 - Ht location 10 of 11 KV Stp jgy broken and fallen on Activa which was parked by viktin Velabhai Bijalbhaj desai below Ht LINE On 13 MTR Girder pole . As Per eye witness Viktim Shree Velabhai Bijal bhai desai run towards Activa to shift from Ht broken conductor and came in contact with Activa metal parts and electrocuted .At same time seeing his son in troubled his mother shree latachiben Bijalbhaj desai run towards her son to safeguard her son but she also fallen on ground in rush.	Regulation 14 and 15 of central electricity authority regulations 2023 has been violated	Power line should be maintained time to time.	Yes	THE BROKEN CONDUCTOR WAS JOINTED IN SPAN	8600/28.1.25
212	Sabarmati /Bopal /Shilaj	Shilaj/ Town	Sureshbhai Dashrathbhai lohar	10.17.24	FHO	Victim was cutting tree inside private premises of Amitbhai Naranbhai patel without prior information to UGVCL. During tree cutting, branch of tree fallen on 11 kv Infrastructure feeder & victim was tried to remove the branch from Line & suddenly he fall down & shifted to hospital & declared as dead.	Yet not received	N/A	N/A	People were educated and keep safe distance from Network	0
213	Sabarmati/ Sabarmati /Kathwada	Odhav/ Rural	Dineshkumar Amritlal Saroj	10.11.24	FHO	As per eye witness statement, Victim was working for roof work. While carrying iron pipe from bottom to top, at that time iron pipe touched to the 11kv AIA feeder HT line passing near the above shed location and the victim got electric shock, shifted hospital for treatment and lost his life afterwards.	Yet not received	N/A	N/A	People were educated and keep safe distance from Network	0
214	Sabarmati /Bopal/ Bavla Ind.	Lodariyal / Rural	Vinod Kumar prabhubhai mahato	10.23.24	FHO	As msg recieved from Police Station Sanand Police On dt.28.10.24 regarding Fatal human accident that on Dt.23.10.24 in night @ 17:30 hrs , Victim was working inside the factory (name-Phoebix retail Pvt Ltd) with his other worker on soda feeling machine and suddenly internal short circuit occurred in solenoid valve of soda feeling machine at the same time he had touched with his hand on soda feeling machine so he got electrocuted and shifted to government Hospital Bavla,where he had declared as Dead .the said matter of fatal human electrical accident happens in party's private premises as no any UGVCL network involved.	Yet not received	N/A	N/A	Proper Wiring to be done at factory premises to avoid any type of leakage current	0

Sr. No.	Circle, Division, Subdivision	Location of Accident and Rural or Urban	Name of Victim/Owner & Designation	Date of Occurrence	Type of Accident FHD/NFHD/FHO/NFHO/FAO	Cause of Accident	Findings of CEI/EI/ AEI	Remedies suggested by CEI / EI/ AEI in various cases	Whether the remedy suggested is complied	Action taken to avoid recurrence of such Accident.	Amount of Compensation and Date of compensation paid (in Rs.)
1	2	3	4	5	6	7	8	9	10	11	12
215	Sabarmati / Sabarmati /Gobljaj	Radhu/ Rural	Hareshbhai Khimabhai Kalotara	10.27.24	FHO	As per site visit, the victim was traveling with dumper vehicle, as labour. While lifting the rear hydraulic part for dumping stone (Kapchi), the lifting hydraulic part, touch with nearby 11 KV Manpura ag line. As victim was touching the dumper, he got electrocuted and fatal accident occurred.	Yet not received	N/A	N/A	People were educated and keep safe distance from Network	100000/2.12.24
216	Sabarmati /Sabarmati /Viramgam R	Thori Mubarak/ Rural	Hanifbhai Hajibhai Fakri	10.30.24	FHO	As per site visit, the victim was moving in Tata Eicher loading vehicle as Helper(Co driver) in the farm of Babubhai Lagrabhai Koli patel to collect(Dangar na Gantha). To lift (Dangar na gantha) vehicle was moving in farm from one place to other, As victim sit on the extended roof of the loading vehicle,While moving in the farm victim touched the 11 KV Thori Thambha ag line.,he got electrocuted and fatal accident occurred. Further report can be done after PM report received.	Yet not received	N/A	N/A	DUE TO LONG SPAN OF APPROX 70 MTR BETWEEN 2 POLE OF THE LINE 1 ADDITION POLE WILL BE INSTALLED.	0
217	Sabarmati /Sabarmati /Gobljaj	Nayka/ Rural	Jakshibhai Ramjibhai Bharvad	11.2.24	FAO	The conductor of Chitarsar ag HT line is slipped from Disc insulator, but not touched ground, only loosened conductor span. As 3 nos of Buffaloes while grazing, passing through the field, came in contact with the live conductor and got electrocuted and fatal accident occurred.	Yet not received	N/A	N/A	Replacement Carried Out	45000/1.1.25
218	Sabarmati /Sabarmati /Kujad	Kuha/ Rural	Prakash Amra Damor	10.21.24	FHO	As per eye witness statement on date 29.10.2024 and as per primary investigation, while taking/adjusting iron stand(khapeda)approx. 10 ft*1 ft long to the terrace of plot no. B/60, swastik ind. Estate, kuha unknowingly touched to the line passing near plot no. B/60.Suddenly victim fall down on terrace and iron stand fall on victim. Eye witness with the help of other labour shifted victim to the Singarava hospital and on duty Doctor declared victim dead.	Yet not received	N/A	N/A	People were educated and keep safe distance from Network	0
219	Sabarmati / Kalol /Kalol-2	Narola/ Rural	Rabari Lalabhai Nanjibhai	11.12.24	FAO	The 11 kv pin of 11 kv narola ag feeder fire at loc no 164 and came in contact of 4.5 ft angle at same location the cow came in contact of same pole and electrocuted due to leakage current and die on the spot. There is crossing of another non ag feeder at same location so to maintain clearance between 2 feeder the 4.5 ft angle installed on that angle 11 kv pin insulator install for safety purpose.	Yet not received	N/A	N/A	REPLCAED PIN.	0
220	Sabarmati /Bavla /Dholka R	Pisawada/ Rural	Mevada Merabhai Arjanbhai	11.13.24	FAO	on dated 13/11/24 approximate 10:00 am in pisawada village sim one buffalo was grazing in a farm, while grazing buffalo came in contact with nearby live HT line of virdi ag feeder, A buffalo got electrocuted and died on the spot. (I.e. due to said line is very old span length is almost 80 to 90 meter, nearby vertical tapping pole stay is damage by farm owner due to this conductor distance from ground is around 5 ft) Remark- No any tripping record found of virdi ag feeder	Yet not received	N/A	N/A	NEW POLE ERECTED TO REDUCE SPAN LENGTH	15000/12.12.24
221	Sabarmati /Bopal/ Shilaj	Sola/ Town	Maheshbhai Prahladbhai Raygor(EA)	11.14.24	NFHD	During Replacing Faulty Meter of Acolade 2 Scheme M p raygor were initially try for taking reading through push button of meter and suddenly during pressing push button meter were blast and he got burnt.	Yet not received	N/A	N/A	Existing Meter Replaced	0
222	Sabarmati /Sabarmati /Kathwada	Singarva/ Rural	Manibhai Koyabai Rohit	8.4.24	FHO	As per eye witness statement, after starting the motor while trying to connect, victim touched a live wire with a joint near the motor terminal and got electric shock and died at site	Yet not received	N/A	N/A	Proper Wiring to be done at consumer premises to avoid any type of leakage current	0
223	Sabarmati / Sabarmati /Kathwada	Nikol/ Rural	Jayeshbhai Ramjibhai Sakariya	12.1.24	FHO	As per eye witness, the victim touched HT line wire with left hand while standing on terrace and got electrocuted and died at site.	Yet not received	N/A	N/A	People were educated and keep safe distance from Network	0

Sr. No.	Circle, Division, Subdivision	Location of Accident and Rural or Urban	Name of Victim/Owner & Designation	Date of Occurance	Type of Accident FHD/NFHD/FHO/NFHO/F AO	Cause of Accident	Findings of CEI/EI/ AEI	Remedies suggested by CEI / EI/ AEI in various cases	Whether the remedy suggested is complied	Action taken to avoid recurrence of such Accident.	Amount of Compensation and Date of compensation paid (in Rs.)
1	2	3	4	5	6	7	8	9	10	11	12
224	Sabarmati/ Gandhinagar/ Dehgam R	Vasna Sogathi/ Rural	P R Patel , Elect Assistant Emp No-12226	12.3.24	NFHD	As per information received, 11KV Vitthalpura AG feeder were getting deem power in village- Vasna Sogathi Bore wells, so as per complaints to Shri P R Patel EA on his phon, he started for searching for reason of deem power and got fault of jumper problem so called from his mobile to kadjodra SS for making LCP for 11KV vitthalpura AG feeder, time 12:14 PM and after taking LCP, he step up on Transformers structure but before jumper repairing work, some how any reason , he felt down from that TC structure to ground, got fracture on right hand and back side so called immediately to nearby farmers and line staff also he called to Kadjodra SS for LCP return for Feeder Power ON. So LCP return at 12:28 PM. Also our Line Inspector Shri Bamnabhai immediately reached at site with our UGVCL vehicle but due to fracture on hand and back side Pain so called to 108 Ambulance and after few minutes later Govt. Ambulance 108 came at site and with line staff took him in APOLLO Hospital Ahemdabad (Near Bhat Circle) for further treatment. DE also reached at Hospital after half an hour and talked to employee, his relatives and hospital staff. As per with Hospital Staff and discussion, operation required for fractures joints and will be done tomorrow. JE Vasani with Line Inspector Shri Bamnabhai site and Kadjodra SS visited today afternoon for investigation.	Yet not received	N/A	N/A	Safety Awarness Camp Arranged	0
225	Sabarmati /Bavla /Dholka R	Ganol/ Rural	Sureshbhai Kantibhai Shrimali	12.3.24	FAO	on dated 03/12/24 approximate 4:30 pm in Ganol village deteriorated 1ph 2w LT ABC broken from pole side at Vankarvas near owner's house which emitting from 100 KVA VTC of Ganol at that time victim buffalo was sitted under LT line in open compound of owner's house and broken deteriorated LT ABC snapped on buffalo's head. Because of that buffelow got electrocuted and died on the spot. (No any tripping record found of Varma JGY feeder)	Yet not received	N/A	N/A	INFORM TO HOUSE OWNER TO DO APPLICATION FOR LT LINE SHIFTING FROM HIS COMPOUND.	15000/1.1.25
226	Sabarmati /Gandhinagar U / Adalaj	Uvarsad/ Rural	Kalya Kamla	12.6.24	FHO	On dtd:06.12.2024 at Approx time 10:00AM,A human fatal Electric accident had been occurred to KALYA KAMLA, at Shankara-lok Ashram,ranjipura road, vill: Uvarsad, In this Ashram, there is a kitchen room and its balcony in the west direction cement mortar has been applied to the flooring of this balcony .On this balcony flooring aluminum road length of approx 8 to 10 feet situated. The 11 KV Avkar feeder line of UGVCL passes near the balcony. The horizontal distance of this line is from the wall is 1.5 meters. The balcony is extended about 7 feet in the west direction. while doing the work of flooring of balcony the plaster rod of aluminum came in contact with 11 KV Avkar feeder line passing near the balcony. Due to this, the victim received a severe electric shock and fell to flooring of balcony Seeing this, another person named Nilesh, who was working with him, shouted for help. Hearing the shouts, other people present at the place rushed to the spot and took the injured Kalya kamla to the Uvarsad Primary Health Center. However, the doctor at the health center declared Kalya Kamla dead. Later, his body was taken to the Adalaj PHC for post-mortem examination	Yet not received	N/A	N/A	Notice Issue To Remove Construction Near The HT Line	0
227	Sabarmati/ Sabarmati /Bareja	Paldi Kankaj / Rural	Kanubhai Valabhai Bharwad	12.11.24	FAO	AT the time many Buffaloes were grazing at Gov Premises, one Buffalo suddenly came in contact with stay wire of electric pole. Stay wire stuck in horn of Buffalo and stay wire may came in contact with the wire of switch installed on electric pole.Due to that Buffalo may got electrocuted and died .	Yet not received	N/A	N/A	Maintanance Done	0
228	Sabarmati / Sabarmati /Kathwada	Kathwada / Rural	Harikesh Omprakash Chauhan	12.16.24	FHO	As per eye witness statement, while victim carrying 15 feet iron ladder & passing under 11 KV line, ladder touched a live wire and got an electric shock and died at site.	Yet not received	N/A	N/A	People were educated and keep safe distance from Network	0
229	Sabarmati /Kalol /Kalol-2	Dangarva/ Rural	(1) P K Ninama-EA (2) Y K Parmar-EA	12.18.24	NFHD	during ideal LT line remove work two line staff working on two near by pole.This LT line crossing with HT JGY Shreenath feeder, during LT line conductor cutting process(cutting of second and third no conductor from top conductor i e. Top conductor not cut, LT line having vertical formation) swing and Top wire touch with live HT wire, and one span ahead four LT line conductors touch each other, so return current flow in all LT wire so both line staff working on LT Pole get electrocuted fallen on ground.	Yet not received	N/A	N/A	Power Off Shrinath And Earthing Of JGY Feeder And Remove LT Line	0
230	Sabarmati /Bavla/ Dholka R	Ambareli/ Rural	Nehaben Kishabhai Chauhan	12.23.24	FHO	For water lifting from water line to tank, victim was gone to start 1 PH(0.5 HP Mono block) water pump. At the time of starting water pump at her own house victim may touched to live wire (in which Insulation was damaged at 02 different places and pvc tape was wounded on it)used to connect water pump from switch board to water pump and may electrocuted. On duty doctors declared she was died while being taken to the hospital at Parshwanath Hospital, Dholka for treatment.	Yet not received	N/A	N/A	INFORM CONSUMER TO INSTALLED ELCB	0
231	Sabarmati / Kalol /Chnatral	Rajpur/ Rural	(1) Shivam M saroj (Fatal) (2) Roshni shivam saroj (Non fatal)	12.30.24	FH-NFHO	The accident occured in open land. The work of sand filling in open plot by owner is carried out to raise gound level and constructed compound wall under 11kv chandarda ag feeder line. Due to illegal construction work of compound wall under line the clearance between line and compound wall is not maintain by party, the victims may be climbed on compound wall for any work and got electric shock. The victim shivam mahendra saroj died on location and roshniben shivam saroj having non fatal accident. She admitted in hospital.	Yet not received	N/A	N/A	NEW POLE ERECTED FOR MAINTAIN DISTANCE	0

Sr. No.	Circle, Division, Subdivision	Location of Accident and Rural or Urban	Name of Victim/Owner & Designation	Date of Occurance	Type of Accident FHD/NFHD/FHO/NFHO/FAO	Cause of Accident	Findings of CEI/EI/ AEI	Remedies suggested by CEI / EI/ AEI in various cases	Whether the remedy suggested is complied	Action taken to avoid recurrence of such Accident.	Amount of Compensation and Date of compensation paid (in Rs.)
1	2	3	4	5	6	7	8	9	10	11	12
232	Sabarmati/ Bavlva /Dhandhuka	Fedra/ Rural	(1) Hasnen Mustafabhai Khalifa - FH (2) Sultanbibbi Joravarkhan Pathan-FH (3) Mustakim Aiyubhai Shekh-NFH	1.7.25	FH-NFHO	Accident occurred on dtd.7.1.25 at 16.00 hrs, inform from police station Dhandhuka on dtd.8.1.25 at 10:30 hrs, site visited on 8.1.25 at 11.00 hrs, no eye witness person present, as per land owner statement victim came in contact of 11 kv Gellops JGY feeder HT line while driving truck under through electric line with luggage and bed tide on upperside of kathedo (fabric cage of iron), which is above 12 feet from ground and land owner nake land filling approx 4to 5 feet . so from actual ground to HT line distance 18 feet, from ground to tempo fabrication work is 10 foot and above kathedo 2 foot bed legs and above on luggage which is tide by black plastic tadpatri, so total distance from actual ground (no filled by sand) area to HT line 17 feet.	Yet not received	N/A	N/A	FIR LODGE ON DRIVER DUE TO IRRESPONSIBLE DRIVING AND ALSO FQ ISSUED TO OWNER FOR LINE SHIFTING WHERE ACCIDENT OCCURED.	0
233	Sabarmati /Gandhinagar R/ Gandhinagar	Jalund/ Rural	Rajesh Rama Ramat	1.20.25	FHO	Victim climbed on back side of RMC vehicle (Miller) Eicher no GJ02 at 4787 for dumping RMC cement concrete waste on Jalund-Moti Adaraj Road, Opp. Gayatri Madhyamik School. Under 11 kv Krudhnnagar JGY feeder while dumping RMC waste on open space beside road side at that time victim head came in contact with live line & got electrocuted.	Yet not received	N/A	N/A	POLE HEIGHT TO BE TAKEN AT PARTICULAR MEASURE	0
234	Sabarmati /Sabarmati /NARODA Ind.	Nana Chiloda/ Rural	Ashokbhai R Kalasva	2.25.25	NFHD	As per eye witness statement, while working for jumpering work on pole at above location - victim got electrocuted and fallen from pole, he was taken to hospital.	Yet not received	N/A	N/A	Safety Awareness Camp Arranged	0
235	Sabarmati /Sabarmati /Mandal	Khudad/ Rural	Hitesh S Chauhan	3.6.25	FHD	As per eye witness statement, while working for conductor jointing of snapped conductor on pole, victim got electrocuted and fallen from pole, he was taken to Mahatma Gandhi hospital at Viramgam, where doctor declared him brought dead .	Yet not received	N/A	N/A	New Top Fitting Provided With Stay Pair And Clearance Of Top Wire To Side Wire Maintained	0
236	Sabarmati /Bavlva /Bavlva-1	Chiyada/ Rural	Solanki Nagarbhai Hanubhai	3.15.25	FAO	On Dt:15.3.25, at approx 3.00 pm , Buffalo age 7 years was swipping and floating in pond in farm of Nagarbhai Hanubhai solanki at Village chiyada.during floating buffalo was falled on already broken pole and wire(pole and wires were broken in monsoon , due to water logging pole is not erectable), there was one wire was connected on existing sakodara ag FDR pole which touched to live wire and buffalo came in contact with wire.due to this buffalo got electrocuted and died.PM report is awaited.	Yet not received	N/A	N/A	Broken Pole Conductor Removed From Live Pole	0
237	Sabarmati /Bavlva /Koth	Kalyangadh/ Rural	Bharvad Ganeshbhai Kamshibhai	3.22.25	FAO	Due to long span of existing 11 kv gangad ag feeder and one tapping pole of them was bending toward earth due to existing stay damaged by farmer so that the wire of span become more loose at the time A baffelo is going for grazing in field and passing near by 11 kv live wire and contact with 11 kv Gangad ag live wire and got electrocuted and die.	Yet not received	N/A	N/A	STRATGHIT OF POLE AND SAFE DISTANCE FROM EARTH HT WIRE	0
238	Sabarmati /Bopal/ Bavlva Ind.	Rajoda/ Rural	1.Suramal Katara 2.Kanubhai Thakor	3.28.25	FH-NFHO	While installation of fencing above the RCC compound wall of M/S HRS Aluglaze P L (HT No. 66701) at village Rajoda Victim named as Suramal Katara was working to install angle in center of the fencing above compound wall and after climbing on the compound wall while lifting the angle he became unbalanced on the wall and the angle came in contact with the HT Conductor of 11kv Dishman HT Exp Line suddenly he got electrocuted and died on the spot and the other person standing on the ground named as Kanu bhai thakor tried to save the victim also got electrocuted but Mr Kanubhai is admitted to Radhey hospital, Bavlva for further treatment and at present he is stable.	Yet not received	N/A	N/A	Issued Notice To Consumer For Raising Height Of Electrical Pole Outside Premises.	0
239	MSH/Visnagar/Satlana	Sudasana/Rural	Khanbala Kalabhai Bhavaji	30.09.24	FA	Fatal animal outsider electrical accident occurred on 30.09.2024 time approx 09.00 am.On wet land surface victim was passing under the 4 wire LT line of Khari AG feeder,one of the LT wire of same line broken by yesterday's cyclonic rainy effect and finally fallen on Buffalo ang got electrocuted and died.	Yet not received	N/A	N/A	Conductor Re Joint & Restraining Done	15000
240	MSH/Patan/ Harij	Harij/Urban	Bhoi Vijaykumar Nathubhai	02.10.24	NFH(Elect.)	On dt. 02.10.24, a complaint of Galaxy Hotel regarding no power was received at complaint centre . Shri B C Bhagora ALM and V N Bhoi EA has reached at Galaxy Hotel TC at around 12.30 PM. After get down of DO fuse from TC by EA Shri V N Bhoi ,he was climbed on TC structure for checking the Lug and started to remove creeper from TC structure(standing on Transformer Base Angle) by naked hand & during creeper removal ,creeper may touched to live 11 KV HT conductor and got electrocuted and fell down from TC structure and he got burnt on Hand backside and on stomach and also got injury on chest .After then first he was transferred to Pvt. Hospital at Harij and then shifted to Patan pvt. Hospital for further medaical treatment.	Yet not received	N/A	N/A	Safety equipment must be used, Earthing to be done before commence of work. Safe distance must be maintain from live parts	
241	MSH/Vijapur /Vijapur	Khanusa/Rural	1.Aryrjasinh Upendrasinh Sisodiya. 2.Aditya Jitendra Bhatiya 3.Sujankumar Kaushikbhai Chaudhari 4.Sujalgiri Bhikhagiri Bava 5.Kuldipsinh Shivrambhai Senma	09.10.24	FH & NFH-4	Accident occurred on dtd:- 09.10.2024 about 12:15 pm approx Due to Victim was climbing on iron ladder and other 4 victims kept holded ladder with their handat that time ladder come to contact with live conductor of 11 kv line .	Yet not received	N/A	N/A	Letter was issued to Consumer for line shifting and was infoemred and educated about not to do any activity under the HT Line	

Sr. No.	Circle, Division, Subdivision	Location of Accident and Rural or Urban	Name of Victim/Owner & Designation	Date of Occurance	Type of Accident FHD/NFHD/FHO/NFHO/FAO	Cause of Accident	Findings of CEI/EI/ AEI	Remedies suggested by CEI / EI/ AEI in various cases	Whether the remedy suggested is complied	Action taken to avoid recurrence of such Accident.	Amount of Compensation and Date of compensation paid (in Rs.)
1	2	3	4	5	6	7	8	9	10	11	12
242	MSH/Patan/Harij	Jamanpur/Rural	Raval Mangalbhai Ramabhai	16.10.24	NFH(Elect.)	As per information provided by Complainer's shri Vaghela Gopalji Rahuji of Jamanpur Village, on dt. 16.10.24 at around 10.45 AM EA of Jamanpur village Shri M R Raval reached at Ag connection transformer center having consumer No.28540102779 for attending the dim power complaint. Even though he brought operating rod with him he climbed on transformer center without remove of all DO fuse & got contact with 11 KV conductor and electrocuted. After that he was transferred to Referel hospital Harij by 108 ambulance from village & then shifted at Dharpur General hospital Patan for further medical treatment & then he was transferred to pvt.hospital patan by his relative.	Yet not received	N/A	N/A	Safety equipment must be used, Earthing to be done before commence of work on Discom infrastructure.	
243	MSH/Kadi/Detroj	Panar/Rural	Thakor Ganpatbhai Ishvarji	04.10.24	FH	As per the statement of eyewitness, the victim might have gone for some kind of work in the paddy farm. This paddy farm was found surrounded by fencing wire for safety of this paddy crops, and only LT phase supply from the fuse board of agricultural electric connection in name of Mahendrasinh Mulsang Zala bearing consumer no 25849101381 was found illegally connected to this fencing of paddy farm. It can be assumed that the victim might have come into direct contact of this live fencing wire and got electrocuted and died on the spot. No official electricity connection of ugvl is found in this farm land where victim was found electrocuted. So, there is no fault of UGVCL in this case.	Yet not received	N/A	N/A	attribute to victim and awareness to the villagers given	
244	MSH/Kadi/Detroj	Rampura/Rural	Od Manishaben Jitendrabhai	15.10.24	FH	As per the site inspection, internal wiring of house which is supported with GI wire connected with metal sheet of house and insulation of wire is found damage and leakage current passed. Meanwhile during morning at approximately 5.30 am the victim drying the cloth and came in contact with GI wire she got electrocuted.	Yet not received	N/A	N/A	attribute to victim, INTERNAL WIRING FAULT, awareness to the villagers given and educated to install ELCB in private premises.	
245	MSH/Visnagar/Visnagar city	Neuton Park Society Kamana Road /Urban	Raval Ajaykumar Pravinbhai	17.10.24	NFH(Mech.)	The Said Accident occurred on dtd.17.10.2024 at about 11.45 AM. Shree A P Raval EA Climb on LT Pole inside Neuton park society for service replacement. After replacement of service line, Shree A P Raval was climbing downward from pole. At that time from the second step of pole from upper side due to some reason Shree A P Raval lost his balance and fallen down on ground. After that Shree A P Raval taken to hospital and After primary treatment doctor refer to MRI and in MRI report fracture of right hand and injury in spine and Admitted to Hospital for treatment. This accident is purely mechanical.	Yet not received	N/A	N/A	Line staff should inspect the pole before commencement of work and maintain safety aspect during work	
246	MSH/Mehsana/Mehsana City	Mehsana /Urban	Vinodkumar Sitaram Verma	17.10.25	FH	During the time of accident, Home renovation work was under progress of 58-B, Labh Nagar Society, Jay-Vijay Neliya, Mehsana. The Victim was doing tiles fitting work at gallery of same house. During this work, victim might accidentally touched level patti to HT line of 11 KV Agro feeder which is passing near by the house. The burning spots can be seen on aluminium level patti which is still available on site. The details investing is under progress.	Yet not received	N/A	N/A	11KV line converted to underground.	100000
247	MSH/Visnagar/Visnagar-2	Visnagar /Rural	Shri Suver Lokashkumar Hirjibhai	15.11.24	FH	Fatal human outsider electrical accident occurred to Shri Huver Lokashkumar Hirjibhai on Dated 15.11.24 time approx 07:00 AM Victim was engaged in well construction, accidentally lifted an L-shaped iron rod (6mtr x 6.2mtr) into contact with the 11 KV Sevaliya Ag feeder high-tension power line. got electric shock and died. The HT line, approximately 20mtr from the well, had a ground clearance of 11kv sevaliya Ag feeder HT Line approx -5.8mtr. Evidence of the incident includes burning spots on the tail end of the L shape iron rod, which remains on site. The detail investing is under progress. he is admitted to civil hospital visnagar where victim was declared dead by doctor. Police panchanama and PM report awaited.	Yet not received	N/A	N/A	People were educated and keep safe distance from Network	
248	MSH/Vijapur/Gozariya	Vasai /Rural	Alpeshkumar Parsottambhai Parmar (EA)	13.11.24	NFH(Mech.)	The maintenance work 11 KV Harnahola AG feeder of 66 KV Vasai SS had given to Vasai Gang with ALM and other Line staff on date 13.11.24. After tree cutting work completed at loc no 48/2/A by Shri Alpeshkumar P Parmar EA(VS), He fell down from tree while he was descending from the tree and got injured.	Yet not received	N/A	N/A	Line staff was informed and educated about using proper tools while doing tree cutting and not to hurry when working	
249	MSH/Kadi/Kadi-2	Nagarsan/Rural	Owner Of Rabari Kanajibhai Dajibhai	20.11.24	FA	as per site visit a camel was passing from farm for a graze and at that time somehow touched to hv line which was passing above farm and got shock and electrocuted, detail investigation under process	Yet not received	N/A	N/A	new pole erected in long span at accident location and vertical clearance from ground to line is increased	12500
250	MSH/Kadi/Kadi-1	Kadi/Rural	Patel Chintankumar Harikrushnabhai	07.12.24	NFH(Elect.)	Victim had parked Ashok Layland hydraulic truck below 11KV Amul ind feeder line near garage for radiator and hydraulic service. Victim turn on the truck engine and came off from the truck, at that time he noticed that hydraulic of truck is going upward, and the 11kv line was above the truck, so he went to turn off the engine of truck. As he was going to climb on truck cabin by grabbing the handle and his both foot on the ground, that same time hydraulic of the truck touched the 11KV line. Due to that Victim got electric shock and fell down on earth. Victim burnt on right hand palm and sole of the both foot. Immediately he was sent to Hospital for further treatment. During site visit by DE and JE the height of 11 KV line is 22 Feet from ground level and the truck below 11 KV line at time of visit.	Yet not received	N/A	N/A	vertical clearance from line to ground is as per norms, accident occurred due to victim side fault	

Sr. No.	Circle, Division, Subdivision	Location of Accident and Rural or Urban	Name of Victim/Owner & Designation	Date of Occurance	Type of Accident FHD/NFHD/FHO/NFHO/FAO	Cause of Accident	Findings of CEI/EI/ AEI	Remedies suggested by CEI / EI/ AEI in various cases	Whether the remedy suggested is complied	Action taken to avoid recurrence of such Accident.	Amount of Compensation and Date of compensation paid (in Rs.)
1	2	3	4	5	6	7	8	9	10	11	12
251	MSH/Vijapur/Lodra	Ajol/Rural	Chauhan Sohilsinh Anopsinh	30.12.24	FH	Victim was climbed on cattle shed and came in contact with 11 kV ,line of Ajol JGY feeder and got electrocuted which is passing over cattle shed	Yet not received	N/A	N/A	Letter was issued to Consumer for line shifting and was informed and educated about not to do any activity and construction near the HT Line	100000
252	MSH/Kadi/Kadi City	Kadi Kasba/Urban	NFH to Malek Suferabanu ramzanbhai (Non fatal) age about-34 Years & FH to Malek Mahmad Farhan Ishmailbhai (fatal) age about-31 Years	14.01.25	FH & NFH (Elect.)	At Nr House of Ishmailbhai Malek, Malekvas ,LT LINE WITH ABC OF Transformer Centre Near OLD MUSARAF COURT, Village – KADI-KASBA, Ta-KADI, Dist- Mehsana, 200 KVA Transformer is there for supplying power to Malekvas, as per the statement of Eyewitness, A kite is hanging with 6 mt long thin iron flexible wire (senting wire) on LT network passing by street and Victim-2 Smt Suferabanu ramzanbhai Malek passed by the street and was trying to remove kite and touched to iron wire and felt shock and that time instantly victim-1 Shri Malek Mahmad Farhan Ishmailbhai came to save her and somehow came in contact with senting wire & got electrocuted and immediately victim-1 & 2 was taken to the hospital for further treatment and doctor declare him(victim-1) dead at the hospital & Victim-1 admitted to hospital for medical treatment.	Yet not received	N/A	N/A	survey for replacement of lt abc is done and will be replaced short time.	
253	MSH/Patan/Harij	Vansa/Rural	Prajapati Somabhai Shankarbhai	22.01.25	FH	As per press note published in Divya Bhaskar on dtd.24.01.25 regarding accident to Prajapati Somabhai Shankarbhai at Vansa village, site was visited on same day by undersigned. There is a Ag connection exist in LS no-67 in name of victim at Vansa village. As per eye witness statement, on dtd.22.01.25 victim seen in electric Ag. meter room in such a way that head side body laid at outside electric room & both leg laid in Ag. meter installed room. There is no any leakage current found on electric equipment like starter ,UGVCL Neutral Black wire (in motor on position) ,TC stay wire ,TC earthing wire etc. After seen in this position ,victim was transferred to Patan Janta Hospital by private vehicle & 108. After inspected by doctor , victim was declared dead by Hospital. Reason of accident is under investigation .PM report awaited.	Yet not received	N/A	N/A	Proper Wiring to be done at consumer premises to avoid any type of leakage current	
254	MSH/VJP/Mansa	Mansa/Urban	Thakor Vishnuji Popatji	01.02.25	FH	Due to internal fault of submersible motor leakage current found on body of submersible motor and Victim had come in touch with body of submersible motor and got electrocuted.	Yet not received	N/A	N/A	Consumer was informed and educated about Use of proper three pinplug with earthing terminal, also install ELCB/MCB/RCB for safety	
255	MSH/Patan/Ranuj	Rajpur/Rural	Sumitra Riteshbhai Mori	03.03.25	FH	A Fatal Human electrical accident (Outsider) occurred to smt. Sumitra Riteshbhai Mori, Age: 20 years at Ambeshwar Godown Vill. Rajpur on dated 03.03.2025 at 6:00 PM. Above information received from Sandesh press note on dated 06.03.2025. On same day undersigned has visited the site and it was to know from unknown present person that, victim worked as a labourer and lived at Ambeshwar godown vill. Rajpur. On dated 3.3.2025 @ 6:00 pm, victim was trying to dry the clothes on approx. 7 feet high fencing wall of ambeshwar godown , during that one clothe fell down at other side of wall. The victim tried to catch the cloth with the help of approx. 8 feet long iron rod and climbed on the wall at that time it seems that the iron rod came to the induction zone of 11 kv line of Gadosan AG feeder, which is passing over the wall at a height of approx. 17 feet from ground level and victim got electrocuted. After that victim was immediately admitted in Janata hospital Patan. In the hospital doctor declared, the victim was dead. There is no tripping was recorded in 11 kv Gadosan AG feeder from 66 kv Rajpur substation on that day. Deatill investigation is under process and PM report awaited.	Yet not received	N/A	N/A	To keep Safe distace from live wire and not to use conducting material near by line	
256	MSH/Visnagar/Satlasana	Satlasana/Urban	Shri Chauhan Yuvrajsinh Dinsinh	08.03.25	FH	As per the eye witness statement, victim was trying to removing big plastic banner tied to iron pipes of @ 5 MTR length. While doing so, he accidentally lost the balance of pipe and it came in contact to a 11 KV line passing near by to it. A FDR tripping is recorded at @ 15.10 Hrs..He was shifted to Satlasana PHC by gathered public where Doctor declared him dead ..	Yet not received	N/A	N/A	People were educated and keep safe distance from Network	
257	MSH/Patan/Chanasma	Sendha/Rural	Thakor Sovanji Dargaji	19.03.25	FA	Information received from concern village electrical assistant on dated 19.03.2025 on the same day undersigned has visited the site and found that 2 no. of buffalo are tied under HT line of 11 kv om ag feeder between location number 92-93 (TC) and 94. At this location due to broken of shackle live 11 kv wire has fallen on mouth of 2 no. of buffloes, which are tied under this line and these buffloes contact to live wire and got electrocuted.	Yet not received	N/A	N/A	Do Not construct animal habitat under distribution network to avoid such type of accident.	
258	MSH/Mehsana/Mehsana Highway	Opp Natraj Havelli, Hinglaj Chock, Mehsana/Urban	Ashish Govindbhai Prajapati	22.03.25	FH	On Dtd. 22/3/25 at morning 11:18 , Victim was trying to Tie the Internet cable with UGVCL Yash Banglows TC , 5 Wire LT Line. When He was Trying to Climbing the pole Unauthorised , touched With Live LT Line & Fallen on Ground RCC Road & Died when Shifting to hospital.	Yet not received	N/A	N/A	Public is advised to do not climb to UGVCL HT/LT/TC unathorisely.	
259	Himatnagar / Modasa/ Meghraj-1	Gayvacharda /RURAL	Asari somabhai rajabhai	30.09.24	FAO	Asari somabhai rajabhai, a resident of Gayvacharda Village, his wife in his farm grazing buffalo. There, a wire of jgy deteriorated LT abc line of u.g.v.c.l. passing through the farm the adjacent to his farm was broken and fell down. So Asari somabhai rajabhai's buffalo got electrocuted and died when it came in contact with the broken wire.	RECEIVED	RECEIVED	LT MAINTANANCE DONE	LT MAINTANANCE DONE	30000

Sr. No.	Circle, Division, Subdivision	Location of Accident and Rural or Urban	Name of Victim/Owner & Designation	Date of Occurance	Type of Accident FHD/NFHD/FHO/NFHO/FAO	Cause of Accident	Findings of CEI/EI/ AEI	Remedies suggested by CEI / EI/ AEI in various cases	Whether the remedy suggested is complied	Action taken to avoid recurrence of such Accident.	Amount of Compensation and Date of compensation paid (In Rs.)
1	2	3	4	5	6	7	8	9	10	11	12
260	Himatnagar / Modasa / TINTOI	JALIYA / RURAL	Tarar Nathabhai Valjibhai	10.12.24	FAO	On Dtd. 12.10.24, Electrical Accident occurred to Buffalow age Apprx.6-7 year while in the afternoon time apprx. 2.00 to 2.30 P.M. Owner shri Tarar Nathabhai Valjibhai, Vill Jaliya, A Buffalow while grazing the grass near transformer centre touched to staywire got shocked and died. One extra wire connected with stay wire below stay insulator and other end of which is connected with earthing wire of transformer. Hence, Leakage current from earth wire to stay wire passes and buffalow got electric shock and died.	RECEIVED	REQUIRED MAINTANANCE	LT MAINTANANCE DONE	LT MAINTANANCE DONE	15000/25.12.2024
261	Himatnagar / Modasa / MALPUR	LALODIYA / RURAL	Marivad Keshabhai Ramabhai	10.13.24	FAO	On date 13-10-24 at approximately 18:00 hours near the house of Mariwad Kesha Bhai Ramabhai at Lalodia village the pole of It 2 wire line of 11 KV nava JGY feeder was broken due to the fallen of a tree on 2 wires. The cow died on the spot due to electrocution when it fell on the cow contact with Live conductor wire and got electric shock.	RECEIVED	REQUIRED MAINTANANCE	LT MAINTANANCE DONE	BROKEN CONDUCTOR REPAIR AND MAINTANANCE DONE	30000/23.1.2025
262	Himatnagar / HIMATNAGAR / PRANTU	PRANTU / URBAN	Makwana chhayaben rajendrasinh	11.17.24	FHO	The victim was trying to remove kite from nearby 11KV highway feeder line. victim was utilised any conductive object for removing kite. Meanwhile victim got electrocuted due to conductive object touched the 11 kv feeder.After that nearby people removed her from conductive object and reached to nearby CHC, Prantji. On duty officer decaled victim was dead. Site has been visited. 11 kv feeder to house horizontal distance was safe. 11 highway feeder tripping observed :: 16:39 to 16:42	Yet not received	NA	NA	MAINTANANCE DONE	100000/26.11.2024
263	Himatnagar / Modasa / MEGHRAJ-1	ROLA / RURAL	Shekh Yusufbhai Aiyubhbhai	12.18.24	FAO	A fatal animal electric accident occurred in Network on dated 18/12/2024 on the basis of the information received by phone, shekh yusufbhai aiyubhbhai resident of Rolla village whose, 3 buffaloes including 1 buffalo and 2 calves were grazing in sipai yasinbhai aiyubhbhai's farm. 11 KV Rola ag feeder HT line passing over that farm. A line is passed through which the one wire was broken from the dis insulator of nearer transformer and falls on the ground, the buffaloes were electrocuted coming into contact with broken conductor wire.	Yet not received	NA	NA	BROKEN CONDUCTOR REPAIR AND MAINTANANCE DONE	15000/15.1.2025
264	Himatnagar / Modasa / MODASA-R	MADASANA KAMPA / RURAL	Patel Hareshkumar Virsangbhai (electrical assistant)	1.29.25	NFHD	Victim Patel Hareshkumar Virsangbhai had received complain directly from consumer of broken AG LT line near Tranformer centre. So he went there at the location of broken conductor where he had removed D.O of transformer to stop electric supply. He then there started rectification of conductor, where he met with electrical accident. He was immediately shifted to hospital by local villager to private hospital at modasa. As reviewed by that doctor he was found stable. As per site visit it was found there LT line was broken due to tree branch fallen on line, D.O of transformer centre was removed, there was line crossing of 11 kv Kabola JGY which was safe on primary observation. At the time of either restringing of conductor or due to tree branch fallen while rectification conductor may have touched live line of Kabola JGY feeder electrical accident have occurred. Detail investigation can be reviewed after final statement of the victim.	Yet not received	NA	NA	BROKEN CONDUCTOR REPAIR AND MAINTANANCE DONE	PENDING
265	Himatnagar / HIMATNAGAR / HMT R	KANKROL / RURAL	DESAI MUKESHBHAI BALDEVBHAI	1.17.25	FAO	A fatal animal accident occurred to a Cow due to Cow was Running and her Horn got Stuck with Stayset Provided on AB Switch of 11 KV Mahakali Urban Feeder .Staywire Broken and upper part of Staywire Comes in Contact with Jumper of AB switch and Girder Pole Due to Live Contact with Girder Pole leakage current passes through girder pole and cow accidentally comes in contact with girder pole .got electrocuted and died.	Yet not received	NA	NA	NEW STAY WIRE PROVIDED AND MAINTANANCE DONE	15000/25.2.2025
266	Himatnagar / HIMATNAGAR / HMT R	KANKROL / RURAL	DESAI JIGARBHAI BABUBHAI	1.17.25	FAO	A fatal animal accident occurred to a Cow due to Cow was Running and her Horn got Stuck with Stayset Provided on AB Switch of 11 KV Mahakali Urban Feeder .Staywire Broken and upper part of Staywire Comes in Contact with Jumper of AB switch and Girder Pole Due to Live Contact with Girder Pole leakage current passes through girder pole and cow accidentally comes in contact with girder pole .got electrocuted and died.	Yet not received	NA	NA	NEW STAY WIRE PROVIDED AND MAINTANANCE DONE	15000/25.2.2025
267	Himatnagar / Modasa / MODASA-R2	MEDHASAN / RURAL	Goswami Kirtigiri Babugiri	2.20.25	FHO	During site inspection as per the statement of Eyewitness, the victim was gone to start the motor of well in his farm, meanwhile he came in contact with the open wire of starter and due to electric shock, he fell down on the spot.So he might have experienced electric shock due to came in contact with open wire of starter. There is no fault on UGVC side. Detail cause of death will come to know after Doctor's PM report.	Yet not received	NA	NA	The Faulty Motor of ww was replaced and aware people about to use healthy equipment .	PENDING
268	Himatnagar / IDAR / DESHOTAR	GOLVADA / RURAL	Thakor Jyantiji kadvaji	2.6.25	FAO	Cause of Accident: date 06/02/2025 @4.00pm suddenly Dry tree fallen on 11 kv line chodap ag and HT line wire broken At that time buffalo passing and come with contact of wire so Buffalow get electrocuted and died.	Yet not received	NA	NA	BROKEN CONDUCTOR REPAIR AND MAINTANANCE DONE	PENDING
269	Himatnagar / IDAR / KHEROJ	PALIYABIYA / RURAL	Gamar Bhamarabhai Babubhai	2.2.25	NFHO	A Non Fatal Human electrical accident outsider of Gamar Bhamarabhai Babubhaiwas occurred on dated. 02.02.2025 time approx 03.30 PM.As per Police Repor tVictim was climbed on BORADI tree and suddenly touch with the line victim electrocuted and fallen below tree.victim sent to Poshina CHC and after primary treatment Dr.referred him to Ahmedabad Asarva civil hospital dt07.02.2025 site visited and Panchnama prepared Further statement and investigation is under process as per facts which may different from police complain.Final investigation is under progress.	Yet not received	NA	NA	MAINTANANCE DONE	PENDING

Sr. No.	Circle, Division, Subdivision	Location of Accident and Rural or Urban	Name of Victim/Owner & Designation	Date of Occurance	Type of Accident FHD/NFHD/FHO/NFHO/FAO	Cause of Accident	Findings of CEI/EI/ AEI	Remedies suggested by CEI / EI/ AEI in various cases	Whether the remedy suggested is complied	Action taken to avoid recurrence of such Accident.	Amount of Compensation and Date of compensation paid (in Rs.)
1	2	3	4	5	6	7	8	9	10	11	12
270	Himatnagar / HIMATNAGAR / SALAL	PILUDRA / RURAL	PARAMAR KAUSHIKSINH LAXMANSINH	2.24.25	NFHD	Victim went for attending of Ag complaint of transformer.He wore helmet and removed all the d.o fuses, then after he climbed over the d.p structure, as per eye witness statement victim took seat over tc structure to attend fault suddenly huge spark and he fallen down from the TC structure. The eye witness & other one immediately took him to Prantij CHC & after that he was taken to Hope Hospital .It was a Single consumer transformer. There is no any 11 kv tripping found on 11 kv piludara at feeder in 66 kv prantij ss .	Yet not received	NA	NA	Safety Awareness Camp Arranged	PENDING
271	Himatnagar / TALOD / SATHAMBA	MEGHAPUR A KAMPA / RURAL	BHARVAD VINUBHAI REVABHAI	3.9.25	FAO	A MESSAGE RECEIVED FROM LOCAL VILAGERS AT APPROX 17:30 PM REGARDING ACCIDENT AT COMPALIN CENTRE UGVC. SATHAMBA. THE CONCERN OFFICER (J.E)HAD VISITED SITE AT MEGHAPURA KAMPA. THERE IS MEGHAPURA AG FEEDER THREE WIRE LOW TENTION LINE PASSING FROM PATEL RATILALABHAI GOVINDBHAI AG CONNECTION. ONE WIRE BROKEN & LAYING AT GROUND AT SAME TIME SOME HOW SHE COW CAME IN CONTACT WITH LIVE WIRE AND GOT ELECTROCUTED & DEAD ON SPOT.	Yet not received	NA	NA	MAINTANANCE DONE	PENDING
272	Himatnagar / TALOD / SATHAMBA	ZANKHARIYA / RURAL	SOLANKI KAILASHBEN JAGDISHBHAI	3.19.25	FHO	ON DATED 19.03.2025 AROUND 20:00 HRS, FATAL HUMAN ACCIDENT WAS OCCURRED. MESSAGE RECEIVED FROM VILLAGE LOCAL PERSON. VICTIM CLIMBED UP 11 KV ZANKHARIYA AG FEEDER HAVING POLE NO 115/16/2. SOMEHOW VICTIM FELL DOWN OR MAY BE CAME IN CONTACT WITH LIVE WIRE AND GOT ELECTROCUTED AND DIED ON SPOT.	Yet not received	NA	NA	MAINTANANCE DONE	PENDING
273	Himatnagar / TALOD / BAYAD	UDEPUR / RURAL	PATEL PRAKASHBHAI MAGANBHAI	3.20.25	FAO	On Date 20March2025 At 5 Pm Approx Mr Patel Prakashbhai Maganbhai's Bull Was Tied To Graze Green Grass In Patel Mihirbhai Shamalbhai's Farm Under 3 Phase 3 Wire Lt Line Of 11 Kv Gadh Ag Feeder Which Eminating Power From 66 Kv Akhund Ss At This Time Due To Heavy Wind Pressure Lt Wire Snapped And Fall Down On A Bull And Bull Came On Contact With Live Wire Got Electrocuted And Died On The Spot	Yet not received	NA	NA	BROKEN CONDUCTOR REPAIR AND MAINTANANCE DONE	PENDING
274	Himatnagar / Modasa / MODASA-R	ITADI / RURAL	Rabari Hiraram Bhuraram	3.21.25	FHO	During site inspection as per the statement of Eyewitness, the victim was working on a grass cutter machine in the farm, meanwhile he came in contact with the motor of the grass cutter machine whose motor body is short. Due to shock he fell down on the spot. Victim might have experienced electric shock due to came in contact with short motor body. There is no fault on UGVC side.	Yet not received	NA	NA	MAINTANANCE DONE	PENDING
275	Himatnagar / Modasa / MODASA-R	RAKHIYAL / RURAL	Makwana Babsinh Pruthvisinh	3.26.25	FAO	Fatal Animal Accident occured to bullock of Makwana Babsinh Pruthvisinh at village :Rakhiyal Ta:Modasa Dist. Arvali around 06:30 pm on date :26.03.2025. As per owner's statement, around 6:30pm , Bullocks were passing near 100KVA TC where water logging there due to of breakage of water pipeline. Momentary leakage current may be reflect on transformer center due to of any residential appliances were short and accident occured to bullock due to of wet land.At the time of investigation, on transformer center no leakage current found at transformer center till this time.Further Detail investigation under progress	Yet not received	NA	NA	MAINTANANCE DONE	PENDING
276	PLN,SIDHPUR,SIDHPUR/R	BRAHMANVADA /RURAL	THAKOR HARDIKKUMAR KIRTUJI	27.10.2024	FHO	in Brahmanvada village behind Dudh utpadak Sahkari dairy shri Patel Chaturbhai Bhudardas house behind iron shed. Date:27.10.2024 at the time approximate 10.30 am shri Thakor Hardikkumar Kirtiji.age appro.10 years kite fly on his rent house. And this time kite is fitted on 11 kv Chamunda jgy line so at time shir hardikkumar was stretching kite by 11 feet long aluminum rod and touch the conductor electrocuted and got shocked and fatal electrical accident occurred.	Yet not received	NA	NA	People were educated to keep safe distance from Network	100000/07.01.2025
277	PLN,SIDHPUR,KAKOSHI	KAKOSHI /RURAL	PARMAR JAYESHKUMAR JAYANTIBHAI	25.10.24	FHO	Victim was climbed on first floor for new home construction centing work , Then after he was taken 5 Amp switch plug board for centing work, he dont know that plug board was damaged , so he was touched directly plug board and got electric shocked.	Yet not received	NA	NA	Accident occurred in private premises due to faulty inhouse wiring and premises owner are educated to rectify inhouse wiring and provide proper ELCB.	

Sr. No.	Circle, Division, Subdivision	Location of Accident and Rural or Urban	Name of Victim/Owner & Designation	Date of Occurance	Type of Accident FHD/NFHD/FHO/NFHO/FAO	Cause of Accident	Findings of CEI/EI/ AEI	Remedies suggested by CEI / EI/ AEI in various cases	Whether the remedy suggested is complied	Action taken to avoid recurrence of such Accident.	Amount of Compensation and Date of compensation paid (in Rs.)
1	2	3	4	5	6	7	8	9	10	11	12
278	PLN,RADHANPUR,DEODAR 2	DAUVA /RURAL	SIDHRAJBHAI BHARATBHAI THAKOR	10.09.2024	FHO	AS PER PRESS NOTE IN DIVYA BHASKAR NEWS PAPER PALANPUR AVRUTI ON DTD 12.09.2024 ABOUT FATAL HUMAN ACCIDENT. AS PER PANCH STATEMENT SIDHRAJBHAI WAS NORMALLY USE THE BATTERY OPERATED ZATKA MACHINE TO SAVE STANDING CROP FROM ANIMALS ON THE DATE 10.09.2024 NIGHT TIME AROUND 12:30 SOME FAMILY MEMBERS WAS CALLING HIM ON HIS MOBILE NO AND HE WAS NOT PICKED UP THE CALL SO AFTER THAT SOME ONE FROM HIS FAMILY WAS CALLED TO THAKOR MADHUBEN BHUPATBHAI SHE IS ALSO LIVING THERE IN DIFF FARM HOUSE SO SHE WAS SEARCHING SIDHRAJBHAI IN FARM AND SHE FOUND WAS LAID DOWN AND DEAD NEAR THE FARM FENCING WHICH IS WIRED OF ZATKA MACHINE AND THEN AFTER THEIR FAMILY MEMBERS TOOK AWAY HIS BODY AT THEIR VILLAGE BHESANA SO HE MIGHT GOT THE ELECTRIC SHOCK OF BATTERY OPERATED ZATKA MACHINE AND ELECTROCUTED AND LAID DOWN AT SPOT .	Yet not received	NA	NA	THERE IS NO ANY NEGLIGENCE FOUND IN NETWORK . ITS VICTIME FAULT.	
279	PLN,PLN/2,DANTA	Vasi /RURAL	Manknojiya Allubhai Narsibhai & Manknojiya Mahmadbhai Allubhai	30.10.2024	FHO	As per preliminary investigation victim and his son drive tractor with trolly in farm and passing under 11 KV Divdi AG that time in trolly extra extension of iron chenal touch to 11 KV Divdi AG live line and victim and his son electrocuted and 1 Human Fatal and 1 Non Fatal accident occurred.	Yet not received	NA	NA	People were educated to keep safe distance from Network	
280	PLN,PLN/2,AMBALI	Bhanpur /RURAL	Prajapti Maheshbhai chunabhai (urfe chunilal)	26.10.2024	FHO	This information received from hadad police station on dated 16.11.2024 and Accident occurred on dated 26.10.2024, hence on site visit on dated 16.11.2024 no any physical evidence and spot found on accident place ,also no any eye witness present on today at place .Detail investigation the victim was try to take unauthorized utilization of power from ag connection of Paraghi Harsanbhai khatarabhai 71043/10237/0 fuse board and can in touch with the live phase and electrocution.	Yet not received	NA	NA	inform consumer's not use unathorise power	
281	PLN,DEESA 2,THARAD 2	Naroli /RURAL	Owner Chauhan Ranaji Jorji	19.11.2024	FAO	Fatal animal electrical accident occurred to 2 nos Cow owner Chauhan Ranaji Jorji at Village: Naroli Ta: Tharad on dated:19.11.2024 @ 07.10 am . As per Site verification a Cow and a Calf came in contact with live broken Conductor of 11 KV Bhardasar JGY eminating from 66 KV Piluda SS. Conductor broken at Chauhan Ranji Jorji's farm.No any tripping recorded at 66 KV Piluda SS.Accident place is 15 KM away from SS.	Yet not received	NA	NA	Routine maintence of HT network is done.	23000/29.11.2024
282	PLN,PLN/2,JBALGADH	Dholiya /RURAL	Parthibhai Hirabhai Mansa & Bharatbhai Bhurabhai Mori	12.01.2025	NFHO(E)	On dtd.12.01.2025,11.15 AM Parthibhai Hirabhai Mansa & Bharatbhai Bhurabhai Mori working on pole for LT open conductor to LT ABC conversion.while both touch nuetral wire of LT line both got electrocuted & getdown to land. And Non fatal accident occurred.reason under investigation	Yet not received	NA	NA	Line staff were educated to ensure power off postion and utilise safety gadgets before starting of work	
283	PLN,DEESA/1,BHILDI	BALODHAR /RURAL	Mrs. Sangitaben Bachuji Vaghela	21.01.2025	FHO	The eyewitness reported that a pregnant lady cutting grass near the LT (Low Tension) line pole, came into contact with the earthing wire of the pole and received an electric shock. A detailed investigation into the incident is ongoing	Yet not received	NA	NA	Earthing reactivation and maintenance is done	
284	PLN,DEESA/1,WAV	Bhatvarvas /RURAL	rajkumar chhedi sardar	27.01.2025	FHO	As per Praimary report on Date-27.01.2025 The victim was Labour of Truck GJ-08-AU-5827 in which Banas dan fill in it, The truck driver parked the truck in front of the warehouse and below the 11 kv padan jgy line. Victim Climbing on Truck for unloading banas dan bags from truck in to warehouse. at that time victim Head touch with direct electric live wire of 11 kv padan jgy and got electrocuted, and died on the spot .During Site Visit at Jaloya ss no Tripping of 11 Kv padan jgy Feeder on Time12.30.	Yet not received	NA	NA	People were educated to keep safe distance from Network and Line clearance should be maintained as per regulation	
285	PLN,PLN/2,AMBALI	Jetvas /RURAL	Dalpatsinh Godaji Devra	12.02.2025	NFHO(E)	As per eye witness , shri Thakor Ratuji , village-Rupal,Ta- Vadgam, Contractor gang came at Jetvas khakhara khetra fali. for TC replacement work.victim has not wear the safety gadgets and earthing not done at place.TC replacement work Supervision given to shri I.N. Taral ALM.By mistake supervisor isolated wrong DO section which its appr.1.5 km far away from the accident location TC center.victim shri Dalpatsinh Godaji Devra climbed on a TC center & fitted kappi cumbler on TC center top angle,at that time his right hand touched on conductor .He got electrocuted and fallen down from the TC center.Our staff call the 108 and sifted at Ambaji civil hospital for further treatment.He is a stable condition.feeder tripping not recorded as per GETCO data.	Yet not received	NA	NA	ACCIDENT DUE TO NEGLIGENCE OF EMPLOYEE & SHOW CAUSE ISSUED	
286	PLN,SIDHPU R,KAKOSHI	DASHAWADA /RURAL	DESAI BABUBHAI VARVABHAI'S COW	13.02.2025	FAO	Dashawada indiranagr ww tc fancing near cow passing to road side and touched fancing and got electric shocked due to leakage current ww motor	Yet not received	NA	NA	The Faulty Motor of ww was replaced and aware people about to use healthy equipment .	15000/01.04.2025
287	PLN,PLN/2,DANTA	Abhapura /RURAL	Prajapati Ashokkumar Gobarbhai & Electrical Assistant	01.03.2025	NFHD (Mechanical)	As per statement of victim attending of single phase power off complain of name consumer Barad Navalsinh Kalusinh village - Abhapura,During attending consumer complaint victim work on transformer center and work completed after victim down from transformer center that time victim climbing twisted conductor use for transformer support (non use of nut bolt for supporting angle)that time this twisted conductor open from twist and victim fall down from transformer center and occur mechanical accident	Yet not received	NA	NA	Aware to staff use of nut bolt for supporting angle	

Sr. No.	Circle, Division, Subdivision	Location of Accident and Rural or Urban	Name of Victim/Owner & Designation	Date of Occurance	Type of Accident FHD/NFHD/FHO/NFHO/F AO	Cause of Accident	Findings of CEI/EI/ AEI	Remedies suggested by CEI / EI/ AEI in various cases	Whether the remedy suggested is complied	Action taken to avoid recurrence of such Accident.	Amount of Compensation and Date of compensation paid (in Rs.)
1	2	3	4	5	6	7	8	9	10	11	12
288	PLN,PLN/2,D ANTA	Nagel /RURAL	Kediben Bhanabhai Babubhai Kher	11.03.2025	FHO	As per statement of owner of farm Thakor prakashkumar magaji victim Kediben Bhanabhai Babubhai Kher age : approx 55 years from Udaipur Rajasthan is doing labour crop farming work from week in this farm. on Date 11.03.2025 at 5:00 am she climb on 16 kva transformer structure at village -Nagel (Deravalu khetar)and touch live part of 11 KV Harigadh AG feeder and got shock and died ."victim comitted suicide due to internal family problems as per site report."	Yet not received	NA	NA	Public is advised to do not climb to UGVCL HT/LT/TC unauthorisely.	

Uttar Gujarat Vij Company Limited								
Year 2024-25 (April-24 to March-25)								
Performa SoP 003 B:								
APPENDIX - B								
REGISTER FOR COMPILING THE COMPLAINTS CLASSIFICATION WISE								
Classification	Pending complaints of previous Year	Complaints received during the Year	Total complaints	No. of complaints redressed during the month			Balance complaints to be redressed (4) - (9)	Classification of complaints
				Within stipulated time	Beyond stipulated time	Total		
1	2	3	4 = 2 + 3	5	6	7 = 5 + 6	8 = 7 - 4	9
A(I)	0	108753	108753	105030	3723	108753	0	Loose connections at meter, MCB or service line or from pole
A(II)	0	60850	60850	59151	1699	60850	0	Interruption due to line breakdown
A(III)	0	13449	13449	12953	496	13449	0	No power complaint on account of blowing of HT/ DropOut (DO)/ LT fuse
A(IV)	0	9360	9360	8773	587	9360	0	Interruption due to failure of transformer or distribution transformer MCB
A(V)	0	3650	3650	3441	209	3650	0	Load shedding/ schedule outages
B(I)	0	1962	1962	1809	153	1962	0	Ordinary case, which requires no augmentation
B(II)	0	1790	1790	1678	112	1790	0	Where augmentation is required
B(III)	0	140	140	96	44	140	0	Harmonics related issue
B(IV)	0	1409	1409	1197	212	1409	0	Neutral voltage related issue
B(V)	0	5650	5650	5272	378	5650	0	Voltage variations related issue
C(I)	0	17752	17752	12493	5259	17752	0	Stopped/Defective Meters.
C(II)	0	2673	2673	2474	199	2673	0	Meter accuracy test (Fast/ Slow)
C(III)	0	3123	3123	2684	439	3123	0	Burnt Meter
C(IV)	0	195	195	177	18	195	0	Stolen Meter
C(V)	0	7685	7685	7411	274	7685	0	Billing on average basis for more than two bills
C(VI)	0	3117	3117	2441	676	3117	0	Meter boxes/ metering system
D(I)	0	8671	8671	8068	603	8671	0	Loose Wires
D(II)	0	991	991	907	84	991	0	Inadequate ground clearance
E(I)	0	3226	3226	3065	161	3226	0	For current bills where no additional information is required
E(II)	0	3308	3308	3069	239	3308	0	Where additional information relating to correctness of reading etc. is required
E(III)	0	416	416	369	47	416	0	Final bill for vacation of premises/ change of occupancy
E(IV)	0	887	887	730	157	887	0	Change of Tariff
F(I)	0	1532	1532	1455	77	1532	0	Where extension of LT line up to 150 Metre is required
F(II)	0	858	858	779	79	858	0	Where extension of LT line of more than 150 Metre and/or augmentation of distribution transformer is required
F(III)	0	1312	1312	1205	107	1312	0	Where erection of new distribution transformer is required
F(IV)	0	884	884	864	20	884	0	Where erection of new HT line and distribution transformer is required and/ or existing HT line network is required to be augmented
F(V)	0	33	33	33	0	33	0	Where EHT level line and/ or Sub-station is required to be erected and/ or augmented
F(VI)	0	4121	4121	3872	249	4121	0	Modification in connected load
F(VII)	0	5557	5557	5222	335	5557	0	Name change/reconnection/ change of category
F(VIII)	0	412	412	398	14	412	0	In case connection is denied after payment against demand note
F(IX)	0	1119	1119	980	139	1119	0	Transfer of connection
G	0	2419	2419	1952	467	2419	0	Request for reconnection/ consumer wanting disconnection
H	0	1791	1791	1762	29	1791	0	Refund of amount due in regard to temporary connection
I	0	1253	1253	1142	111	1253	0	Street Light complaint
J	0	15763	15763	14968	795	15763	0	Others
Total	0	296111	296111	277920	18191	296111	0	

Uttar Gujarat Vij Company Limited

Year 2024-25 (April-24 to March-25)

Performa SoP 004

Sr. No.	Actions or steps carried out by UGVCL towards public awareness in the quarter	Likely number of consumers influenced	Details about the media
1	Display board of SOP at circle, Division & S/Dn	466481	Notice Board
2	Display board of Name of information officers under RTI Act 2005 at Circle,Division,Sub- division offices.	592238	Notice Board
3	Consumer care centers at various places	574362	Verbal & Notice Board at CCC
4	Advertisement through Daily News papers	761677	Daily News papers
5	Pamphlets distributed among public	884425	Pamphlets
6	Advertisement through slide in TV / Banners	562504	T V Channels
7	On Web site of Uttar Gujarat Vij Company Limited	924259	Internet
8	Through Regular Energy Bills	9562256	Energy Bill
9	Others	1627	CD

Uttar Gujarat Vij Company Limited

Year 2024-25 (April-24 to March-25)

Performa SoP 005 : Failure of Distribution Transformer.

Sr. No.	No. of existing Distribution transformer at the start of the Quarter	No.of Distribution transformers added during the Quarter	Total number of Distribution transformers	Total number of Distribution transformer failed during the Quarter	% failure rate of Distribution transformer
	A	B	C=A+B	D	E = (D) * 100/C
1	412770	22717	435487	29251	6.72
<u>Total</u>	412770	22717	435487	29251	6.72

Uttar Gujarat Vij Company Limited

Year 2024-25 (April-24 to March-25)

Performa SoP 007: Compliance of Sample Test result for Neutral Voltage

Sr. No	Category of consumers	Sample Size (Numbers)	Standard specified in regulations	Non-Deviation of results from the sample test (Numbers)	% age compliance
					(6) = (5)*100/(3)
1	2	3	4	5	6
	LT consumers				
1	Domestic	183962	2%	2117	1.15
2	Commercial	22216	2%	255	1.15
3	Industrial	6302	2%	47	0.75
4	Agricultural	60524	2%	1429	2.36
5	Public water works	3703	2%	51	1.38
	HT consumers				
6	HT Industrial	3974	2%	20	0.50

Uttar Gujarat Vij Company Limited

Year 2024-25 (April-24 to March-25)

Performa SoP 008: Compliance of Sample Test Report for voltage variations

1	2	3	4	5
Voltage Level	Sample Size (numbers)	Limit or prescribed standard	Non-Deviation of results from the sample test (Numbers)	
				% age compliance
				(5) = (4)*100/(2)
Low Voltage	16167	+6% to -6%	244	1.51
High Voltage	2354	+6% to -9%	12	0.51
Extra High Voltage	24	+10% to -12.5%	0	0.00

Uttar Gujarat Vij Company Limited

Year 2024-25 (April-24 to March-25)

Performa SoP 009: Compliance of Sample Test result for Harmonics

1	2	3	4	5	6
Sr. No	Category of consumers	Sample size (Numbers)	Limit or prescribed standard	Non- Deviation of results from the sample test (Numbers)	%age compliance
					(6) = (5)*100/(3)
1	LT consumers	16454	3.50%	35	0.21
2	HT consumers	489	3.00%	8	1.64
3	EHT consumers	8	3.00%	0	0.00

Uttar Gujarat Vij Company Limited

Year 2024-25 (April-24 to March-25)

SoP 010 - A : System Average Interruption Frequency Index (SAIFI) for AG. Dominant

Category

Sr. No	Month	Number of Sustained Interruptions during the Reporting Period = Ai	Number of Interrupted Customers for Sustained Interruption events during the Reporting Period = Ni	Total number of Customers Served for the Areas = Nt	Total Number of Interrupted Customers for Sustained Interruption events during the Reporting Period = $\Sigma (Ai \times Ni)$	SAIFI = $\Sigma (Ai \times Ni) / Nt$
1	2	3	4	5	6 = $\Sigma (3 \times 4)$	7 = 6 / 5
1	Apr-24	6730	448910	659187	1447753	2.20
2	May-24	9559	514637	660321	1878380	2.84
3	Jun-24	14811	551561	661810	3043225	4.60
4	Jul-24	16763	594787	665598	3337458	5.01
5	Aug-24	17089	607432	666053	3333427	5.08
6	Sep-24	14383	597874	666957	2988115	4.48
7	Oct-24	10130	539106	668410	2024223	3.03
8	Nov-24	17696	410146	677000	1261714	1.86
9	Dec-24	20783	573607	688365	4769940	6.93
10	Jan-25	19803	576158	690333	4646951	6.73
11	Feb-25	21065	531941	693757	2969209	4.28
12	Mar-25	21485	585224	694342	5346376	7.70
Total		190297	6531383	8092133	37046771	4.58

SoP 011 : System Average Interruption Duration Index (SAIDI) for AG. Dominant category

Sr. No	Month	Number of Sustained Interruptions during the Reporting Period = Ai	Total Outage Duration	Restoration time for each Interruption Event = Ri	Number of Interrupted Customers for Sustained Interruption events during the Reporting Period = Ni	Total Customer Interruption Duration = $Ri \times Ni$	Total Number of Customers Served for the Areas = Nt	Cumulative Customer Interruptions Duration = $\Sigma (Ri \times Ni)$	SAIDI = $\Sigma (Ri \times Ni) / Nt$
		Nos	Hr : Min	Hr : Min	Nos	Hr : Min	Nos	Hr : Min	Hr : Min
1	2	3	4	5 = 4 / 3	6	7 = 5 * 6	8	9 = $\Sigma (5 \times 6)$	10 = 9 / 8
1	Apr-24	6730	8676:35	1:17:21	448910	8676:35:00	659187	1800483:31	2:43
2	May-24	9559	12507:26	1:18:30	514637	12507:26:00	660321	2447736:19	3:42
3	Jun-24	14811	20177:23	1:21:44	551561	20177:23:00	661810	3862398:40	5:50
4	Jul-24	16763	22625:13	1:20:59	594787	22625:13:00	665598	4340888:51	6:31
5	Aug-24	17089	23356:03	1:22:00	607432	23356:03:00	666053	4422369:45	6:55
6	Sep-24	14383	18175:10	1:15:49	597874	18175:10:00	666957	3593955:35	5:23
7	Oct-24	10130	12281:54	1:12:45	539106	12281:54:00	668410	2403390:54	3:35
8	Nov-24	17696	5841:09	0:19:48	410146	5841:09:00	677000	1133854:17	1:40
9	Dec-24	20783	18948:21	0:54:42	573607	18948:21:00	688365	4066678:12	5:54
10	Jan-25	19803	20128:55	1:00:59	576158	585640:22:34	690333	4170283:37	6:02
11	Feb-25	21065	13344:45	0:38:01	531941	336986:27:15	693757	2756000:03	3:58
12	Mar-25	21485	18953:14	0:52:56	585224	516261:54:17	694342	3995838:28	5:45
Total		190297	195016:08	1:01:29	6531383	1581477:58:07	8092133	38993878:12	4:49

SoP 012 : Momentary Average Interruption Frequency Index (MAIFI) for AG. Dominant category

Sr. No	Month	Total Number of Momentary Interruptions = Imi	Total Number of Consumers affected due to Momentary Interruption Events during the Reporting Period = Nmi	Number of Customer Momentary Interruptions = $Imi \times Nmi$	Total Number of Customers Served for the Areas = Nt	Cumulative Momentary Customer Interruptions = $\Sigma (Imi \times Nmi)$	MAIFI = $\Sigma (Imi \times Nmi) / Nt$
1	2	3	4	5 = 3 * 4	6	7 = $\Sigma (3 \times 4)$	8=7/6
1	Apr-24	13931	598454	8337062674	659187	3367211	5.11
2	May-24	15686	606550	9514343300	660321	3569901	5.41
3	Jun-24	20704	608494	12598259776	661810	4760872	7.19
4	Jul-24	24066	637315	15337622790	665598	5277153	7.93
5	Aug-24	23836	636202	15164510872	666053	5274981	7.92
6	Sep-24	23642	637340	15067992280	666957	5502988	8.25
7	Oct-24	18895	627060	11848298700	668410	4295656	6.43
8	Nov-24	17696	556114	9840993344	677000	4042580	5.97
9	Dec-24	36041	636102	22925752182	688365	8802305	12.79
10	Jan-25	31604	641488	20273586752	690333	7586870	10.99
11	Feb-25	21065	612235	12896730275	693757	5296742	7.63
12	Mar-25	37910	657948	24942808680	694342	9366364	13.49
Total		285076	7455302	2125327672952	8092133	67143623	8.30

SoP 013 – : Customer Average Interruption Duration Index (CAIDI) for AG.

Dominant category

Sr. No	Month	Total Number of Sustained Interruptions during the Reporting Period = ΣAi	Total Restoration time for Interruption Events = ΣRi	Total Number of Interrupted Customers for Sustained Interruption events during the Reporting Period = ΣNi	CAIDI = $\Sigma (Ri \times Ni) / \Sigma (Ai \times Ni)$ = SAIDI / SAIFI
1	2	3	4	5	6 = (4 x 5) / (3 x 5)
1	Apr-24	6730	8676:35	448910	1:14
2	May-24	9559	12507:26	514637	1:18
3	Jun-24	14811	20177:23	551561	1:16
4	Jul-24	16763	22625:13	594787	1:18
5	Aug-24	17089	23356:03	607432	1:21
6	Sep-24	14383	18175:10	597874	1:12
7	Oct-24	10130	12281:54	539106	1:11
8	Nov-24	17696	5841:09	410146	0:53
9	Dec-24	20783	18948:21	573607	0:51
10	Jan-25	19803	20128:55	576158	0:53
11	Feb-25	21065	13344:45	531941	0:55
12	Mar-25	21485	18953:14	585224	0:44
Total		190297	195016:08	6531383	1:01

Uttar Gujarat Vij Company Limited

Year 2024-25 (April-24 to March-25)

SoP 010 - A : System Average Interruption Frequency Index (SAIFI) for JGY Dominant Category

Sr. No	Month	Number of Sustained Interruptions during the Reporting Period = Ai	Number of Interrupted Customers for Sustained Interruption events during the Reporting Period = Ni	Total number of Customers Served for the Areas = Nt	Total Number of Interrupted Customers for Sustained Interruption events during the Reporting Period = $\Sigma (Ai \times Ni)$	SAIFI = $\Sigma (Ai \times Ni) / Nt$
1	2	3	4	5	6 = $\Sigma (3 \times 4)$	7 = 6 / 5
1	Apr-24	1791	1422890	2182113	3455050	1.58
2	May-24	2969	1813596	2186280	5943619	2.72
3	Jun-24	4272	1898906	2189209	8466213	3.87
4	Jul-24	4246	1929409	2187493	8478784	3.88
5	Aug-24	5305	1949251	2192932	10387612	4.76
6	Sep-24	3992	1921425	2197157	8142060	3.71
7	Oct-24	2309	1573768	2206011	4413258	2.00
8	Nov-24	1079	1008302	2220967	2293645	1.03
9	Dec-24	3436	1624947	2218864	6465292	2.91
10	Jan-25	3471	1685455	2208010	6861413	3.11
11	Feb-25	2259	1475876	2212373	4302561	1.94
12	Mar-25	3103	1518217	2216729	5509530	2.49
Total		24884	12509245	15341195	49286596	3.21

SoP 011 : System Average Interruption Duration Index (SAIDI) for JGY Dominant category

Sr. No	Month	Number of Sustained Interruptions during the Reporting Period = Ai	Total Outage Duration	Restoration time for each Interruption Event = Ri	Number of Interrupted Customers for Sustained Interruption events during the Reporting Period = Ni	Total Customer Interruption Duration = $Ri \times Ni$	Total Number of Customers Served for the Areas = Nt	Cumulative Customer Interruptions Duration = $\Sigma (Ri \times Ni)$	SAIDI = $\Sigma (Ri \times Ni) / Nt$
1	2	3	4	5 = 4 / 3	6	7 = 5 * 6	8	9 = $\Sigma (5 \times 6)$	10 = 9 / 8
1	Apr-24	1791	1673:18	0:56:03	1422890	1673:18:00	2182113	3023975:01	1:23
2	May-24	2969	2818:09	0:56:57	1813596	2818:09:00	2186280	5454491:02	2:29
3	Jun-24	4272	3602:45	0:50:36	1898906	3602:45:00	2189209	6831368:10	3:07
4	Jul-24	4246	3510:20	0:49:36	1929409	3510:20:00	2187493	6661685:26	3:02
5	Aug-24	5305	4603:18	0:52:04	1949251	4603:18:00	2192932	8899958:35	4:06
6	Sep-24	3992	3328:03	0:50:01	1921425	3328:03:00	2197157	6635421:41	3:01
7	Oct-24	2309	2053:17	0:53:21	1573768	2053:17:00	2206011	3727861:15	1:41
8	Nov-24	1079	739:43	0:41:08	1008302	739:43:00	2220967	1541765:22	0:41
9	Dec-24	3436	2874:33	0:50:12	1624947	2874:33:00	2218864	5012311:29	2:15
10	Jan-25	3471	2671:44	0:46:11	1685455	2671:44:00	2208010	5169250:34	2:20
11	Feb-25	2259	2217:30	0:58:54	1475876	2217:30:00	2212373	3941382:20	1:46
12	Mar-25	3103	2357:06	0:45:35	1518217	2357:06:00	2216729	4039353:14	1:49
Total		38232	32449:46	0:50:56	19822042	32449:46:00	26418138	60938824:09	2:18

SoP 012 : Momentary Average Interruption Frequency Index (MAIFI) for JGY Dominant category

Sr. No	Month	Total Number of Momentary Interruptions = Imi	Total Number of Consumers affected due to Momentary Interruption Events during the Reporting Period = Nmi	Number of Customer Momentary Interruptions = $Imi \times Nmi$	Total Number of Customers Served for the Areas = Nt	Cumulative Momentary Customer Interruptions = $\Sigma (Imi \times Nmi)$	MAIFI = $\Sigma (Imi \times Nmi) / Nt$
1	2	3	4	5 = 3 * 4	6	7 = $\Sigma (3 \times 4)$	8=7/6
1	Apr-24	4807	2054812	9877481284	2182113	10521582	4.82
2	May-24	5411	2067224	11185749064	2186280	11823717	5.41
3	Jun-24	7267	2108158	15319984186	2189209	15463607	7.06
4	Jul-24	7679	2129075	16349166925	2187493	16443201	7.52
5	Aug-24	7933	2133870	16927990710	2192932	17016236	7.76
6	Sep-24	7172	2119910	15203994520	2197157	15484363	7.05
7	Oct-24	6020	2131171	12829649420	2206011	12985830	5.89
8	Nov-24	4302	1848495	7952225490	2220967	10390475	4.68
9	Dec-24	7912	2089502	16532139824	2218864	17777758	8.01
10	Jan-25	7840	2049022	16064332480	2208010	18297704	8.29
11	Feb-25	4395	1884500	8282377500	2212373	9781685	4.42
12	Mar-25	7547	2027760	15303504720	2216729	16309513	7.36
Total		78285	24643499	1929216319215	26418138	172295671	6.52

SoP 013 -- : Customer Average Interruption Duration Index (CAIDI) for JGY Dominant category

Sr. No	Month	Total Number of Sustained Interruptions during the Reporting Period = ΣAi	Total Restoration time for Interruption Events = ΣRi	Total Number of Interrupted Customers for Sustained Interruption events during the Reporting Period = ΣNi	CAIDI = $\Sigma (Ri \times Ni) / \Sigma (Ai \times Ni)$ = SAIDI/ SAIFI
1	2	3	4	5	6 = $(4 \times 5) / (3 \times 5)$
1	Apr-24	1791	1673:18	1422890	0:52
2	May-24	2969	2818:09	1813596	0:55
3	Jun-24	4272	3602:45	1898906	0:48
4	Jul-24	4246	3510:20	1929409	0:47
5	Aug-24	5305	4603:18	1949251	0:51
6	Sep-24	3992	3328:03	1921425	0:48
7	Oct-24	2309	2053:17	1573768	0:50
8	Nov-24	1079	739:43	1008302	0:40
9	Dec-24	3436	2874:33	1624947	0:46
10	Jan-25	3471	2671:44	1685455	0:45
11	Feb-25	2259	2217:30	1475876	0:54
12	Mar-25	3103	2357:06	1518217	0:43
Total		38232	32449:46	19822042	0:50

Uttar Gujarat Vij Company Limited

Year 2024-25 (April-24 to March-25)

SoP 010 - A : System Average Interruption Frequency Index (SAIFI) for other than

Ag & JGY Dominant Category

Sr. No	Month	Number of Sustained Interruptions during the Reporting Period = Ai	Number of Interrupted Customers for Sustained Interruption events during the Reporting Period = Ni	Total number of Customers Served for the Areas = Nt	Total Number of Interrupted Customers for Sustained Interruption events during the Reporting Period = $\Sigma (Ai \times Ni)$	SAIFI = $\Sigma (Ai \times Ni) / Nt$
1	2	3	4	5	6 = $\Sigma (3 \times 4)$	7 = 6 / 5
1	Apr-24	994	697118	1366165	1831190	1.34
2	May-24	1539	923560	1369684	2890342	2.11
3	Jun-24	1870	934712	1385147	3064720	2.21
4	Jul-24	1930	908394	1386146	2865184	2.07
5	Aug-24	2142	945477	1397880	3382060	2.43
6	Sep-24	2113	896450	1404241	3005456	2.14
7	Oct-24	1264	740159	1410224	1887498	1.34
8	Nov-24	720	582001	1426641	1211645	0.85
9	Dec-24	1463	759437	1433287	2602706	1.82
10	Jan-25	1645	873993	1459691	3381809	2.32
11	Feb-25	1161	737113	1460883	1790630	1.23
12	Mar-25	1291	775620	1466408	2208793	1.51
Total		11852	6045870	9719487	18926450	1.95

SoP 011 : System Average Interruption Duration Index (SAIDI) for other than Ag & JGY Dominant category

Sr. No	Month	Number of Sustained Interruptions during the Reporting Period = Ai	Total Outage Duration	Restoration time for each Interruption Event = Ri	Number of Interrupted Customers for Sustained Interruption events during the Reporting Period = Ni	Total Customer Interruption Duration = $Ri \times Ni$	Total Number of Customers Served for the Areas = Nt	Cumulative Customer Interruptions Duration = $\Sigma (Ri \times Ni)$	SAIDI = $\Sigma (Ri \times Ni) / Nt$
1	2	3	4	5	6	7	8	9	10
		Nos	Hr : Min	Hr : Min	Nos	Hr : Min	Nos	Hr : Min	Hr : Min
								9 = $\Sigma (5 \times 6)$	10 = 9 / 8
1	Apr-24	994	832:52	0:50:16	697118	832:52:00	1366165	1047893:37	0:46
2	May-24	1539	1096:22	0:42:45	923560	1096:22:00	1369684	1416407:26	1:02
3	Jun-24	1870	1388:03	0:44:32	934712	1388:03:00	1385147	1572540:53	1:08
4	Jul-24	1930	1310:08	0:40:44	908394	1310:08:00	1386146	1402747:56	1:00
5	Aug-24	2142	1599:16	0:44:48	945477	1599:16:00	1397880	1567251:14	1:07
6	Sep-24	2113	1497:02	0:42:31	896450	1497:02:00	1404241	1542851:13	1:05
7	Oct-24	1264	877:10	0:41:38	740159	877:10:00	1410224	845737:23	0:35
8	Nov-24	720	535:17	0:44:36	582001	535:17:00	1426641	536646:37	0:22
9	Dec-24	1463	990:17	0:40:37	759437	990:17:00	1433287	1082482:13	0:45
10	Jan-25	1645	1357:24	0:49:31	873993	1357:24:00	1459691	1965501:38	1:20
11	Feb-25	1161	1115:59	0:57:40	737113	1115:59:00	1460883	1122706:20	0:46
12	Mar-25	1291	1031:00	0:47:55	775620	1031:00:00	1466408	1169064:51	0:47
Total		18132	3317:17	0:10:59	9774034	13630:50:00	16966397	15271831:21	0:54

SoP 012 : Momentary Average Interruption Frequency Index (MAIFI) for other than Ag & JGY

Dominant category

Sr. No	Month	Total Number of Momentary interruptions = Imi	Total Number of Consumers affected due to Momentary Interruption Events during the Reporting Period = Nmi	Number of Customer Momentary Interruptions = $Imi \times Nmi$	Total Number of Customers Served for the Areas = Nt	Cumulative Momentary Customer Interruptions = $\Sigma (Imi \times Nmi)$	MAIFI = $\Sigma (Imi \times Nmi) / Nt$
1	2	3	4	5 = 3 * 4	6	7 = $\Sigma (3 \times 4)$	8=7/6
1	Apr-24	1648	1010310	1664990880	1366165	2855058	2.09
2	May-24	1898	2067224	3923591152	1369684	3396521	2.48
3	Jun-24	2268	1093507	2480073876	1385147	4135287	2.99
4	Jul-24	2267	1088953	2468656451	1386146	3900519	2.81
5	Aug-24	2426	1085545	2633532170	1397880	4124623	2.95
6	Sep-24	2445	1114959	2726074755	1404241	4145264	2.95
7	Oct-24	1844	1028662	1896852728	1410224	2975723	2.11
8	Nov-24	1565	966646	1512800990	1426641	3002354	2.10
9	Dec-24	2497	2089502	5217486494	1433287	5753365	4.01
10	Jan-25	2968	1172574	3480199632	1459691	7048285	4.83
11	Feb-25	1666	1020849	1700734434	1460883	3391894	2.32
12	Mar-25	2284	2027760	4631403840	1466408	3987686	2.72
Total		25776	15766491	406397072016	16966397	48716579	2.87

SoP 013 – : Customer Average Interruption Duration Index (CAIDI) for

other than AG & JGY Dominant category

Sr. No	Month	Total Number of Sustained Interruptions during the Reporting Period = ΣAi	Total Restoration time for Interruption Events = ΣRi	Total Number of Interrupted Customers for Sustained Interruption events during the Reporting Period = ΣNi	CAIDI = $\Sigma (Ri \times Ni) / \Sigma (Ai \times Ni)$ = SAIDI/ SAIFI
1	2	3	4	5	6 = $(4 \times 5) / (3 \times 5)$
1	Apr-24	994	832:52	697118	0:34
2	May-24	1539	1096:22	923560	0:29
3	Jun-24	1870	1388:03	934712	0:30
4	Jul-24	1930	1310:08	908394	0:29
5	Aug-24	2142	1599:16	945477	0:27
6	Sep-24	2113	1497:02	896450	0:30
7	Oct-24	1264	877:10	740159	0:26
8	Nov-24	720	535:17	582001	0:26
9	Dec-24	1463	990:17	759437	0:24
10	Jan-25	1645	1357:24	873993	0:34
11	Feb-25	1161	1115:59	737113	0:37
12	Mar-25	1291	1031:00	775620	0:31
Total		18132	13630:50	9774034	0:45

Uttar Gujarat Vij Company Limited

Year 2024-25 (April-24 to March-25)

SoP 010 - A : System Average Interruption Frequency Index (SAIFI) for Overall

Dominant Category						
Sr. No	Month	Number of Sustained Interruptions during the Reporting Period = Ai	Number of Interrupted Customers for Sustained Interruption events during the Reporting Period = Ni	Total number of Customers Served for the Areas = Nt	Total Number of Interrupted Customers for Sustained Interruption events during the Reporting Period = $\Sigma (Ai \times Ni)$	SAIFI = $\Sigma (Ai \times Ni) / Nt$
1	2	3	4	5	6 = $\Sigma (3 \times 4)$	7 = 6 / 5
1	Apr-24	9515	2568918	4207465	6733993	1.60
2	May-24	14067	3251793	4216285	10712341	2.54
3	Jun-24	20953	3385179	4236166	14574158	3.44
4	Jul-24	22939	3432590	4239237	14681426	3.46
5	Aug-24	24536	3502160	4256865	17103099	4.05
6	Sep-24	20488	3415749	4268355	14135631	3.31
7	Oct-24	13703	2853033	4284645	8324979	1.94
8	Nov-24	19495	2000449	4324608	4767004	1.10
9	Dec-24	25682	2957991	4340516	13837938	3.19
10	Jan-25	24919	3135606	4358034	14890173	3.42
11	Feb-25	24485	2744930	4367013	9062400	2.08
12	Mar-25	25879	2879061	4377479	13064699	2.98
Total		246661	36127459	51476668	141887841	2.76

SoP 011 : System Average Interruption Duration Index (SAIDI) for Overall Dominant category

Sr. No	Month	Number of Sustained Interruptions during the Reporting Period = Ai	Total Outage Duration	Restoration time for each Interruption Event = Ri	Number of Interrupted Customers for Sustained Interruption events during the Reporting Period = Ni	Total Customer Interruption Duration = $Ri \times Ni$	Total Number of Customers Served for the Areas = Nt	Cumulative Customer Interruptions Duration = $\Sigma (Ri \times Ni)$	SAIDI = $\Sigma (Ri \times Ni) / Nt$
		Nos	Hr : Min	Hr : Min	Nos	Hr : Min	Nos	Hr : Min	Hr : Min
1	2	3	4	5 = 4 / 3	6	7 = 5 * 6	8	9 = $\Sigma (5 \times 6)$	10 = 9 / 8
1	Apr-24	9515	11182:45	1:10:31	2568918	11182:45:00	4207465	5872352:09	1:23
2	May-24	14067	16421:57	1:10:03	3251793	16421:57:00	4216285	9318634:47	2:12
3	Jun-24	20953	25168:11	1:12:04	3385179	25168:11:00	4236166	12266307:43	2:53
4	Jul-24	22939	27445:41	1:11:47	3432590	27445:41:00	4239237	12405322:13	2:55
5	Aug-24	24536	29558:37	1:12:17	3502160	29558:37:00	4256865	14889579:34	3:34
6	Sep-24	20488	23000:15	1:07:21	3415749	23000:15:00	4268355	11772228:29	2:45
7	Oct-24	13703	15212:21	1:06:37	2853033	15212:21:00	4284645	6976989:32	1:37
8	Nov-24	19495	7116:09	0:21:54	2000449	7116:09:00	4324608	3212266:16	0:44
9	Dec-24	25682	22813:11	0:53:18	2957991	22813:11:00	4340516	10161471:54	2:20
10	Jan-25	24919	24158:03	0:58:10	3135606	24158:03:00	4358034	11305035:49	2:35
11	Feb-25	24485	16678:14	0:40:52	2744930	16678:14:00	4367013	7820088:43	1:47
12	Mar-25	25879	22341:20	0:51:48	2879061	22341:20:00	4377479	9204256:33	2:06
Total		246661	241096:44	0:58:39	36127459	241096:44:00	51476668	115204533:42	2:14

SoP 012 : Momentary Average Interruption Frequency Index (MAIFI) for Overall Dominant category

Sr. No	Month	Total Number of Momentary interruptions = Imi	Total Number of Consumers affected due to Momentary Interruption Events during the Reporting Period = Nmi	Number of Customer Momentary Interruptions = Imi * Nmi	Total Number of Customers Served for the Areas = Nt	Cumulative Momentary Customer Interruptions = $\Sigma (Imi \times Nmi)$	MAIFI = $\Sigma (Imi \times Nmi) / Nt$
1	2	3	4	5 = 3 * 4	6	7 = $\Sigma (3 \times 4)$	8=7/6
1	Apr-24	20386	3663576	74685660336	4207465	16743851	3.98
2	May-24	22995	4740998	109019249010	4216285	18790139	4.46
3	Jun-24	30239	3810159	115215398001	4236166	24359766	5.75
4	Jul-24	34012	3855343	131127926116	4239237	25620873	6.04
5	Aug-24	34195	3855617	131842823315	4256865	26415840	6.21
6	Sep-24	33259	3872209	128785799131	4268355	25132615	5.89
7	Oct-24	26759	3786893	101333469787	4284645	20257209	4.73
8	Nov-24	23563	3371255	79436881565	4324608	17435409	4.03
9	Dec-24	46450	4815106	223661673700	4340516	32333428	7.45
10	Jan-25	42412	3863084	163841118608	4358034	32932859	7.56
11	Feb-25	27126	3517584	95417983584	4367013	18470321	4.23
12	Mar-25	47741	4713468	225025675788	4377479	29663563	6.78
Total		389137	47865292	18626156133004	51476668	288155873	5.60

SoP 013 -- : Customer Average Interruption Duration Index (CAIDI) for Overall category

Sr. No	Month	Total Number of Sustained Interruptions during the Reporting Period = ΣAi	Total Restoration time for Interruption Events = ΣRi	Total Number of Interrupted Customers for Sustained Interruption events during the Reporting Period = ΣNi	CAIDI = $\Sigma (Ri \times Ni) / \Sigma (Ai \times Ni)$ = SAIDI/ SAIFI
1	2	3	4	5	6 = $(4 \times 5) / (3 \times 5)$
1	Apr-24	9515	11182:45	2568918	0:52
2	May-24	14067	16421:57	3251793	0:52
3	Jun-24	20953	25168:11	3385179	0:50
4	Jul-24	22939	27445:41	3432590	0:50
5	Aug-24	24536	29558:37	3502160	0:52
6	Sep-24	20488	23000:15	3415749	0:49
7	Oct-24	13703	15212:21	2853033	0:50
8	Nov-24	19495	7116:09	2000449	0:40
9	Dec-24	25682	22813:11	2957991	0:44
10	Jan-25	24919	24158:03	3135606	0:45
11	Feb-25	24485	16678:14	2744930	0:51
12	Mar-25	25879	22341:20	2879061	0:42
Total		246661	241096:44	36127459	0:58

Uttar Gujarat Vij Company Ltd ,Mehsana

FY 2024-25 (April-24 to March-25)

YEAR: 2024-25

Performa SoP 014: Statement Showing the ATC losses, collection efficiency and Billing Efficiency

Qtr.	Months	Units input (Mus)	Units Billed (Mus)	Billing Efficiency	Revenue Billed (Rs. Crore)	Revenue Collected (Rs. Crore)	Collection Efficiency* %	Business Efficiency	AT & C Losses %
A		B	C=(B/A)*100	D	E	F=(E/D)*100	G=(C*F)/100	H=100-G	
I	Apr-24	3096.119	2616.274	84.50	1449.130	1629.065	100.00	84.50	15.50
	May-24	3389.460	2822.644	83.28	1620.482	1814.404	100.00	83.28	16.72
	Jun-24	3007.335	2845.406	94.62	1753.211	2009.036	100.00	94.62	5.38
	Sub Total	9492.915	8284.325	87.27	4822.824	5452.505	100.00	87.27	12.73
II	Jul-24	2397.558	2533.356	105.66	1732.019	1901.454	100.00	105.66	-5.66
	Aug-24	2157.004	2320.840	107.60	1645.713	1892.882	100.00	107.60	-7.60
	Sep-24	2346.112	2278.977	97.14	1613.694	1920.389	100.00	97.14	2.86
	Sub Total	6900.675	7133.173	103.37	4991.426	5714.725	100.00	103.37	-3.37
III	Oct-24	2678.544	2659.733	99.30	1558.382	1899.492	100.00	99.30	0.70
	Nov-24	2687.033	2651.287	98.67	1417.283	1859.385	100.00	98.67	1.33
	Dec-24	2864.622	2727.359	95.21	1413.221	1704.533	100.00	95.21	4.79
	Sub Total	8230.199	8038.379	97.67	4388.886	5463.410	100.00	97.67	2.33
IV	Jan-25	2939.851	2807.636	95.50	1540.289	1543.708	100.00	95.50	4.50
	Feb-25	2686.339	2736.601	101.87	1352.679	1741.060	100.00	101.87	-1.87
	Mar-25	3059.941	2863.002	93.56	1449.133	1614.611	100.00	93.56	6.44
	Sub Total	8686.131	8407.238	96.79	4342.101	4899.379	100.00	96.79	3.21
Grand Total		33309.920	31863.115	95.66	18545.236	21530.019	100.00	95.66	4.34

* Collection Efficiency above 100% is taken as 100%

Uttar Gujarat Vij Company Limited

Year 2024-25 (April-24 to March-25)

Performa SoP 015 : Meter faults

Consumer Category	No. of faulty meters at the start of the Quarter	No. of faulty meters added during the Quarter	Total No. of defective / faulty meter	No. of faulty Meters repaired and replaced	No. of faulty meters pending at the end of the Quarter
	1	2	3=2+1	4	5=3-4
Single Phase	14952	106535	121487	117718	3769
Three Phase	0	31119	31119	26378	4741
HT	0	0	0	0	0
Total	14952	137654	152606	144096	8510

Uttar Gujarat Vij Company Limited							
Year 2024-25 (April-24 to March-25)							
Performa SoP 016 : Compensation details							
COMPENSATION DETAILS							
Sr. No.	Service Area	Compensation payable to consumer for the period of default in case of violation of standard	Claimed		Payable		
			No. of cases	Amount (Rs.)	No. of cases in which compensation is payable	Amount payable (Rs.)	Amount paid (Rs.)
1	Registration of complaint and intimation of Unique complaint Number to the Complainant	Rs. 50/- for each default	Nil			Nil	
2	Issuance of Demand Note for New Connection, Load Enhancement, Shifting of connection at other premises, Conversion of Service, Temporary Supply, Shifting of Service Connection in exiting premises, Deviation of line and Shifting of equipments.	Rs. 50 for each day of default.					
3	New Connection, Load Enhancement, Shifting of connection at other premises and Conversion of Service where no Network erection and/or augmentation is required.	Rs. 50 for each day of default.					
4	New Connection, Load Enhancement, Shifting of connection at other premises and Conversion of Service where Network erection and/or augmentation is required.	Rs. 50 for each day of default.					
5	Release of temporary supply	Rs. 50 for each day of default.					
6	Shifting of meter/services in the existing premises	Rs. 50 for each day of default.					
7	Shifting of LT/HT lines						
8	Shifting of Transformer structures						
9	Settlement of amount for refunding of excess amount after completion of work.	Rs. 50 for each day of default.					
10	Transfer of Service Connection with respect to change of name or change of ownership						
11	Application from consumer requesting Change in Tariff Class/Category.	Rs. 50 for each day of default.					
12	Complaint Related to Billing	Rs. 50 for each day of default.					
13	Replacement of Meter	Rs. 25/- for each day of default subject to maximum of Rs. 1500/- for LT connections and Rs. 250/- for each day of default subject to maximum of Rs. 2500/- for HT connections.					
14	Reconnection of Supply	Rs. 25/- for each six hours (or part thereof) of delay in restoration of supply subject to maximum Rs. 500/- for LT connection and Rs. 50/- for each six hours (or part thereof) of delay in restoration of supply subject to maximum Rs. 1000/- for HT connection.					
15	More than 2 interruptions in a day to the consumer for the reasons not attributable to the nature of fault as mentioned in Clause 8.4 of these Regulations.	Rs. 25/- for each interruption subject to maximum Rs. 500/- for LT connection and Rs. 50/- for each interruption subject to maximum Rs.1000/- for HT connection.					
16	Failure to restore power supply in case of blowing of fuse of LT side distribution transformer, at consumer premises, trouble of MCB of distribution transformer, loose connection at pole, MCB or meter, etc.	Rs. 50/- per hour per Consumer for the first two hours of default. Thereafter Rs. 100/- per hour per Consumer subject to maximum of Rs. 500/- per day for LT consumer and maximum of Rs. 2000/- per day for HT consumer.					
17	Failure to restore power supply in case of blowing of HT side fuse of distribution transformer						
18	Failure to restore power supply in case of HT and LT line fault.						
19	Failure to restore power supply in case of Distribution transformer failure						
20	Failure to restore power supply in case of failure of underground service or underground HT/LT cable						
21	Scheduled Power Outage	Rs. 50/- per hour per Consumer for the first two hours of default. Thereafter Rs. 100/- per hour per Consumer					
22	Site Visit and Intimation to the Consumer about likely time to resolve the complaint related to voltage fluctuation.	Rs. 200/- for each instance for each complaint.					
23	Complaint of Neutral Voltage	Rs. 250/- for each complaint					
24	Complaint regarding Voltage variations at the point of commencement of supply.	Rs. 25/- for each day of default subject to maximum of Rs. 500/-					

Uttar Gujarat Vij Company Limited								
Year 2024-25 (April-24 to March-25)								
Performa SoP 017: Individual Complaint where Compensation has been paid								
Sr. No.	Complaint No.	Date of filing Complaint/ Automatic Compensation	Consumer No. and Name and Address of the Consumer	Nature of Complaint	Reference Standard of Performance	Amount of compensation (Rs.)	Whether Compensation paid automatically or Consumer has to approach CGRF to get compensation	Whether CGRF has upheld demand of Consumer of Compensation and if Yes, date of order of CGRF and date of compensation paid
Nil								

Uttar Gujarat Vij Company Limited

Year 2024-25 (April-24 to March-25)

Performa SoP 018: Unauthorised Use of electricity

No. of cases booked	No. of cases where UUE is established by the Licensee	No. of cases where appeal filed by the consumer before the Appellate Authority	No. of cases decided by the Appellate Authority in favour of the Licensee	No. of cases decided by the Appellate Authority in favour of the consumer
6366	6366	12	3	0

Uttar Gujarat Vij Company Limited

Year 2024-25 (April-24 to March-25)

SoP 019: Theft of electricity

No. of cases booked	No. of complaints filed by the Licensee in Police Station	No. of cases in which judgment delivered by the Special Court	No. of cases decided by the Special Court in favour of Licensee	No. of cases decided by the Special Court in favour of Consumer
12313	12313	0	0	0