

Uttar Gujarat Vij Company Ltd ,Mehsana		
Performas for FY 2024-25		
<u>Performa No.</u>	<u>Particulars</u>	<u>Remarks/Report</u>
SoP 001	Fatal & Non Fatal Accident Report	Qtrly FY 2024-25
SoP 002	Action taken report for safety measures complied for the accidents occurred	Half Yearly FY 2024-25
SoP 003	Register for compiling the complaints classification wise	Qtrly FY 2024-25
SoP 004	Actions or steps carried out by UGVCL towards public awareness in the year	Qtrly FY 2024-25
SoP 005	Failure of Distribution Transformer.	Qtrly FY 2024-25
SoP 007	Sample Test result for Neutral Voltage	Half Yearly FY 2024-25
SoP 008	Sample result for Voltage Variations	Half Yearly FY 2024-25
SoP 009	Sample Test result for Harmonics	Half Yearly FY 2024-25
SoP 010 - A	System Average Interruption Frequency Index (SAIFI)	Qtrly FY 2024-25
SoP 011	System Average Interruption Duration Index (SAIDI)	Qtrly FY 2024-25
SoP 012	Momentary Average Interruption Frequency Index (MAIFI)	Qtrly FY 2024-25
SoP 013	Customer Average Interruption Duration Index (CAIDI)	Qtrly FY 2024-25
SoP 014	System Losses at EHT / 11 KV and below	Half Yearly FY 2024-25
SoP 015	Meter Faults	Qtrly FY 2024-25
SoP 016	Compensation Details	Qtrly FY 2024-25
SoP 017	Individual Complaint where Compensation has been paid	Qtrly FY 2024-25
SoP 018	Unauthorised Use of electricity	Qtrly FY 2024-25
SoP 019	Theft of electricity	Qtrly FY 2024-25

Uttar Gujarat Vij Company Limited

Performa - SoP 001 : Fatal and Non-fatal Accident report

YEAR 2024-25 (July-24 to Sept.-24)

Sr. No.	Name of Circle	No.of accidents during the quarter					Cumulative since the first quarter of the current FY				
		Departmental		Outside			Departmental		Outside		
		FH	NFH	FH	FA	NFH	FH	NFH	FH	FA	NFH
1	Sabarmati	0	5	23	18	3	0	10	29	23	3
2	Mehsana	0	1	11	8	1	0	3	19	13	3
3	Palanpur	0	6	13	11	4	0	7	23	14	6
4	Himatnagar	0	1	10	25	2	0	2	18	29	2
	<u>TOTAL</u>	0	13	57	62	10	0	22	89	79	14

SOP 002 Action taken report for safety measures complied for the accidents occurred half yearly 2024-25 (April-2024 to Sept.-2024)											
Sr. No.	Circle, Division, Subdivision	Location of Accident and Rural or Urban	Name of Victim/Owner & Designation	Date of Occurrence	Type of Accident FHD/NFHD/ FHO/NFHO/ FAO	Cause of Accident	Findings of CEI/EI/ AEI	Remedies suggested by CEI / EI/ AEI in various cases	Whether the remedy suggested is complied	Action taken to avoid recurrence of such Accident.	Amount of Compensation and Date of compensation paid (in Rs.)
1	2	3	4	5	6	7	8	9	10	11	12
1	MSH/Mehs ana/Jotana	Tejpura (rural)	Raval Kirankumar Amrutbhai (EA)	07-04-24	NFHD(Mech.)	On Dtd. 07-04-2024 at morning, a private vehicle damaged the LT pole near the cabin of Dasharathsinh Hathisinh Zala near the Gram Panchayat water tank at Tejpura village. Therefore, Supervisor Shri R K Panda, LI and Shri Kiran Raval, EA were tasked to restore power at Tejpura village using a contractor gang. Before arrival of contractor gang initially they have decided to cut down the damaged portion of the line to restore power to the remaining portion of the village. Hence, it is necessary to cut down the power supply from the shackle near this broken pole. For the same work, both employees isolated the power supply of the same LT line feeding from the transformer center near Gram Panchayat. After isolating the power supply, Victim Shri K A Raval, EA climbed the pole connected to the damaged pole near the house of Rabari Dharamsinhbhai Karmanbhai. During the removal of the shackle; suddenly the LT pole broken from the bottom side (inside the ground). As a result, the victim fell down from the LT pole onto the ground. The victim was immediately shifted to Vibrant Hospital by a 108 ambulance and is currently under treatment at Vibrant hospital.	Yet not received	N/A	N/A	Line staff were educated to inspect the pole before commencement of work	
2	MSH/Visnagar/Vadnagar-1	Vaktapura (rural)	Patel Sureshbhai Bhikhabhai	12.04.2024	FHO	On dated 12.04.2024 call received around 7.00pm on DE's mobile that victim Sh. Patel Sureshbhai Bhikhabhai was fatal under Transformer center due to got electric accident and take him at civil hospital for PM. At that time DE visit hospital but hospitalize victim was declared dead by hospital. Immeditely than after DE with staff are visited accident place on dated 12.04.24 around 08:30 PM and next day on dated 13.04.2024.It has been observed that there were not found any sparking mark on the parts of Ag transformer center like earthing wires,stay wires,all MS angels and also not found any dark spot on vela (galo)which were wrapped up with left side of transformer center's cement pole,staywires,earthing wire and also not found any leakage current at transformer center and near vela(galo).As per 66 KV schedule of 11 kv undani ag feeder was under 1 phase from 07:00 to 23:00 and no tripping recorded of this feeder at 66 KV KHANPUR SS on date 12.04.2024.	Yet not received	N/A	N/A	AS PER FORENSIC REPORT CAUSE OF DEATH IS NOT ELECTRIC CURRRENT.ALSO EI LETTER RECEIVED EI/FA/499 DT:26.06.2024	
3	MSH/Kadi/Kadi-1	Zalora (rural)	Damor Jaydeepbhai Kanubhai	14.04.2024	NFHO(Elect.)	At Village- Zalora, Ta. Kadi, During Erection work of new AG connection, Victim who was labour of Contractor, climbed on 11kv pole of Chandanpura AG feeder to dismantle off power. LT line conductor where HT & LT line was on same pole and Three phase power supply of 11 KV Chandanpura AG was ON in the line/Pole. Due to live power of 11 KV line, When Victim stand near V cross arm & his chest part touched with 11 kv conductor & got electric shocked & fell down from pole. His team member & other villagers sent him to hospital for further treatment.	Yet not received	N/A	N/A	People should ensure the power position before commencement of work	
4	MSH/Visnagar/Kheralu-2	Mandali(rural)	Prajapati Amitkumar Ramjibhai, Electrcal Assistant	25.04.24	NFHD(Mech.)	During conductor replacement of 11kv Virpura Ag feeder, Victim was on HT shackle Pole Location 67, one side replaced by new conductor and was making new jumper with other side old conductor. Mean while old conductor jumpering work other sided old conductor was accidentally broken. And Victim lost his balance and fallen down from pole.	Yet not received	N/A	N/A	Line staff were educated to inspect the pole before commencement of work	
5	MSH/Vijapur/Ladol	Falu(rural)	Suryaben Chhabilsinh Rathod	07-05-24	FHO	The victim got electrocuted when she came in contact with iron wire (Vargadi) in her house. This iron wire (Vargadi) was in contact with iron shed and this iron shed was in contact with short circuit ceiling fan through from which current leakage was happening.	Yet not received	N/A	N/A	People were educated to keep safe distance and not to tied varangni with Pole	
6	MSH/Patan/harij	Harij(Urban)	Bharvad Kanubhai Ganeshbhai	14.05.2024	FAO	During site visit it was found that 11 kv nedharland jgy feeder ht line is passing through thakkar vipulkumar ishvarlal farm. There is one conductor broken between location number 8 and 9 of 11 kv nedharland jgy feeder. In this situation feeder power is still on. At early morning three buffalows of shree bharvad kanubhai ganeshbhai was passing from farm of thakkar vipulkumar ishvarbhai , at that time all three buffalows came in contact with live broken conductor and got electrocuted.	Yet not received	N/A	N/A	Maintenance work of HT line carried out	45000
7	MSH/Vijapur/Kukarvada	Umiyanagar (Bilodara)(rural)	Rabari Vishnubhai Prabhatbhai	15.05.24	FAO	Due To Internal Fault Of Consumer Motor So Leakage Current Found At Ag Tc Centre At The Time Cow Touch To Gi Wire Of Ag Tc Centre And Cow Got Electrocuted And Died.	Yet not received	N/A	N/A	Give advice for proper house wiring.	15000
8	MSH/Visnagar/Satlasana	Sudasana(rural)	Shri Rathod Takhaji Madji	20.05.2024	FHO	Information received from 108 person on mobile about electrical accident occurred at sudasna village. And by knowing further information from villagers victim working on his metal shed and than after during climb down from shed , victim may be got electric shock by his internal wiring. Further detail investigation is in under progress	Yet not received	N/A	N/A	People were educated to install ELCB at their premises	
9	MSH/Kadi-2/Kadi	Indrad(rural)	Sharma Shani Savarajit	13.05.2024	FHO	As per the statement given by person present on site The victim was working on iron plat and doing hole in plate using magnet drill machine & While doing work by this machine which may be faulty & leakage current drawn in Magnet drill machine & while during work with fauly magnetic drill machine victim was electrocuted.	Yet not received	N/A	N/A	Accident occurred in private primises due to faulty consumer side wiring and company supervisor is educated to rectify internal wiring and provide proper ELCB.	
10	MSH/Mehs ana/Dhinoj	Mervada(rural)	Patel Prakashbhai Jayantibhai	23.05.2024	FHO	Victim was outsider. Tractor with thressar was under line 11 kVAG feeder. A victim tried to clean charna of thressor extrsact with taveta of thressar and came to induction zone and electrocuted. He fell on ground he was shifted to lanva CHC by EECO car. present doctor there declared him dead	Yet not received	N/A	N/A	Line clearance should be maintained as per regulation	
11	MSH/Kadi-2/Kadi	Katosan Road(Urban)	Solanki Uttamsinh Pravinsinh	27.05.2024	NFHO(Elect.)	As per eye witness statement, Victim was doing sprinkler work on Dt. 27.05.2024, at Approx 10.45 AM, on a roof of a newly under constructed shop. While doing sprinkler work, victim came in contact with live wire of 11 KV Katosan road jgy feeder's HT line, which is passing above shop's roof and that time victim got shocked and felt down on ground.	Yet not received	N/A	N/A	Accident occurred due to victim side fault and also provided new 10 mtr psc pole below the Existing 11 kv line to improve vertical clearance. Also primises owner is educated to take proper care while doing any work below the line and maintain safe clearance from existing HT Line.	
12	MSH/Kadi-2/Kadi	Indrad(rural)	Yashvant Subhashbhai patel	22.05.2024	FHO	As per site visit & eye witness statement victim was doing a welding work of a PA fan airbox in a boiler in a Aksherchem company and at that time somehow by doing above work victim electrocuted & died in private premises,	Yet not received	N/A	N/A	Accident occurred in private primises due to faulty consumer side wiring and company supervisor is educated to rectify internal wiring and provide proper ELCB.	
13	MSH/Patan/Patan Rural	Dharnoj(rural)	Patel Pitambarbhai shivrambhai	03.06.2024	FHO	During site visit , it was found that the victim often used to fillup mineral water from Dharnoj PHC centre. On dtd 03.06.2024 he came at PHC centre for filling up mineral water in his jug. After filling up his jug with mineral water, he found no powersupply in PHC premise. So he kept his water filled jug inside PHC and without informing anyone he went outside to the LT pole from where service wire was coming to PHC centre. He climbed up the LT pole to start powersupply and thus came in contact with live conductor and electrocuted and fell down. The patient outside the PHC centre informed to PHC centre employees. After which PHC centre employee gave him(victim) first aid treatment and for further reference sent to Civil hospital Patan in Pvt vehicle where present doctor declared him dead.	Yet not received	N/A	N/A	People were aware about no any work to be carried out unauthorized working on Discom Network	100000
14	MSH/Patan/Sami	Vaval(rural)	Mahadevi Ratuji Thakor	12.06.2024	FAO	During site visit it was found that HT line of 11 KV Varana AG feeder is passing through Nadoda Kanubhai Motibhai farm. There is one conductor snapping between location no. 139/18/17 & 139/18/16 from Shackle Pole Side of 11 KV Varana AG feeder and power of feeder found lying on land. During early morning 2 nos Buffalo's & 1 no Calf was passing from farm of Nadoda Kanubhai Motibhai, at that time all three buffaloes came in contact with live broken conductor and got electrocuted. PM Report & Police Panchnama awaited.	Yet not received	N/A	N/A	Maintenance work of HT line carried out	32500

15	MSH/Patan /Sami	Sami(Urban)	Mahadevbhai Matambhai Bharwad	14.06.2024	FAO	During site visit, it was found that, Accident site is located near Waterworks sump of Ektanagar Sami on mujpur Road, There is a LT pole on site, on which 200A LT DB Switch mounted on LT PSC pole. The incoming cable come to LTDB Switch is of 25 mm2 LT PVC 3 Phase 4 Wire cable, which is hinged on PSC Pole to LT DB Switch, From this LT DB Switch two Conductor of Coated wire of 34 mm2 is in outgoing side and running up side to this LT PSC pole and connected in 1 Phase 2 wire LT line conductor. Also Found that this insulation of this LT coted 34 mm2 conductor is rusted due to heating & Aging effect and Phase conductor may be come in contact with said LT PSC Pole. On Date of Accident ie 14.06.2024, Land Surrounding to said LT PSC pole was highly wet. So cow passing through that wet land and come in contact with leakage current, and got electrocuted and met with Fatal electrical Accident.	Yet not received	N/A	N/A	Maintenance work of LT line carried out	15000
16	MSH/Vijapur/Gozariya	Gozariya(rural)	Raval Rajnikant Amratbhai	19.06.2024	FHO	While Plugging male contact of plug into female contact of plug which was installed on motor body, victim got electric shock due to contact with live part of male contact of plug. Because switch where plug was connected was on	Yet not received	N/A	N/A	People were educated to install ELCB at their premises	
17	MSH/Patan /Jangral	Mesar(rural)	Buffalo of Shri Thakor Arvindji Vanvirji	26.06.2024	FAO	During Site Visit, A Single Phase Connection Of Mr.Thakor Vanvirji Dhiraji connected from the Agriculture transformer of Mr. Thakor Arvindji Vanvirji , an agricultural consumer in Mesar village.The service line of 1-ph connection touches near by shade due to wind and rain and insulation is damaged and the line leakage current return from the agriculture transformer descends to the earth, and the Buffalo dies due to electric current coming into contact with this agriculture transformer.	Yet not received	N/A	N/A	Service Line is replaced and required maintenance is done	15000
18	MSH/Kadi/Detroj	Madrisana(rural)	Cow of Rabari Manubhai Shankarbhai	01.07.2024	FAO	As per site visit At-Madrisana village, near primary school, left side of Madrisana- Indrapura road one dead cow (animal) found on the grass approximately 2-3 feet away from existing LT Line pole and there is no any avoidance found for electrical accident. Also we tested earthing wire of this pole, there is no any current found in GI wire & no any electric spot found.	Yet not received	N/A	N/A	Earthing reactivation and maintenance is done	
19	MSH/Patan /Harij	Nana(rural)	(1) Thakor Keshaben Mafaji (FH) (2) Thakor Sejalben Alkeshji (FH) (3) Thakor Alkeshji Abhuji (NFH)	02.07.2024	FHO & NFHO	During site visit it was found that 1 Ph. Connection in name of Thakor Keshaben Mafaji is exist at Indiranagar area of Nana village.Outgoing cable of meter connected to simple on-off switch & from switch, two core cable connected to switch board.There is adjacent another house of same owner. This house have cement sheet roof by support of iron hollow square pipe.This second house is used as kitchen purpose by owner. Owner of house has extended illegally two core cable to adjacent house from their first house switch board and this illegally cable was passing in between cement sheet & horizontal iron hollow square pipe and same pipe is supported by vertical iron square pipe.The open space in front of second house is fenced by iron wire and tied with this vertical iron pipe. Due to friction of insulation of two core cable between cement sheet roof & iron pipe,a live wire of cable is touched to iron horizontal pipe and then current passed through vertical iron pipe and then passing to fencing iron wire.At early morning approx. 6 o'clock, Thakor keshaben mafaji touched to fencing wire and got electrocuted and to seeing that, Thakor sejalben alkeshji rushed and in attempt of save her life ,she also got electrocuted. Both of them transferred to pvt.hospital of Harij where doctor has declared dead.	Yet not received	N/A	N/A	Public was aware to installed ELCB & house wiring must be installed by Approved electrical contractor to prevent leakage current.	
20	MSH/Patan /Sami	Khandiya(rural)	Buffalo of Shankarbhai Sangrambhai Rabari	02.07.2024	FAO	During site visit, it was found that, Accident site is located near Shakti Mataji Temple at Village Khandiya. There is a single phase connection having consumer No. 28841101113 of Temple,for said connection LT line of 3-Ph 4 Wire LT ABC coming from Kandiya village Transformer Under 11 KV Bolera JGY Feeder. Also there is a LT PSC Pole Where this Accident occurred found completely wet due to heavy rain on dated 02/07/24. Also the Land surrounding this LT Pole found water logged. LT ABC cable tied on this LT PSC Pole via LT shackle insulator and one of the phase of this LT ABC cable come in contact with wet psc pole. Also found that the insulation of LT ABC cable phase touching with LT psc pole was rusted due to heating effect. On date of Accident around 10:00 AM buffalo of Shankarbhai Sangrambhai Rabari may passed near this wet LT psc pole and come in contact with leakage current through wet PSC pole and got electrocuted and met with Fatal electrical Accident.	Yet not received	N/A	N/A	Routine maintence of LT network is done.	15000
21	MSH/Vijapur/Lodra	Anodiya(rural)	Rathod Ramilaben Ranjitsinh	02.07.2024	FAO	Accident occurred on dtd:- 02.07.2024 about 05:30 am. Big neem tree fallen on 2W LT line so conductor broken from LT pole and conductor fallen on 2 buffeloes and got electrocuted and died.. As, per Statement of owner,	Yet not received	N/A	N/A	Tree cutting maintenance has been carried out	30000
22	MSH/Kadi-1/Kadi	Visatpura(rural)	1 nos Buffalo of Bharvad baldevbhai vashrambhai	07.07.2024	FAO	Buffalo of Bharvad Baldevbhai Vashrambhai was grazing in the Farm Visatpura Village. While grazing, Buffalo came in contact with Stay wire of D.P. structure location no. 97 of 11kV Charol Ag feeder. This HT location was shakle type D.P. structure having A.B. switch mounted on it. While buffalo was grazing near the pole, buffalo come in contact with stay wire & horns of buffalo was stucked with stay wire and due to this stay wire broken from anker rod & lower part from stay insulator of stay wire came in contact of jumper wire of A B Switch. Due to this current passes through the stay wire and as buffalo was in contact with the stay wire, it got electric shock and died on the spot.	Yet not received	N/A	N/A	Routine maintence of HT network is done.	15000
23	MSH/Patan /Sami	Jilwana(rural)	Bharwad Rajabhai Malubhai- Savasda	10.07.2024	FAO	During site visit, it was found that, on date of Accident the one conductor of 11 KV Ravad AG Feeder from pin pole location no. 67/Ravad AG feeder was snapped from Pin Insulator of said pole due to heavy wind. At that time one cow of Bharwad Rajabhai Malubhai Passed through Agriculture Land Below this Electrical line of Which one Conductor Snapped from PSC pole. So cow may be came in contact of that live conductor and got electrocuted and met with Fatal electrical Accident. PM Report & Police Panchnama awaited.	Yet not received	N/A	N/A	Routine maintence of HT network is done.	15000
24	MSH/Mehsana/Mehsana Highway	Mehsana(Urban)	Vaghari (Devipujak) Ramubhai Varvabhai	31.05.2024 Reported on 01.07.2024	FHO	While operating electric water motor to his working place, victim Late Vaghari (Devipujak) Ramubhai Varvabhai got electrocution due to live motor operation . Then shifted to Lions hospital & site doctor declared as dead. The cause of dead in PM report is shock due to head injuries.	Yet not received	N/A	N/A	Public was aware to installed ELCB & house wiring must be installed by Approved electrical contractor to prevent leakage current.	
25	MSH/Visnagar/Satlasana	Rinchhada(rural)	Smt Chaudhari Ashaben Raghjibhai	17.07.2024	FHO	At the time of site inspection inspection it was found that victim was taken cloth from iron string(Vargani) one end tied with roof angle and other end with roof vertical cement support inside her primeses (osri)and got electric shock due to leakage current from electricly short consumer ceiling fan . In osri Current passing from ceiling fan to tied iron rod to support horizontal iron angle for roof support where iron string (vargani) is tied .Victim was came with electrically live iron string (vargani) contect and got electricuted..she is admitted to Satlasana PHC	Yet not received	N/A	N/A	People were educated to keep safe distance and not to tied varangni with Pole	
26	MSH/Detroj/Kadi	Kukvav(rural)	Solanki Kuldipsinh Madhubha	13.07.2024	FHO	Victim was climbed on HT pole of 11 KV Kukvav JGY Feeder at-kukvav village. At that time body part of victim was touched to open conductor of 11 KV line and victim got electrocuted and fall down on ground. He was taken to the hospital for first aid where the doctor was declared him dead.	Yet not received	N/A	N/A	Victim climbed himself on HT line	100000
27	MSH/Mehsana/Mehsana Rural	Hanumat Heduva(rural)	Lavar Rameshbhai Chhaganbhai & Lavar Dasharathbhai Virambhai	19.07.2024	NFHO(Elect.)	In priate property of Acharya Ankitbhai Hariharbhai at acharya Farm Vill-Hanumant Heduva, A construction of new shed is under progress. The victims were working there as labour contractor and a labour. Both victims were transporting a 16.2 feet long ladder from one place to other place and while doing so, the ladder came in contact with the live eletric line of 11kv Hebua Ag feeder which is also at 16.2 feet from ground level and both got electrocuted. Thus the accident was occurred because the metallic ladder of height 16.2 feet came in contact with the electric line.	Yet not received	N/A	N/A	Consumer is advised to do not work below HT/LT line	
28	MSH/Mehsana/Mehsana Rural	Rajgar Heduva(rural)	Thakor Vinuji Javanaji	24.07.2024	FAO	On date 24.06.2024 at around 15.30 Hrs. an incident of Buffalo electrocution was occurred under TC structure of AG-A1 tariff connection named Thakor Pradhanji Jesangji with Con no. 20917001320 at village Rajgar Heduva. The incident was caused by fault in internal wiring of consumer's private installation. A ceiling fan was short circuited in consumer's installation and thus the current leaked to neutral wire of transformer centre. Due to heavy rain the surrounding area was wet. The buffalo was passing nearby the TC structure and came in contact with the TC structure and got electrocuted.	Yet not received	N/A	N/A	Consumer is advised to use Earth Leakage circuit breaker to avoid such occurrence. Also proper consumer wiring to be doen by consumer	Police panchnama not done by consumer.
29	MSH/Patan /Patan Rural	Sagodiya(rural)	Bharvad Haribhai Ganeshbhai	31.07.2024	FAO	As per site visit, it was found that at around 10:00 am buffalo of Shri Haribhai Ganeshbhai Bharvad was grazing at Sagodiya sim farm where 11 KV HT line of Kunvarika JGY feeder emanating from 66 KV Kimbuva ss passed. Buffalo might have came near Loc no 168 Switch pole's stay wire anchor rod for itching and got stuck in horn of buffalo and in panic buffalo removed anchor rod and died.Cause of death is under investigation and also PM report is awaited.	Yet not received	N/A	N/A	Sufficient distance between AB switch jumper and stay wire is kept	15000
30	MSH/Mehsana/Visnagar-1	Kansa(rural)	Thakor Mayurji Narshihji	03.08.24	FHO	Fatal human outsider electrical accident occurred to Thakor Mayurji Narshihji on Dated 03.08.24 time approx 9:00 AM Victim was work on Vibrator machine for making blocks and cleaning platform due to moisture atmosphere while cleaning the platform his hand touch to platform he got electrocuted and fallen down near to vibrator machine and he is admitted to civil hospital visnagar where victim was declered dead by doctor.meter and service line are found in good condition no leakage current fond at the time of site investigation Police panchanama and PM report awaited.	Yet not received	N/A	N/A	The Faulty Motor of PVT Promise was replaced and aware people about to use healthy equipment .	
31	MSH/Patan /Patan Rural	Bhemosan(rural)	Thakor Niteshji Abhesangji	09.08.2024	FHO	As per information received from Divyabhasker Newspaper on Dt:11.08.2024. The site is visited and as per statement of eye witness the victim Thakor Niteshji Abhesangji was playing at Home and The private wire coming from Swich bord which goes to singal phase in the moter, The child died of Electrocution by touching the wire and the actual causewill be found out after futher detail investigation and PM Report. and child transferred to hospital whwre Doctor has declared dead.	Yet not received	N/A	N/A	People were aware to installe ELCB and joint in wiring to be avoided	
32	MSH/Vijapur/Ladol	Mandali(rural)	Amitaben Pravinji Thakor	13.08.2024	FHO	The victim got electrocuted when she came in contact with iron wire (Vargadi) in her house. This iron wire (Vargadi) was in contact with iron shed and this iron shed was in contact with short circuit ceiling fan through from which current leakage was happening.	Yet not received	N/A	N/A	People were educated to remove varagani and keep safe distance from Network	

33	MSH/Patan /Harij	Harij(Urban)	Shailendra Shyamsunder Goswami	21.08.2024	FHO	During site visit & ground witness statement it was found that on dtd.21.08.24 ,victim shri Shailendra Shyamsunder Goswami has came for colour work on private street Light Tubular poles at Harij ITI with other two labour .At around 8.00 AM ,when he was transferring the aluminium ladder from one street light pole to another street light pole ,at that time the ladder came in contact with conductor of 11 KV Kukarana AG feeder which is passing from ITI campus and got electrocuted .Then after victim shri Shailendra was trasferred to Harij hospital by two others labour for further treatment. where doctor has declared him dead.	Yet not received	N/A	N/A	Prpoer safety norms must be followed by while working near to live conductor.	
34	MSH/Vijapur/Lodra	Mahudi(rural)	Rathod Dolatsinh Laxmansinh	26.08.2024	FAO	Accident occurred on dtd:- 26.08.2024 about 02:00 am. Due to heavy rain and cyclone big tree fallen on 2W LT line and conductor fallen on ground and bullock touch in conctect with conductor got electrocuted and died.	Yet not received	N/A	N/A	Maintenance of line is carried out	
35	MSH/kadi/ Kadi-2	Deusana(rural)	Gajiben Revabhai Raval	29.08.2024	FHO	As per information received from site, victim was trying to switch on the some electric instrument by connecting to defective switchboard, having open inhouse defective wiring .While doing this accidently touch that defective wiring victim was got shock and electroctured	Yet not received	N/A	N/A	Accident occurred in private primises due to faulty inhouse wiring and premises owner are educated to rectify inhouse wiring and provide proper ELCB.	
36	MSH/Mehsana/Dhinoj	Laxmipura(rural)	Patel Jaimin Vipulbhai, Age-22 years	01.09.2024	FHO	The Victim was repalcing the bulb of Sarapanch Gram panchayat street light at umiyapara in the railwaypura village. while working on the pole victim came into contact with the service line extension of street light on same pole. As a result, he lost his balance and fell to the ground. The victim was immediately shifted to hospital, where doctors declared him dead. The victim was a trainee apprentice lineman under dhinoj subdivision he was on Leave due to sunday and was not programmed by the subdivision office.	Yet not received	N/A	N/A	Public is advised to do not climb to UGVCL HT/LT/TC unathorisorily.	
37	MSH/kadi/ Kadi-2	Karannagar(Urban)	Jayani Chunilal Fusaram Dangaram	30.08.2024	FHO	As per letter received from police inspector ,kadi police station victim was trying to cover the truck by tarpaulin and iron pipe (approx 20 feet) which was standing under the HT line but anyhow iron pipe had been touch to lower conductor of budasan ag HT line which was approximately 18 feet from the ground and he got electrocuted and immediately shifted to private hospital at kadi and he was declared dead at hospital ,	Yet not received	N/A	N/A	Accident occurred due to victim side fault. Also primises ownerd is educated to take proper care while doing any work below the line and maintain safe clearance from existing HT Line..	
38	MSH/Kadi/ Kadi-1	Rangpurda(rural)	Bhupendrakumar Dhuljibhai Taral, Electrical Assistant	12-09-24	NFHD(elect.)	During work of change of jumper of 11 KV XLPE HT Cable at outside Gentry of 11 KV Veer Ind. feeder in Rangapurda S/S, Generator back power may came from any industries in one phase at outdoor cable box to AB Switch jumper, where victim was changing middle jumper of AB switch - outdoor cable box and touched with jumper. At that time Generator back power may came from any industries and victim get an electric shock /current. Victim felt down from Gentry structure on land below 11 KV Gentry. Victim burnt at leg, hand, bump part and head. Victim admitted at Bhavyodaya Hospital Kadi, then transferred at K.D. Hospital Ahmedabad for further treatment. The work was carrying out by taking line clear of the feeder by supervisor- P.S. Parmar Lineman, The 11 KV Veer Ind Feeder is having XPLE HT U/G Cable from S/S. Thus as per preliminary report the accident occurred due to back power of Generator may came from any industry.	Yet not received	N/A	N/A	Line staff were educated to ensure power off postion and utilise safety gadgets before starting of work	
39	Sabarmati Sabarmati Mandal	Endla	B.P.Nayakpuria(Elie.Asst)	09-Apr-24	NFHD	As per site visit, the victim and other staff after taking l.c of 11 kv Jesangpura Jgy from 66 kv Endla ss, made earthing on 2 side of the above said location and isolating the section by opening AB switch prepared for wire stringing with Safety belt and helmet. Victim climbed the PSC pole no. 17 Jesangpura JGY with extension, hooked up the safety belt in V-x arm, opened up the 1st pin binding, meanwhile the pole tilted down and fell on to the ground, and right leg of victim came under V-x arm's one side and got injured. Then immediately victim was shifted to Shiv Hospital at Viramgam by private vehicle for further medical treatment. On Further investigation in site pole was found cracked & damaged beneath the ground level.	Yet not received			NEW POLE ERECTED	
40	Sabarmati Bopal Changodar	Navapura	Jigarkumar R Thakor EA	10-Apr-24	NFHD	On Date 10/04/24 Approximately 13:20 HR at Navapura , Sun Shine Ind hub shri Jigar R Thakor EA was working for binding a insulated twin wire on Transformer centre's pole , near DO's Angle to lift the Service wire to be laid for new service connection. As 11 kv power supply was ON at the upper side of DO fuse , while binding this wire suddenly the wire came in contact with live side of DO pin and he got shocked, electrocuted and fell down from the pole but he was still conscious	Yet not received			Memo issued by SDO for proper observing safety norms and Monthly one Safety meeting carried out for line staff by SDO in which they are educated for the same.	
41	Sabarmati Bavla Sanand-2	Iyava	Rabari Ramjibhai Vastabhai	12-Apr-24	FAO	While eating leaves of Neem tree Camel came in contact with live conductor of 11 kv Khanderapoura AG HT line and got electrocuted and died	Yet not received			LINE RE-STRINGING OF LINE & RE STRAIGHTNING OF GUY DONE & TREE CUTTING	
42	Sabarmati Gandhinagar U Adalaj	Moti Adaraj	Thakor Dashrathji Rajijji	27-Apr-24	FHO	On dt 27.4.24 time 18:30 hrs there is a marriage function at Thakor Bhikhaji jivaji 's home. so Shri Dashrathji Rajijji Thakor come to there house and climb on LT LINE POLE for hanging light Fox for lighting on street. During climbing on LT pole he fall down on RCC road and then people took him to Gandhinagar civil but Doctor declared him dead.	Yet not received			No any Action Taken	
43	Sabarmati Bopal Bavla Ind.	Ch Vasna	Amrutbhai Kachrabhai Prajapati LM	04-Jun-24	NFHD	On Dt.04/06/24 at 2.22 am Msg received from 66 kv Bhat Substation that 11kv Shivanta Ind Feeder under p.f. So Mr A K Prajapati LM & Other EA went to attend Feeder fault and while Feeder Petrolling they came to know that One heavy Trailor having 21ft height passed near fourvent company and broken HT line conductor in Akshar Industrial Park as well as jumper burnt on Schackle Pole at Loc.13 & Loc.14 then after disconnecting AB Switch at Loc no.10 & Feeder made ON and then after rectified fault in Akshar Park they shifted on Loc13 to attend Burnt Jumper and Mr A K Prajapati (L.M) climb on Pole to rectify jumper and suddenly Power came from unknown location (Location still not identified) and he got shocked, electrocuted and hanged on 9ft. Angle of Two Pole Structure and other staff Mr K K Sathwara E.A.(V.S) has taken him out from the Pole and shifted him for primary treatment at Sola Civil Hospital, Ahmedabad and then shifted at SAL Hospital for further treatment and at present Mr A K Prajapati is in normal condition and conscious .	Yet not received			Memo issued by SDO for proper observing safety norms and Monthly one Safety meeting carried out for line staff by SDO in which they are educated for the same.	
44	Sabarmati Sabarmati Barejadi	Kanij	Hajaraben Mohamadbbhai Vohra	06-Jun-24	FHO	As per site visit investigation, at consumer no: 26501102154 name: AMINABEN KASHAMBHAI MANSHURI, power supply at accident place is given. Approx.07:30am dated: 06.06.2024 accident took place and we visited the site at 11:30 am on dated: 06.06.2024. Arriving at site, we firstly inspected the service connection wire of consumer no: 26501102154 and found that service connection wire was not cracked, damaged as well as not puncharted (leakage) neither was cut nor joint from anywhere around. On further investigating the site, near the entrance of the house we found the iron rope wire was one side tied with supporting wood clamp for metal roof sheet and another side with the plastic pipe of the bathroom terrace. Across the plastic pipe there was a private wire (for bathroom bulb connection) which was tied surrounding the plastic pipe and iron rope wire and the private wire was found puncharted (Insulation was broken). That private wire (Insulation was broken) was in contact with the iron rope wire. As per witness present, Victim was drying wet clothes on that rope wire and got electrocuted. It can be conclude that accident was taken place due to the consumer wiring. At Premises no MCB or ELCB was installed. So, Meter connection is disconnected till new test report is submitted by consumer. No any complain received from kanij village regarding above-mentioned	Yet not received			TEST REPORT WAS ACCEPTED WITH NEW ELCBS TESTING REPORT	
45	Sabarmati Gandhinagar R Dehgam T	Dehgam	Amit A Dantani EA	08-Jun-24	NFHD	on dt. 07/06/2024 @ 11.40 pm shivnagar area power off complaint registered on complaint office no.vide 2096. @ 12.00 am Shri Amit A Danatani Electrical assistant & shri P A Mahida apprentice lineman reach at site and they found that LTDB switch was OFF and he tried twice to ON without stripping of transformer DO but it didnot. Again he try to ON the switch and suddenly Blast occured and shri A A dantani, EA came in touch with the flame of fire and his face, hair, and left hand scene burnt and he was transferred to the Civil Hospital, Dehgam and he has taken primary treatment then present Dr referred him to private hospital. He was then admitted to Shelby Hospital, Naroda in office vehicle. Now he is stable .	Yet not received			FAULTY LTDB REMOVED FROM PLACE AND POWER SUPPLY RESTORED	
46	Sabarmati Bavla Dhandhuka	Dhandhuka	Musebhai Rahimbhai Desai	13-Jun-24	FAO	Return power came on neutral on Tc due to contact with street light phase to fabrication of pole and due to heavy wind dp box open and came in touch with fencing. Water logging under tc structure and fencing. When cow passing through water in which leakage current flow from fencing so cow is electrocuted and died. Cow was pregnant.	Yet not received			LEKAGE CURRENT PROBLEM RESOLVED	15000 / 09-08-2024

47	Sabarmati Gandhinagar U Ognaj	Jagatpur	Mahipal Ravji Nanoma	15-Jun-24	FHO	Late Shri Mahipal Ravji Nanoma was doing hole in the wall for wiring with cutter machine . The plug of the cutter machine was connected with binding wire which is further connected with extra long wire to switch board.The plug of the cutter machine which is connected with wire was found open and might be live while making hole in the wall.The live plug might have come in contact with body and victim might be electrocuted from live plug.Final actual cause of accident may be known after PM report and EI report.	Yet not received		Not applicable ..Inside Private Premises	
48	Sabarmati Bavlia Koth	Dholi	Chavda Natvarbhai popatbhai	23-Jun-24	FAO	While going to the field for grazing the Cow .cow is passing below the HT Line of 11 kv Sarandi Ag Feeder. suddenly due to heavy wind Conductor Broken and Fell down on Cow. And due to cow came in live wire contact got electrocuted and die.	Yet not received		SNAPPED HT CONDUCTOR RECTIFIED	
49	Sabarmati Sabarmati Naroda U	Enasan	Thakor Karan Ravjibhai	25-Jun-24	FHO	On dated 25.06.2024 around 02:20 am during night hours outside person Other than Indian oil petrol pump namely Jitendra Rohit Bhai Chauhan resident at Enasan park their Kia car behind the petrol pump open space area. After parking their car nearer white iron ladder height around 5 MTR found at that location, for no further scratch or damage by this iron ladder while in the rainy atmosphere he gave directives to Shri Karan Ravjibhai Thakor to take it to other open space by pushing it, And during this iron ladder touch the live 11 kv rudra fdr line & electrocuted & died. Height of 11 kv rudra fdr line to ground level 6.2 MTR , but in petrol pump premises height of 11 kv rudra fdr 4.8 MTR due to sand filling area. No any line shifting or line raising application given by the petrol pump premises owner.	Yet not received		HT LINE INSIDE PETROL PUMP AREA SHIFTING OUT SIDE DONE DUE SAFETY POINT OF VIEW.	100000 & 12.09.2024
50	Sabarmati Sabarmati Viramgam R	Meldinagar	Bharvad Nanubhai Lalabhai	25-Jun-24	FAO	A cow is passing through near by TC center and During the time of Horn of cow is entagaed in Transformer Fensing touches when leakage current passed by Transformer earthing to Fensing.Therefore power becomes earth and cow got electrocuted and died.	Yet not received		NEW TC EARTHING PROVIDED	
51	Sabarmati Bavlia Dholka R	Rajpur	Anandbhai Maheshbhai Chauhan	25-Jun-24	FHO	when he went to see if there was water fill up on the roof of the house, he may got electrocuted by nearby HT line passing over the roof of the house.	Yet not received		LINE SHIFTING ESTIMATE ISSUED BUT NPC.	
52	Sabarmati Bopal Changodar	Juna Vanjar	Popatbhai Nanjibhai Ninama EA (Emp No 12434)	28-Jun-24	NFHD	On Date 28/06/24 in the morning there was a tripping on Ashapura JGY feeder @ 0557 am , feeder was kept in PF after not getting ON and SS staff informed Shri Popatbhai Ninama so he got ready with his safety equipment to attend the fault meanwhile he got a call from Juna Vanjar village that HT pole (location no 228)broken by Dumper near village TC so immediately he rushed to the location and made feeder ON after isolating the section of Juna Vanjar as the pole was broken and hanging above the road he needs to get the pole moved aside the road ,shri Popatbhai Ninama EA was removing the conductors from the pole but while removing last conductors suddenly and accidentally pole got swing and fallen on left feet of Shri Popatbhai Ninama and he got injured so immediately he called his colleague EA Shri Sanjay Ninama , and Shri Sanjay Ninama took him to the nearest hospital, Navjivan hospital, Sarkhej, Shri Popat Ninama was given first aid there and as he got Major injury he was taken to CIMS hospital, Sola , Ahmedabad	Yet not received		Memo issued by SDO for proper observing safety norms and Monthly one Safety meeting carried out for line staff by SDO in which they are educated for the same.	
53	Sabarmati Sabarmati Vinzol	Dhamatvan	Kanubhai Naranbhai Rabari	29-Jun-24	FAO	a fatal accident occurred due to a cow came in contact of fencing of transformer of Bhatiji maharaj temple,On inspecting site, no leakage current found on fencing or transformer earthing, hence accurate decision can be taken after post mortam report	Yet not received		EARTHING RECTIFICATION DONE	
54	Sabarmati Bopal Changodar	Changodar	Luvkush Yadav	30-Jun-24	FHO	On Date 30/06/24 @ 2050 hrs the evening it was raining , Victim shri Luvkush Yadav came to the Grocery Shop of Shri Ramesh Yadav which is located at Tajpur road near Ratnam residency , he was a regular customer of this shop , he came for "Garam Masala " so he was finding on his own in the shop , somehow suddenly he hold the shutter by his right hand and he got shocked and stuck to the shutter so he screamed , Shri Ramesh Yadav , shop keeper , saw him so immediately he tried to separate him from shutter with his bare hand so Ramesh Yadav also got shocked and fell down so he took wooden strip and separated him from the shutter , as soon as he separated Luvkush fainted on ground and got unconscious. Ramesh Yadav and other customer shri Rinku took him to nearby hospital but Doctor referred Victim to bring him to Civil hospital, Ahmadabad , so he was taken to the Civil Hospital, Sola . Where he was declared dead by resident doctor	Yet not received		Advised Shop Owner Not To Use MCB Intead Of That Strictly Instructed Him To Use ELCB / RCCB	
55	Sabarmati Gandhinagar U Chandkheda	Chandkheda	Kinjal Ben Sahdevbhai Rabari	01-Jul-24	NFHO	As per report received of Chandkheda police station as on dated 2.7. 24 at 6.00 pm Kinjal Ben sahdev Bhai Rabari as on dated 01.7.24 at approx 7 pm during shifting of house hold on first floor of new made house she touch Ugvcl LT line passing near to the wall of First floor gallery. She stand up in gallery and touches the hand of LT line and electrocuted . immediately Sent to shayon hospital by her family members .As on dated 2.7.24 at evening discharged to the victim and health is normal .This office had already given notice to owner and line shifting estimate but not paid by owner. Estimate with Notice outward no 4717/ 18.12.2023 .. eventhough issue notice owner had made new/extension of house near by UGVCL line...	Yet not received		1nos of Pole Shifted ..and Restraining Work Carried out	
56	Sabarmati Gandhinagar U Ognaj	Jagatpur	Mahendrasinh Mohansinh Ravat	01-Jul-24	FHO	During site visit,it is found that one white coloured metal cabin installed for the employee of the contractor and from this cabin one iron sheet supported through iron angle to top of this cabin and other side of iron sheet also supported to ground through iron angle.Behind the cabin one ELCB and MCB installed for electricity of the cabin.When checked, the outgoing wiring from ELCB to cabin it is found that one red colour and one black colour wire's insulation found broken.After giving power supply to this ELCB and MCB and checked by tester on broken wire ,leakage current found on tester.As per statement from person available at site on date of accident there was rain and one labour named Mahendrasinh Ravat was passing near this cabin and due to wet ground due to rain , victim slipped and lost his balance and taken the support of iron angle and may be electrocuted due to leakage of current passing from broken wire from ELCB outgoing to metal cabin and iron sheet to iron anele...	Yet not received		Not applicable ..Inside Private Premises	
57	Sabarmati Bopal SHILAJ	Ambali	Achintabhai Dhirendranath Bishvas	02-Jul-24	FHO	On Date 02/07/2024 @ 1830 hrs the evening shri achintabhai dhirendrabhai bisvaas was came at his onsite iron container Type residence beside west side of Village ambali.When he had just touch the handle of door of container to open.he suddenly got shocked and felt down on ground and shouting other for help so nearer neighbour took him to hospital for primary treatment but at late night doctor of hospital declared him as dead.	Yet not received		ELCB Installed	
58	Sabarmati Bopal Sanand 1	Vadnagar	RM Chauhan	03-Jul-24	NFHO	On Date 3-7-2024 Shri RM Chauhan EA and Shri CB Dabhi EA has sent for complain of light off of single house at village Vadnagar. At location there is tree near pole and tree branch cut down by both te EA. At that time Shri RM Chauhan try to cut upper tree branches and somehow his leg slipped and fallen on RCC road street. He got injury on his head and shifted to near by hospital at Sanand and then after he was shifted to Sterling Hospital, Drive in road, Ahmedabad for further treatment. He is under supervision of Doctors right now.	Yet not received		Mechanical Accident due to tree branches fallen during tree cutting,	
59	Sabarmati Bavlia Koth	Vejalka	Sabhad Sardulbhai Bhikhabhai	04-Jul-24	FAO	Due to Heavy rain the bending of the pole of 11 kv motiboru jgy emitting of 66 kv koth ss so the wire comes down at the time the cow is going to the field for grazing and contact with 11 kv motiboru jgy live wire and got electrocuted and die.	Yet not received		TILTED POLE RECTIFIED	
60	Sabarmati Kalol Chhatral	Chhatral	Thakor Aashishiji Arjanji	05-Jul-24	FHO	Victim working in factory, while switch on the power by switch of extension board by one hand and having hand drill in another hand of victim, the hand drill found short circuted, and victim electrocuted by short circuted hand drill machine having iron body, Thus the accident occured due to internal fault of hand drill machine i.e factory side internal fault	Yet not received		CONNECTION DISCONNECTED AND NOTICE GIVEN FOR ELCB INSTALLATION.	
61	Sabarmati Sabarmati Viramgam R	Ogan	Gangadhar Sohanlal Rajput	07-Jul-24	FHO	As per report recieved by Viramgam-rural police station victim got shock and died while doing internal electrical bulb wiring under the shed of HYS comp. After site visit it is observed that there were two private live internal cable wire one with connector and one without connector. As per site available representative victim tries to to do wiring for bulb connection and he may touched live phase neutral and got electric shock and died.	Yet not received		DC DONE AND NEW TEST REPORT AWAITED FOR RECONNECTION	
62	Sabarmati Kalol Nardipur	Langhnaj	Vijaykumar Manilal Mistri	08-Jul-24	FHO	as per eye witnesses victim got electric shock while victim was wet his cloth in his house, During sitevisit no any leakage current found but thoroughly check service found spark and jointed with angle and current may be pass through angle, channel, cloth wire tided with iron channel in his house and victim got electrocuted.	Yet not received		CONNECTION DISCONNECTED AND NOTICE GIVEN FOR ELCB INSTALLATION.	
63	Sabarmati Sabarmati Goblj	Chandana	Parasbhai Sahiravalji Raval	09-Jul-24	FHO	As per information received by Kheda police station, & as per site visit and witness statement, the victim was trying to change/install bulb near his premise (shed). It is presume, that while doing internal electrical bulb wiring outside his premise, might have accidentally got shocked. As per site visit, it is observed, that one live wire (with one phase without insulation) is found on site. As per victim's brother statement, as per his talk with victim on previous night, he informed to replace bulb in the premise. It can be assume, he may touched live phase and got electric shock and died.	Yet not received		TEST REPORT WAS TAKEN WITH NEW ELCB TESTING REPORT	
64	Sabarmati Bavlia Dholka T	Dholka	Unknown	09-Jul-24	FAO	Accident occurred on 9.7.24 near B P Davda High School, Dholka, on TC near above location. The Phase wire of 150mm ² cable of TC got heat and touch nearby neutral of service wire of 6mm ² on TC. Due to above leakage current was flowing in earthing of TC, while cow was passing narby TC came in area of earthing so got electrocuted and died.	Yet not received		LEKAGE OF CURRENT PROBLEM RESOLVED.	

65	Sabarmati Bopal Changodar	Visalpur	Sanjay Kalaji Ninama EA	10-Jul-24	NFHD	On Date 10/07/24 in evening @ 1735 hrs , Shri Sanjay Ninama received a complaint of broken service wire from consumer Shri Rajnikant Vegda of Vankar Vas , Visalpur so he went to the site , and after making joint in the service line he was working on the pole to make connections with the LT line while moving his right hand , touched his elbow to the live phase of the 6 mm2 ideal cable and he got shock so he lost his hold from the pole and fell down to the ground. He got injured in his right elbow and in his Back , Gathered villagers brought him to nearby local clinic for emergency treatment but as he had too much pain in his back and elbow so brought him to CIMS hospital, Sola , Ahmedabad . he was fully conscious after met with accident	Yet not received			Memo issued by SDO for proper observing safety norms and Monthly one Safety meeting carried out for line staff by SDO in which they are educated for the same.	
66	Sabarmati Sabarmati Viramgam R	Hansalpur	Ranchhodbhai Somabhai Bharvad	15-Jul-24	FAO	A Cow passing through LT pole (Pole number : TC/4/P/8) and there were little rainy water nearby area of the pole. GI earthing wire of this LT pole found broken from upper side and touched with phase of LT line. Hence earth leakage current is flowing through GI wire and water around this pole may also under induction zone.As cow passing near this pole, cow got electrocuted and died.	Yet not received			RECTIFICATION DONE TO AVOID LEAKAGE CURRENT	
67	Sabarmati Sabarmati Viramgam R	Hansalpur	Rameshbhai Manabhai Bharvad	15-Jul-24	FAO	A Cow passing through LT pole (Pole number : TC/4/P/8) and there were little rainy water nearby area of the pole. GI earthing wire of this LT pole found broken from upper side and touched with phase of LT line. Hence earth leakage current is flowing through GI wire and water around this pole may also under induction zone.As cow passing near this pole, cow got electrocuted and died.	Yet not received			RECTIFICATION DONE TO AVOID LEAKAGE CURRENT	
68	Sabarmati Kalol Kalol-2	Vadsma	Chavda Mahendrasinh Kacharaji	17-Jul-24	FAO	While going to the field for grazing the buffalo .buffalo was passing from the transformer structure of 11 kv vadsma ag feeder and during that time the rain was raining and the buffelow came in contact of stay wire of the transformer structure and fell down at site and die. The proper reason will get after post mortam report because during the panchanama time there was no any leakage current found at site so waiting for the Dr report.	Yet not received			Maintanance done of 11 KV Vdasma AG feeder	15000
69	Sabarmati Bavla Sanand-2	Rethal	Jetabhai Khengarbhai Bharvad	19-Jul-24	FAO	Buffaloes were electrocuted due to return power from a hooking in the LT line passing through the nearby area.The power had been switched off in the specific area for safety reasons	Yet not received			NEW POLE ERECTED & ACCIDENT OCCURED DUE TO DIRECT HOOKING BY MR. MATHURBHAI JERAMBHAI BOOKED U/S 135.	
70	Sabarmati Gandhinagar R Rakhival	Sahebji na muvada	Zala Dilipsinh Gulabsinh	19-Jul-24	FAO	The Buffalo was passing through incident site. buffalo near existing lt pole buffalo used to scratch near the electricity pole.leaked current to stay wire therefore the buffalo was electrocuted and died near existing pole.	Yet not received			WIRE IS REMOVED	
71	Sabarmati Sabarmati Kujad	Bakrol-Bajrang	Ramkishan Premial Goswami	21-Jul-24	FHO	As per site visit, primarily (as per owner's statement), while cleaning the bathroom through pvc coated pipe connected through motor, he got electrocuted. As per primary investigation neatral return power found on bulb holder's copper coated cap.	Yet not received			TEST REPORT WAS TAKEN WITH NEW ELCB TESTING REPORT	
72	Sabarmati Gandhinagar U Adalaj	Adalaj	Thakor Baldevji Amaji	21-Jun-24	FHO	On dtd 29.06.2024 at approx. 13:00 pm hours a letter received from police station that a person named Baldevji Amaji Thakor working at Trisha Crane Service has died on dtd 21.06.2024 due to current. While doing site visit on dtd 05.07.2024, it was found that Baldevji Amaji Thakor was working as driver cum mechanic at Trisha Crane Service. While doing service of Crane no- RJ 27 EA 0711, the boom of crane was opened by Baldevji Amaji Thakor and by mistake it was touched to the agriculture HT line which were passing by. Trisha Crane Service is situated in open farm at Adalaj-Trimandir road, opp. Manekba School where so many cranes are parked and everyday cranes are moving in and out. The HT line that is located above is at proper height and clearance from ground is also appropriate and as per rules. From the above mentioned situation, it is found that Baldevji Amaji Thakor was either servicing of driving the crane and by opened the crane boom and by mistake, the boom was touched to the line and he may get electrocuted. The tyres and rubber pipes of the crane were perfectly fine. No any information about accident given by Trisha Crane Service on dtd 21.06.2024 at UGVCL. No post mortem carried out at Civil Hospital. Whether Thakor Baldevji Amaji had license for driving or not is not confirmed by Trisha Crane Service.	Yet not received			No any Action Taken	
73	Sabarmati Gandhinagar R Dehgam R	Vehlal	Sonu Brajmohan Rajput	23-Jul-24	FHO	As per information received date 25.07.24 evening by Police, we have site visited but above said Plot was shutter Locked and no any labour or owner at site. So as per kanbha police station letter information , we have observed at site that the victim might walking with iron bed (Khatalo) on iron made round Fix ladder outside nearby Entry Gate and nearby 11KV Vibrant Industrial Feeder Line 10 Meter PSC Pole line passing where one room entry on first floor but some how Iron bed (Khatalo) above side touch with line while walking with Iron bed (Khatala) and victim might got shocked and felt down, time 13:05 pm, immediately he was admitted at SELBI hospital Naroda where death occurred at Time 13:57 pm but no any information give by Owner or Victim's relative yet. We approached to owner on telephone for said incident matter but he was Outside and as per discussed with Owner, no any mistake of UGVCL but their side victim's mistake or lacuna.	Yet not received			CLOSE LADDER	
74	Sabarmati Gandhinagar R Chiloda-1	Limbadiya	R V Makawna (EA)	23-Jul-24	NFHD	Shri R V Makawana (EA) was working on LT pole after string of wire he try to cut old stay wire and his leg slip from pole so he fall down on land.	Yet not received			DVICE FOR PROPERLY TAKEN CARE WHILE WORKING	
75	Sabarmati Bavla Dholka R	Sahij	Sanjaybhai Chehubhai Devipujak	25-Jul-24	FHO	victim was working on the roof of the house and fixing iron rods for construction of a house ,while working he was electrocuted by a nearby HT line of 11 kv zanand jgy feeder and fell from the roof of the house and died while being taken to the hospital for treatment.	Yet not received			LINE SHIFTING ESTIMATE PAID ON 14-08-2024 & WORK DONE	
76	Sabarmati Sabarmati Goblaaj	Pansoli	Ratilal Harjibhai Bharvad	26-Jul-24	FAO	A buffalo was grazing near Ongc Well-293 transformer. The buffalo While rubbing her trumpet with guy wire of the Transformer, the guy wire accidentally come off and touch with live DO of the Transformer. The buffalo came in contact with live wire, and got electcuated and fatal accident occurred.	Yet not received			THE GUY WIRE WAS REFITTED AND ENTIRE TC LOCATION WAS PILFUR PROOFED FOR ANY LEAKAGES	1500
77	Sabarmati Gandhinagar R Dehgam R	Vehlal	(1) Harish Tripathi (2) Bansilal Mina (3) Kanubhai Gadiya (4) other one	26-Jul-24	NFHO	As per information received yesterday 26.07.24 by local line staff, we have site visited Owner not present. Labour nearby Plots were present. As information received for accident, immediately local line staff reached at site. Where Iron Shed work was going on and 2 Labours residing Ahmedabad were came for shed Fitting work and other 2 Labours Local from Shed owner. They all walking with Fully Iron 4 leg ladder without tyre (Sidi) in hand above land height and without not watching above paaaing line so touch 11 KV line. Instant line was tripping but all got shocked. They informed to Local Village staff so they reached and line Touched ladder was removed and after then11 KV line made ON. 11 KV line on 8 Meter PSC Pole at proper height but ladder for shed work so length was more and also in victims hand above height from land so incident occurred. All were taken to private Hospital Ahmedabad by Local rent owner Jayeshbhai Patel and all were normal and treatment was going on. We approached to owner on telephone for said incident matter but he was at hoapital and as per discussed with him, no any mistake of UGVCL but their side all victim's mistake or lacuna.	Yet not received			LADDER IS REMOVE FROM THERE	
78	Sabarmati Gandhinagar U Adalaj	Adalaj	Desai Ravibhai Virambhai	29-Jul-24	FAO	While going for eating leaves, the cow was roaming in the Bagaliya vas and she got electrocuted by the leakage current comes from street light service which contact with stay and flowing through stay set of LT pole	Yet not received			Stay Set was removed.LT maintenance Completed	
79	Sabarmati Bopal Shela	Kolat	Rabari Jivanbhai laxmanbhai	02-Aug-24	FAO	While buffalo was roaming at jivanpura kolat road nr shiv Shiva residency, buffalo was electrocuted by came in contact of broken LT conductor due to tree branch fallen on line	Yet not received			Power Supply Is Disconnected After Receiving Message And Tree Branch Fallen On LT Line Which is Removed. Also Line Rectified After Police Panchanama And PM	15000 on 9.10.24
80	Sabarmati Bopal Changodar	Visalpur	Ajitbhai Gandaji Thakor	09-Aug-24	FHO	On Date 09.08.24 @ 0740 hrs in the morning , Victim shri Ajitbhai Gandaji Thakor was working on the steel platform to get ON the power supply of Vibrator Needle , as soon as he put ON the switch of the Panel suddenly he collapsed and fell down on the platform and got unconscious, he was given primary treatment but he couldn't make it so he was taken to the Civil Hospital, Sola . Where he was declared dead by resident doctor As came to know yesterday only by police department, site visited by sdn today , i.e. on 21.08.24 As per statement of Eyewitness Shri Piyush hai Patel , he is not sure about Ajitbhai got electrocuted because right after the incident he checked the leakage on panel	Yet not received			ELCB installedl by consumer .	

81	Sabarmati Kalol Kalol-1	Arasodiya	Deepchand Manohardas Bavari	13-Aug-24	FHO	At place of accident 04,Amiganga socity renovation and extention of house under construction. victim was doing furniture work of first floor of above mention address. During furniture work victim pulled stainless steel pipe(approx 12 feet)from ground floor to first floor, near newly constructed stair. which is below existing 11 KV Marketyard feeder line. While Deepchand Manohardas Bavari was pulling stainless steel pipe from ground floor to first floor pipe came in contact with 11 KV line, he was electrocuted being taken to the hospital for treatment, where he declared as died.	Yet not received			CONNECTION DISCONNECTED AND NOTICE GIVEN FOR UNAUTHORISED CONSTRUCTION NEAR BY 11 KV MARKET YARD FDR.	
82	Sabarmati Bopal Bavla Ind	Dhedhal	Rathod Bharatbhai Punjabhai	14-Aug-24	FHO	On Date 14/8/24 in morning @ 1030 hrs , Due to Heavy water logging in Victim's House of Rajput vas of Dhedhal Village then Lt Shri Bharatbhai Punjabhai Rathod came in the house and was working to pumping out the water with a 1ph 1.6hp Motor in his house and suddenly he got shocked through his internal wiring. Fallen down and got electrocuted and died at site.	Yet not received			Connection is disconnected.	
83	Sabarmati Kalol Kalol T	Kalol	Karan Arjanbhai Salat	14-Jun-24	FHO	The victim was washing the tractor at work space area of Dhiraj Engineering , GIDC , Kalol by means of water tube connected to the three phase motor. Suddenly he got electric shock and fell on the ground. The nearby worker saw the situation and instantly switched off the motor and took him to the Nearby Private hospital where he was declared dead by the In charge doctor.	Yet not received			CONNECTION DISCONNECTED AND NOTICE GIVEN FOR ELCB INSTALLATION.	
84	Sabarmati Gandhinagar U Motera	Chandkheda	Goswami kaushikgiri rameshgiri	26-Aug-24	FHO	Illegal wire extension from RGP connection to Parlor , Parlor close & leakage current running in parlor, victims touch with parlor & got shocked & died.	Yet not received			Not applicable ..Inside Private Premises	
85	Sabarmati Gandhinagar U Motera	Chandkheda	Thakor Rohitji Prahladi	26-Aug-24	NFHO	Illegal wire extension from RGP connection to Parlor , Parlor close & leakage current running in parlor, victims touch with parlor & got shocked but no any causality with him as per eye witness statement.	Yet not received			Not applicable ..Inside Private Premises	
86	Sabarmati Bavla Koth	Gangad	Munjava Ganshyambhai Bholabhai	26-Aug-24	FAO	Due to Heavy wind and rain tree branch fallen on LT line of koth jgy emitting from 66kv koth ss so lt conductor broken and comes down from the baffelo.At the time baffelo is contact with live lt wire and got electrocuted and died.	Yet not received			DAMAGED LT LINE RECTIFIED	
87	Sabarmati Gandhinagar U Adalaj	Moti Adraj	Rabari Kismet Amrutbhai	26-Aug-24	FAO	While going for grass eating, one cow went to the left side of the road where 4W LT line was broken due to heavy rain and got electrocuted	Yet not received			Stay Set was removed.LT maintenance Completed	
88	Sabarmati Kalol Kalol-2	Navapura	Natubhai Raymalbhai Rabari	26-Aug-24	FAO	Conductor of phase wire of 2 wire line broken due to tree branch fallen on line due to heavy rain and thunderstorm. The buffalo was tied up in the enclosure below came to contact with broken conductor and got electrocuted and died.	Yet not received			Maintanance done of 11 KV Nvapura JGY feeder, and consumer aware for risk of tie any animal under the electric line.and instructed not to repeat the mistake.	15000 on 11.10.24
89	Sabarmati Bopal Sanand 1	SANAND	Ashok Girilal Parmar	26-Aug-24	FHO	As per statement of eyewitness there was heavy rain at sanand area on dt 26.8.24. Victim lt. Ashok Girilal Parmar was climbing on iron stairs which was inside the house and got electrocuted and died. The source of current and its path is not yet traced.	Yet not received			ELCB Installed	
90	Sabarmati Gandhinagar R Gandhinagar	Unava	Dinesh S Ambliya	27-Aug-24	NFHO	While attending 11kv jogmaya feeder fault.While going to cut baval tree near talav.Leg slip due to wet and water logging And felt down.Staff taken him to High tech hospital Gandhinagar for treatment As per Dr report fracture occured in leg near Ankle	Yet not received			NA	
91	Sabarmati Bavla Koth	Bagodara	Solanki Dineshbhai mohanbhai	27-Aug-24	FHO	In consumer promises out going flexible internal wire installation in house passing through the dor ,the dor section is alluminium, wire insulation damage due to many time open-close dor and damage wire contact with dor section at the time the victim is contact with alluminium dor and died on the spot due to electrocution.	Yet not received			IT IS OCCURED IN PRIVATE PREMISES & SAID CONNECTION CUT & INFORMED TO APPLY FOR NEW TEST REPORT.	
92	Sabarmati Gandhinagar U Ognaj	Jagatpur	Roshani Vijaybhai Bharathari	29-Aug-24	FHO	As per Eye witness statement and person available during panchnama , victim was doing floor cleaning work inside house With water , She was plugging 2 pin plug of table fan into switch board laid on speaker on floor of room and at the same time she got electrocuted. There is no ELCB installed in house. Victim was taken to nearest hospital for treatment and after short treatment doctor declared her dead.	Yet not received			Not applicable ..Inside Private Premises	
93	Sabarmati Bavla Dholka R	Chandisar	Ashokbhai Dhillajibhai Palat,EA	31-Aug-24	NFHD	On Dt:31.08.24 a LT complain was registered at Dholka R complain center by Phone from Chandubhai Hirabhai Kabira, 05 nos. Houses power off at Valmiki vas Village Chandisar. While attending complain after TC DO removed from particular X'mer anyhow victims leg slip from LT pole and he Fallen down on ground and injured.	Yet not received			WARNING MEMO ISSUED TO A.D.PALAT VIDE LETTER NO:- 871 ON DATED :- 26-09-2024 & SAME WARNING MEMO ISSUED TO R.H.BHOI VIDE LETTER NO:-872 ON DATED :- 26-09-2024	
94	Sabarmati Bavla Dholka T	Dholka	Pareshbhai Gafurbhai Rabari	01-Sep-24	FAO	Live LT line of trasad ag FDR conductor broken near Gimatex company (trasad road) while both cow was passing nearby live lt conductor area so got electrocuted and both cows died.	Yet not received			BROKEN LT.LINE WIRE RECTIFIED	30000 / 03-10-2024
95	Sabarmati Sabarmati Barejadi	Sadra	Harjibhai Sharkabhai Rabari	04-Sep-24	FAO	Herd of cow was gazing near TC structure as routine. Since many days heavy rainfall with heavy wind has blown and due to it service cable from Transformer LT side to terminal cable(for nearby 1 pH 2 wire LT lines)was broken and leakage current was flowing to earth through pole due to rain. And cow was gazing nearby TC structure and got electrocuted and cow died.	Yet not received			6SQM MM BROKEN SERVICE CABLE WAS REPLACED	
96	Sabarmati Bavla Koth	Bagodara	Boliya Vitthalbhai Bhurabhai	20-Aug-24	FAO	11 kv Loliya Ag line emitting from Bagodara 66 kv substation. The pole of the line fell down but power was ON, at that time the cow was grazing on that side and came in contact with a live conductor and died on the spot due to electrocution.	Yet not received			DAMAGED POLE RECTIFIED	
97	Sabarmati Kalol Chhatral	Billeshwarpura	Komalsinh Bindarsinh Gond	05-Sep-24	FHO	As per site visit victim working in factory he was trying to move the pedestal fan having iron body by his wet hand got electrocuted.he may electrocuted through either leakage from jointed wire near by fan body due to touching to fan or by holding jointed wire having insulated tape by wet hand. Actual cause of death will be decided after receiving of P. M. Report.thus the accident occurred at factory Side wiring.	Yet not received			CONNECTION DISCONNECTED AND NOTICE GIVEN FOR ELCB INSTALLATION.	
98	Sabarmati Sabarmati Kathwada	Kathwada	Pintu Kedar Mahto	05-Sep-24	FHO	As per eye witness statement, while working on buffing machine, the victim got electric shock from the motor and lost his life. But at site, we could not find any clue for leakage current from the motor.	Yet not received			DC DONE AND NEW TEST REPORT AWAITED FOR RECONNECTION	
99	Sabarmati Gandhinagar U Adalaj	Adalaj	Baldevbhai Sartanbhai Desai	06-Sep-24	FAO	A Live wire Flexible wire comes into its mouth ,While a Buffalo eating grass at shivpuri hudko Adalaj , she got electrocuted by the leakage current comes from flexible wire.	Yet not received			No any Action Taken required	
100	Sabarmati Gandhinagar R Dehgam T	Dehgam	Parbatsinh Punjaji Solanki	09-Sep-24	FAO	Herd of Buffalow was gazing near TC structure as routine. Since it was rainy season and ckt cable was jointed and leakage current was flowing through it to earthing wire through pole. And buffelo was gazing nearby TC structure and touch the Earthing wire and got electrocuted and died.	Yet not received			EARTHING REACTIVATED	
101	Sabarmati Gandhinagar R Gandhinagar	Randheja	Jaydip Gandbhai Patel	11-Sep-24	FHO	Due to short circuit of single pole MCB of domestic flour mill victim came in contact with metal part of flour mill with main switch in ON position got electrocuted and died.	Yet not received			ADVISE TO INSTALL ELCB FOR SAFETY PURPOSE	
102	Sabarmati Bopal Bavla Ind.	Nani Devti	Lavkush Rambhavan Nishad	15-Sep-24	FHO	As msg recieved from Police Station Sanand Police On dt.18.09.24 regarding Fatal human accident that on Dt.15.09.24 in night @ 2100 hrs , Victim was working inside his house and keeping his wet clothes on Iron string inside his house but by mistake he had connected iron string on live wire and got electrocuted and shifted to Civil Hospital Sanand where he had declared as Dead.	Yet not received			ELCB Installed	

103	Sabarmati Bopal Changodar	Moraiya	Prakashbhai Nanjibhai Nayak	29-Sep-24	FHO	On Date 29/09/24 @ 1100 hrs in the morning , Victim shri Prakashbhai was working for Giving water supply to the Astron Packaging by his Tractor with Tank , it was raining in the morning and water logged surrounding the tractor , he was getting empty his tank which was attached to the single phase Motor , as per saying of company's Employee he connect the wire of single ph motor to the MCCB near to the tank and made the power supply ON , after getting the supply ON he went back to his driver seat , as soon as he hold the handle pipe he might have got shock of electric current and fallen on the ground after giving him primary treatment at place immediately he was brought to Civil Hospital, Sola . Where he was declared dead by resident doctor. Exact cause of death can be said after receipt of Post Mortam report	Yet not received		Connection is disconnected.	
104	PLN,DEESA-1,DEESA R-2	JUNA DEESA AND RURAL	Mali (Parmar) Naitik Kumar Nalin Bhai	01.04.2024	FHO	As per Primairy report On site inspection at Village Juna Deesa in Farm land of Shri Mali Hira Bhai Pitamabar Bhai in this Land One Transformer in which Power feed From 11 kv Swami Ag Feeder From 66 kv Juna Deesa ss & One Installation room of A2 Conn.No.74326026782 in which three phase meter & load side Outgoing 3 Fuses,starter etc .in Farm Fencing done by using Wires around Farm Boundaries. any Illegal Person done Unauthorised connection by Using Extra Private Cable (Approx. 227.4 Meter) of size 2.5 SQ.MM Cable, this Extra Cable Connected between Outgoing Fuses of Ag Connections & fencing Wires,So Illegal Current flow in all wires of fencing in farm. on Date-01-04-2024 The victim was Passes toward fencing ,victim touch with Wire of fencing in which already electric current flow Due to Illegal Connection.Victim got electrocuted.Fallen in land and died on the spot.	Yet not received		inform consumer's not use unathorise power	
105	PLN,DEESA-1,DEESA R-2	JUNA DEESA AND RURAL	Thakor Jasvantsingh Khetaji (Urfe Udaysinh)	07.04.2024	FHO	Raval Hargovan Bhai Mafa bhai (Conn.no. 74326120967)house Power off Complain on date 07-04-2024,at evening around 19:00 p.m.,Consumer's wife Surya ben Raval Seen that Jasvantsingh (urfe Udaysinh) going on the road & informing Javantsingh for her house power off Complain, then Jasvantsingh Shows that 1 Wire of Cable got loose (i.e.seperate) from LT Pole, then Jasvantsingh was climbing with taking iron stand for lag support which is insert on top hall of Electric LT pole ,then he take a position on iron stand for repair the loose cable wire ,he suddenly sleeping due to unbalanced iron stand & fall down on land badly & injured on Right back of head ,victim dead on spot at around 19:00 p.m.	Yet not received		inform consumer's not to touch any electrical wire	
106	PLN,SIDHPUR,SIDHPUR R-T	SIDHPUR AND URBAN	Thakor Haresh kumar Jivan bhai	21.04.2024	FHO	During Site observation it is found that 11KV Ambaji Feeder is passing from Dethali Circle to Dethali road & near to Shivanagar Society Main gate . There was marriage function in house of Shri Bharatbhai Laxman bhai thakor. During marriage wedding hall/ mandap was built up near the 11 KV Ambaji feeder urban feeder. After completing marriage dismantling work of mandap/weeding hall was continue and dismantling work carried out by Haresh kumar Jivanji Thakor & on that time dismantled big Iron pld was trying to put in Pick up dala by Haresh kumar Thakor . & dismantled IRON PIPE was touched with 11 KV Ambaji Urban Feeder & got electric Shock & he injured & refer to hospital at Sidhpur Civil found he was died .	Yet not received		inform consumer's not to touch any electrical wire	
107	PLN,PLN-2,DANTA	MOR DUNGARA AND RURAL	Dabhi Karniben Ashvinbhai & Dabhi Divaben Ashvinbhai	05.04.2024	FHO	As per site visit private black colour twin core cable used for 1 ph motor starter which is binding on swing and this cable end side both phase and neutral open from starter contact and touched to iron swing and 3 nos. OF Girls electrocuted. Which are swinging on swing. This private cable coming from consumer load side near by rooms where our 1 ph meter is provided, so UGVCL is not responsible for this accident.	Yet not received		aware consumer to use ELCB	
108	PLN,SIDHPUR,SIDHPUR R-R	KAHODA AND RURAL	THAKOR KIRANKUMAR VELAJI	17.05.2024	FHO	ON DTD:17.05.2024 ,APPROX TIME: 04:00 A.M. SHRI THAKOR KIRANKUMAR VELAJI VICTIM IS EARLY MORNING GO TO WASHROOM THAT'S TIME VICTIM TOUCHED GI VARGADI AND GI VARGADI FITTED WITH IRON ANGLE OF HOUSE SHED AND IN HOUSE THAKOR JESHAI NATHAJI LEAKAGE CURRENT FLOW BECAUSE OF CEILING FAN IS SHORT AND POWER SUPPLY ON THAT'S TIME PROBABILITY VICTIM GOT ELECTROCUTED AND FATAL ELECTRICAL ACCIDENT OCCURED AND DIED.	Yet not received		aware consumer to use ELCB	
109	PLN,DEESA-1,SHIHORI	JAMANAPADAR AND RURAL	Bhiliadiya Ashwinji Paraji,Bhiliadiya Kiranji Panjiji,Dhumadiya Shivaji Babuji	13.05.2024	NFHO	As per telephonic message received from line staff at 11.00 am about non fatal human outsider accident occured at vill. Jamanapadar, Dy engg Shihori personally visit the site and as per eye witness statement at site a live DJ with vehicle Eischer passing from Deliyathara to Jamanapadar to attend marriage function, at that time at approximately 10.25 hrs live DJ with vehicle passing from road in front of Thakor Padji Virchandaji farm house at village Jamnapadar. At that time of live DJ program all the people enjoying dance program on live DJ vehicle, at that time Shri Bhildiya Kiranji Panjiji who climbed on DJ set which was set up on vehicle, came in live contact with 11 KV Panna Ag feeder line crossing through road and other two victims Bhildiya Ashwinji Paraji and Dhumadiya Shivaji Babuji who also in physical contact with Bhildiya Kiranji Panjiji got electrocuted.	Yet not received		inform consumer's not to touch any electrical wire	
110	PLN,DEESA-1,SHIHORI	UMBARI AND RURAL	(Buffalow-01) Thakor Sangramaji Gumji	29.05.2024	FAO	As per telephonic message received from line staff at 10.00 am about fatal animal accident occured at vill. Umbari , Dy engg Shihori personally visit the site and as per eye witness statement, at approximately 7.00 am when he was brushing conductor of Ag 3ph4w Lt line passing near his house was broken due to wind and fall on a Buffalo eating grass under Lt line. Live Broken conductor snapped and fall on Buffalo and due to this buffalo got electrocuted on her stomach portion and died immediately on the spot.	Yet not received		To Avoid Any More Unwanted An Electrical Accident Our Line Staff Had Been Repaired Broken Conductor And Repaired Wire Restrstring Also Done.	
111	PLN,PLN-1,PLN-T	PALANPUR AND URBAN	Lalabhai Gajrabhai Kharadi-Contractor Labour-Age 19 years aprox	09.05.2024	NFHO	The Fatal Human (outsider-Contractor Labour) Electrical Accident occurred while replacement of deteriorated pole at Oad was after dismentalling of service lines and LT line conductor from old deteriorated pole by contractor labour shri Lalabhai Gajrabhai Kharadi , New LT pole was erected than after while stringing of LT line conductor again by contractor labour shri Kharadi Lalabhai Gajrabhai suddenly he felt induction and got electric shock. Immediately he admitted to civil hospital for further treatment and after primary treatment he discharged from hospital. No any current burn on body,only experience of iur , no any type of injury.	Yet not received		work with safety	
112	PLN,PLN-1,PLN-T	PALANPUR AND URBAN	PATNI ROHITKUMAR PAPPUBHAI-OUTSIDER-AGE 09 YEAR APROX	30.05.2024	FHO	The Fatal Human (outsider) Electrical Accident occurred in private premises (in Home) of shri Ishwarbhai Raymalbhai Patni, Consumer No: 70106/10904/9 to Shri Rohitkumar Pappubhai Patni due to leakage current flows from faulty ceiling fan to iron shed in home and victim was touches the iron string tied up with iron sheet shed pole in home and victim got electric shock and died.	Yet not received		aware consumer to use ELCB	
113	PLN,DEESA-2,PANTHA WADA	GUNDARI AND RURAL	Dhanaram Nebaram Meghwal	03.05.2024	FHO	Fatal Human Outer side electric accident was occurred on dated 03.05.2024 around 8:30 am at Gundari .Duringsite observationit is found that temporary connection of Shri Kanaksing Karatngsing Thakor exist at PanthawadaGundri highway in front of Police check post, after Ugvcl meter and MCB, private black colour twin core cable and flexible cable used for operation of uria pump and other lightning work, which is clamping with iron frame of uria pump machine structure and also adjoining lightning pole where led focus lamp installed. Moreover, lightning pole structure tightening by iron wire (used as stay) which is joint with nearby uria tank iron frame stand. Due to leakage current in private cable/wire in lightning pole structure which is connected with uria tank frame by iron wire , victim touched the uria tank iron frame and got electric shock and died	Yet not received		aware consumer to use ELCB	
114	PLN,DEESA-2,ZERDA	BHADATH AND RURAL	Sonalben Hathising Vaghela	18.05.2024	FHO	As per daily news paper Press note ,accident occurred on dated:18.05.2024 but no one informed to UGVCL office.After Press note report Site visited by SDO,Zerda on dated:03.06.2024 but due to Suicide case,no further information found at that time and second time visited on 13.06.2024.As per Victim father's statements Sonalben herself Climbed on 11 KV Baiwada Ag feeder(single phase time) at location no:125/24/20/3 in their farm.As per PM report ,Cardio-Respiratory arrest due to heavy electric burn, she was died.Final Cause of death is pending on F.S.L. report.	Yet not received		inform consumer's not to touch any electrical wire	
115	PLN,PLN-2,DANTA	RANGPUR AND RURAL	Chauhan Kiranbhai Ishvarbhai	05.06.2024	NFH MECHANICAL -DEPT.	As per statement of victim and other line staff working on 11 KV Rangpur AG feeder Provide New Shacke with Switch. During working two line staff working on pole one Top phase work complete after work on side phase victim suddenly feel induction or by any others reason and fallen from v cross arms of pole and hanging on pole by safety belt after help with other staff victim remove from safety belt and down on ground after that for medical treatment admit at private hospital Satlasna now victim health is stable other EA working on pole is safe no any induction zone	Yet not received		work with safety	
116	PLN,SIDHPUR,UNJHAR	UNAVA AND RURAL	NAVNIKUMAR AMRABHAI KHANT	07.06.2024	NFH MECHANICAL -DEPT.	ON DTD 7.06.02024 AT AROUND 5:45PM SHRI NAVNIKUMAR AMRABHAI KHANT WAS STRINGING A 2CORE 4MM CABLE AND GI WIRE OF SERVICE CONNECTION OF EXISTING SINGLE PHASE CONNECTION OF SHRI BABULAL PRAHLADBHAI MEWADA (CONS NO:22301002624) AT UNAVA.DURING STRINGING A GI WIRE GETS BROKEN AND VICTIM LOST HIS BALANCE AND FELL DOWN ON GROUND AND GET INJURED.ESS.	Yet not received		work with safety	
117	PLN,PLN-2,AMBAJI	NAVAVASKANTHA AND RURAL	(01 BULLOCK) Gamar Vinodbhai Ajkabhai	22.06.2024	FAO	Due to rain and heavy wind, big pipal tree broken and fall on AG LT Wire and LT wire broken from Pole ,both tree and LT wire fall on bullock and it had *major head stock by tree branch and Bullock directly connect with live LT conductor* and get shocked than after died. Final reason Will be clarified after Pm Report	Yet not received		At accident spot the tree cutting work done. Also in all span of It wire conductor stringing work done and all conductor properly tightening with It shackle insulator.	
118	PLN,PLN-2,AMBAJI	BAMNOJ AND RURAL	(01 COW) Kodarvi Rameshbhai Bhudabhai	25.06.2024	FAO	During heavy rain,a cow eating a grass near by village TC ,cow got electrocuted due to ground voltage difference leakage current paas and died.Final conclude after PM report.	Yet not received		Remove the leakage current	15000/20.08.24
119	PLN,PLN-1,GADH	MADANA AND RURAL	UNKNOWN UNIDENTIFIED MALE PERSON	28.06.2024	FHO	AN UNIDENTIFIED MALE PERSON HMSELF CLIMB ON 11 KV SALLA FEEDER POLE LOCATION NO 91/6 DUE TO ANY REASON AND CAME WITH CONTACT OF 11 KV SALLA FEEDER LIVE CONDUCTOR AND DIED.	Yet not received		inform consumer's not to touch any electrical wire	10000
120	PLN,DANTIWADA	VELAVAS AND RURAL	BHUTADIYA PARTHIBHAI LAXMANBHAI AGE-65 YEARS APPRX	29.06.2024	FHO	AS PER FIRST EYE WITNESS STATEMENT , VICTIM SHRI BHUTADIYA PARTHIBHAI LAXMANBHAI WENT TO START THE MOTOR OF AGRICULTURAL CONNECTION NO-70930/00113/3 (A1 CATEGORY) AND WHILE VICTIM WAS OPERATING THE FUSE MAY CAME IN CONTACT WITH LIVE PART OF FUSE AND GOT ELECTROCUTED AND DIED. VICTIM WAS IMMEDIATELY SHIFTED TO CHC DANTIWADA AND WAS DECLARED DEAD	Yet not received		inform consumer's not to touch any electrical wire	

121	PLN,SIDHPUR,SIDHPU R-R	BHUNAV AND RURAL	THAKOR JIVANJI MANAJI	17.07.2024	FHO	ON DATED:17.07.2024 APPROX TIME:06:30 P.M SHRI THAKOR JIVANJI MONAJI WORK VICTIM WAS WET BATHROOMAL PUT ON ALUMINIUM GI VARGADI,BUT GI VARGADI FITTED AT ONE POINT WITH IRON ROD ELECTRIC ROOM OF PATEL MANILAL RAMDAS AND IRON ROD CONTACT WITH OPEN PHASE WIRE INTO SWITCH BOARD TO LED BULB THAT'S TIME VICTIM TOUCH GI VARGADI AND OPEN PHASE WIRE CONTACT WITH IRON ROD CURRENT FLOW POWER SUPPLY ON THAT'S TIME PROBABILITY VICTIM GOT ELECTROCUTED AND FATAL ELECTRICAL ACCIDENT OCCURED AND DIED.AND HIS DAUGHTER CAME TO SAVE BUT THAT'S TIME CURRENT FLOW IN THAKOR DAXABEN JIVANJI.	Yet not received			aware consumer to use ELCB	
122	PLN,DEESA 2,DHANERA 2	MANDAL AND RURAL	Rishipalsinh Sujansinh Solanki	10.07.2024	FHO	As per site visited & Farm owner's Son Shri Narpatsinh statement Ag flat tariff Ag Connection no 71425000924 is running in his father name Solanki Savsibhai Versibhai.fencing done around Agriculture land which is farming by Narpatsinh.He has illegle flexible single core wire connected from Ag(A1)connection on fencing instead of Zatka machine and Current passes in fencing,Victim Solanki Rishipalsinh Sujansinh came in contact with live power fencing and died on the spot	Yet not received			inform consumer's not to touch any electrical wire	
123	PLN,PLN-1,GADH	SASAM AND RURAL	Mukeshji Mafaji Bokarvadiya (Thakor)	04.07.2024	FHO	As per information received from social media, Shri Mukeshji Mafaji Bokarvadiya (Thakor) got electric shock due to came in contact with iron pipe.this leakagr current flow through a NRGp Connection Consumer number: 70742/10018/9 private wire given to outside shop cabin and this private wire hanging on iron aple ,in detail investigation, this private wire insulation punctured touch with angle and victim came in contact with private iron pole connected with this angle and got electric shock & died	Yet not received			aware consumer to use ELCB	
124	PLN,PLN-1,PLN-R	BANASDAIRY ,LALAWADA AND RURAL	Pritambhai Kamleshbhai Raval	15.07.2024	FHO	Ondate: 15.07.2024 , 10:30 AM (Approx time) a private person of Vendor replacing valve in butter -2 plant of Banas dairy, Palanpur. At the working site insulation of phase wire of tubelight power supply found damaged and live phase wire found open, unfrtunately the said person during work came in contact with this live phase of wire and got electrocuted.	Yet not received			aware consumer to use ELCB	
125	PLN,PLN-2,VADGAM	IQBALGADH AND RURAL	Harssadbhai Savjibhai Chaudhary (33years)	06.07.2024	NFHD	onsumer no 70306/10060/6, After removing DO fuse from Separate Transformer , Victim climb on maintenance of 2 core cable and giving new connection on LT side of transformer, A flying peacock is strike on in between DO , So victim got momentary current on his right hand , and burns on his right hand also.the . Victims may came in contact with LT side stud and may got current , So victim is got treatment at Narendra Chaudhary Ankur hospital and Anil D Suthar Ravi surgical Hospital Visnagar for primary medical treatment. .Health conditions of victim is fine currently.	Yet not received			work with safety	
126	PLN,SIDHPUR,UNJHAR	MAHERWADA AND RURAL	(1) THAKOR ARUNABEN SURESHJI (2) THAKOR ARUNABEN SURESHJI	02.07.2024	NFHO	ON DTD 2.07.2024 (11:00PM)IN THE HOUSE OF THAKOR KANAJI KUVARJI FLEXIBLE WIRE WAS WINDED AROUND ROOF SUPPERT MADE OF IRON.DUE TO DAMAGED INSULATION OF FLEXIBLE WIRE CURRENT START TO FLOW IN THE IRON ROOF AND MAIN DOOR MADE OF IRON.AT THE TIME VICTIMS CAME IN CONTACT WITH THE DOOR AND GOT ELECTROCUTED SO FATAL ELECTRICAL ACCIDENT OCCURED.	Yet not received			aware consumer to use ELCB	
127	PLN,DEESA 2,LAKHANI	CHITRODA AND RURAL	Chauhan Kiranbhai Ishvarbhai	18.08.2024	FHO	One bat(Chamachidiyu)bird sitted on LT line wire and short circuit occurred between three LT wire and one LT wire conductor broken near pole side.Victim at that time working in tabela of buffalo and broken wire fallen on Thakor Balvantji Rupshiji and died on the spot.	Yet not received			To Avoid Any More Unwanted An Electrical Accident Our Line Staff Had Been Repaired Broken Conductor And Repaired Wire Restrindina Also Done.	
128	PLN,RADHANPUR,RADHANPUR R-2	RADHANPUR AND RURAL	NARSANGBHAI GOVBABHAI CHOUDHARY	08.04.2024	FAO	A FATAL ANIMAL ELECTRICAL OUTSIDER ACCIDENT OCCURRED DUE TO CONDUCTOR OF 11 KV JAVANTRI AG FDR GOT BROKEN AT THE PLACE OF INCIDENT AND IT FELL ON GRASS (JAR PULA) THE FDR GOT TRIPPED BUT AS A ROUTINE FDR TRY WAS TAKEN TO RESTORE POWER SUPPLY AND THE GRASS UNDER THE LINE FIRE.THE SPREAD THE FIRE TO ADJACENT BUFFALOW HOUSE WHOSE ROOF COVERED WITH GRASS AS PER EYE WITNESS STATEMENT THE INTESITY OF FIRE WAS HIGH SO UNABLE TO HELP POOR BUFFALOW AND BOTH BUFFALOWS DIED BY SHOCK DECLARE BY POST MORTEM REPORT.	Yet not received			To Avoid Any More Unwanted An Electrical Accident Our Line Staff Had Been Repaired Broken Conductor And Repaired Wire Restrinding Also Done.	
129	PLN,RADHANPUR,DEODAR 2	CHIBHDA AND RURAL	SONI ROHITBHAI NAGJIBHAI	13.05.2024	FHO	AS PER PRESSNOTE IN SANDESH NEWS PAPER (BANASKANTHA AVRUTI) ON DTD 15.05.2024 ABOUT FATAL HUMAN ACCIDENT AS PER SITE VISITED ACCIDENT TOOK PLACE IN THE PREMISES OF SHRI SONI MERUMAL KALIDAS HAVING CONSUMER NO. 73934001637 AT METER INSTALLATION CONSUMER HAS INSTALLED THE ELCB WHICH ARE NOT CONNECTED WITH EARTHING WIRE ON DTD 13.05.2024 LATE SHRI SONI ROHITBHAI NAGJIBHAI PLAN TO DRAIN THE WATER WHICH ARE LOGGING NEAR BATHROOM SIDE HE WAS DRILLING THE WALL BY DRILL MACHINE WHOSE BODY ARE FULLY COVERED BY METAL HE WAS HANDELLING THE DRILL MACHINE WITHOUT HAND GLOVES AND SHOES AND SAME TIME LAND WAS WET DUE TO CYCLONE .HE HAD PLUGGED MACHINE FROM NEAR BY PLUG POINT IN HOUSE AS HE HAD SWITCH ON THE DRILL MACHINE FAULT HE GOT THE ELECTRIC SHOCK AND ELECTROCUTED AND LAID DOWN THE SPOT THIS ACCIDENT TOOK PLACE INSIDE THE CONSUMER PREMISESAND AFTER THE UGVCL METER INSTALLATION.	Yet not received			Use ELCB connected with earthing	
130	PLN,RADHANPUR,RADHANPUR 1	BHILOT AND RURAL	AHLETAR JASWANTKUMAR KANJIBHAI	18.05.2024	NFH MECHANICAL-DEPT.	AS PER STATEMENT OF EYE WITNESS & SUPERVISOR WHILE ATTENDING COMPLAIN REGARDING POWER OFF IN TWO AG CONNECTION BEING FED FROM 11 KV RANGPURA AG FDR THERE WAS ONE NEEM TREE BRANCH FOUND FALLEN ON THIS 11 KV LINE SUPERVISOR TOOK LC FROM 66 KV DAISAR SS AT TIME 12:45 & ALSO SHACKLE POINT JUMPER ALREADY CUTTED AT LOCATION NO.RANGPURA AG/92/41/32/18/5 AS IT WAS REQUIRED TO CUT NEEM TREE VICTIM CLIMBED ON THIS TREE TO CUT ITS BRANCH AND WHILE DOING SO A SQUIRREL SUDDENLY CAME IN TOUCH WITH HIS LEG AND HE LOST HIS BALANCE AND FELL DOWN FROM A TREE FROM HEIGHT @15 FEET AND VICTIM MEET AN UNFORTUNATE NON FATAL MECHANICAL ACCIDENT	Yet not received			work with safety	
131	PLN,RADHANPUR,THARA	BHADREVADI AND RURAL	DESAI ASHISH SAVABHAI	05.06.2024	NFHO	AS PER THE STATEMENT OF EYE WITNESS AT VILL BHADREWADI NEAR DUDH MANDALI WHERE 11 KV SHIYA AG FDR PASSES FROM THE FRONT SIDE OF THIS DAIRY IN MORNING TODAY AT @ 10:45 AM A VEHICLE OF BANAS DAIRY VEHICLE NO GJ 213 Y5404 CAME TO FILL UP THE MILK STORED IN THIS DAIRY WITH NEW DRIVER AND CLEANER AND THEY PARK THIS VEHICLE EXACTLY BELOW THIS EXT HT LINE OF 11 KV SHIYA AG FDR AS PER EYE WITNESS A CLEANER CLIMBED ON VEHICLE TO OPEN A CAP OF MILK TANK WITH A MONKEY WALK SO AS TO FILL UP MILK AND WHILE REACHING NEAR CAP VICTIM SUDDENLY STOOD UP AND THERE HIS HEAD CAME IN CONTACT WITH LIVE CONDUCTOR A WHILE SPARK WAS OBSERVED IN TYRE AND VICTIM GOT ELECTROCUTED AND FELL DOWN AND MEET AN UNFORTUNATE NON FATAL ELECTRICAL ACCIDENT.	Yet not received			inform consumer's not to touch any electrical wire	
132	PLN,RADHANPUR,RADHANPUR R-2	CHHANİYATHAR AND RURAL	BHARWAD VISNUBHAI BHAGABHAI	29.08.2024	FAO	RAINY SEASON DUE TO HEAVY WIND AND RAIN LT CONDUCTOR BROKEN AND ONE NO COW CAME IN CONTACT WITH LIVE BROKEN CONDUCTOR AND ELECTROCUTED AND DIED ON SPOT	Yet not received			To Avoid Any More Unwanted An Electrical Accident Our Line Staff Had Been Repaired Broken Conductor And Repaired Wire Restrinding Also Done.	1500/03.09.24
133	PLN,RADHANPUR,RADHANPUR R-2	JUNA PORANA AND RURAL	RABARI HEMABHAI GOVINDBHAI	29.08.2024	FAO	RAINY SEASON DUE TO HEAVY WIND AND RAIN LT CONDUCTOR BROKEN AND ONE NO COW CAME IN CONTACT WITH LIVE BROKEN CONDUCTOR AND ELECTROCUTED AND DIED ON SPOT	Yet not received			To Avoid Any More Unwanted An Electrical Accident Our Line Staff Had Been Repaired Broken Conductor And Repaired Wire Restrinding Also Done.	1500/03.09.24
134	PLN,PLN-2,DANTA	KANBIYAVAS AND RURAL	Lalabhai Dharmabhai Pargi	28.08.2024	FAO	As per eye witness statement during there was continues heavy rain with wind snapping of LT wire on farm and Buffalo grazing on farm and come in contact with live wire and got electrocuted. Due to that PM is awaited and detail investigation would be carried out after PM report received.	Yet not received			To Avoid Any More Unwanted An Electrical Accident Our Line Staff Had Been Repaired Broken Conductor And Repaired Wire Restrinding Also Done.	15000
135	PLN,DEESA-1,BHILDI	MOTI GHARNAL AND RURAL	1) Rupsang Parthiji Solanki (Thakor)-FH 2) Panchai Chothabhai Babubhai- NFH 3) Panchai Chetanbhai Choitabhai-NFH	16.08.2024	FHO-1 NFHO-2	During the construction of a cattle shed at the site, the victim attempted to erect an angle or channel to support the structure. Unfortunately, the angle/channel inadvertently came into contact with a nearby high-tension (HT) line associated with the Chitroda AG feeder. As a result, the victim received a severe electric shock.	Yet not received			inform consumer's not to touch any electrical wire	

136	PLN,DEESA-1,DEESA R-2	NAVA AND RURAL	1) PARMAR(THAKOR) PARJIJI VELAJI'S COW	28.08.2024	FAO	During rain and due to wind in morning, Dry Acacia tree branch fall on LT line so 1 LT wire broken and fallen on land in between cow of shri thakor parjiiji velaji passes on this broken wire and got electrocuted and died on the spot	Yet not received			At accident spot the tree cutting work done. Also in all span of It wire conductor stringing work done and all conductor properly tightening with It shackle insulator.	
137	PLN,SIDHPUR,KAKOSHI	KAKOSHI AND RURAL	THAKOR VIKESHJI VANAJI	10.08.2024	NFHO	LM Shri M P Baranada(work supervisor) of Kakoshi City has started the work for ground clereance maintaining work of 11 KV Kakoshi JGY Feeder by power Off through operating of AB Switch . After erection work completion of HT Line, shri M P Baranda informed to contractor Gang leader that he is restoring the power supply of 11 KV Kakoshi JGY feeder and then we will start the work of LT Line.After ward he, Shri M P Baranda gone to AB Switch operation. Mean while Contractor Gang leader start the work without any presence & inform to UGVCL supervisor and Contractor labour climbed on LT Pole of 11 KV Kakoshi JGY feeder and start the work of opening of LT binding. In between LM shri MP Baranda has restored the power of 11 KV Kakoshi JGY Feeder by operateine AB Switch. hence victium has electrocuted.	Yet not received			inform supervisor before work start	
138	PLN,SIDHPUR,UNJHAR	AITHOR AND RURAL	THAKOR KAJALBEN GOVINDJI	09.08.2024	FHO	AT AITHOR VILLAG IN THE HOUSE OF THAKOR VALAJI AMTHAJI ON THE SUPPORT ANGLE OF ROOF AN IRON WIRE IS TIGHTENED AND TWO CORE PRIVATE CABLE OF INTERNAL OPEN WIRING IS PASSING ON THE SAME IRON ANGLE.DUE TO DETERIORATION OF INSULATION OF TWO CORE CABLE LIVE PHASE WIRE GET SHORT WITH THE IRON WIRE AND CURRENT STARTED TO FLOW FROM IRON WIRE.ON DTD 9.08.2024 AT AROUND 9:00PM THAKOR KAJALBEN GOVINDJI CAME IN CONTACT WITH THE LIVE IRON WIRE AND GOT ELECTROCUTED AND DIED.	Yet not received			aware consumer to use ELCB	
139	PLN,RADHANPUR,VARAHI	JARUSHA AND RURAL	SIPAI HANIFBHAI ABRAHMBHAI	28.08.2024	FAO	RAINY SEASON DUE TO HEAVY WIND AND RAIN LT CONDUCTOR BETWEEN AND OUTGOING NEUTRAL WIRE OF LT CONDUCTOR BROKEN AND BUFFALOW CAME IN CONTACT WITH LIVE BROKEN CONDUCTOR AND ELECTROCUTED AND DIED ON SPOT.	Yet not received			To Avoid Any More Unwanted An Electrical Accident Our Line Staff Had Been Repaired Broken Conductor And Repaired Wire Restrining Also Done.	1500/03.09.24
140	PLN,PLN-1,GADH	SAGROSANA AND RURAL	(1) Judal Manjibhai Rajsangbhai (2) Judal Bhikhiben Manjibhai	01.09.2024	FHO	As per received First information of accident by pressnote in Divyabhaskar News Paper on Dtd 03.09.24, DE Gadh sdn has visited site and as per Eye witness Statement it is state that on dtd 01.09.24 time approx 5.30 am Shri Manjibhai Rajsangbhai Judal-Husband & his wife Shrimati Bhikhiben Manjibhai Judal went to his farm at sagrosana village and those both victims are came with contact of Zatk machine wire which are wired between headland (SHEDHA) of his own farm as per eye witness at that time rainy season. 11KV Sagrosana agriculture feeder line is 30 meter away from accident place without any creeper on pole and no any LT line OR other UGVCL Network near by accident place.One agricultural connection is 100 meter away from accident place	Yet not received			inform consumer's not use unathorise power	
141	PLN,PLN-1,PLN-T	PALANPUR AND URBAN	Rajubhai Natwarlal Joshi-Age-51 years,Lineman, Employee No:6651	17.09.2024	NFHD (Mechanical)	The Non Fatal Mechanical accident occurred to Shri R N Joshi,LM During cable replacement work of consumer Patel Daxaben Hareshbhai, conn No:70101/10180/5, Pvt Waterworks. While working on an Iron ladder (Ghoda) to replace a cable, he suddenly lost his balance by any reason and fell down to the ground. So,He was taken to Gokul Hospital for medical treatment . And the heel of the Left Leg is fractured. Then, He is discharged and advised to rest.	Yet not received			work with safety	
142	PLN,DEESA-1,DEESA -T	DEESA AND URBAN	BADARSINH ISHVARSINH CHUNDAVAT	26.09.2024	FHO	When sudden rain and cyclone came, LT wire broken and fell on his Icecream lorry at that location of sid tc, victim touched to this LT conductor for make away from his lorry and came in contact with live line and got shocked and met with non fatal human accident then he was shifted to hospital by nearby public where after some time he was declared as dead so converted in fatal accident.	Yet not received			To Avoid Any More Unwanted An Electrical Accident Our Line Staff Had Been Repaired Broken Conductor And Repaired Wire Restrining Also Done.	
143	PLN,DEESA 2,RAH	MORTHAL AND RURAL	Surekhaben Ashokbhai Mali	11.09.2024	FHO	fatal human accident outsider occurred approximately 09:15 A.M to Mali Surekhaben Ashokbhai, Age – 30 Years on Dated –11.09.2024 at Village –Morthal, Ta – Tharad On Dated 11.09.2024, Surekhaben was electrocuted when she was plugging the open wire (Without Plug) of Valona in to the plug in the switch board Filled in her House for buttermilk churn.The house in which the electrical accident occurred, There is no any UGVCL Connection exist but they are using power from nearby Residential farm house Connection of shri MALI BABUJI SAVAJI through extended about 15 mtr black color 2 – core wire.	Yet not received			aware consumer to use ELCB	
144	PLN,DEESA 2,DHANERA 2	BHATIB AND RURAL	BUFFALOW OF LAVAR KANTIBHAI MANJIBHAI	13.09.2024	FAO	As per site visited & talk with the EA, there was one load side line conductor of 11 KV Manthan AG Feder (under 3-ph power Schedule Bhatip s/s) broken from shackle insulator (tapping pole no: 23/1) fall down in small pond so feeder tripped . After few minutes, No any message received from field , So Sub station staff has taken Second try of feeder to ON but feeder not ON but at the time of feeder's Second try one Buffalo was came in contact with broken Conductor which was lay down in small pond. buffalo was came in contact with load side conductor and due to return power of feeder , Buffalo got electric shock and died on the spot . But feeder was not tripped from Sub station side due to return conductor broken.	Yet not received			To Avoid Any More Unwanted An Electrical Accident Our Line Staff Had Been Repaired Broken Conductor And Repaired Wire Restrining Also Done.	1500
145	PLN,RADHANPUR,THARA	BHALGAM AND RURAL	VIMLABA VINUBHA VAGHELA	11.08.2024	FAO	AT @9:30 AM IT WAS FOUND THAT MINOR LEAKAGE CURRENT FLOW IN EARTHING OF BHALGAM VILLAGE TC WHERE TRY OF LT POLE SUPPORTED WHICH ALSO HAVING SUPPORT OF FENCING DUE TO THAT LEAKAGE CIRENT PASSES THROUGH IN MORNING COW WHICH TRY TO PASSES BETN NARROW PASSAGE BETN WALL AND FENCING GOT ELECTROCUTED AND MET WITH FATAL ELECTRICAL ACCIDENT .	Yet not received			Remove the leakage current	
146	PLN,RADHANPUR,THARA	BHALGAM AND RURAL	MUNECHA (BHANGI)JITUBHAI JYANTIBHAI	09.08.2024	FAO	AT @11.05 AM IT WAS FOUND THAT DUE TO HEAVY WIND TREE BRANCHES FALLEN ON LT LINE OF BHALGAM VILLAGE TC AND LT LINE OF OF VILLAGE TC CONDUCTOR SNAPPED DURING THAT TIME THE CALF WAS PASSING FROM THERE WHERE IT CAME IN CONTACT WITH BROKEN CONDUCTOR AND GOT ELECTROCUTED AND MET WITH FATAL ACCIDENT .	Yet not received			At accident spot the tree cutting work done. Also in all span of It wire conductor stringing work done and all conductor properly tightening with It shackle insulator.	
147	PLN,SIDHPUR,SIDHPUR-T	SIDHPUR AND URBAN	Prajapati Pankaj Kumar Dhanjibhai (Electrical Assistant)	18.09.2024	NFHD (Mechanical)	A non fatal Mechanical Departmental accident occurred to Shri.P.D.Prajapati EA while attaining complain of Shri Lokhandwala Hamida husain consumer no-22207004791. An Iron Stand was placed between 3rd & 4th step of PSc pole(Approximately height 3to 3.5 meter from ground & victim was trying to climb on PSc pole for attending service replacement Complain of Shri. Lokhandwala Hamida Hussain during that time his right lag slipped from PSc pole & fall down & injured his left hand.	Yet not received			work with safety	
148	PLN,SIDHPUR,SIDHPUR-R	BHUNAV AND RURAL	THAKOR BHARATJI PRAHLADJI	24.09.2024	FAO	In bHUNAV village near matsiya mahadev Temple near Transformer cetnre of 11 kv Kahoda Telephone Jgy feeder Loc no.108/2,Shri Thakor Bharatji Prahladij's buffalo came to drink water in artificial reservoir at near Transformer cetnre,at that time buffalo might came in contact with Leakage current flowing from Post office electrical equipment shot ann monkey jump on neutral cable break and touch with stay wire and During drinking water in reservoir buffalo might got shocked and died in the Reservoir.	Yet not received			Remove the leakage current	
149	PLN,SIDHPUR,CHHAPI	NALASAR AND RURAL	(1) ANGARI LALABHAI CHANDUBHAI AGE-41 YEARS (2) ANGARI DILIPBHAI URFE KALUBHAI CHANDUBHAI AGE 41 YRS RES-AT VILL-PIPALIYA,TA-POSHINA,SABARKANTHA	08.09.2024	FHO	AS PER STATEMENT OF LAND OWNER SHRI DALSANGBHAI LALIBHAI CHAUDHARY & POLICE STATION REPORT ON DTD:08.09.2024, APPROX TIME: 00.30 A.M. VICTIM SHRI LALABHAI CHANDUBHAI ANGARI & DILIPBHAI URFE KALUBHAI CHANDUBHAI ANGARI WAS COME IN CONTACT WITH THE WIRE IN WHICH THE ELECTRIC CURRET PASSES GOT SHOCKED AND DIED ON THE SPOT.THE CURRENT WAS COME FROM THE ZATKA MACHINE PUT BY FARMER TO AVOID DAMAGE IN FARM DUE TO ANIMALS.IN THE MORNING THE RELATIVES OF BOTH VICTIMS WERE COME & INFORM TO CHHAPI POLICE STATION & VICTIM WERE TAKEN TO VADGAM CIVIL HOSPITAL FOR PM.	Yet not received				
150	PLN,PLN-2,DANTA	KUNDEL AND RURAL	Ajaybhai Monabhai Saragra	06.08.2024	FHO	As per eye witness statement victim doing water heating in steel basket by electric heater and leakage current flow in water that time victim touch to basket and got electrocuted	Yet not received			aware consumer to use ELCB	
151	PLN,PLN-2,AMBAJI	JETVAS AND RURAL	Jitendrakumar Ramanbhai Solanki	16.09.2024	NFHO	As per eye witness statement solanki Jitendrakumar Ramanbhai appx 35 yr himself climb on 11 kv Koteswar JGY DP structure due to unknown reason and touch 11 kv Koteswar JGY live conductor and got electical shock and fall under DP structure fencing.	Yet not received			inform people's not to touch any electrical wire	
152	PLN,PLN-2,MALAN	VIRAMPUR AND RURAL	Shri Parathibhai Vasharambhai Parmar	17.09.2024	NFHD (Mechanical)	The non fatal Electrical accident occurred to Shri P V parmar, EA, while attaining complain of shri Rupsinh Gumansinh consumer no 77339/00007/0 and others on Ag TC loc no 27/1-2. victim got electric shock and he met with non fatal electrical accident while working on transformer. He got injury of burn on left leg foot and peeling of skin over left elbow	Yet not received			work with safety	
153	PLN,PLN-2,DANTA	CHHOTA BAMODRA AND RURAL	Bumbadiya Sureshbhai Bandhubhai	26.09.2024	FAO	As per Preliminary investigation due to heavy wind from LT line phase wire slipped from shackle insulator and touch to U Clamp and leakage current pass through earth wire to ground that time Bullock passes near pole and contact in leakage current and got electric shocked and death on the spot and fetal Animal Accident occurred .	Yet not received			Remove the leakage current	12500

154	HMT / Talod / Sathamba	TALOD / (RURAL)	1. BARIYA JAGATSINH FATAJI AND 2. BARIYA ASHWINSINH BUDHAI	08-04-24	FHO	On Dated 08.04.2024 call received on Complaint Centre regarding Snapped Conductor and NonFatal Accident. DE Sathamba visited the site. 11 KV Hamiriya AG passing from farm of Parmar Muljibhai Khanabhai and Parmar Ramanbhai Mavabhai. Very Old GI wire tied on Pole from Loc No 23 to 30(Which was previously used for earthing)Due to some reason, GI wire snapped from Loc No 23 and one end of GI Wire fitted to 11 KV Hamiriya AG feeder and touched to said ag feeder and broken GI wire's other end fallen on ground. At that time, Fatal Victim Bariya Jagatsinh Fataji came in Farm for routine labour work and Accidentally said Victim came in contact with GI wire and dead on spot while on the other side another Non Fatal Victim Bariya Ashwinsinh Budhaji touched the GI wire and got electrocuted and sent to Hospital for Further Treatment. During whole Incident there is no any Tripping recorded in 11 KV Hamiriya AG at SS End... Police Panchnama and Post Mortem Report Pending.	CEI PENDING	CEI PENDING	CEI PENDING	HT SPAN STRINGING WORK COMPLETED & EXTRA GI WIRE REMOVED FROM LINE	100000/-
155	HMT / HIMATNAG AR / Salal	Amodara / (RURAL)	MUKESHBHAI LAXMANBHAI NADIYA	26-04-24	NFHD	on dt. 26/04/2024 programme of Maintenance 11KV Deep Industrial feeder was given from office. Prantji TMS staff alongwith Salal Supervisor M R. Patel had started work after having all procedure of Line clear permit of 11KV Deep Industrial feeder. After Every safety precautions like- Line discharge, earthing of line, disconnect cross boundary switch & pole erthing was done. Then with safety gadget staff started work. During that victim M L Nadiya(E.A) & G C Makwana (ALM) went for maintenance works. Suddenly He came down from the pole to ground. On inquiry of present staff, it was shown that by one or other reason victim M L Nadiya climbed over nearby 11KV Mark Industrial feeder, which was already ON. He got induction & fallen down. After sound of victim near by working line staff rushed at accident location & gave him primary treatment then took him to local dispensary. The local Dr. Advised to Admit him to Himatnagar civil hospital. Later on after treatment Himmatnagar Civil hospital he was taken to Apollo hospital, Ahmedabad for further treatment.	CEI PENDING	CEI PENDING	CEI PENDING	ACCIDENT DUE TO NEGLIGENCE OF EMPLOYEE & SHOW CAUSE ISSUED	NA
156	HMT / HIMATNAG AR / HIMATNAG ART	Shantipura / (RURAL)	Rathod Narendrasinh Devusinh	02-05-24	FHO	On dt. 02/05/2024 message regarding fatal accident occurred given by Nagarpalika employees Shri Rambhai and Dineshbhai at complaint center OF UGVCL at about 16:35 hrs.Immediately site has been visited and panchanama carried out.Victim and his colleague Shree Sajjansinh started the work of attending street light complaint lodged at Nagarpalika Himmatnagar without any information to UGVCL office & with live LT line.It is found that stand for work on pole utilized by victim rest at second hole of the said pole. Any how the victim fallen down from the pole to ota near by said pole and severe injury occurred to head of Victim .There are signs of blood found on the ota,then after surrounded people gathered and called to 108 ambulance and immediately shifted the victim at Hope hospital for treatment but the victim died and dead body shifted to Civil hospital Himmatnagar for PM.PM report and eye witness statement is awaited.Victim himself is responsible for the accident & there is no any fault at UGVCL side.	CEI PENDING	CEI PENDING	CEI PENDING	ACCIDENT DUE TO NEGLIGENCE OF NAGARPALICA PERSON(CAME IN CONTACT WITH LIVE WIRE)	100000/- & 9.8.2024
157	HMT / Modasa / Modasa R2	Amalai / (RURAL)	Khant Kankabhai Abhubhai	15-05-24	FAO	On date 15.04.24 approx. 12:10 hr, at Amlai-Mathasuliya road the owner of Bullock sh. Kankabhai Abhubhai Khant was passing with his Bullock under the HT line of 11 KV Napa Ag feeder and at the same time one conductor of Y-ph was snapped from joint and the Bullock was came contact with live wire and got electric shock and died on the spot. 11 Kv Napa Ag Feeder was tripped at 12:17 PM.	CEI PENDING	CEI PENDING	CEI PENDING	stringing of conductor and tree cutting caried out	12500/24.6.24
158	HMT / TALOD / Talod-1	Mahiyal / (RURAL)	Desai Naranbhai Vihabhai	24-05-24	FAO	Date:- 24/5/2024, at 8:30am approximate LT pole having 1-ph 2-wire ABC, which was stand in pond's water logging area, said pole had fallen in water of pond, but DO fuse link of transformer had not burnt & current remains flowing in water, as when owner of cow passing near this pond with his cattles out of them one cow came near pond for drinking water, she got electrocuted & died on spot	CEI PENDING	CEI PENDING	CEI PENDING	LT ABC LINE STRINGING WORK COMPLETED	15000/-
159	HMT / Modasa / Meghraj-2	Vank / (RURAL)	Bhambhi Kanabhai Punjabhai	30-05-24	FHO	AS PER INFOMRRMATION HAS BEEN GOT FORM OUR STAFF ON DATED 30.05.2024 AT AROUND 1:00 PM VICTIM SHREE BHAMBHI KANABHAI PUNJABHAI WAS TREE CUTTING WORK AT THEIR FARM. HE WAS CUTTING TREE NEAR 11 KV MUNSHIWADA AG LINE AND SUDDENLY ONE LONG BRANCH OF THAT TREE FALLEN ON 11 KV MUNSHIWADA AG LINE DUE TO THAT BHAMBHI KANABHAI PUNJABHAI GOT ELECTRIC SHOCK & FALL DOWN ON EARTH. AND DIED ON PLACE AT THAT TIME.	CEI PENDING	CEI PENDING	CEI PENDING	Mmaintanance Done	100000/8.10.24
160	HMT / Modasa / Modasa R2	Sakariya / (RURAL)	Chamar Rameshbhai Kuberbhai	09-06-24	FAO	On date 09/06/2024, approx at 11:00 hr, at Sakariya,theowner of Buffalo Shri. Rameshbhai Kuberbhai chamar waspassing with his Buttalo.when they approached near thettransformer center of Girishbhai Ramnbhai patel of 11 kvsakariya ag teeder, Buffalo came in contact with iron wire anddied on spot.iron wire was connected to the neutral earthwire and stay wire,so due to leakage current of transformerthrough the conductor wich was joint with stay wire oftransformer Buffalo got electric shock and died on the spot.	CEI PENDING	CEI PENDING	CEI PENDING	Mmaintanance Done	15000/24.7.24
161	HMT / HIMATNAG AR / PRANTUJ	PRANTUJ (RAMNAGAR) / (RURAL)	SAVITABEN AMRUTJI MAKWANA	20-06-24	FHO	THE VICTIM WAS DOING NORMAL HOUSE HOLD WORK AT HER HOUSE AS PER ROUTINE SCHEDULE.DURING ABOVE SAID WORK SHE GOT ELECTROCUTED,WHILE SHE HOLDS IRON GRILL WHICH WAS CONNECTED ALONG WITH GALVANISED ROOF OF HER HOUSE.AS PER DETAILED INVESTIGATION A TWIN CORE PVC SERVICE CABLE FIRED AND CAME IN CONTACT WITH gi WIRE NO 10,RESULTING LEAKAGE POWER PASSES AT IRON GRILL THROUGH GALVANIZED ROOF OF HOUSE AND SHE GOT ELECTROCUTION AND DIED DUE TO ELECTRIC SHOCK.	CEI PENDING			SERVICE WIRE REPLACED WITH PROVIDING NEW GI WITH EGG & REEL	PENDING
162	HMT / Talod / CHOILA	Junvada / (RURAL)	Vaghari Sajjanben Manubhai	25-06-24	FAO	Date:- 25/06/2024, at 16:30 pm approx on 11 kv Tenpur ag fdr pin pole - As an iron senting wire was placed by a bird on the top wire of the pin pole, due to the wind the iron senting wire touched the iron top of the pole and leakage current was passing through pole. At that time cow passing near the pin pole and touch the pole, she got electrocuted & died on spot,	CEI PENDING	CEI PENDING	CEI PENDING	CENTING WIRE REMOVED FROM THE LT LINE & STRINGING WORK DONE	15000/-
163	HMT / TALOD / DHANSURA	SIKKA / (RURAL)	Khant Arajanbhai Mathurbhai	01-07-24	FAO	On date:- 1/7/2024, at 10 :30 am approximate, Khant Arajanbhai Mathurbhai 's a cow and a buffello were going for grassing and both came in contact to fencing of village tc near gram panchayat and got electrocuted due to leakage current and died at location.As per site verification by sdn officer the site is wet and water logged due to rainy atmosphere And There was no leakage current found. PM report and police panchnama awaited.	CEI PENDING	CEI PENDING	CEI PENDING	TC FENCING MAINTENENCE WORK COMPLETED	30000/-
164	HMT / IDAR / KHEDBRAHMA	KHEDBRAHMA, BHATVAS / (TOWN)	Vanzara Sureshbhai Babubhai	04-07-24	FAO	Vanzara Sureshbhai Babubhai's buffaloes were tied to wall by metal chain under the electric line in front of his own house. During that time, a live electric line suddenly broke from the electric pole and fell on the buffaloes tied down and died unfortunately on the spot.	CEI PENDING	CEI PENDING	CEI PENDING	It abc provided	1500*3=45000/2 3.07.2024
165	HMT / HIMATNAG AR / HMT R	MOTI DEMAI / (RURAL)	MAKAVANA FATAJI JAVANJI	17-07-24	FHO	On dated 17.07.2024,at about 19:30 hours (Evening) victim named Fataji Javanji Makwana was Spreading Towel after bath on Iron wire wound on Iron Pipe Stuck with Outer balcony of house at that time Incoming Service wire came in contact with faulty wire of street light lamp connected which was before Egg ,Reel Insulator of GI wire and Victim got electrocuted and died As no other person was present at the time of electrical accident, some neighbors saw the victim laying on ground so, they gathered to all and admitted to Civil Hospital Himatnagar by private vehicle, where consult medical officer declared him dead.accident occurred due to negligence of gram panchayat .	CEI PENDING	CEI PENDING	CEI PENDING	FAULTY STREET LIGHT WIRE REMOVE & ASK PANCHAYAT TO REPLACE WITH NEW WIRE	100000/- & 12.9.2024
166	HMT / Modasa / Modasa R2	DUGARVADA / (RURAL)	Rabari Mafatbhai karsanbhai	19-07-24	FAO	On date 19.07.24 approx. 18:10 hr, at near Devjibhai dhulabhai farm of village Dugarvada, the one conductor of 4 wire LT line of 11 KV Kadamb Ag feeder was snapped due to Su-baval tree fallen on line and the cow of sh. Lagdhirbhai mafatbhai rabari was grassing near the conductor was came in contact with Live conductor wire and got electric shock and died on the spot.	CEI PENDING	CEI PENDING	CEI PENDING	stringing of conductor and tree cutting caried out	15000/21.9.24
167	HMT / TALOD / BAYAD	DAKHANESHWAR / (RURAL)	Raval Sureshbhai urfe Dipakbhai Kalabhai	26-07-24	FHO	As per eye witness and panchnama nivedan, On date 26/7/24 Time approx 11.30 am,Victim was climbed on iron shed was built under 5 wire LT line of Arjanvav JGY Feeder.This iron shed was illegally constructed recently.Distance between iron shed to bottom LT Conductor was approx 3.25 ft.Victim was climbed on iron shed to his house roof for his slab leakage repairing work. After completed repairing work he passed on iron shed under LT line, suddenly Victim was lapsed and touches to LT line,got electrocuted and death at site. Police panchnama and PM report awaited. Remarks:For this Fatal Accident case UGVCL is not responsible.	CEI PENDING	CEI PENDING	CEI PENDING	THERE IS NO ANY NEGLIGENCE FOUND IN NETWORK . ITS VICTIME FAULT.	100000/-
168	HMT / HIMATNAG AR / HMT T	HIMMATNAGAR / (TOWN)	DESAI SHNAKRBHAI CHEHARBHAI	27-07-24	FAO	As soon as telephonic complain received at complain centre regarding accident on dtd 27.6.24 Approx. 21:28 hrs.Immediately site has been visited and it is found that Nagarpalika street light repairing-maintenance person has given extra twin core wire in LTDB box of Avadh park soc in that there is a joint which touch the LTDB & leakage current flow to fencing.The cow came in contact with leakage current So got electrocuted & died.The Details investigation follows.The cause of leakage i.e. extra wire that was joined by Nagarpalika person remove & leakage stopped.	CEI PENDING	CEI PENDING	CEI PENDING	FAULTY EXTRA WIRE JOINT BY NAGARPALIKA WAS DISMENTAL	15000/- & 30.8.2024
169	HMT / TALOD / CHOILA	CHOILA / (RURAL)	ZALA VISHNUBHAI BADAJI	04-08-24	FHO	As on dated 5.8.24 information received by police station Bayad, under singh visited site on dated 5.8.24 ,4:30 pm. As per eye witness and panchanama nivedan, On Dated 4.8.24 time Approx 3:30 pm, Victim was arrived at Patel Kiritbhai Bhikhabhai house for plumbing work, said victim climbing at second floor for plumbing work like fitting of water tank and pipe line. 11 KV Ghadiya Jgy Ht line passed above second floor front side salb wWhich is unauthorised construction under HT line, so Some How said victim come in induction zone and touched this 11 Kv Ghadiya Jgy line and got electrocuted and fall down from second floor to first floor unauthorised slab and victim died. police panchanama and PM report awaited. Remarks:For This Fatal Accident case UGVCL is not responsible. NOTE:-Notice for Unleagal Construction under HT line is already issued wide letter No:-UGVCL/Choila/3512 dated 15.12.23.	CEI PENDING	CEI PENDING	CEI PENDING	THERE IS NO ANY NEGLIGENCE FOUND IN NETWORK . ITS VICTIME FAULT.	NILL
170	HMT / HIMATNAG AR / GAMBHOI	AMBAVADA / (RURAL)	RATHOD GANPATSINH KESHARISINH	05-08-24	FAO	On date 05.08.2024 at approximately 17:25 hours a buffalo was grazing in a fallow land of Ambavada village. A LT line with 4 wires emerges from the transformer of 11 KV Lalpur AG feeder in the fallow land. Due to the LT wires broken of this outgoing It line due to the wind, the return power entered the neutral of transformer. The buffalo came in contact with leakage current and died due to electrocution on the spot .The cause of leakage current Stop by binding the wire with LT line.	CEI PENDING	CEI PENDING	CEI PENDING	CONDUCTOR RE JOINT & RESTRINGING DONE	PENDING
171	HMT / Modasa / Meghraj 1	Mevda / (RURAL)	Patel Kanubhai dhulabhai	06-08-24	FAO	Patel Kanubhai Dhulabhai, a resident of Mevda village, was going to his farm along with his wife in a bullock cart to get fodder. There, a wire (neutral wire) of Ag LT line of u.g.v.c.l. passing through the farm of Patel Gordhanbhai in the eastern direction adjacent to his farm was broken and fell down. So Patel Kanubhai Dhulabhai's bull got electrocuted and died when it came in contact with the broken wire.	CEI PENDING	CEI PENDING	CEI PENDING	stringing of conductor and tree cutting caried out	

172	HMT / Modasa / Tintol	Charanvada / (RURAL)	Parmar Dashratsinh Takhtasinh	10-08-24	FAO	on 10/08/2024 Buffalo of Parmar Dashratsinh Takhtasinh, resident of village Charanvada, tied in his barn but the buffalo rubs his horns with earthing wire of LT pole due to this at the upper end of pole one open end of service tapping wire touches with earth wire resulted into leakage current passes through earth wire to bottom of pole where buffalo came in contact with earth wire got electrocution and died.	CEI PENDING	CEI PENDING	CEI PENDING	Maintenance Done	15000/27.9.24
173	HMT / HIMATNAG AR / MEHTAPUR A	ILLOL / (RURAL)	RABARI RAGHUNATHBHAI MANDANBHAI	11-08-24	FAO	On Dt. 11.08.2024 , At Village. IlloI , Darbagadh area village transformer a black clour cow was died near trasformer fencing . At the time of inspection it was found that the D.O. Fuse of transformer centre was found removed , transformer LT Side power was off at that time , After our UGVCL Employees had turn on the power of transformer providing HT Side D.O. Fuse , thus after that LT Power supply was restored & at that time no leakage power was present at transformer neutral earthing , but when gram panchayat water works 3 ph motor started for water supply , there was leakage current present at transformer neutral , thus water work 3 ph motor was found short (faulty) . cow's death reason will be confirmed after post mortem report of vaternity officer . may be due to return current on netural wire cow get electrocuted	CEI PENDING	CEI PENDING	CEI PENDING	PANCHAYAT MOTOR SHORT & IT WAS REPLACED WITH NEW BY PANCHAYAT	15000/- & 24.9.2024
174	HMT / BHILODA / VIJAYNAGAR	JALETI / (RURAL)	BODAT KIRTANKUMAR CHINUBHAI	11-08-24	FHO	As per eye witness statement the victim was climbed on 11 Badarkha AG feeder passing from his farm the neighbours shouted and asked him to come down but the victim might have been drunk and not come down and his left hand elbow touched live wire and electrocuted and fell down from pole and died	CEI PENDING	CEI PENDING	CEI PENDING	LINE MAINTENANCE DONE	-
175	HMT / Modasa / Malpur	Tiski / (RURAL)	Kotwal Ramanbhai Ramabhai	25-08-24	FAO	As per information received from Owner of Bullock, While in night approx at around 11:40 pm, he found that one of Bullock was lying dead over one of the broken conductor of 3 wire JGY LT line under which the Bullock had been tied by the owner. The suspected cause of the conductor snapping could be due to touching of tree branches over the conductor. Thus, due to snapping of LT conductor over the Bullock tied under the line resulted in electrocution of the Bullock which could have led to its death on spot.The post mortem report of the victim Bullock is awaited.	CEI PENDING	CEI PENDING	CEI PENDING	stringing of conductor and tree cutting carried out	12500/21.9.24
176	HMT / HIMATNAG AR / PRANTUJ	BALISANA / (RURAL)	MAHENDRASINH SOMSINH RATHOD	26-08-24	FAO	On dated 26.08.2024 around 3:00 am due to heavy rain & wind big tree fallen on Unchha JGY LT line at balisana village so one conductor broken from It line & came in contact with Buffalo. Buffalo died on spot.	CEI PENDING	CEI PENDING	CEI PENDING	CONDUCTOR RE JOINT & RESTRINGING DONE	PENDING
177	HMT / IDAR / KHEDBRAHMA, BHATVAS / (TOWN)	KHEDBRAHMA, BHATVAS / (TOWN)	RABARI BHERAJI DUNGARAJI	26-08-24	FAO	The Accident occurred at village:- Khedbrahma dated 26.08.2024 at approx. 14:30 near virbavaji mandir, Rabari bheraji dungaraji was returning to home after grazing his cow and buffalo, one buffalo passed by a broken conductor on the road near the virbavaji temple and died instantly. seeing that Rabari Bheraji Dungaraji drove away his other cow and buffaloes, another cow also died unfortunately on the spot due to passing through the broken live conductor.	CEI PENDING	CEI PENDING	CEI PENDING	It spacer provided	1500*2=30000/2 0.09.2024
178	HMT / IDAR / VADALI	MAHOR / (RURAL)	RABARI VIRABHAI GOBARBHAI	27-08-24	FAO	ON DATE 27.08.2024 RABARI VIRABHAI GOBARBHAI buffaloes were tied to wall by metal chain under the electric line in front of his own house. During that time, very heavy rain and wind pressuer a tree branches suddenly fall down on the live electric conductor and so broke from the electric pole and fell on the buffaloes and cow tied down and died on the spot.ess.	CEI PENDING	CEI PENDING	CEI PENDING	It spacer provided	1500*2=30000/0 5.09.2024
179	HMT / IDAR / DESHOTAR	VERABAR / (RURAL)	PATEL RAKESHBHAI RAMANBHAI	27-08-24	FAO	ON DATE 27/08/2024@ 03.00 PM Patel Rakeshbhai Ramanbhai buffaloes were tied to wall by metal chain under the electric line in front of his own house. During that time, very heavy rain and wind pressuer1 ph service wire broken suddenly fall down live electric service wirecame with contact buffelo and fell on the buffaloes and cow tied down and died on the spot.	CEI PENDING	CEI PENDING	CEI PENDING	maintenance done	15000/20.09.2024
180	HMT / TALOD / Talod-1	BHATIYA / (RURAL)	SOLANKI DIPSINH KARANSINH	29-08-24	FAO	Date:- 29/08/2024, at 04:30am approximate Mr Solanki DilipsinhKarnsinh's She Buffalo was tied front of his house under Three phase, four wire LT line of 11KV Chamunda Ag feeder which eminating power from 66KV Dalani Muvasi Ss. At this time due to heavy rain and wind pressure LT wirebroken and fall down on buffalo and buffalo came contact with live conductor she got electrocuted and died on the spot.	CEI PENDING	CEI PENDING	CEI PENDING	BROKEN CONDUCTOR JOINTED & MAINTENANCE WORK CARRIED OUT	15000/-
181	HMT / Modasa / Modasa R2	volva / (RURAL)	Bharvad vastabhai Naranbhai	29-08-24	FAO	On date 29.08.24 approx. 13:05 hr, at near Shiram soc. Volva village farm of punjabhai revabhai the one conductor of 4 wire LT line of 11 KV vaniyad Ag feeder was snapped due to tree fallen on line and the Two nos sheep & one nos Goat of sh. Vastabhai naranbhai bharvad was grassing near the conductor was came in contact with Live conductor wire and got electric shock and died on the spot.	CEI PENDING	CEI PENDING	CEI PENDING	dead line dismentalled	
182	HMT / TALOD / CHOILA	PALDI / (RURAL)	Vanjara Lilaben Hsamukhbhai	30-08-24	FAO	As per primary investigation on dated 30.08.2024 time 12.00 approx owner of She Buffalo name Vanzara Lilaben Hasmukhbhai going for grazing grass for She Buffalo. and due to heavy wind and rain, 11 kv Sultanpur AG LT line pole tilted, so that LT Line to land distance was reduced, at that time She Buffalo going under this LT line and touched the line and electrocuted and died.	CEI PENDING	CEI PENDING	CEI PENDING	TILTED POLE RECTIFIED & MAINTENANCE WORK CARRIED OUT.	15000/-
183	HMT / Modasa / Modasa R1	Galsundra / (RURAL)	Parmar Nareshbhai Lalaji	31-08-24	FAO	Fatal Animal Accident occurred to 1 nos of Cow of Parmar Nareshbhai Lalaji at Village Galsundra, Ta. Modasa, Dist. Arvali around 08.00 am. As per owner's statement, around 08.00 am. Conductors of 3ph 4wire ag LT line which was passing above the open area where cow were tied under the LT line, Conductor broken from Sspan and one side of broken conductor comes towards the cow of Parmar Nareshbhai Lalaji, conductor may be broken due to tree branch fall to conctuctor of LT line. Because of coming in contact of live broken conductor Buffaloe may got shock and died, but detail cause of death may be justified after PM report.	CEI PENDING	CEI PENDING	CEI PENDING	stringing of conductor and tree cutting carried out	15000/12.9.24
184	HMT / HIMATNAG AR / MEHTAPUR A	ILLOL / (RURAL)	VANZARA TULSIBEN JIVAJI	02-09-24	FAO	On Dt. 02.09.2024 , At Village. IlloI , Near Vanzara vas to Dhavni river road , a aluminium weasal conductor of agricultural 4 wire LT Line was broken & fallen on ground , while victim's buffalo was passing from said road , it comes in direct contact with live wire & died at spot .	CEI PENDING	CEI PENDING	CEI PENDING	CONDUCTOR RE JOINT & RESTRINGING DONE	PENDING
185	HMT / TALOD / BAYAD	Jumatral / (RURAL)	Raval Dineshbhai Sankalbhai	02-09-24	FAO	Date:- 02/09/2024, at 05:30 pm approximate Mr Raval DineshbhaiSakalbhai's Cow was tied near of his house under Single phase, Three wire LT line of 11KV Sarsoli JGY feeder which eminating power from 66KV BayadsS. At this time due to heavy rain and wind pressure LT wire Snapped and fall down on cow & cow came contact with live conductor she got electrocuted and died on the spot.	CEI PENDING	CEI PENDING	CEI PENDING	Maintenance Done	
186	HMT / IDAR / KHEROJ	Navamota / (RURAL)	Gamar Mashrubhai Ratabhai	04-09-24	FAO	On dtd. 04-09-2024 11KV Navamoya JGY LT 1-PH service cracked due to heavy rain and wind GI wire touched to turn buckle touched to Stay wire after stay insulator and it came in contact with metal shade where cow was tied with pole of metal shade and got electrocuted and died on the spot.	CEI PENDING	CEI PENDING	CEI PENDING	Maintenance Done	
187	HMT / IDAR / JADAR	RUDARDI / (RURAL)	Patel Mihirbhai Kanubhai (Montu)	06-09-24	NFHO	For the Purpose of suicide , The victim caught with Non Fatal human outsider electrical accident occured to patel Mihirbhai Kanubhai on dated- 05.09.2024 time approx 06:20 AM. As Victim was mentally disturbed due to some reason hence he decided to suicide so he climbed on 11 kv line of jogani ag feeder location no-76 and touch to the live conductor of 11 kv jogani ag feeder and got electrocuted and fall down.after that he was taken to private hospitals idar for primary treatment and after that victim shifted to civil hospital ahemdabad for more treatment.at present victim health is good and stable and conscious.	CEI PENDING	CEI PENDING	CEI PENDING	Maintenance Done	
188	HMT / TALOD / SATHAMBA	Bhempoda / (RURAL)	Khant Bhupatbhai shanabhai	06-09-24	FAO	On Date 16.09.2024 Approx 12.05 Pm Bharvad Babubhai Hakabhai Cow Was Eating Grass Came In Contact With Earthing Wire Of Transformer Body Of AG Tc Of 11 Kv Kashiapura Ag Fdr,Which Eminating Power From 66 Kv Demai Ss.As Per Owner And Surrounding Peoples Statement Cow Came In Contact With Earthing Wire Of Transformer Body,She Got Electrocuted And Died On The Spot.	CEI PENDING	CEI PENDING	CEI PENDING	LT POLE RECTIFICATION WORK CARRIED OUT	
189	HMT / Modasa / Modasa R1	Kolikhad / (RURAL)	Bharvad Dahyabhai Mathurbhai	08-09-24	FAO	Fatal Animal Accident occurred to Cow of Bharvad Dahyabhai Mathurbhai at Village-kolikhad, Ta. Modasa, Dist. Arvali around 05.00 pm on date 08.09.2024. As per owner's statement, around 05.00 pm cows were grazing in field. Out of which one cow went near 63 KVA TC structure and cow may come in contact of earthing wire and cow may got shock and died . But detail cause of death may be justified after PM report.	CEI PENDING	CEI PENDING	CEI PENDING	Maintenance Done	15000/8.10.24
190	HMT / Modasa / Meghraj-2	Moti Panduli / (RURAL)	Kharadi Hirabhai Sardarbhai	08-09-24	FHO	AS PER INFORMATION RECEIVED FROM OUR STAFF (WHO WAS INFORMED BY LOCAL VILLAGER) ON DATED 08.09.2024 AT AROUND 10.00 AM. ON VISITING SITE, DEADBODY OF VICTIM SHREE KHARADI HIRABHAI SARDARBAHAI WAS FOUND IN FARM, BROKEN LT LINE CONDUCTOR WAS FOUND UNDER HIS FEET. AS THE STENCH OF THE ROTTING BODY WAS HIGH, IT WAS DIFFICULT TO LOCATE THE MARK OR SPOT ON DEAD BODY WHETHER LT LINE CONDUCTOR TOUCHED BODY.	CEI PENDING	CEI PENDING	CEI PENDING	stringing of conductor and tree cutting carried out	
191	HMT / BHILODA / CHORIWAD	ISHAVARPURA KAMPA / (RURAL)	ASHVINSINH VAKHATSHINH ZALA	08-09-24	NFHD	Non Fatal Departmental Accident occurred to victim at village : Ishavarpura kampa, Ta: idar, Dist:S.K.. Approx 17:00 pm, while attending pole plumbing complined of 11KV TakhatgadH Ag feeder at Ishavarpura village with A R parmar(EA). That time attend the complaint victim climbed on sonariya TCstructure for cutting the jumper to dead 11 KV line. sudedenly victim was fell down on the ground due to electrocution and was admitted to idar Pancham Hospital for treatment and is currently in consious state.	CEI PENDING	CEI PENDING	CEI PENDING	LINE MAINTENANCE DONE	-
192	HMT / TALOD / BAYAD	Demai / (RURAL)	BHARVAD BABU HAKA	16-09-24	FAO	On Date 16.09.2024 Approx 12.05 Pm Bharvad Babubhai Hakabhai Cow Was Eating Grass Came In Contact With Earthing Wire Of Transformer Body Of AG Tc Of 11 Kv Kashiapura Ag Fdr,Which Eminating Power From 66 Kv Demai Ss.As Per Owner And Surrounding Peoples Statement Cow Came In Contact With Earthing Wire Of Transformer Body,She may Electrocuted And Died On The Spot.	CEI PENDING	CEI PENDING	CEI PENDING	TC MAINTENANCE WORK CARRIED OUT.	
193	HMT / BHILODA / BHILODA-1	MAU(SATKORA) / (RURAL)	KHARADI MANHARBHAI CHUNILAL	17-09-24	FAO	On dtd. 17.09.2024 at 09:30 Pm approx. Due to a big tree near to party's house fall on 1ph 2w abc line passing through There so line break down and conductor fall on Buffalo tied under line hence electrocuted and buffalo died on the spot	CEI PENDING	CEI PENDING	CEI PENDING	LINE MAINTENANCE DONE	15000

194	HMT / Modasa / Meghraj-2	Kasana / (RURAL)	Solanki Yashpalsinh Dolatsinh	29-09-24	FAO	FATAL ANIMAL ACCIDENT OCCURRED TO BUFFALO(SHE) OF SOLANKI YASHPASINH DOLATSINH AT KASANA (LIMDA PADAR) VILLAGE, TA - MEGHRAJ, DIST- ARVALLI. AT AROUND 08:30 PM, AS PER TELEPHONIC INFORMATION FROM OWNER. THE ANIMAL FATAL ELECTRICAL ACCIDENT OCCURRED TO BUFFALO(SHE). BUFFALO(SHE) WAS TIED NEAR 11 KV CHHIKARI JGY FEEDER LT LINE. ACCIDENTLY NEUTRAL LINE CONDUCTOR (LT LINE) OF 11 KV CHIKARI JGY FEEDER WAS BROKEN AND FALLEN ON EARTH. AS NEUTRAL LT LINE CONDUCTOR BROKEN, IT TOUCHED TO AG LT LINE OF 11 KV MANDA AG FEEDER PASSING UNDER, HENCE CURRENT GOT PASS THROUGH THAT NEUTRAL LINE CONDUCTOR (LT LINE) OF 11 KV CHIKARI JGY FEEDER. BUFFALO(SHE) CAME IN CONTACT WITH THAT LIVE WIRE (LT LINE) OF 11 KV CHIKARI JGY FEEDER ON EARTH AND GOT ELECTROCUTED AND DIED ON THE SPOT.	CEI PENDING	CEI PENDING	CEI PENDING	stringing of conductor and tree cutting carried out	
195	HMT / Modasa / Meghraj-1	Bhemapur / (RURAL)	Katara kalubhai navabhai	13-04-24	FHO	A fatal human Outsider electric accident occurred in Private premises on dated 13-04-2024 Shri Katara kalubhai navabhai. While checking the spot, Katara Kalubhai Navabhai in Mandli area of Bhemapur village, customer no. 29217/00482/0 load. 5 Hp by Agricultural power connection has been provided. On the load side of the connection, the consumer connected a private flexible wire to the starter of the motor and turned on the LED bulb. There are many joints at some distance between the flexible wire and the other flexible wire strung on a stick between the irrigated fields. On dt. 13/04/2024, consumer Katara Kalabhai Navabhai while irrigating the field died due to electrocution at the place where he came in contact with the jointed wire of the flexible wire tied on the wood towards the bulb.	CEI PENDING	CEI PENDING	CEI PENDING	PRIVATE PREMISIS	PRIVATE PREMISIS
196	HMT / HIMATNAG AR / HMT R	hadiyol / (RURAL)	Parmar Savaji Kalaji	22-04-24	FHO	on dated 22.04.2024 at village Hadiyol human fatal outsider accident occur in party premises. Victim Parmar Savaji Kalaji age 37 yr (approx) died due to touching private premises fencing wire of farm . there was no any cause and fault of leakage current by UGVCL line in this incident.	CEI PENDING	CEI PENDING	CEI PENDING	PRIVATE PREMISIS	PRIVATE PREMISIS
197	HMT / HIMATNAG AR / HIMATNAG AR-TOWN	HIMMATNAGAR / (TOWN)	1) Mangalram Ukarji Prajapati 2)Rahulkumar Jashvantbhai Dabagar	13-05-24	NFHO	on dtd 13.05.24 about 15:45 hrs heavy cyclonic wind & rain started in him atnagar and surrounding area. The telephonic message regarding the incident has been received from shak market. Immediately power supply cut off of 11 kv Durga urban feeder and power supply disconnected of shop no :33.due to power given in iron shed in front of this shop.due to rainy day the iron wire and tad patri wet and tadpatri came in contact with faulty wire to pin connected in internal wiring of shop no 33.No major injuries found to both victim.(1) 1 st Victim has been found electric spot in his both palm and head injuri found on his back side head (2) nd Victim has been found slide injuri on his noze due to he helt on the ground & no electric spot found in his body.	CEI PENDING	CEI PENDING	CEI PENDING	PRIVATE PREMISIS	PRIVATE PREMISIS
198	HMT / BHILODA / CHORIWAD	KESHARPURA / (RURAL)	DUND NIRMABEN PRAKASHBHAI	14-05-24	FHO	An outsider Fatal Human accident was occurred to victim at : Kesharpura ,Ta: Vadali, Dist: S.K. on dated: 14-05-2024 time, approximately 10:30 am due to leakage current passes in iron channel though faulty wiring in House. Iron wire tied with iron channel of house, victim got electrocuted and died on the spot in consumer premises.	CEI PENDING	CEI PENDING	CEI PENDING	PRIVATE PREMISIS	PRIVATE PREMISIS
199	HMT / HIMATNAG AR / HIMATNAG AR TOWN	HIMMATNAGAR / (TOWN)	Barot Radhaben Rajubhai	26-06-24	FHO	PRIMARY OBSERVATION FOUND THAT IN EXISTING PREMISE RENOVATION WORK OF WALL IS UNDER PROGRESS. SO SMC BOX AND PRIVATE CONSUMERBOARD REMOVED AND PLACED ON GROUND BY PARTY ITSELF WITHOUT INFORMING TO UGVCL. METER SERVICE WIRE AND METER ARE FOUND IN GOOD CONDITION.THE PARTYSIDE WIRING FOUND FAULTY HENCE ANYHOW THE VICTIM MAY CAME IN CONTACT WITH FAULTY CONSUMER WIRING, SO SHE GOT ELECTROCUTED.THE POWER SUPPLY OF SAID CONNECTION DISCONNECTED IMMEDIATELY. SHE WAS SHIFTED TO HOSPITAL FOR TREATMENT. DETAILS INVESTIGATION FOLLOWS THE SAID ACCIDENT OCCURED IN PARTY PREMISE & NO FAULT AT UGVCL SIDE	CEI PENDING	CEI PENDING	CEI PENDING	PRIVATE PREMISIS	PRIVATE PREMISIS
200	HMT / HIMATNAG AR / PRANTUJ	PRANTUJ / (URBAN)	KANAIALAL VARSANGJI MAKWANA	02-07-24	FHO	On dated 02.07.2024,at about 14:30 hours victim named Kanaiyalal Varsangji Makwana was storing water at under premises water tank from panchayat water supply. For that purpose he was using 0.5 HP single phase motor having black color flexible wire(1/18) with joint and another plug point was laid on ground level . Plug point laid at ground level was connected through motor (single phase) having blue color flexible wire with black PVC tape. Due to some electrical fault in said motor wiring or mal operation by victim the leakage current was passes through his body & gets electrocuted. On dated 03.07.2024 said site was visited by undersigned and JE, technical staff at that time the wiring of said meter up to meter incoming points and outgoing points were normal. As no other person was present at the time of electrical accident, some neighbors saw the victim laying on ground so, they gathered to all and admitted to CHC Prantij by private vehicle, where consult medical officer declared him dead.	CEI PENDING	CEI PENDING	CEI PENDING	PRIVATE PREMISIS	PRIVATE PREMISIS
201	HMT / IDAR / VADALI	KUBADHAROL / (RURAL)	RADHABEN DILIPBHAI PATEL	30-07-24	FHO	A Fatal human outsider electrical accident occurred to radhaben dilipbhai patel on dated- 30.07.2024 time approx 08:30 AM. Victim was cutting the grass from chap cutter machine, at that time due to internal electrical wiring problem current leakage on chap cutter machine and she got electrocuted and died on spot. Accident occurred at consumer premasis. After metering point UGVCL not Responsible for Accident.	CEI PENDING	CEI PENDING	CEI PENDING	PRIVATE PREMISIS	PRIVATE PREMISIS
202	HMT / HIMATNAG AR / GAMBHOI	Mahadevpura(kevan) / (RURAL)	MAKAVANA KAMLESHSINH VAKTUSINH	05-08-24	FHO	On dt.05.08.2024 Makwana Kamlesh Singh Vaktusinh, a native of Mahadevara Kevan village, who has singal phase motor which is outside of his house. During afternoon about 1 pm, victim switched on the motor by wire was insterted from the switch board of the house for household work. Later he was touched the motor meanwhile leakage came in motor & victim was got electrocuted and died on the spot , after which he was taken to Gambhoi Government Hospital for treatment where he was declared brought dead. The incident of this electrical accident has not been reported by any person to the office here.Accident occurred due to internal wiring's fault in Pvt premises.	CEI PENDING	CEI PENDING	CEI PENDING	PRIVATE PREMISIS	PRIVATE PREMISIS
203	HMT / TALOD / CHOILA	Dabha / (RURAL)	ZALA BHUPATSINH CHANDRESH (FH) ZALA VIRENDRASINH BHUPAT (FH) ZALA KAILASHBA BHUPATSINH (NFH)	14-08-24	FHO	AS PER PRIMARY INVESTIGATION IN DABHA VILLAGE AN IRON SHEET SHED IS INSTALLED IN THE FRONT OF THE JOINT HOUSE WITH THE COMMON WALL OF ZALA BHUPATSINH CHANDRASINH AND ZALA UMEDSINH CHANDRASINH THE CELLING FAN WAS INSTALLED WITH IRON ANGLE UNDER THE IRON SHEET SHED IN THE FRONT OF ZALA UMEDSINH HOUSE THE WIRING OF THE CELLING FAN IS OPENED AND SHORTED SO THAT THE THE LEAKAGE CURRENT WAS PASSING IN THE IRON SHEET SHEDAND ALSO THE IRON SENTING WIRE WHICH WAS ATTACHED TO TABELO WHICH WAS MADE IN THE BACK OF THE HOUSE THE ROOF OVER ZALA BHUPATSINH HOUSE WAS ALSO MADE OF IRON SHEET WHICH WERE CONNECTED TO THIS FRONT SIDE IRON SHEET SHED TO BACK SIDE IRON SENTING WIRE SO LEAKAGE PASSING FROM CELLING FAN TO IRON SHED AND IRON SHED TO ROOF OF IRON SHEET AND ALSO IRON SENTING WIRE TO TABELO ON DATED 14.8.2024 TIME 6.30 AM APPROX ZALA BHUPATSINH CHANDRASINH TOUCHED THIS IRON SENTING WIRE SO HE ELECTROCUTED SO THAT SON ZALA VIRENDRASINH AND HIS WIFE KAILASHBA WENT TO SAVE ZALA BHUPATSINH SO THAT BOTH ARE ALSO ELECTROCUTED AFTER TAKING EVERYONE TO THE HOSPITAL ZALA BHUPATSINH CHANDRASINH AND HIS SON ZALA VIRENDRASINH BHUPATSINH DIED AND HIS WIFE CURRENTLY UNDERGOING TREATMENT IN THE PRIVATE HOSPITAL AND THEIR HEALTH IS GOOD POLICE PANCHANAMA AND PM REPORT AWAITED	CEI PENDING	CEI PENDING	CEI PENDING	PRIVATE PREMISIS	PRIVATE PREMISIS
204	HMT / TALOD / CHOILA	Moti Zer / (RURAL)	ZALA MAHESH SANA (FH) ZALA MAHESH BALA (NFH)	03-09-24	FHO	AS PER PRIMARY INVESTIGATION ON DATED 3.9.24 APPROX 9.00 PM ZALA MAHESHBHAI SANABHAI AND ZALA MAHESHBHAI BALABHAI ARE WENT FOR TAKING CARE OF CROP WHICH LAND IS TAKEN ON RENT BY SAID VICTIM WHILE THEY ARE GOING FOR CARRING CROP AT THAT TIME IN BETWEEN NEAR TO ZALA RANGITBHAI FARM VIA IRON SENTING WIRE POWER TAKEN ON FARM BORDER AT ALL FOUR SIDE SO THAT SAID VICTIM SOME HOW TOUCHED THIS IRON WIRE AND ELECTROCUTED SO ZALA MAHESHBHAI BALABHAI RAN FOR SAVE TO ZALA MAHESHBHAI SANABHAI SO HE WAS ALSO ELECTROCUTED BUT ZALA MAHESHBHAI SANABHAI AT THAT TIME DIED AND ZALA MAHESHBHAI BALABHAI NON FATAL AND TAKEN ON PHC HOSPITAL FOR PRIMARY TREATMENT POLICE PANCHANAMA AND PM REPORT AWAITED	CEI PENDING	CEI PENDING	CEI PENDING	PRIVATE PREMISIS	PRIVATE PREMISIS

Uttar Gujarat Vij Company Limited								
Year 2024-25 (July-24 to Sept.-24)								
Performa SoP 003 B:								
APPENDIX - B								
REGISTER FOR COMPILING THE COMPLAINTS CLASSIFICATION WISE								
Classification	Pending complaints of previous Year	Complaints received during the Year	Total complaints	No. of complaints redressed during the month			Balance complaints to be redressed (4) - (9)	Classification of complaints
				Within stipulated time	Beyond stipulated time	Total		
1	2	3	4 = 2 + 3	5	6	7 = 5 + 6	8 = 7 - 4	9
A(I)	0	33313	33313	33202	111	33313	0	Loose connections at meter, MCB or service line or from pole
A(II)	0	23213	23213	22928	285	23213	0	Interruption due to line breakdown
A(III)	0	4667	4667	4629	38	4667	0	No power complaint on account of blowing of HT/ DropOut (DO)/ LT fuse
A(IV)	0	3559	3559	3518	41	3559	0	Interruption due to failure of transformer or distribution transformer MCB
A(V)	0	1071	1071	1031	40	1071	0	Load shedding/ schedule outages
B(I)	0	501	501	496	5	501	0	Ordinary case, which requires no augmentation
B(II)	0	503	503	491	12	503	0	Where augmentation is required
B(III)	0	24	24	24	0	24	0	Harmonics related issue
B(IV)	0	403	403	395	8	403	0	Neutral voltage related issue
B(V)	0	2134	2134	2075	59	2134	0	Voltage variations related issue
C(I)	0	5160	5160	3061	2099	5160	0	Stopped/Defective Meters.
C(II)	0	539	539	536	3	539	0	Meter accuracy test (Fast/ Slow)
C(III)	0	857	857	804	53	857	0	Burnt Meter
C(IV)	0	51	51	51	0	51	0	Stolen Meter
C(V)	0	2498	2498	2466	32	2498	0	Billing on average basis for more than two bills
C(VI)	0	1104	1104	938	166	1104	0	Meter boxes/ metering system
D(I)	0	3236	3236	3158	78	3236	0	Loose Wires
D(II)	0	243	243	243	0	243	0	Inadequate ground clearance
E(I)	0	965	965	965	0	965	0	For current bills where no additional information is required
E(II)	0	939	939	939	0	939	0	Where additional information relating to correctness of reading etc. is required
E(III)	0	85	85	84	1	85	0	Final bill for vacation of premises/ change of occupancy
E(IV)	0	220	220	193	27	220	0	Change of Tariff
F(I)	0	459	459	447	12	459	0	Where extension of LT line up to 150 Metre is required
F(II)	0	217	217	194	23	217	0	Where extension of LT line of more than 150 Metre and/or augmentation of distribution transformer is required
F(III)	0	360	360	360	0	360	0	Where erection of new distribution transformer is required
F(IV)	0	502	502	501	1	502	0	Where erection of new HT line and distribution transformer is required and/ or existing HT line network is required to be augmented
F(V)	0	25	25	25	0	25	0	Where EHT level line and/ or Sub-station is required to be erected and/ or augmented
F(VI)	0	978	978	978	0	978	0	Modification in connected load
F(VII)	0	1288	1288	1288	0	1288	0	Name change/reconnection/ change of category
F(VIII)	0	43	43	43	0	43	0	In case connection is denied after payment against demand note
F(IX)	0	224	224	201	23	224	0	Transfer of connection
G	0	471	471	451	20	471	0	Request for reconnection/ consumer wanting disconnection
H	0	218	218	218	0	218	0	Refund of amount due in regard to temporary connection
I	0	334	334	314	20	334	0	Street Light complaint
J	0	5104	5104	5010	94	5104	0	Others
Total	0	95508	95508	92257	3251	95508	0	

Uttar Gujarat Vij Company Limited

Year 2024-25 (July-24 to Sept.-24)

Performa SoP 004

Sr. No.	Actions or steps carried out by UGVCL towards public awareness in the quarter	Likely number of consumers influenced	Details about the media
1	Display board of SOP at circle, Division & S/Dn	111045	Notice Board
2	Display board of Name of information officers under RTI Act 2005 at Circle,Division,Sub- division offices.	121546	Notice Board
3	Consumer care centers at various places	116265	Verbal & Notice Board at CCC
4	Advertisement through Daily News papers	127274	Daily News papers
5	Pamphlets distributed among public	138615	Pamphlets
6	Advertisement through slide in TV / Banners	93999	T V Channels
7	On Web site of Uttar Gujarat Vij Company Limited	155601	Internet
8	Through Regular Energy Bills	2353362	Energy Bill
9	Others	500	CD

Uttar Gujarat Vij Company Limited

Year 2024-25 (July-24 to Sept.-24)

Performa SoP 005 : Failure of Distribution Transformer.

Sr. No.	No. of existing Distribution transformer at the start of the Quarter	No.of Distribution transformers added during the Quarter	Total number of Distribution transformers	Total number of Distribution transformer failed during the Quarter	% failure rate of Distribution transformer
	A	B	C=A+B	D	E = (D) * 100/C
1	418911	10798	429709	11676	2.72
<u>Total</u>	418911	10798	429709	11676	2.72

Uttar Gujarat Vij Company Limited

Year 2024-25 (April-24 to Sept.-24)

Performa SoP 007: Compliance of Sample Test result for Neutral Voltage

Sr. No	Category of consumers	Sample Size (Numbers)	Standard specified in regulations	Non-Deviation of results from the sample test (Numbers)	% age compliance
					(6) = (5)*100/(3)
1	2	3	4	5	6
	LT consumers				
1	Domestic	87338	2%	1085	1.24
2	Commercial	9949	2%	115	1.16
3	Industrial	2916	2%	23	0.79
4	Agricultural	26345	2%	701	2.66
5	Public water works	1621	2%	26	1.60
	HT consumers			0	
6	HT Industrial	1768	2%	5	0.28

Uttar Gujarat Vij Company Limited

Year 2024-25 (April-24 to Sept.-24)

Performa SoP 008: Compliance of Sample Test Report for voltage variations

1	2	3	4	5
Voltage Level	Sample Size (numbers)	Limit or prescribed standard	Non-Deviation of results from the sample test (Numbers)	
				% age compliance
				(5) = (4)*100/(2)
Low Voltage	7735	+6% to -6%	142	1.84
High Voltage	1102	+6% to -9%	5	0.45
Extra High Voltage	11	+10% to -12.5%	0	0.00

Uttar Gujarat Vij Company Limited

Year 2024-25 (April-24 to Sept.-24)

Performa SoP 009: Compliance of Sample Test result for Harmonics

1	2	3	4	5	6
Sr. No	Category of consumers	Sample size (Numbers)	Limit or prescribed standard	Non- Deviation of results from the sample test (Numbers)	%age compliance
					(6) = (5)*100/(3)
1	LT consumers	8087	3.50%	17	0.21
2	HT consumers	257	3.00%	4	1.56
3	EHT consumers	5	3.00%	0	0.00

Uttar Gujarat Vij Company Limited

Year 2024-25 (July-24 to Sept.-24)

SoP 010 - A : System Average Interruption Frequency Index (SAIFI) for AG. Dominant Category

Sr. No	Month	Number of Sustained Interruptions during the Reporting Period = Ai	Number of Interrupted Customers for Sustained Interruption events during the Reporting Period = Ni	Total number of Customers Served for the Areas = Nt	Total Number of Interrupted Customers for Sustained Interruption events during the Reporting Period = $\Sigma (Ai \times Ni)$	SAIFI = $\Sigma (Ai \times Ni) / Nt$
1	2	3	4	5	6 = $\Sigma (3 \times 4)$	7 = 6 / 5
1	Jul-24	16763	594787	665598	3337458	5.01
2	Aug-24	17089	607432	666053	3333427	5.08
3	Sep-24	14383	597874	666957	2988115	4.48
Total		48235	1800093	1998608	9659000	4.83

SoP 011 : System Average Interruption Duration Index (SAIDI) for AG. Dominant category

Sr. No	Month	Number of Sustained Interruptions during the Reporting Period = Ai	Total Outage Duration	Restoration time for each Interruption Event = Ri	Number of Interrupted Customers for Sustained Interruption events during the Reporting Period = Ni	Total Customer Interruption Duration = $Ri \times Ni$	Total Number of Customers Served for the Areas = Nt	Cumulative Customer Interruptions Duration = $\Sigma (Ri \times Ni)$	SAIDI = $\Sigma (Ri \times Ni) / Nt$
		Nos	Hr : Min	Hr : Min	Nos	Hr : Min	Nos	Hr : Min	Hr : Min
1	2	3	4	5 = 4 / 3	6	7 = 5 * 6	8	9 = $\Sigma (5 \times 6)$	10 = 9 / 8
1	Jul-24	16763	22625:13	1:20:59	594787	22625:13:00	665598	4340888:51	6:31
2	Aug-24	17089	23356:03	1:22:00	607432	23356:03:00	666053	4422369:45	6:55
3	Sep-24	14383	18175:10	1:15:49	597874	18175:10:00	666957	3593955:35	5:23
Total		48235	64156:26	1:19:48	1800093	64156:26:00	1998608	12357214:11	6:10

SoP 012 : Momentary Average Interruption Frequency Index (MAIFI) for AG. Dominant category

Sr. No	Month	Total Number of Momentary Interruptions = Imi	Total Number of Consumers affected due to Momentary Interruption Events during the Reporting Period = Nmi	Number of Customer Momentary Interruptions = $Imi \times Nmi$	Total Number of Customers Served for the Areas = Nt	Cumulative Momentary Customer Interruptions = $\Sigma (Imi \times Nmi)$	MAIFI = $\Sigma (Imi \times Nmi) / Nt$
1	2	3	4	5 = 3 * 4	6	7 = $\Sigma (3 \times 4)$	8=7/6
1	Jul-24	24066	637315	15337622790	665598	5277153	7.93
2	Aug-24	23836	636202	15164510872	666053	5274981	7.92
3	Sep-24	23642	637340	15067992280	666957	5502988	8.25
Total		71544	1910857	136710353208	1998608	16055122	8.03

SoP 013 – : Customer Average Interruption Duration Index (CAIDI) for AG. Dominant category

Sr. No	Month	Total Number of Sustained Interruptions during the Reporting Period = ΣAi	Total Restoration time for Interruption Events = ΣRi	Total Number of Interrupted Customers for Sustained Interruption events during the Reporting Period = ΣNi	CAIDI= $\Sigma (Ri \times Ni) / \Sigma (Ai \times Ni)$ = SAIDI/ SAIFI
1	2	3	4	5	6 = $(4 \times 5) / (3 \times 5)$
1	Jul-24	16763	22625:13	594787	1:18
2	Aug-24	17089	23356:03	607432	1:21
3	Sep-24	14383	18175:10	597874	1:12
Total		48235	64156:26	1800093	1:16

Uttar Gujarat Vij Company Limited

Year 2024-25 (July-24 to Sept.-24)

SoP 010 - A : System Average Interruption Frequency Index (SAIFI) for JGY Dominant

Category						
Sr. No	Month	Number of Sustained Interruptions during the Reporting Period = Ai	Number of Interrupted Customers for Sustained Interruption events during the Reporting Period = Ni	Total number of Customers Served for the Areas = Nt	Total Number of Interrupted Customers for Sustained Interruption events during the Reporting Period = $\sum (Ai \times Ni)$	SAIFI = $\sum (Ai \times Ni) / Nt$
1	2	3	4	5	6 = $\sum (3 \times 4)$	7 = 6 / 5
1	Jul-24	4246	1929409	2187493	8478784	3.88
2	Aug-24	5305	1949251	2192932	10387612	4.76
3	Sep-24	3992	1921425	2197157	8142060	3.71
Total		13543	5800085	6577582	27008456	4.10

SoP 011 : System Average Interruption Duration Index (SAIDI) for JGY Dominant category

Sr. No	Month	Number of Sustained Interruptions during the Reporting Period = Ai	Total Outage Duration	Restoration time for each Interruption Event = Ri	Number of Interrupted Customers for Sustained Interruption events during the Reporting Period = Ni	Total Customer Interruption Duration = $Ri \times Ni$	Total Number of Customers Served for the Areas = Nt	Cumulative Customer Interruptions Duration = $\sum (Ri \times Ni)$	SAIDI = $\sum (Ri \times Ni) / Nt$
		Nos	Hr : Min	Hr : Min	Nos	Hr : Min	Nos	Hr : Min	Hr : Min
1	2	3	4	5 = 4 / 3	6	7 = 5 * 6	8	9 = $\sum (5 \times 6)$	10 = 9 / 8
1	Jul-24	4246	3510:20	0:49:36	1929409	3510:20:00	2187493	6661685:26	3:02
2	Aug-24	5305	4603:18	0:52:04	1949251	4603:18:00	2192932	8899958:35	4:06
3	Sep-24	3992	3328:03	0:50:01	1921425	3328:03:00	2197157	6635421:41	3:01
Total		13543	11441:41	0:50:41	5800085	11441:41:00	6577582	22197065:42	3:22

SoP 012 : Momentary Average Interruption Frequency Index (MAIFI) for JGY Dominant category

Sr. No	Month	Total Number of Momentary interruptions = Imi	Total Number of Consumers affected due to Momentary Interruption Events during the Reporting Period = Nmi	Number of Customer Momentary Interruptions = $Imi \times Nmi$	Total Number of Customers Served for the Areas = Nt	Cumulative Momentary Customer Interruptions = $\sum (Imi \times Nmi)$	MAIFI = $\sum (Imi \times Nmi) / Nt$
1	2	3	4	5 = 3 * 4	6	7 = $\sum (3 \times 4)$	8=7/6
1	Jul-24	7679	2129075	16349166925	2187493	16443201	7.52
2	Aug-24	7933	2133870	16927990710	2192932	17016236	7.76
3	Sep-24	7172	2119910	15203994520	2197157	15484363	7.05
Total		22784	6382855	145426968320	6577582	48943800	7.43

SoP 013 -- : Customer Average Interruption Duration Index (CAIDI) for JGY Dominant category

Sr. No	Month	Total Number of Sustained Interruptions during the Reporting Period = $\sum Ai$	Total Restoration time for Interruption Events = $\sum Ri$	Total Number of Interrupted Customers for Sustained Interruption events during the Reporting Period = $\sum Ni$	CAIDI = $\sum (Ri \times Ni) / \sum (Ai \times Ni)$ = SAIDI / SAIFI
1	2	3	4	5	6 = $(4 \times 5) / (3 \times 5)$
1	Jul-24	4246	3510:20	1929409	0:47
2	Aug-24	5305	4603:18	1949251	0:51
3	Sep-24	3992	3328:03	1921425	0:48
Total		13543	11441:41	5800085	0:49

Uttar Gujarat Vij Company Limited

Year 2024-25 (July-24 to Sept.-24)

SoP 010 - A : System Average Interruption Frequency Index (SAIFI) for other than

Aq & JGY Dominant Category

Sr. No	Month	Number of Sustained Interruptions during the Reporting Period = Ai	Number of Interrupted Customers for Sustained Interruption events during the Reporting Period = Ni	Total number of Customers Served for the Areas = Nt	Total Number of Interrupted Customers for Sustained Interruption events during the Reporting Period = $\sum (Ai \times Ni)$	SAIFI = $\sum (Ai \times Ni) / Nt$
1	2	3	4	5	6 = $\sum (3 \times 4)$	7 = 6 / 5
1	Jul-24	1930	908394	1386146	2865184	2.07
2	Aug-24	2142	945477	1397880	3382060	2.43
3	Sep-24	2113	896450	1404241	3005456	2.14
Total		6185	2750321	4188267	9252700	2.20

SoP 011 : System Average Interruption Duration Index (SAIDI) for other than Aq & JGY Dominant category

Sr. No	Month	Number of Sustained Interruptions during the Reporting Period = Ai	Total Outage Duration	Restoration time for each Interruption Event = Ri	Number of Interrupted Customers for Sustained Interruption events during the Reporting Period = Ni	Total Customer Interruption Duration = Ri x Ni	Total Number of Customers Served for the Areas = Nt	Cumulative Customer Interruptions Duration = $\sum (Ri \times Ni)$	SAIDI = $\sum (Ri \times Ni) / Nt$
		Nos	Hr : Min	Hr : Min	Nos	Hr : Min	Nos	Hr : Min	Hr : Min
1	2	3	4	5 = 4 / 3	6	7 = 5 * 6	8	9 = $\sum (5 \times 6)$	10 = 9 / 8
1	Jul-24	1930	1310:08	0:40:44	908394	1310:08:00	1386146	1402747:56	1:00
2	Aug-24	2142	1599:16	0:44:48	945477	1599:16:00	1397880	1567251:14	1:07
3	Sep-24	2113	1497:02	0:42:31	896450	1497:02:00	1404241	1542851:13	1:05
Total		6185	4406:26	0:42:45	2750321	4406:26:00	4188267	4512850:23	1:04

SoP 012 : Momentary Average Interruption Frequency Index (MAIFI) for other than Aq & JGY Dominant category

Sr. No	Month	Total Number of Momentary interruptions = Imi	Total Number of Consumers affected due to Momentary Interruption Events during the Reporting Period = Nmi	Number of Customer Momentary Interruptions = IMI * Nmi	Total Number of Customers Served for the Areas = Nt	Cumulative Momentary Customer Interruptions = $\sum (Imi \times Nmi)$	MAIFI = $\sum (Imi \times Nmi) / Nt$
1	2	3	4	5 = 3 * 4	6	7 = $\sum (3 \times 4)$	8=7/6
1	Jul-24	2267	1088953	2468656451	1386146	3900519	2.81
2	Aug-24	2426	1085545	2633532170	1397880	4124623	2.95
3	Sep-24	2445	1114959	2726074755	1404241	4145264	2.95
Total		7138	3289457	23480144066	4188267	12170406	2.89

SoP 013 – : Customer Average Interruption Duration Index (CAIDI) for other than AG & JGY Dominant category

Sr. No	Month	Total Number of Sustained Interruptions during the Reporting Period = $\sum Ai$	Total Restoration time for Interruption Events = $\sum Ri$	Total Number of Interrupted Customers for Sustained Interruption events during the Reporting Period = $\sum Ni$	CAIDI= $\sum (Ri \times Ni) / \sum (Ai \times Ni)$ = SAIDI/ SAIFI
1	2	3	4	5	6 = $(4 \times 5) / (3 \times 5)$
1	Jul-24	1930	1310:08	908394	0:29
2	Aug-24	2142	1599:16	945477	0:27
3	Sep-24	2113	1497:02	896450	0:30
Total		6185	4406:26	2750321	0:29

Uttar Gujarat Vij Company Limited

Year 2024-25 (July-24 to Sept.-24)

SoP 010 - A : System Average Interruption Frequency Index (SAIFI) for Overall

Dominant Category						
Sr. No	Month	Number of Sustained Interruptions during the Reporting Period = Ai	Number of Interrupted Customers for Sustained Interruption events during the Reporting Period = Ni	Total number of Customers Served for the Areas = Nt	Total Number of Interrupted Customers for Sustained Interruption events during the Reporting Period = $\sum (Ai \times Ni)$	SAIFI = $\sum (Ai \times Ni) / Nt$
1	2	3	4	5	6 = $\sum (3 \times 4)$	7 = 6 / 5
1	Jul-24	22939	3432590	4239237	14681426	3.46
2	Aug-24	24536	3502160	4256865	17103099	4.05
3	Sep-24	20488	3415749	4268355	14135631	3.31
Total		67963	10350499	12764457	45920156	3.59

SoP 011 : System Average Interruption Duration Index (SAIDI) for Overall Dominant category

Sr. No	Month	Number of Sustained Interruptions during the Reporting Period = Ai	Total Outage Duration	Restoration time for each Interruption Event = Ri	Number of Interrupted Customers for Sustained Interruption events during the Reporting Period = Ni	Total Customer Interruption Duration = Ri x Ni	Total Number of Customers Served for the Areas = Nt	Cumulative Customer Interruptions Duration = $\sum (Ri \times Ni)$	SAIDI = $\sum (Ri \times Ni) / Nt$
		Nos	Hr : Min	Hr : Min	Nos	Hr : Min	Nos	Hr : Min	Hr : Min
1	2	3	4	5 = 4 / 3	6	7 = 5 * 6	8	9 = $\sum (5 \times 6)$	10 = 9 / 8
1	Jul-24	22939	27445:41	1:11:47	3432590	27445:41:00	4239237	12405322:13	2:55
2	Aug-24	24536	29558:37	1:12:17	3502160	29558:37:00	4256865	14889579:34	3:34
3	Sep-24	20488	23000:15	1:07:21	3415749	23000:15:00	4268355	11772228:29	2:45
Total		67963	80004:33	1:10:38	10350499	80004:33:00	12764457	39067130:16	3:03

SoP 012 : Momentary Average Interruption Frequency Index (MAIFI) for Overall Dominant category

Sr. No	Month	Total Number of Momentary Interruptions = Imi	Total Number of Consumers affected due to Momentary Interruption Events during the Reporting Period = Nmi	Number of Customer Momentary Interruptions = Imi * Nmi	Total Number of Customers Served for the Areas = Nt	Cumulative Momentary Customer Interruptions = $\sum (Imi \times Nmi)$	MAIFI = $\sum (Imi \times Nmi) / Nt$
1	2	3	4	5 = 3 * 4	6	7 = $\sum (3 \times 4)$	8=7/6
1	Jul-24	34012	3855343	131127926116	4239237	25620873	6.04
2	Aug-24	34195	3855617	131842823315	4256865	26415840	6.21
3	Sep-24	33259	3872209	128785799131	4268355	25132615	5.89
Total		101466	11583169	1175297825754	12764457	77169328	6.03

SoP 013 -- : Customer Average Interruption Duration Index (CAIDI) for Overall category

Sr. No	Month	Total Number of Sustained Interruptions during the Reporting Period = $\sum Ai$	Total Restoration time for Interruption Events = $\sum Ri$	Total Number of Interrupted Customers for Sustained Interruption events during the Reporting Period = $\sum ni$	CAIDI= $\sum (Ri \times Ni) / \sum (Ai \times Ni)$ = SAIDI/ SAIFI
1	2	3	4	5	6 = $(4 \times 5) / (3 \times 5)$
1	Jul-24	22939	27445:41	3432590	0:50
2	Aug-24	24536	29558:37	3502160	0:52
3	Sep-24	20488	23000:15	3415749	0:49
Total		67963	80004:33	10350499	0:51

Uttar Gujarat Vij Company Ltd ,Mehsana

Half Yearly : (April-24 to Sept-24)

YEAR: 2024-25

Performa SoP 014: Statement Showing the ATC losses, collection efficiency and Billing Efficiency

Qtr.	Months	Units input (Mus)	Units Billed (Mus)	Billing Efficiency	Revenue Billed (Rs. Crore)	Revenue Collected (Rs. Crore)	Collection Efficiency* %	Business Efficiency	AT & C Losses %
		A	B	C=(B/A)*100	D	E	F=(E/D)*100	G=(C*F)/100	H=100-G
I	Apr-24	3096.119	2616.274	84.50	1449.130	1629.065	100.00	84.50	15.50
	May-24	3389.460	2822.644	83.28	1620.482	1814.404	100.00	83.28	16.72
	Jun-24	3007.335	2845.406	94.62	1753.211	2009.036	100.00	94.62	5.38
	Sub Total	9492.915	8284.325	87.27	4822.824	5452.505	100.00	87.27	12.73
II	Jul-24	2397.558	2533.356	105.66	1732.019	1901.454	100.00	105.66	-5.66
	Aug-24	2157.004	2320.840	107.60	1645.713	1892.882	100.00	107.60	-7.60
	Sep-24	2346.112	2278.977	97.14	1613.694	1920.389	100.00	97.14	2.86
	Sub Total	6900.675	7133.173	103.37	4991.426	5714.725	100.00	103.37	-3.37
Grand Total		16393.589	15417.498	94.05	9814.249	11167.230	100.00	94.05	5.95

* Collection Efficiency above 100% is taken as 100%

Uttar Gujarat Vij Company Limited

Year 2024-25 (July-24 to Sept.-24)

Performa SoP 015 : Meter faults

Consumer Category	No. of faulty meters at the start of the Quarter	No. of faulty meters added during the Quarter	Total No. of defective / faulty meter	No. of faulty Meters repaired and replaced	No. of faulty meters pending at the end of the Quarter
	1	2	3=2+1	4	5=3-4
Single Phase	18414	17204	35618	9688	25930
Three Phase	1968	5435	7403	4441	2962
HT	0	0	0	0	0
Total	20382	22639	43021	14129	28892

Uttar Gujarat Vij Company Limited							
Year 2024-25 (July-24 to Sept.-24)							
Performa SoP 016 : Compensation details							
COMPENSATION DETAILS							
Sr. No.	Service Area	Compensation payable to consumer for the period of default in case of violation of standard	Claimed		Payable		
			No. of cases	Amount (Rs.)	No. of cases in which compensation is payable	Amount payable (Rs.)	Amount paid (Rs.)
1	Registration of complaint and intimation of Unique complaint Number to the Complainant	Rs. 50/- for each default	Nil	Nil	Nil	Nil	
2	Issuance of Demand Note for New Connection, Load Enhancement, Shifting of connection at other premises, Conversion of Service, Temporary Supply, Shifting of Service Connection in exiting premises, Deviation of line and Shifting of equipments	Rs. 50 for each day of default.					
3	New Connection, Load Enhancement, Shifting of connection at other premises and Conversion of Service where no Network erection and/or augmentation is required.	Rs. 50 for each day of default.					
4	New Connection, Load Enhancement, Shifting of connection at other premises and Conversion of Service where Network erection and/or augmentation is required.	Rs. 50 for each day of default.					
5	Release of temporary supply	Rs. 50 for each day of default.					
6	Shifting of meter/services in the existing premises	Rs. 50 for each day of default.					
7	Shifting of LT/HT lines						
8	Shifting of Transformer structures						
9	Settlement of amount for refunding of excess amount after completion of work.	Rs. 50 for each day of default.					
10	Transfer of Service Connection with respect to change of name or change of ownership						
11	Application from consumer requesting Change in Tariff Class/Category.	Rs. 50 for each day of default.					
12	Complaint Related to Billing	Rs. 50 for each day of default.					
13	Replacement of Meter	Rs. 25/- for each day of default subject to maximum of Rs. 1500/- for LT connections and Rs. 250/- for each day of default subject to maximum of Rs. 2500/- for HT connections.					
14	Reconnection of Supply	Rs. 25/- for each six hours (or part thereof) of delay in restoration of supply subject to maximum Rs. 500/- for LT connection and Rs. 50/- for each six hours (or part thereof) of delay in restoration of supply subject to maximum Rs. 1000/- for HT connection.					
15	More than 2 interruptions in a day to the consumer for the reasons not attributable to the nature of fault as mentioned in Clause 8.4 of these Regulations.	Rs. 25/- for each interruption subject to maximum Rs. 500/- for LT connection and Rs. 50/- for each interruption subject to maximum Rs.1000/- for HT connection.					
16	Failure to restore power supply in case of blowing of fuse of LT side distribution transformer, at consumer premises, trouble of MCB of distribution transformer, loose connection at pole, MCB or meter, etc.	Rs. 50/- per hour per Consumer for the first two hours of default. Thereafter Rs. 100/- per hour per Consumer subject to maximum of Rs. 500/- per day for LT consumer and maximum of Rs. 2000/- per day for HT consumer.					
17	Failure to restore power supply in case of blowing of HT side fuse of distribution transformer						
18	Failure to restore power supply in case of HT and LT line fault						
19	Failure to restore power supply in case of Distribution transformer failure						
20	Failure to restore power supply in case of failure of underground service or underground HT/LT cable						
21	Scheduled Power Outage						
22	Site Visit and Intimation to the Consumer about likely time to resolve the complaint related to voltage fluctuation.	Rs. 200/- for each instance for each complaint.					
23	Complaint of Neutral Voltage	Rs. 250/- for each complaint					
24	Complaint regarding Voltage variations at the point of commencement of supply.	Rs. 25/- for each day of default subject to maximum of Rs. 500/-					

Uttar Gujarat Vij Company Limited								
Year 2024-25 (July-24 to Sept.-24)								
Performa SoP 017: Individual Complaint where Compensation has been paid								
Sr. No.	Complaint No.	Date of filing Complaint/ Automatic Compensation	Consumer No. and Name and Address of the Consumer	Nature of Complaint	Reference Standard of Performance	Amount of compensation (Rs.)	Whether Compensation paid automatically or Consumer has to approach CGRF to get compensation	Whether CGRF has upheld demand of Consumer of Compensation and if Yes, date of order of CGRF and date of compensation paid
Nil								

Uttar Gujarat Vij Company Limited

Year 2024-25 (July-24 to Sept.-24)

Performa SoP 018: Unauthorised Use of electricity

No. of cases booked	No. of cases where UUE is established by the Licensee	No. of cases where appeal filed by the consumer before the Appellate Authority	No. of cases decided by the Appellate Authority in favour of the Licensee	No. of cases decided by the Appellate Authority in favour of the consumer
1647	1647	1	Judgement awaited	Judgement awaited

Uttar Gujarat Vij Company Limited

Year 2024-25 (July-24 to Sept.-24)

SoP 019: Theft of electricity

No. of cases booked	No. of complaints filed by the Licensee in Police Station	No. of cases in which judgment delivered by the Special Court	No. of cases decided by the Special Court in favour of Licensee	No. of cases decided by the Special Court in favour of Consumer
2308	2308	0	0	0